| | Co | ates Inspection | | | |
|---|---|--------------------------|--|---------------------------|---|
| Vac Trailer | | | | | Pump Photos |
| See Pump Photo Log for req | uired pictures | | Asse | t # 1145222 | |
| Make/ Model Vermee Year 2019 | er | | otor - Make / Mod <u>el</u> rial Number | Yanmar Y9B3464 2506 | Data Plate |
| Inlet Dia Outlet C | tures or options for t ameter: Diameter: Volume: | he machine: 75MM 100MM | Self Priming Frame Mount | □ Trailer Mount □ □ | 4-Corner Photos Left-Front Corner Left-Rear Corner Right-Front Corner Right-Rear Corner Damage Damage Damage |
| Overall Appearance: Control Station\Operator Station Sheet metal\Fiberglass Condition Paint Lights | Good Fair | Poor | | | |
| Control Station Opc Yes Operator Controls Gauges Operational? | erates No N/A | Comments: | | | Hour Meter Guages Damage Damage |
| Engine or Electric Motor: Power: Diesel Yes Does it start? | Gas 🗌 No | Electric Comments: | _ | | Right Side hood open Left Side hood open |
| Does it start? Did it need to be jumped? Acceptable Power Unusual Noises | | Commonte. | | | |
| Chassis Frame Condition Trailer Lights Trailer Electrical Connections Trailer Brakes Switches | Good | | Inoper Missing N/A | Comments: | Hitch |
| Tire Condition: Left Brand- Goodyear Size- 225 /75 Condition- Fair | Right Brand- Kumho Size- 225/16 Condition- | Good | | | Tire pictures at a 45 degree angle showing the tread and side walls Left Right |