Coates Inspection Checklist Boom Lift (Electric or Internal Combustion)		Photos
See Boom Lift Photo Log for required pictu	Boom Lift Photo Log for required pictures Asset # 1148798	
Comments: Trailer mounted Boom lift - Dispose		Data Plate
Features: Drive Syatem 2WD 4WD N/A Trailer mounted Yes Notes A AC Chord to Basket	Max Lift Height Platform size (L x W) Yes No	4-Corner Photos Left-Front Corner Left-Rear Corner Right-Front Corner Right-Rear Corner Damage Damage Damage Damage
Overall Appearance: Control Station\Operator Station Sheet meta\\Fiberglass Condition Paint Lights Control Station Operates Yes No N// Operator Controls: Platform Operator Controls: Ground Gauges Operational?		Hour Meter Ground Controls Basket Controls Guages Damage Damage
Engine or Electric Motor: Power: Diesel Gas Yes No Does it start?	Dual Fuel ☐ Electric ☐ Petrol ■ Comments:	Right Side hood open Left Side hood open
Operates Yes No Ye Yes No Yes Y	Leaks s No Comments:	Pump Cylinders Drive Motor Damage Damage Damage Damage
Chassis: Good Fair Frame Condition Mast/ Boom Sections Boom Extension Wear Guides Basket Condition Outriggers and Pads Condition Rotational Gear Condition Extendable Axle TumTable Bearing Play	r Poor Inoper Missing N/A Comments:	Rotational Gear Boom (Extended) Basket
Irre Condition: Left - Rear Left - Front Brand- Brand- Triangle Size- Size- Condition- Good Condition- Condition-	N/A Right-Front Right - Rear Brand- Transporter Brand- Size- 185R14C Size- Condition- Good Condition-	Tire pictures at a 45 degree angle showing the tread and side walls Left-Front Left-Rear Right-Front