

Condition Report



Service

Greys Auction Perth
WD600-6 | 55016

Australia - Ph: 1300 566 287 | komatsu.com.au

New Zealand - Ph: 0800 566 2878 | komatsu.co.nz

New Caledonia - Ph: +687 43 53 06 | komatsu.com.au

KOMATSU
Creating value together



General Information		Customer Details	
Case Number	AD61161741060937	Customer Name	Greys Auction Perth
Date	04/03/2025	Customer No.	
Equipment	Wheel Dozer	Location	Jandakot
Model	WD600-6	Contact Name	Taine Yates
Serial No.	55016	Contact No	0452482963
S.M.R	23127	Contact Email	
Engine Serial No.	512384	Service Details	
Technician	Ruby Livingstone		
Supervisor	Kieron Hinsley		
Case Description	Condition Report on a used WD600-6		
Report Completed By	Ruby Livingstone	Component Report Recommended	
		Delivery Name	

Safety Report

Photo of I.D Plate (as required)	Yes	All warning decals in place and in good condition	Yes
Windows free from cracks with clear visibility	No	Access steps and handrail intact and operational	Yes
Seat and seat belt undamaged and operational	Yes	Mirrors undamaged and operational	Yes
Lights, beacon and instruments undamaged and operational	Yes	Horn and reversing alarms operational	Yes
Fuel system hoses and tubes free of leakage	Yes	Quick hitch safety lock in place and operational	N/A
Operation safety lever in place and working	Yes	Monitor panel operational	Yes
Machine camera's operational	N/A	Machine photos attached	Yes
Accumulator functioning correctly	Yes	PPC lock lever operational	Yes
ROPS/FOPS tight secure and free of damage	Yes	Brake and parking brake operating correctly	Yes
Steering system free from leaks and wear and operating correctly	Yes	Cabin egress and emergency exit points clear of obstructions	Yes
Door Seals and latches in good condition and functioning to prevent dust entry into cabin	Yes	Recirculation filters functioning correctly (Cabin fresh and clear of dust in air)	Yes

General Inspection

All lockable panels functioning correctly	Yes	Radiator clean and free of leaks	Yes
Hydraulic cylinders free of oil leaks	Yes	Under machine free of leaks	Yes
Hydraulic system free of leaks	Yes	Frame and work equipment free of cracks and wear	Yes
Tyres, rims secure and free of damage and wear	Yes	Work equipment pin and bush free of wear	Yes
Engine free of oil and coolant leaks	Yes	Outer body panels and paint in good condition	Yes

General Inspection

Engine air system in good condition	Yes	UHF and radio aerials attached and operational	Yes
KOMTRAX aerial attached and transmitting	N/A	Complete Manual Downloads where required for VHMS, PLM and GE	N/A
E-stop in good condition and operational	Yes	Windows and wiper system operational	Yes
Auto greaser system operational	Yes	Check and clear faults on monitor	Yes
Machine free of unusual Noises	Yes	Throttle, travel movement, control levers operating correctly	Yes
Drive shafts tight and free of movement	Yes	Battery Terminals and frame secure and free of corrosion	Yes
Blade, Bucket, Ripper and GET in good condition, If No please include photo of ID plate	Yes		

Comments

Component:
Steering system

Comments:
LH and RH steering cylinders in good condition

Diagrams



Component:
Hydraulic cylinders

Comments
blade tilt cylinder in good condition

Diagrams





Component:
Tyres and rims

Comments:
All tyres in used condition, few minor
defects in tyres

Diagrams



Diagrams



Component
Blade, Bucket, Ripper and GET

Comments:
Blade, Bucket, Ripper and GET in good condition

Diagrams



Diagrams



Component:
Drive shafts

Comments:
Drive shafts have usual wear and tear

Diagrams



Component:
Work equipment

Comments:
Grease lines and injector in good order

Diagrams



Diagrams



Component:
Windows

Comments:
Front LH windscreen cracked. The tint on the rear windscreen is bubbly

Diagrams



Diagrams



Component:
Lights, beacon and instruments

Comments:
In good condition

Diagrams



Diagrams



Component:
Door Seals and latches in good condition
and functioning to prevent dust entry into
cabin

Comments:

Diagrams



Component:
Radiator

Comments:
In good condition

Diagrams



Diagrams



Diagrams





Component:
Lockable panels

Comments:

Diagrams



Component:
Outer body panels and paint

Comments:
Paint and body panel in good order-
normal amount of wear around machine

Diagrams



Component:
UHF and radio aerials

Comments:

Diagrams



Component:
Monitor panel

Component:
Dash upholstery appear in good condition

Diagrams



Component:
Photo of I.D Plate

Comments:

Diagrams



Component:
Machine photos attached

Comments:

Diagrams



Signature

Name	Ruby Livingstone
Position	3rd Year Apprentice
Employer	Komatsu
Date	04/03/2025



Terms and Conditions

1. Visual inspection

- a. This visual inspection report (**Inspection Report**) is strictly confidential and has been prepared by Komatsu Australia Pty Ltd (ABN 63 053 514 739) or Komatsu New Zealand Limited (NZBN 9429050679508) (**Komatsu**) for review only by the Customer named in the Report. This Inspection Report must not be provided to, or relied upon by, any other persons or organisations. Any person who reads the contents of this Inspection Report does so agreeing and acknowledging the scope, limitation and disclaimers set out in this Inspection Report. This Inspection Report must not be reproduced or copied, in whole or in part without the prior written consent of Komatsu.
- b. The scope of this Inspection Report is limited to completing a visual inspection and assessment of the specified machine (**Machine**) as at the date of inspection by Komatsu personnel within the scope of work agreed with the Customer, or for a "PM Clinic Report", "Defect Report", "New Machine Report", "Mining Hex UC Report", "Core Installation Report" or "Core Return Report" (as applicable), within the scope of work specified, or for a "Condition Report", "PM Service Report", "Rental Receiving Report", "Rental Delivery Report" or "Final Inspection Report" (as applicable), within the scope of work specified (as indicated by those inspection items marked as 'Yes' or 'No') (**Scope**). Komatsu will complete the Scope of this Inspection Report by observing and viewing the visual condition and status of the Machine at the date of the inspection. Any instrument readings, indicators, warning lights or other signaling devices on or in the Machine will be taken to be accurate without further investigation, in particular the Machine's hourly service meter unit (**SMU**) indicator will be taken to be accurate and representative of the actual number of hours performed by the Machine. Komatsu in no way represents or warrants the instruments, readings and/or data used to complete this Inspection Report are true and accurate.

2. Limitation of liability

To the extent permitted by law, Komatsu and the author of this Inspection Report expressly exclude all liability for loss, damage or injury, including Consequential Loss, whether under contract, tort, equity or otherwise, caused directly or indirectly by any errors in, omissions from, or actions taken or not taken because of the information or opinions provided in this Inspection Report. In this clause 2, "Consequential Loss" means all loss of actual or anticipated profit, loss of use, loss of productivity, loss of revenue, business interruption of any nature, loss of contracts, loss of opportunity, increased costs and expenses, wasted expenditure, loss or corruption of data, loss arising from delay, loss by reason of shutdown or non-operation or increased cost of borrowing capital or financing, loss of business reputation or goodwill and all special, indirect and consequential losses whether caused by or contributed to by a breach of contract or statute, breach of warranty (express or implied), tort, strict liability or any other cause whatsoever.

3. Disclaimer

- a. This Inspection Report is not an all-encompassing report dealing with the issues and defects under review from every aspect. It is a reasonable attempt to identify the condition of the Machine and/or any obvious or significant defects, faults or issues apparent at the time of the visual inspection and which are within the Scope. Where a defect or issue is identified it is recommended that prompt action is taken to investigate and appropriately rectify the identified defect or issue.
- b. No warranty is given as to the accuracy or completeness of the information provided in this Inspection Report, including any data, research, models, charts, forecasts, recommendations or other material and no responsibility is accepted by Komatsu or its employees, contractors or agents for any loss or damage arising from reliance on the information provided.
- c. No warranty is provided in relation to the Machine or any component of it.

Terms and Conditions

4. Qualifications and assumptions

This Inspection Report and the opinions expressed in it are subject to the following qualifications and assumptions:

- a. that all information given to the author of this Inspection Report and Komatsu is correct, complete, reliable, not misleading (by omission or otherwise) and prepared with reasonable care; and
- b. any documents referred to, or relied upon in this Inspection Report have been assessed by the author at their face value and neither the author or Komatsu has made further investigations of the circumstances in which the documents were brought into existence unless this Inspection Report specifically provides otherwise.

5. Statutory warranties

All conditions and warranties of any type in relation to the goods or services are excluded to the maximum extent allowed by the law. Nothing in these terms and conditions limit those provisions of the Competition and Consumer Act 2010 (Cth), the Consumer Guarantees Act 1993 nor any other statutes, rules or regulations from time to time in force in Australia, New Zealand or New Caledonia which imply or guarantee certain conditions or warranties or impose obligations on Komatsu which conditions, warranties and obligations cannot, or cannot except to a limited extent be excluded, restricted or modified. If any such statutory provisions apply, then to the extent to which Komatsu is entitled to do so, its liability shall be limited at its option to: (a) in the case of goods: (i) the replacement of goods or the supply of equivalent goods; or (ii) the payment of the cost of replacing the goods or of acquiring equivalent goods; or (iii) the payment of the cost of having the goods repaired; or (iv) the repair of the goods; and (b) in the case of services: (i) the supply of the services again; or (ii) the payment of the cost of having the services supplied again.

6. General

If the Inspection Report is provided in Australia, the document is governed by the laws of New South Wales. These terms and conditions are in addition to Komatsu's Terms and Conditions - Parts and Service, available at <http://www.komatsu.com.au/Pages/Terms-and-Conditions.aspx>, which governs the provision of services provided by Komatsu (unless otherwise agreed in writing).

If the Inspection Report is provided in New Zealand, the document is governed by the laws of New Zealand. These terms and conditions are in addition to Komatsu's Terms and Conditions - Parts and Service, available at <https://www.komatsu.co.nz/pages/terms-conditions>, which governs the provision of services provided by Komatsu (unless otherwise agreed in writing).

If the Inspection Report is provided in New Caledonia, the document is governed by the laws of New Caledonia. These terms and conditions are in addition to Komatsu's General Terms and Conditions of Sale and of Provision of Services, which govern the provision of services provided by Komatsu (unless otherwise agreed in writing).