



MAZDA RECALLS

View your vehicles details below

Model: RX8 6 SPEED MANUAL WITH LEATHER PACK AND SAT NAV
2005

VIN: JM0FE103100103745

Year:



NO OUTSTANDING RECALLS

0 Active Recalls | 0 Pending Recalls

Result returned on: 17/05/2022 09:06 AM AEST

TAKATA - DRIVER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

17/09/2021

RECALL CODE

R201602

PRA NUMBER

2015/14761

Summary

In the affected vehicles continued exposure of the driver-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact all affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the driver-side airbag inflator at no charge.

TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED
17/09/2021

RECALL CODE
R201702

PRA NUMBER
2015/14761

Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.

RX - 8 (FE) FUEL PUMP DISCHARGE PIPE CRACK RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED
17/09/2021

RECALL CODE
R201808

PRA NUMBER
2016/15789 REC-000877

Summary

The fuel pump discharge pipe may have insufficient durability. The effects of fuel pressure and engine/exhaust heat may cause the pipe to deteriorate.

Risk

If the vehicle continues to be used in this condition, continued deterioration may lead to a crack in the pipe and cause a fuel leak, creating an increased risk of fire.

Remedy

Mazda Australia will contact all affected customers by mail. Customers will be advised to present their vehicle to their preferred Mazda Dealer for the replacement of the fuel pump retainer rings and the fuel filter body and installation of thermal insulation pads onto the fuel tank at no charge.

RX - 8 (FE) FUEL PUMP AND RETAINING RINGS RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED
17/09/2021

RECALL CODE
R201807

PRA NUMBER
2016/15789 REC-000876

Summary

The plastic fuel pump retaining rings on the fuel tank may be exposed to heat from the engine and exhaust due to insufficient thermal insulation, causing heat deterioration of the plastic material of the pump retaining rings. In addition, a reaction force from the gasket (seal rubber) may be applied to the fuel pump rings.

Risk

If the vehicle continues to be used in this condition, continued deterioration may lead to a crack in the fuel pump rings and cause a fuel leak, creating an increased risk of fire.

Remedy

Mazda Australia will contact all affected customers by mail. Customers will be advised to present their vehicle to their preferred Mazda Dealer for the replacement of the fuel pump retainer rings and the fuel filter body and installation of thermal insulation pads onto the fuel tank at no charge.
