



Vehicle History Summary



| | |
|-----------------|-------------------|
| Fleet # | 111 |
| Registration | KST34 |
| Make | Kenworth |
| Model | K104 |
| VIN / Chassis # | 6F50000003A423863 |
| Build Date | 2003 |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|---------------|---|-------------------------------|
| S-5151 | 12/11/2022 | 232026 | 0 | A - 30 Days | | Colin Scott |
| S-5075 | 14/10/2022 | 225282 | | A - 30 Days | | Kelvyn Fuller |
| S-5041 | 07/10/2022 | 222744 | 0 | A - 30 Days | | Colin Scott |
| S-5037 | 01/10/2022 | 220294 | 0 | B - 30k | | Colin Scott |
| R-2143 | 29/09/2022 | 0 | 0 | ELECTRICIAL | Check condenser by flushing with nitrogen. | ROTHALE PTY LTD |
| S-4990 | 10/09/2022 | 212886 | 0 | A - 30 Days | headlight | Colin Scott |
| R-2138 | 10/09/2022 | 0 | 0 | ELECTRICIAL | Fit high temp plug LH headlamp. | ROTHDALE |
| R-2137 | 07/09/2022 | 0 | 0 | Air Leak | fit up spare unit. evacuate and re gas. | ROTHDALE |
| S-4965 | 20/08/2022 | 205553 | 0 | A - 30 Days | | Colin Scott |
| R-2134 | 09/08/2022 | 201265 | 0 | Brake | | |
| S-4840 | 16/07/2022 | 192084 | 0 | A - 30 Days | | Colin Scott |
| S-4817 | 18/06/2022 | 188487 | 0 | A - 30 Days | | Colin Scott |
| R-2092 | 17/06/2022 | 0 | 0 | HUB SEAL LEAK | REPLACE LEAKING HUB SEAL | SH&M Fuller Transport Repairs |
| S-4721 | 21/05/2022 | 188416 | 0 | A - 30 Days | | Colin Scott |
| S-4686 | 23/04/2022 | 185659 | 0 | A - 30 Days | | Colin Scott |
| R-2065 | 10/04/2022 | 0 | 0 | Misc | REMOVE AND REPLACE TREADLE VALVE | SH&M Fuller Transport Repairs |
| R-2055 | 23/03/2022 | 183229 | 0 | MICS | R & R DOOR LOCKS, FRONT SPRINGS, SHOCK PINS AND BUSHES, REAR SHOCKIE BUSHES, REAR CAM BUSH KITS, REAR HUB SEAL, FRONT DIFF INPUT UNIVERSALS, RADIATOR SUPPORT ROD ENDS, WEATHER SHIELD, DASH BULBS, FUEL LEVEL SENSOR REPAIR TO FUEL HOSE LEAK, POWER STEER HOSE LEAK | SH&M Fuller Transport Repairs |
| S-4685 | 18/03/2022 | 183233 | 0 | A - 30 Days | | Colin Scott |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|--|--|-----------------|
| R-2060 | 06/03/2022 | 0 | 0 | ELECTRICIAL | FIT UP NEW R/D , TX VALVE AND COMPRESSOR (supplied) EVACUATE , ADD OIL AND REGAS WITH R134A. FIT UP NEW DRIVE BELT | ROTHALE PTY LTD |
| R-2049 | 04/02/2022 | 0 | 0 | STARTER | PICK UP AND DELIVER NEW STARTER TO SHAM | ROTHALE PTY LTD |
| S-4455 | 03/02/2022 | 183218 | 0 | B - 30k | FURTHER REPAIRS Front spring bushes & pins Position 5,6 hub seal Position 3,4,5,6 S Cam & bushes Uni joint on front diff Fuel leak - hose Power steering leak - near pump Rod end for radiator stays Door locks Lights | Colin Scott |
| S-4441 | 27/01/2022 | 183101 | 0 | A - 30 Days | | Colin Scott |
| T-1331 | 17/01/2022 | 0 | 0 | STRIP & FIT | 2 STRIP AND FIT 2 BALANCE | Tyreright |
| S-4293 | 13/01/2022 | 185090 | 0 | A - 30 Days | replace left side cab grab rail | Colin Scott |
| S-4226 | 16/12/2021 | 166139 | 0 | A - 30 Days | | Colin Scott |
| I-11 | 20/11/2021 | 155709 | 0 | HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS | | Colin Scott |
| S-4200 | 18/11/2021 | 155709 | 0 | B - 30k | | Colin Scott |
| S-4215 | 18/11/2021 | 155709 | 0 | C - Annual | | Colin Scott |
| T-1283 | 16/09/2021 | 0 | 0 | FIT NEW | | Tyreright |
| T-1282 | 15/09/2021 | 0 | 0 | strip and fit | | Tyreright |
| S-3215 | 28/08/2021 | 122898 | 0 | B - 30k | | Colin Scott |
| S-3214 | 28/08/2021 | 122898 | 0 | A - 30 Days | | Colin Scott |
| T-1263 | 28/07/2021 | | | Rotate | | Tyreright |
| T-1262 | 28/07/2021 | | | Re - Treads | | Tyreright |
| S-4130 | 17/07/2021 | 106007 | 0 | A - 30 Days | | Colin Scott |
| T-1248 | 07/07/2021 | | | STIP & FLIP | | Tyreright |
| S-4143 | 03/07/2021 | 100186 | 0 | A - 30 Days | | Colin Scott |
| R-1347 | 03/07/2021 | | | AIR Conditioner | FIT NEW A/C HEATER MOTOR SUPPLIED. A/C COMPRESSOR SEIZES , FIT UP NEW UNIT. FLUSH CONDENSOR AND IT NEW R/D . REGAS SYSTEM | ROTHALE PTY LTD |
| S-4152 | 19/06/2021 | 93961 | 0 | A - 30 Days | | Kelvyn Fuller |
| S-3933 | 12/06/2021 | 91109 | 0 | A - 30 Days | | Kelvyn Fuller |
| S-3934 | 12/06/2021 | 91109 | 0 | B - 30k | | Kelvyn Fuller |
| T-1224 | 02/06/2021 | | | STRIP | | Tyreright |
| S-3938 | 30/05/2021 | 84990 | 0 | A - 30 Days | | Kelvyn Fuller |
| T-1195 | 07/05/2021 | | | STRIP | | TYRE EVOLUTION |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|-------|-------|-----------------|---|-----------------|
| T-1161 | 15/04/2021 | | | Pressure Test | | TYRE EVOLUTION |
| T-1162 | 15/04/2021 | | | Rotate | | TYRE EVOLUTION |
| R-1303 | 09/04/2021 | 60104 | | oil leak | REPAIR OIL LEAK REMOVE AND REPLACE TURBO DRAIN PIPE. REMOVE AND REPLACE BOLTS ON L/H CAB MOUNT. REPAIRS TO DRIVERS DOOR | SH&M Fuller |
| R-1301 | 01/04/2021 | | | MISC | REPLACE TURBO MOUNT GASKET, TURBO DRAIN GASKET, EXHAUST MANIFOLD GASKET. MACHINED MANIFOLD. TRAVEL TO SITE TO HARD WIRE TPS AND REPLACE EXHAUST MANIFOLD | TRANSMARINE |
| S-3638 | 19/03/2021 | 58536 | 0 | A - 30 Days | | Colin Scott |
| S-3639 | 19/03/2021 | 58536 | 0 | B - 30k | | Colin Scott |
| T-1095 | 22/02/2021 | | | Pressure Test | | TYRE EVOLUTION |
| T-1096 | 22/02/2021 | | | Puncture | | TYRE EVOLUTION |
| S-3138 | 19/02/2021 | 52697 | 0 | A - 30 Days | | Colin Scott |
| R-1256 | 06/02/2021 | | | AIR Conditioner | LOCATE EXCESS AIR GAP ON AUXILARY A/C CLUTCH. FIT UP NEW ALERATURE. | ROTHALE PTY LTD |
| R-1249 | 30/01/2021 | | | MISC | REMOVE COMPRESSOR AND FIT NEW UNIT . FIT NEW R/D X VALVE AND THERMOSTAT. REMOVE EVAPORATOR CORE AND CLEAN FOR BETTER FILTER | ROTHALE PTY LTD |
| S-3682 | 22/01/2021 | 45898 | 0 | A - 30 Days | | Colin Scott |
| T-1031 | 23/12/2020 | | | New | BALANCE | TYRE EVOLUTION |
| R-1210 | 12/12/2020 | | | Air Conditioner | GO TO VEHICLE CHECK A/C LOCATE FAULTY . AUCTION AND DISCHARGE HOSES. REPLACE BOTH EVACUTATE AND REGAS . SWITCH WIRNG , CONNECT NEW PROTENTIONETRE WITH ENVONMENT PROOF PLUG . | ROTHALE PTY LTD |
| S-3208 | 28/11/2020 | 27431 | | A - 30 Days | | Kelvyn Fuller |

Signed: _____

Name: _____

Date: _____