

B53 - 2017 DAF FTTXF105

2019 DAF FTTXF105

Unit #: B53
 Tag #: XV43GK
 Kilometers 837,300
 Serial #: JG242803
 ENGINE NO A360849

Date	Kilometers	Notes	Vendor	Employee	Total Cost
17/02/2021	288,851	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -38DEG REPLACED REAR DRIVE BRAKE PADS	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00
31/03/2021	315,633	CARRY OUT 100,000 KM SERVICE AS PER SERVICE SHEET ZS DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -35DEG	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00
4/05/2021	334,874	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI, AL CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -36DEG CCH@460HRS REPAIRED L/H REVERSE LIGHT WIRING ===WARRANTY=== FAN CLUTCH FRONT R/H CALIPER	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00
29/06/2021	354,100	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -40DEG CCH@464 =WARRANTY= ENGINE OIL LEAKS	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00
30/07/2021	373,051	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI ZS REPLACED OIL AND FILTES COOLANT -42 DEG CCH@464	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00

6/09/2021 394,448 CARRIED OUT 100,000KM SERVICE AS PER SERVICE SHEET JI, RS
DID NOT CHANGE ENGINE OIL OR FILTERS
CHECKED COOLANT -44DEG
ADJUSTED VALVES , \$0.00

Maintenance Performed **Cost**
SERVICE \$0.00
Total: \$0.00

15/10/2021 417,884 CARRY OUT 20,000KM SERVICE AS PER SERVICE SHEET JI,AL
CHANGED ENGINE OIL AND FILTERS
COOLANT -42
CCH 470
REPLACE BELTS
===WARRANTY===
MANIFOLD GASKETS
STEERING BOX , \$0.00

Maintenance Performed **Cost**
SERVICE \$0.00
Total: \$0.00

22/12/2021 434,722 REPORT #24698 RS
REPLACED FAULTY START BATTERIES
REPLACED INTERIOR LIGHTS
REPAIRED SUN VISOR , \$0.00

Maintenance Performed **Cost**
REPAIRS \$0.00
Total: \$0.00

24/12/2021 437,762 CARRIED OUT 20,000KM SERVICE AL
DID NOT CHANGE OIL OR FILTER
COOLANT -35DEG
CCH@485
REPLACED LH MUD GARD
REPLACED MISSING RH STEERING STOP
BOLT , \$0.00

Maintenance Performed **Cost**
SERVICE \$0.00
Total: \$0.00

17/02/2022 457,357 CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI, RS
CHANGED ENGINE OIL AND FILTERS
CHECKED COOLANT -40DEG
SERVICED CAB COOLER @685 HRS , \$0.00

Maintenance Performed **Cost**
SERVICE \$0.00
Total: \$0.00

17/03/2022 470,626 DRIVERS FAULT #26883 AL
CHECKED ALL FAULT CODES, ACC HAD
WHEEL SPEED FAULTS 1006 KM/H
CLEARED ALL CODES ROAD TESTED OK , \$0.00

Maintenance Performed **Cost**
REPAIRS \$0.00
Total: \$0.00

21/03/2022 476,457 CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS, JI , \$0.00

DID NOT CHANGE ENGINE OIL OR
 FILTERS
 CHECKED COOLANT -42DEG
 CCH@ 834
 == WARRANTY==
 OIL LEAK OUT OF REAR OF
 COMPRESSOR
 L/H STEER CALLIPER SEIZED
 REAR R/H LOWER SHACKLE BUSH

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

12/05/2022	496,637	CARRIED OUT 100,000KM SERVICE AS PER SERVICE SHEET AL JS CHANGED OIL AND FILTERS COOLANT -43DEG ADJUSTED TURN TABLE CCH@857 ==DID NOT CHANGE COOLANT HOSES NIL STOCK== DRIVERS FAULT #26893,26894 AND 26895 REPLACED FAULTY STOP TAIL LIGHT AND REPAIRED BROEN WIRES LH REAR LIGHTS RESEALED TRANS SOLINOID	\$0.00
------------	---------	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

7/07/2022	517,053	CARRY OUT 20,000KM SERVICE AS PER SERVICE SHEET RS DID NOT CHANGE ENGINE OIL AND FILTERS COOLANT -46 860CCH ==COOLANT HOSES STILL TO BE REPLACED== (HAD TO GO)	\$0.00
-----------	---------	--	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

30/08/2022	540,458	CARRIED OUT 20000KM SERVICE AS PER SERVICE SHEET ZS AL CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -42 DEG CCH@860 REPLACED ALL COOLANT AND HEATER HOSES	\$0.00
------------	---------	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

17/10/2022	564,565	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET ZS AL DID NOT CHANGE OIL OR FILTERS COOLANT - 44 DEG CCH@898 REPAIRED EARTH LEAD TO CAB COOLER REPAIRED LEAKNG ADBLUE LINE	\$0.00
------------	---------	---	--------

Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
10/11/2022	575,180	REPLACED FAULTY EBS LEAD AL	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
Total:			\$0.00
30/11/2022	583,366	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS AL CHANGED ENGINE OIL AND FILTERS COOLANT@-45 DEG SERVICED CAB COOLER @965H	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
18/01/2023	610,157	CARRY OUT 100,000 KM SERVICE AS PER SERVICE SHEET ZS, JS DW DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -44DEG CCH@1125 ADJUSTED VALVES	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
ANNUAL CHECK			\$0.00
Total:			\$0.00
27/02/2023	623,748	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS DW CHANGED ENGINE OIL AND FILTERS COOLANT@-44DEG CAB COOLER SERVICED @1231HRS	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
21/04/2023	642,760	TRUCK BROKE DOWN LOST ALL DRIVE AND NEUTRALISED ZS, BR BLOWN GEARBOX / REPLACED GEARBOX REPLACED CLUTCH COMPONENTS PRESSURE PLATE CLUTCH DISC THROWOUT BEARING SPIGOT BEARING MACHINED FLYWHEEL / REPLACED FLYWHEEL BOLTS REPLACED REAR MAIN SEAL	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
Total:			\$0.00
5/05/2023	647,797	CARRY OUT 20000 SERVICE AS PER SERVICE SHEET BR ZS DID NOT CHANGE OIL OR FILTERS COOLENT -41 REPLACED STEER PADS REPLACE ENGINE TENTIONERS AND	\$0.00

BELTS

		Maintenance Performed	Cost
		SERVICE	\$0.00
		Total:	\$0.00
23/06/2023	662,706	CARRIED OUT 20,000KM SERVICE AS PER SHEET DW ZS CHANGED ENGINE OIL AND FILTERS COOLANT @-45 DEG CCH @1301HRS REPLACED BATTERIES REPLACED BOTH ENGINE MOUNTS REPLACED FRONT R/H STEER MUDGUARD ===JOBS TO BE DONE=== SUMP GASKET	\$0.00
		Maintenance Performed	Cost
		SERVICE	\$0.00
		Total:	\$0.00
22/08/2023	682,528	CARRIED OUT 20,000KM SERVICE AS PER SHEET BR DID NOT CHANGE ENGINE OIL OR FILTER COOLANT @ -43 CCH AT 1306 REPLACED LH REAR DRIVE AXEL HUB O RING *****TRUCK TO RETUR FOR***** LH CHACKLE BUSH RH KINGPIN SUMP LEAK	\$0.00
		Maintenance Performed	Cost
		SERVICE	\$0.00
		Total:	\$0.00
26/09/2023	700,616	CARRIED OUT 100,000 KM SERICE AS PER SHEET BC MY CHANGED ENGINE OIL AND FILTERS CCH@ 1319 COOLANT @ -42 =====JOBS DONE===== ROCKER COVER GASKET FRONT DRIVE PADS =====RETURN TO DO ===== LH SHACKLE BUSH SUMP GASKET	\$0.00
		Maintenance Performed	Cost
		SERVICE	\$0.00
		ANNUAL CHECK	\$0.00
		Total:	\$0.00
10/10/2023	707,998	REPLACED WIPER MOTOR MY	\$0.00
		Maintenance Performed	Cost
		REPAIRS	\$0.00
		Total:	\$0.00
10/11/2023	723,109	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC DIDNT CHANGED ENGINE OIL AND FILTERS COOLANT@ -40 DEG	\$0.00

CCH @1341
 GEARBOX OUTPUT SHAFT SEAL
 LEAKING (WARRANTY)
 RH REAR WHEEL SEAL WEAPING
 LH SHACKLE BUSH
 SUMP

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

23/11/2023	724,389	REPLACED ALL SHACKLE BUSHES (UPPER AND LOWER) JS TRUCK SENT TO GTC FOR GEARBOX OUTPUT SEAL (WARRANTY)	\$0.00
------------	---------	--	--------

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

29/12/2023	741,325	CARRY OUT 20000KM SERVICE AS PER SHEET JS BR CHANGED ENGINE OIL AND FILTERS BR COOLANT AT -44 CCH AT 1474, SERVICE CAB COOLER JS	\$0.00
------------	---------	---	--------

FRONT DRIVE OUTPUT SHAFT HAS MOVEMENT AND SEAL WEEPING
 RECHECK NEXT SERVICE
 SUMP WEEPING RECHECK NEXT SERVICE
 STEERING ARM BOOT DAMAGED DRAG LINK
 LH REAR INNER DRIVE TYRE HAS PUNCTURE IN SIDEWALL NOTIFIED TO GET REPLACED.

REPLACED AIR DRYER FILTER DUE TO EXCESSIVE AMMOUNT OF WATER IN SYSTEM , RECHECK NEXT SERVICE IF PROBLEM PRESISTS

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

14/02/2024	755,444	REPLACED ROLLER BLIND JS REPLACED WIPER BLADE RH SIDE JS	\$0.00
------------	---------	---	--------

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

5/03/2024	758,958	REPLACED CAMERA INDICATOR SCREEN BC REPLACED BUNG ON COMPRESSOR	\$0.00
-----------	---------	--	--------

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

2/04/2024	768,584	CCARRIED OUT 20,000KM SERVICE AS PER SHEET BC AR BR DIDNT CHANGE ENGINE OIL AND FILTERS COOLANT @-43 DEG	\$0.00
-----------	---------	--	--------

Maintenance Performed			Cost
SERVICE			\$0.00
			Total: \$0.00
17/05/2024	781,953	CARRY OUT 20,000KM SERVICE AS PER SERVICE SHEET BC, DW, ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -40DEG CCH@1690 REPLACED FRONT DRIVE BRAKE PADS REPLACED CENTIFIGUAL OIL FILTER HOUSING	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
			Total: \$0.00
12/08/2024	800,828	CARRIED OUT 100,000 SERVICE AS PER SHEET BC HA DIDNT CHANGE ENGINE OIL OR FILTERS COOLANT @-44 DEG CCH @1690 HRS WATER IN AIR TANKS	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
ANNUAL CHECK			\$0.00
			Total: \$0.00
22/08/2024	802,036	REPLACED RH KING PIN AR HA BC	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
			Total: \$0.00
29/11/2024	820,496	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC HA CHANGED ENGINE OIL AND FILTERS (CHANGED OIL TO GW) COOLANT @-40 DEG CCH @ 1735 REPLACED STEERING ARM CLEANED DIFF BREATHERS	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
			Total: \$0.00
5/12/2024	821,242	REPLACED REAR R/H AIR BAG DW	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
			Total: \$0.00
24/12/2024	827,500	REPAIRED FUEL TANK BC HA	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
			Total: \$0.00
29/01/2025	837,300	REPLACED REAR DRIVE BRAKE PADS AR DW	\$0.00

Maintenance Performed

REPAIRS

Cost

\$0.00

Total: \$0.00

Total:	Cost Per Mi/Km/Hr:	\$0.00	\$0.00
---------------	---------------------------	---------------	---------------

Grand Total:	\$0.00
---------------------	---------------