Date Kilometers Notes Vendor Employee Total Cost	B54 - 20 2019 DAF F	17 DAF FT TTXF105	TXF105	Unit #: Tag #: Kilometers	B54 XV44GK 943,741	Serial #: ENGINE NO	JG244603 A362272	
PER SERVICE SHEET	Date	Kilometers	Notes	Ve	endor	En	nployee	Total Cost
SERVICE	9/02/2021	270,530	PER SERVICE SHEET JI, RS DID NOT CHANGE ENGINE OIL C FILTERS CHECKED COOLANT- 40DEG SERVICED CAB COOLER @932H REPLACED FRONT DRIVE AXLE	DR IRS		,		\$0.00
18/03/2021 291,787								
PER SERVICE SHEET	92.1110					Total:	· ·	
SERVICE	18/03/2021	291,787	PER SERVICE SHEET ZS CHANGED ENGINE OIL OR FILTE CHECKED COOLANT -35DEG ADJUSTED CAB SUSPENSION			,		\$0.00
Total: \$0.00								
26/04/2021 314,072 CARRY OUT 100,000KM SERVICE AS PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL AND FILTERS CHECKED COOLANT -42DEG TIGHTENED BULLBAR MOUNT BOLTS S0.00	SERVIC	·E				Total		
SERVICE SHEET JI DID NOT CHANGE ENGINE OIL AND FILTERS CHECKED COOLANT -42DEG TIGHTENED BULLBAR MOUNT BOLTS						TOtal.	ψ0.00	
SERVICE	26/04/2021	314,072	SERVICE SHEET JI DID NOT CHANGE ENGINE OIL A FILTERS CHECKED COOLANT -42DEG	.ND		,		\$0.00
Total: \$0.00								
28/05/2021 331,763	SERVIC	E						
PER JOB SHEET AL						i otai:	\$0.00	
\$0.00 Total: \$0.00 28/07/2021 352,534 CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -42DEG CCH@1113 Maintenance Performed Cost \$0.00 SERVICE \$0.00 Total: \$0.00	28/05/2021	331,763	PER JOB SHEET AL CHANGED ENGINE OIL AND FILT CCH@1113			,		\$0.00
Total: \$0.00								
28/07/2021 352,534 CARRIED OUT 20,000KM SERVICE AS , \$0.00 PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -42DEG CCH@1113 Maintenance Performed \$0.00 SERVICE \$0.00 Total: \$0.00	SERVIC	E						
PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -42DEG CCH@1113 Maintenance Performed Cost SERVICE \$0.00 Total: \$0.00						Total:	\$0.00	
SERVICE \$0.00	28/07/2021	352,534	PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL C FILTERS CHECKED COOLANT -42DEG			,		\$0.00
Total: \$0.00								
	SERVIC	, <u>L</u>				Total:		
1/09/2021 372 522 \$0.00	1/09/2021	372,522						\$0.00
7/03/2025 10:31:11 AM Page 1 of 8						,		

CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -42DEG CCH@1120

<i>Maintena</i> SERVICE	ance Performed			Cost \$0.00	
<u> </u>	-		Total:	\$0.00	
7/10/2021	392,227	CARRIED OUT 100,000KM SERVICE AS PER SERVICE SHEET AL DID NOT CHANGE OIL OR FILTERS COOLANT -40DEG CCH@1180 SERVICED AL	,		\$0.00
<i>Maintena</i> SERVICE	ance Performed		Total:	\$0.00 \$0.00	
			Total.	ψ0.00	
2/12/2021	411,840	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -34DEG CCH@1203	,		\$0.00
	ance Performed			Cost	
SERVICE	_		Tatalı	\$0.00 \$0.00	
			Total:	Φ 0.00	
10/01/2022	431,024	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -42DEG CCH 1301 REPLACED ALL DRIVE AXLE BRAKE PADS	,		\$0.00
Maintena	ance Performed			Cost	
SERVICE				\$0.00	
			Total:	\$0.00	
28/02/2022	453,229	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI, ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -41DEG CCH 1414 REPAIRED ELEC LEAD ===WARRANTY=== BOTH REAR BOTTOM SHACKLE BUSHES	,		\$0.00
	ance Performed	1		Cost	
SERVICE			Tatal	\$0.00 \$0.00	
			Total:	\$0.00	
8/04/2022	477,179	CARRY OUT 20,000KM SERVICE AS PER SERVICE SHEET RS DID NOT CHANGE ENGINE OIL AND FILTERS COOLANT -42 SERVICED CAB COOLER 1505HRS FIT DNO SIGN BRACKETS	,		\$0.00
	ance Performed			Cost	
SERVICE	-		Total:	\$0.00 \$0.00	
7/02/2025 10:	.04.44				Dogo 2 of 9

7/03/2025 10:31:11 AM Page 2 of 8

25/05/2022 499,139 CARRY OUT 100,000 KM SERVICE AS , \$0.00 PER SERVICE SHEET ZS, JS CHANGED ENGINE OIL AND FILTER CHECKED COOLANT -44DEG CCH@1529 COOLANT LEAK OUT OF TRANS HOSE

TIGHTENEND FITTING REPLACED R/H STEER SHOCKER PUBBERS

RUBBERS

=JOBS TO BE DONE=

REPLACE FUEL WATER SEPERATOR

COOLANT HOSES

	COOLANT HOSES			
Maintenance Performed			Cost	
SERVICE			\$0.00	
		Total:	\$0.00	
13/07/2022 521,642	CARRIED OUT 20,000 KM SERVICE AL JI JS DID NOT CHANGE OIL OR FILTERS COOLANT -43DEG CCH@1529 REPLACE FUEL WATER SEPERATOR REPLACED CENTRE AXLE DRIVE BRAKE PADS DRIVERS FAULT #29865 REPLACED COOLANT HOSES REPLACED BELTS ==WARRANTY== ENGINE OIL LEAKS FRONT COVER AREA POWER STEERING HOSE STARTING TO LEAK	,		\$0.00
Maintenance Performed			Cost	
SERVICE			\$0.00	
		Total:	\$0.00	
2/09/2022 543,204	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI CHANGED ENGINE OIL FILTERS CHECKED COOLANT -30DEG REPAIRED R/H TAIL LIGHT WIRING AL ===WARRANTY=== ENGINE OIL LEAKS STEERING HOSES AND BOX LEAKS CROSS MEMBER NUTS MISSING	,		\$0.00
Maintenance Performed			Cost	
SERVICE			\$0.00	
		Total:	\$0.00	
12/09/2022 543,282	STEERING BOX LEAK ZS RESEALED TOP OF STEERING BOX	,		\$0.00
Maintenance Performed			Cost	
REPAIRS			\$0.00	
		Total:	\$0.00	
30/09/2022 553,567	REPLACED L/H SPOTTER MIRROR ZS	,		\$0.00
Maintenance Performed			Cost	
REPAIRS			\$0.00	
		Total:	\$0.00	
27/10/2022 563,067	CARRY OUT 20,000 KM SERVICE AS PER	,		\$0.00
7/03/2025 10:31:11 AM				Page 3 of 8

SERVICE SHEET ZS
DID NOT CHANGE ENGINE OIL OR
FILTERS
CHECKED COOLANT -30DEG
REPLACED EBS LEAD

<i>Mainter</i> SERVIC	nance Performe	1		Cost \$0.00	
			Total:	\$0.00	
9/12/2022	585,957	CARRIED OUT 20,000 KM SERVICE AS PER SERVICE SHEET AL CHANGED OIL AND FILTERS COOLANT -29 DEG CCH@1550	,		\$0.00
<i>Mainter</i> SERVIC	nance Performe E	1		Cost \$0.00	
			Total:	\$0.00	
20/01/2023	608,807	CARRIED OUT 100,000KM SERVICE AS PER SEVICE SHEET JS ZS DW DID NOT CHANGE OIL OR FILTERS REPLACED COOLANT@-45 DEG REPLACED FRONT DRIVE AXLE BRAKE PADS REPLACED CENTRE WIPER BLADE WITH WURTH BLADE	,		\$0.00
	nance Performe	1		Cost	
SERVIC ANNUA	E L CHECK			\$0.00 \$0.00	
			Total:	\$0.00	
6/03/2023	632,968	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -34DEG	,		\$0.00
Mainter	nance Performe	1		Cost	
SERVIC	E			\$0.00	
			Total:	\$0.00	
4/04/2023	651,032	CARRY OUT 20,000KM SERVICE AS PER SERVICE SHEET ZS, BR, DW DID NOT CHANGE ENGINEOIL OR FILTERS CHECKED COOLANT -35DEG CCH@ 2023 DID NOT SERVICE NEEDS DOING NEXT SERVICE POWER STEERING HOSE LEAK AIR COMPRESSOR LEAKING COOLANT	,		\$0.00
	nance Performe	d		Cost	
SERVIC	,E		Total:	\$0.00 \$0.00	
40/05/0000	670,000		Total.	7 0.00	#0.00
12/05/2023	678,220	CARRY OUT 20,000KM SERVICE AS PER SHEET BR,JS,ZS CHANGED ENGINE OIL AND FILTERS BR COOLENT AT -35 SERVICED CC @ 2050 HRS JS REPLACED 3X WIPER BLADE INSERTS BR REPLACED ALL ENGINE TENSIONERS PULLEYS AND BELTS JS	,		\$0.00
7/03/2025 10	D:31:11 AM				Page 4 of 8

7/03/2025 10:31:11 AM Page 4 of 8

TRUCK TO RETURN FOR REPAIRS. AIR COMPRESSOR PS HOSE SHACKLE BUSH EXHAUST MANIFOLD GASKETS CROSSMEMBER BOLTS

SERVICE	ance Performed	<u> </u>		<u>Cost</u> \$0.00	
02.11.02			Total:	\$0.00	
20/06/2023	700,101	RESEALED POWER STEERING BOX JS ZS REPLACED POWER STEERING FLUID + FILTER JS ZS REPLACED WIND SCREEN ROLLER CURTAIN JS ZS	,		\$0.00
<i>Maintena</i> REPAIRS	ance Performed	1		Cost \$0.00	
			Total:	\$0.00	
13/07/2023	710,842	CARRIED OUT 100000KM SERVICE AS PER SHEET JS DID NOT CHANGE ENGINE OIL OR FILTER COOLENT @-35 REPLACED ENGINE MOUNTS REAEALED ENGINE BRAKE AIR VALVE REPLACES STEER MUD GUADS REPLACED FRONT DRIVE BRAKE PADS REPLACED CROSSMEMBER BOLTS TRUCK TO RETURN FOR THE FOLLOWING .FRONT DRIVE OUTPUTSHAFT SEAL .SUMP GASKET .FRONT MAIN SEAL	,		\$0.00
Maintena				_	
SERVICE	ance Performed	1		<u>Cost</u> \$0.00	
SERVICE			Total:	\$0.00 \$0.00	
SERVICE 28/07/2023		CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-40 CCH @2060 REPLACED FRONT STEER BRAKE PADS ====JOBS TO BE DONE===== FRONT DRIVE OUTPUT SEAL SUMP GASKET FRONT MAIN SEAL	Total:	\$0.00	\$0.00
28/07/2023	721,702	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-40 CCH @2060 REPLACED FRONT STEER BRAKE PADS ====JOBS TO BE DONE===== FRONT DRIVE OUTPUT SEAL SUMP GASKET FRONT MAIN SEAL		\$0.00 \$0.00	\$0.00
28/07/2023 <i>Maintena</i>	721,702	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-40 CCH @2060 REPLACED FRONT STEER BRAKE PADS ====JOBS TO BE DONE===== FRONT DRIVE OUTPUT SEAL SUMP GASKET FRONT MAIN SEAL		\$0.00 \$0.00	\$0.00
28/07/2023 <i>Maintena</i>	721,702	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-40 CCH @2060 REPLACED FRONT STEER BRAKE PADS ====JOBS TO BE DONE===== FRONT DRIVE OUTPUT SEAL SUMP GASKET FRONT MAIN SEAL	,	\$0.00 \$0.00 Cost \$0.00	\$0.00 \$0.00
Maintena SERVICE 25/08/2023	721,702 Ance Performed 740,249 Ance Performed	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-40 CCH @2060 REPLACED FRONT STEER BRAKE PADS =====JOBS TO BE DONE===== FRONT DRIVE OUTPUT SEAL SUMP GASKET FRONT MAIN SEAL RE-SEELED POWER STEERING BOX MY ZS	, Total:	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	
Maintena SERVICE 25/08/2023	721,702 Ance Performed 740,249 Ance Performed	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-40 CCH @2060 REPLACED FRONT STEER BRAKE PADS =====JOBS TO BE DONE===== FRONT DRIVE OUTPUT SEAL SUMP GASKET FRONT MAIN SEAL RE-SEELED POWER STEERING BOX MY ZS	, Total:	\$0.00 \$0.00 Cost \$0.00 \$0.00	
Maintena SERVICE 25/08/2023	721,702 Ance Performed 740,249 Ance Performed	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-40 CCH @2060 REPLACED FRONT STEER BRAKE PADS =====JOBS TO BE DONE===== FRONT DRIVE OUTPUT SEAL SUMP GASKET FRONT MAIN SEAL RE-SEELED POWER STEERING BOX MY ZS	Total:	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	

PER SHEET BC DIDNT CHANGE ENGINE OIL AND FILTERS COOLANT @-40 DEG CCH @2060

REPLACED REAR DRIVE PADS NEW POWERSTEERING BOX =====JOBS TO BE DONE===== SUMP GASKET RH DRIVE WHEEL SEAL

		THE BINITE WHELE GENE			
Maintenance	Performed			Cost	
SERVICE				\$0.00	
REPAIRS				\$0.00	
			Total:	\$0.00	
29/09/2023 7	762,150	CARRIED OU 20,000KM SERICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-41 DEG CCH @2085 =====JOBS TO DO====== LH KING PIN SUMP GASKET	,		\$0.00
Maintenance	Performed			Cost	
SERVICE				\$0.00	
			Total:	\$0.00	
6/11/2023 7	782,568	CARRIED OUT 20,000 KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS CCH @2118 COOLANT @-40 DEG REPLACED NOX SENSOR AFTER CAT REPLACED CROSSMEMBER BOLTS 6 REPLACED LH REAR INDICATOR GLOBE ==== JOBS TO BE DONE ==== SUMP GASKET LH KING PIN	,		\$0.00
Maintenance	Performed			Cost	
SERVICE				\$0.00	
			Total:	\$0.00	
12/12/2023 7	789,866	TRUCK BROKE DOWN CLUTCH FAILURE REPLACED CLUTCH DISC, PRESSURE PLATE, THROW OUT BEARING, SPIGOT BEARING FLYWHEEL MACHINED REPLACED LEFT HAND SHACKLE BRACKET HOUSING REPLACED ALL REAR TOP AND BOTTOM SHACKLE BUSHS AND BOLTS REPLACED SUMP GASKET REPLACED ENGINE OIL AND FILTER REPLACED COMPRESSURE INTAKE HOSE REPLACED T PIECE AIR FITTING ON GEARBOX	,		\$0.00
Maintenance	Performed			Cost	
REPAIRS				\$0.00	
			Total:	\$0.00	
10/01/2024 8	803,070	CARRIED OUT 100,000KM SERVICE AS PER SHEET BC	1		\$0.00
7/03/2025 10:31:1	11 AM				Page 6 of 8

CHANGED ENGINE OIL AND FILTERS COOLANT @-41 DEG FRONT AND REAR DRIVE OUTPUT SHAFT SEAL WEAPING CLEANED BREATHERS DID NOT CHANGE ADDBLUE FILTER HOUSING

SERVICE	nce Performe	-		<u>Cost</u> \$0.00	
ANNUAL				\$0.00	
			Total:	\$0.00	
3/04/2024	831,506	CARRIED OUT 20,000KM SERVICE AS PER SHEET HA BR AR DIDNT CHANGE ENGINE OIL AND FILTERS REPLACED WIPER BLADES CCH @2510 SERVICED CAB COOLER FRONT OF SUMP WEAPING INJECTOR NO. 4 WEAPING	,		\$0.00
Maintana	Dawfawaa			01	
SERVICE	nce Performe	<u>a</u>		Cost \$0.00	
5262			Total:	\$0.00	
6/04/2024	835,701	REPLACED L/H KING PIN BC REPLACED ADBLUE DOSING HARD LINE	,		\$0.00
Maintena	nce Performe	d		Cost	
REPAIRS				\$0.00	
			Total:	\$0.00	
1/05/2024	844,961	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC HA DW ZS CHANGED ENGINE OIL AND FILTERS COOLANT @-41 DEG CCH @2557 ===REPAIRS=== REPLACED FRONT CRANK SEAL AND COVER GASKET REPLACED BELTS AND TENTIONERS REPLACED BEFORE NOX SENSOR replaced header tank	,		\$0.00
	nce Performe	d		Cost	
SERVICE			Total:	\$0.00 \$0.00	
			i Otai.	ψ0.00	
6/07/2024	865,888	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC DIDNT CHANGE ENGINE OIL OR FILTERS COOLANT @-41 DEG CCH @2557 REPLACED Y SHAPED COOLANT HOSE	,		\$0.00
	nce Performe	d		Cost	
SERVICE				\$0.00	
SLITTICL			Total:	\$0.00	
SERVICE					

7/03/2025 10:31:11 AM Page 7 of 8

SERVICE 1/10/2024	901,000	CARRIED OUT 100,000KM SERVICE AS PER SHEET BC HA DW DIDNT CHANGE ENGINE OIL OR FILTERS COOLANT @-41 DEG CCH @2557	Total:	\$0.00 \$0.00	\$0.00
1/10/2024	901,000	PER SHEET BC HA DW DIDNT CHANGE ENGINE OIL OR FILTERS COOLANT @-41 DEG	,		\$0.00
		REPLÄCED RADIATOR AND RH RAD SUPPORT BRACKET			
Maintenan	ce Performed			Cost	
SERVICE ANNUAL C	HECK			\$0.00 \$0.00	
			Total:	\$0.00	
11/11/2024	921,302	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC AR CHANGED ENGINE OIL AND FILTERS COOLANT @-41 (REPLACED) CCH @2557 CHANGED ENGINE OIL TO GULF AND WESTERN REPLACED WATER PUMP REPLACED GEARBOX OIL TIGHTENED GEARBOX AIR VALVE	,		\$0.00
Maintenan:	ce Performed			Cost	
SERVICE				\$0.00	
			Total:	\$0.00	
25/11/2024	927,440	REPLACED RH HIGH BEAM GLOBE BULL BAR	,		\$0.00
	ce Performed			Cost	
REPAIRS			Totali	\$0.00 \$0.00	
			Total:	\$0.00	
10/01/2025	943,741	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC HA DIDNT CHANGE ENGINE OIL OR FILTERS COOLANT @- 18 DEG GW CCH @2557	,		\$0.00
Maintenan-	ce Performed			Cost	
SERVICE				\$0.00	
			Total:	\$0.00	
Total:		Cost Per Mi/Km/Hr:	\$0.00		\$0.00

7/03/2025 10:31:11 AM Page 8 of 8

\$0.00

Grand Total: