

All Maintenance

Filters applied:

Asset Maintenance Status	Closed
Maintenance Type	A Service, B Service, Brake Test, C Service, D Service, Repair
Asset	HV2289 CAT CT630 6x4 Prime Mover XQ75QC
Asset Status	Active

Id	Created At	Type	Asset Id	Description	Sub-type	Maintenance Type	Asset Maintenance Status	Description	Notes
	9033	23/05/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Repair	Repaired Valve
	8942	16/05/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A Service	L/H Mud guard missing. Windscreen cracked. Battery needs jumpstarting. R/H guard broken. Compressor hose leaking. 2Way not working
	8895	10/05/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	D Service	Closed	D Service	
	8894	10/05/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	B Service	Closed	B Service	
	8893	10/05/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Brake Test	Closed	Brake Test	
	8792	02/05/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	cracked windscreen missing left-hand mud gard and needs new battery 2way not working EA2/5	double up on defects entered
	8594	18/04/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A Service	Left hand front guard missing. Cracked windscreen
	8555	17/04/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Brake Test	Closed	Brake Test	
	8554	17/04/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	B Service	Closed	B Service	Repaired Mud guard
	8470	04/04/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	2289 abs light on abs module fault. windscreen cracked. front mudguard cracked. weeping leak ps of motor.	double up on defects entered
	8428	30/03/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	2289 weeping leak ps of motor. abs light on. both front mudguard plastic cracked and broken.	double up on defects entered
	8417	28/03/2023 Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Brake Test	Closed	brake test	

8378	27/03/2023	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Brake test, replace clearance light.	
8360	24/03/2023	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	D service, grease throughout, check lights, adjust brakes, check bushes/turn table, repair guards, report repairs.	
7657	17/01/2023	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A SVC Completed	1. Right side guard missing 2. 2x mudflaps missing
6818	17/10/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Flashing light out - GS 17/10/22	
6766	12/10/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Inspect front guards for damage. Repair as required.	Front left wheel guard is cracked – truck is not currently being used, sounds like this guard is able to be removed (with Difficulty) The right hand side has already been removed, sounds like it will cause less damage if taken off rather than running it over. Fitter to inspect and advise repairs required. MD 12.10.22
6765	12/10/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A SVC Completed 9.10.22	Front left wheel guard is cracked – truck is not currently being used, sounds like this guard is able to be removed (with Difficulty) tommy may be able to do this when he is here or at least access it. The right hand side has already been removed, sounds like it will cause less damage if taken off rather than running it over
6135	12/09/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A SVC Completed	Nil faults reported
6105	08/09/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A-Service Completed	Operator noted a few washers loose on the brake adjustment on 2260 combination.
5845	24/08/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Various cracks in truck - no real context as to where DDK 24-8-22	DS front mud guard bracket cracked - GS 02/10 wrong unit number listed

5844	24/08/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	LHD drive guards worn and mount poles cracked DDK 24-8-22	replace LHS rear mudguard support pole 23-8
5843	24/08/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Tank straps rubber need replacing DDK 8-22	Replace tank rubbers on truck 24-8-22
5842	24/08/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	RHS steer guard loose (held back) DDK 24-8-22	
5841	24/08/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Beacon wiring damaged DDK 24/8	repair wiring on x 2 rear beacons 23-8
5707	16/08/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed		
5652	11/08/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed		
5328	18/07/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	ds mud guard bracket cracked faring and flap removed to stop further damage - GS	
5326	18/07/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	2289 F/R diff lock not engaging - GS 17/7	No front diff lock, only power divider - diff lock on rear only
5107	24/06/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Fix air line, fix sign and finish off work for truck and trailer	Fix air line, fix sign and finish off work for truck and trailer
5094	23/06/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	final repairs on CAT Water Cart	final repairs on CAT Water Cart
4336	16/05/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	A Service Completed - M BLANCH	A Service Completed 30/04/2022
4335	16/05/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A Service	A service completed - M BLANCH
4261	10/05/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	A Service	Closed	A service	
3914	31/03/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Drivers side bottom tail light out - Gary Sciflet - 30/3	Fault was on connected trailer and fixed
3891	28/03/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Exhaust heat shield top bracket broken - Gary Sciflet - 27/3	Removed welded up clamps and refitted
3844	23/03/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Mudflap missing - Gary Sciflet - 22/3	double up in defects.
3550	09/03/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Brake Test	Closed	brake test	
3506	09/03/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Repaired horn and park brake alarm	
3505	09/03/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	D Service	Closed	D Service	
3504	09/03/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	B Service	Closed	B Service	Replaced diff lock wiring , replaced horn
3153	22/02/2022	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	A/C Blowing hot air - Needs regasing - Tom Kerlin - 21/2	A/C Repairs completed - 28/2 Made condenser fan brackets, ran wiring to condenser fans through relay, Mounted condenser fans - Tested and works good

2540	22/12/2021	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Inspect machine for defects,move into work bay - Remove chaise to diff brace and source new parts and install new one. Remove rear glass panel and clean up and glue back onto cab. Remove broken trailer bearing cover, Tighten up all mudguards covers and straightened up. Remove old fibreglass off Broken R/H front fender make new bracing to support guards and straighten up. Take truck and trailer to twin city for new tyres	Inspect machine for defects,move into work bay - Remove chaise to diff brace and source new parts and install new one. Remove rear glass panel and clean up and glue back onto cab. Remove broken trailer bearing cover, Tighten up all mudguards covers and straightened up. Remove old fibreglass off Broken R/H front fender make new bracing to support guards and straighten up. Take truck and trailer to twin city for new tyres
2150	29/11/2021	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Brake Test	Closed	brake test	
2149	29/11/2021	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	D Service	Closed	D Service	Repaired mud guard, mounting brackets, replaced rear mud flaps and replaced strengthening straps on plastic guards
1751	24/11/2021	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	D Service	Closed	D Service	D Service
1616	12/11/2021	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Brake Test	Closed	brake test	brake test
1528	02/11/2021	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Replaced park brake valve	Replaced park brake valve
1523	02/11/2021	Heavy Vehicles	HV2289	CAT CT630 6x4 Prime Mover	Prime Mover	Repair	Closed	Inspect PTO fault and defects	Inspect PTO fault and defects