



Vehicle History Summary

Fleet #	XQ84CJ			
Registration	XQ84CJ			
Make	Kenworth			
Model	K200			
VIN / Chassis #	6F500000FA454145			
Build Date	2015			

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
S-1939	22/09/2023	688083	0	B	WORK NOTES -Carry out B service as per customer service sheet. Connected laptop up too look at fault codes, found fault codes relating to Low add blue and shorted NOX sensor. Cleared inactive faults low add blue fault still present. Check and found to be low. Removed sender to check if working, topped up with ad blue, code went away and cleared codes. Code for NOX sensor T/Shot and found to be sensor. Advised customer and didn't want to repair. Checked all idler bearing in found of engine to isolate belt squeal. All o.k. Belt found U/S. Customer advise to change out with his spare. Adjusted Pos 1 wheel bearing DEFECTS NOTED Torque rod bushes need replacing. Cab lift cylinder is leaking. Nox sensor bring up faults. Air intake pipe mount rubbers torn	Just Diesel
S-1788	20/09/2023	688082	0	B	B - Service Steer Brakes 60% Drive Axle F 50% Drive Axle 50% Torque Rod Bushes Need Replacing Cab Cylinder Leaking Nox Sensor Faults Air Intake Mount Rubbers worn	Just Diesel
T-376	05/09/2023	680466	0	New	GOODYEAR 295/80R22.5 152/149M S210 KMAX 2. Fit Truck Tyre and/ or Tube Alloy Wheel 2. Sublet Labour 2	Goodyear

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
S-1648	23/08/2023	668756	21054	B	CARRIED OUT B SERVICE. BRING TRUCK IN, DROP BULLBAR, LIFT CAB CARRY OUT B SERVICE AS PER RUSHWAY SERVICE SHEET. REPLACE OIL AND FILTER, BOTH FUEL FILTERS, AIR/OIL FILTER, WIPERS, GREASE ALL GREASE POINTS, ADJUST ALL BRAKES. RH TAIL LIGHT MISSING MULTIPLE LED'S, REMOVE AND REPLACE. FOUND WIRING TO BE EXPOSED AND INSULATION HAS RUBBED THROUGH ON INDICATOR AND BRAKE WIRES, CUT WIRES AND SOLD TOGETHER. INSULATE AND SECURE. LH REVERSE LIGHT OUT, CHECK WIRING ALL OK, REMOVE AND REPLACE LIGHT. REVERSE BEEPER NOT WORKING. CHECK POWER TO IT ALL OK. REMOVE AND REPLACE, CHECK OPERATION NOW OKAY. ADJUST CLUTCH BRAKE AND CLUTCH PEDAL FREE PLAY. CHECK ALL FRONT SUSPENSION AND CAB SUSPENSION COMPONENTS AS PER DRIVER REQUEST. ALL OK. FRONT GRILL HAS LOOSE BOLTS AND ONE NUTSERT WAS MISSING, REMOVE GRILL AND REPLACE NUTSERT. REPAIR DEUTSCHE PLUG FOR KENWORTH LOGO LIGHT. REFIT GRILL. DEGREASE AND WASH DOWN ENGINE BAY & UNDER BODY DROP CAB, WIPE HAND PRINTS. FILL OUT SIMPRO, JOBCARD, UPDATE SVC STKR	Just Diesel

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-1102	31/07/2023	1664019	0	Parts	CORRECTION: -TRUCK ARRIVED AT CUMMINS TOWNSVILLE WITH COMPLAINT OF NOISE -JSA AND DOWNLOAD WORK COMPLETED - LOWERED BULLBAR AND JACKED CAB -STARTED ENGINE AND LISTENED TO ENGINE NOISE, NOISE SUSPECTED TO BE COMING FROM ALTERNATOR -REMOVED BELT FROM ALTERNATOR AND RETESTED. -SOUND FOUND TO BE DISAPPEAR. -TURNED ALTERNATOR BY HAND AND BEARING FEEL GRITTY. -CHECKED ALL TENSIONERS AND IDLERS, A/C TENSIONER AND IDLER BEARING ALSO FOUND TO BE NOISY. - CUSTOMER SUPPLIED ALTERNATOR. -REMOVED & REPLACE ALTERNATOR , TENSIONER AND IDLER. -INSTALLED BELT & STARTED ENGINE. -ALL OKAY NO ABNORMAL SOUNDS HEARD. -CARRY OUT TEST DRIVE TO ENSURE ALTERNATOR CHARGING CORRECTLY, ALL OKAY. -TRUCK RETURNED TO SERVICE	Just Diesel
R-1025	05/07/2023	0	0	Parts	ALTERNATOR 12VOLT 170AMP PAD MOUNT X 1	Truckline
T-311	23/06/2023	661422	0	Puncture	Puncture Repair - Truck Tyre (Fitted) 1	Goodyear
R-1001	12/06/2023	0	0	Parts	1 BELT TENSIONER- 89440	Just Diesel
R-1000	08/06/2023	0	0	Parts	-1 PULLEY IDLER - 3681587	Just Diesel
R-1000	08/06/2023	0	0	Parts	1 BELT FAN DRIVE / D84-1000- 3122380 1 PULLEY IDLER / 3681587	Just Diesel
R-948	03/06/2023	0	0	Parts	EXHAUST CLAMP FLAT 5" - 127MM Z/P. RELAY 12V 4PIN 40A BL PACK (1)	Truckline
T-304	01/06/2023	650902	0	Rotation	P/R POSITION 5. SUBLET ROTATE DRIVES FRONT TO REAR 10. Puncture Repair - Truck Tyre (Fitted) 1	Goodyear
R-933	26/05/2023	0	0	Parts	CREDIT FOR INVOICE 8538142	Truckline
R-938	26/05/2023	0	0	Parts	SPRAYSAFE FENDER SUPPORT 12. BEZEL - SINGLE ROUND 2. SHIELD-MUDFLAP SPRAY 2. PLATE- WARNING LEFT 1. PLATE-WARNING RIGHT 1	Brown & Hurley
R-934	26/05/2023	0	0	Parts	MUDGUARD PLASTIC BLACK 650MM WIDE	Truckline
R-933	26/05/2023	0	0	Parts	MUDGUARD PLASTIC BLACK 620MM WIDE	Truckline
R-893	26/05/2023	0	0	Parts	CREDIT FOR INVOICE 2869349	Brown & Hurley

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
S-1388	24/05/2023	648868	0	B	24/05/2023 Carry out B service as per customer service sheet. Diagnosed horn not working and found clock screw/spring to be faulty and Horn relay to be u/s Removed and replaced both parts. Adjusted and inspected all brakes due to driver complaint Tested all Good. Washed down truck.	Just Diesel
R-957	17/05/2023	0	0	Parts	1 AIR HORN VALVE. 1 LED DOUBLE COMBINATION LAMP. 1 LED RED STOP LAMP. 2 RUBBER WIPER REFILL. 2 WIPER ARM JET WASHER. 2 3/16" WIPER ARM HOSE. 1 FITTING	Just Diesel
R-893	11/05/2023	0	0	Parts	RIM,SUIT 1016	Brown & Hurley
R-901	10/05/2023	643679	21080	GENERAL REPAIRS	Travel to break down. Investigate belt fault - found idler pulley bolts snapped. Remove broken bolts. Fit new bolts. Supply & fit new belt & return.	Just Diesel
R-894	08/05/2023	642203	21045	Steering	Change out supplied steering wheel	Just Diesel
S-1364	06/05/2023	0	0	A	Grease and check over	Internal Workshop
S-1292	15/04/2023	630962	0	A	Grease and check. Secure RHF mirror light cover.	Dynamic Diesel Tech Pty Ltd
R-868	14/04/2023			Air Conditioner	14.04.2023- Found faulty compressor at AC lines. Removed 8 & 10 a/c hoses. Removed old compressor. Ran new 8 & 10 hoses and new fittings. Fitted new a/c compressor. Regassed and oiled a/c system and fitted new drier. Found window not working. Replaced faulty regulator, window switch and door module. Tested ok.	FORTUNA STRAIGHTLINE ENGINEERING
R-923	11/04/2023	0	0	Parts	2 7 PIN LARGE METAL PLUG. 2 INTERIOR VISOR CLIP	Just Diesel
S-1267	07/04/2023	630544	0	A	Grease and check over.	Dynamic Diesel Tech Pty Ltd
S-1713	06/04/2023	629923	0	C	CARRY OUT C SERVICE PER SERVICE SHEET	Internal Workshop
I-214	06/04/2023	629923		Truck Annual Inspection		Internal Workshop
S-1186	25/02/2023	609011	0	B	Carry out B service as per service sheet. Remove and replace steer wheels. Remove and replace leaking passenger side front drive axle hub seal.	Dynamic Diesel Tech Pty Ltd
R-733	15/02/2023	0	0	Parts	Buckle B 36mm Flat Hook. BUCKLE B 46MM FLAT HOOK. WASH POLE 3MT	Brown & Hurley
R-709	03/02/2023	0	0	Parts	TENSIONERS RHS I09B2. JUMBO BUG SPONGE. KROMEBRITE LIQUID CHROME. BRUSH HEAD 10" QUAD DESIGN	Brown & Hurley

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
S-1040	26/11/2022	562862	0	B	Carry out B service. Remove and replace leaking heater hose.	Dynamic Diesel Tech Pty Ltd
T-190	25/11/2022	562862	0	New	6 TYRES FITTER AT REDBANK YARD 2 TYRES FITTED IN PORT MACQUARIE. HIFLY 11r22.5 HH308A DRIVE. HIFLY 11r22.5 HH308A DRIVE. Disposal of Casing - Truck Tyre	Goodyear
R-505	13/10/2022	0	0	Parts	TENSIONERS RHS	Brown & Hurley
O-87	03/10/2022	0	0	Registration		
R-462	26/09/2022			Parts	parts	Brown & Hurley
R-481	20/09/2022	0	0	Parts	PLUG-TRAILER,6MM CABLE,7PIN DISP-DEND. SOCKET-TRAILER,6MM CABLE,BLIDSITS-P-DEND	Brown & Hurley
R-406	23/08/2022	0	0	Parts	PARTS	Brown & Hurley
R-358	09/07/2022	0	0	GENERAL REPAIRS	Fit charge air cooler and grille	Dynamic Diesel Tech Pty Ltd
R-359	09/07/2022	0	0	Parts		Brown & Hurley
S-736	08/07/2022	0	0	B	Carry out B service as per service sheet. Replace leaking passenger side rear axle gasket. Tighten pitman arm bolt. Replace driver side rear axle wheel speed sensor. Remove front grille and replace stainless surrounds. Pressure test charge air cooler and found to be leaking. Remove charge air cooler	Dynamic Diesel Tech Pty Ltd
R-361	08/07/2022	0	0	Parts	SENSOR WHEEL SPEED ABS	Brown & Hurley
R-284	24/05/2022	0	0	Parts	MOTOR-WIPER,DOGA	Brown & Hurley
R-301	20/05/2022	0	0	Parts	LIGHT-TAIL,LED STOP/TAIL	Brown & Hurley
R-258	29/04/2022	0	0	Parts	SENSOR NITROGEN OXIDE, CORE SENSOR, KIT BRAKE SHOE	Brown & Hurley
R-257	29/04/2022	0	0	Parts	PARTS	Brown & Hurley
S-594	29/04/2022	0	0	B	Carry out B service as per service sheet. Remove and replace rear drive axle brake shoes. Remove and replace chrome cover on front grill. Aftertreatment fault for outlet NOX sensor, replace sensor	Dynamic Diesel Tech Pty Ltd
I-130	21/04/2022			Truck Annual Inspection		Dynamic Diesel Tech Pty Ltd
O-51	31/03/2022	0	0	Registration		
R-216	29/03/2022	0	0	Parts	BOOT - GEAR SHIFT	Brown & Hurley
R-235	29/03/2022	0	0	Parts	pulley idler	Brown & Hurley
R-236	23/03/2022	0	0	Parts	control window regulator pack	Brown & Hurley
S-124	12/02/2022	419770	0	B	Carry out B service as per service sheet. Tighten pitman arm bolt, adjust fan shroud, fit tracker and install new gearstick boot.	Dynamic Diesel Tech Pty Ltd

Number	Date	Kilometres	Hours	Type	Repairer Notes	Repairer
R-31	01/12/2021			GENERAL REPAIRS	SUPPLY AND INSTALL AMB/AMB LED LIGHTS TO MIRRORS, DESIGN, MANUFACTURE SUPPLY AND INSTALL CUSTOM STAINLESS STEEL DROP VISOR, DESIGN, MNAUFACURE, SUPPLY AND INSTALL Z PANELS UNDER BOTH DOORS WITH 5 AMB/AMB LED LIGHTS, INSTALL 5 AMB/AMB FOIL LIGHTS SUPPLIED BY CUSTOMER	BRISKAIR
R-8	18/11/2021			GENERAL REPAIRS	Zip tie up wiring under sump, fit stainless intake hat, remove blue plastic off cab.	Dynamic Diesel Tech Pty Ltd
R-49	17/11/2021			Parts	various parts as per attached invoice	Brown & Hurley
S-33	15/11/2021	0	0	C	Carry out C service. Carry out valve set. Tighten belly bar. Fit new spotlights, and diagnose why spot lights wont work. Rotate drive tyres. Get shackle pins to take grease. Inspect oil leak at front of engine, remove damper and found front crank seal leaking, inspect oil leak near compressor and found gear housing leaking. Driver side of flywheel housing leaking. Remove and replace wiper blades. Drain oil and coolant. Remove charge air pipes and top radiator pipe. Pin and wedge motor. Remove belts, fan, fan hub, shroud, alternator, A/C compressor, top tin plate, front crank seal, fuel pump plate, remove all gears, undo air compressor and high pressure fuel pump, cam plates, sump, front engine mounts, gear housing. Clean and inspect gear housing. Clean engine block. 515 gear housing gasket and fit gear housing. Remove and replace front engine mounts	Dynamic Diesel Tech Pty Ltd
R-50	15/11/2021			Parts	BLADE ASSY-WIPER, WASH AND CARNAUBA WAX 20L, LUBE FILTER, SWITCH-ROCKER DRIVING LIGHT	Brown & Hurley
I-43	30/04/2021			Truck Annual Inspection		

Signed: _____

Name: _____

Date: _____