## **BMW RECALL – VEHICLE SEARCH RESULT.**



Searched by: VIN WBAFF42080L180062

Results Generated: 22 June 2022 04:03 PM (AUS Eastern Standard Time)

| MODEL       | YEAR | COLOUR           | VIN               | CHASSIS | REGO |
|-------------|------|------------------|-------------------|---------|------|
| E70 X5_3.0d | 2009 | ALPINE WHITE III | WBAFF42080L180062 | L180062 | ()   |

The following Technical Actions or Recalls have been rectified.

| DEFECT CODE | PRA (ACCC code) | DESCRIPTION  | STATUS   | DEFECT COMMENT |
|-------------|-----------------|--|----------|----------------|
| 0012390300  | N/A             | E7X M57 REPLACE THE THREADED BOLT OF THE DEFLECTING ELEMENT          | <b>Ø</b> | COMPLETED      |
| 0013080200  | N/A             | E60 E61 E7X E8X F01 F02 N47 M57 N57,<br>REPLACING FUEL FILTER HEATER | <b>Ø</b> | COMPLETED      |
| 0032510200  | 2017/16230      | BMW E7x Replace Driver Airbag Generator. (Takata)                    | <b>Ø</b> | COMPLETED      |
| 0061890500  | N/A             | Checking and reworking blower controller plug connection             | <b>Ø</b> | COMPLETED      |
| 0072710100  | 2017/16298      | BMW E7x Replace Passenger Airbag. (Takata)                           | <b>Ø</b> | COMPLETED      |