


# Takata airbag recall

## RECALL SEARCH REPORT


**Date of Search:** 07/03/2023 05:19 AM AEST  
**Report Generated:** 07/03/2023 05:19 AM AEST  
**Search Data:** VIN: JF2BP9KKB6G034072

SHARP METAL FRAGMENTS  
FLY AT HIGH SPEED.



TOWARD YOU AND YOUR PASSENGERS.  
THIS COULD CAUSE SERIOUS INJURY OR DEATH.

**Model Year 2006 SUBARU OUTBACK**  
2.5I WAGON  
VIN: JF2BP9KKB6G034072  
**Status: COMPLETE**  
Recall Reference PRA No.: 2016/15507



Complete. The passenger-side front airbag inflator in this this Model Year 2006 Subaru OUTBACK has been permanently replaced with a non-Takata airbag inflator. No further action is required.

Recall Status Tool Disclaimer: The Recall Status returned by this tool is based on information from multiple sources, (including third party sources). Further, in some circumstances there can be a delay between the time work is conducted and the time it is reported into our systems. Whilst Subaru Australia has taken reasonable precautions to ensure accuracy, the Recall Status may not be up to date as at the date of your search. To the maximum extent permitted by law Subaru Australia disclaims all liability arising from any inaccuracy or reliance on information produced by the Recall Status Tool. If you have a question or comment regarding the Recall Status of your vehicle as reported above please contact the Subaru Recall Contact Centre on 1300 550 994 or email [feedback@subaru.com.au](mailto:feedback@subaru.com.au).