



MITSUBISHI MOTORS RECALL REPORT

Report Generated on 30/03/2023 at 16:21

The following recall notices relate to your vehicle. If the RECORD STATUS shows COMPLETED, then the problem has been rectified and no further action is required.

If the RECORD STATUS shows any other status, Please contact your nearest dealer or call Mitsubishi Motors Australia 1300 13 12 11

Recall Notices for VIN #JMFSMCZ4A9U000432:

Recall ID: 010088 - Engine Accessory Drive Belt Inspection/Replacement

Family: Lancer

Year: 2009

PRA: 2014/14462

Inappropriate material of the ancillary equipment V ribbed belt on the engine may cause the resin pulley to wear unevenly.

In the worst case scenario the belt can be damaged causing it to come off. If this occurs, the charge lamp will illuminate, the battery charge will be depleted and the engine may overheat and the steering effort could increase.

Status: Active

Recall ID: 010108 - Turn Signal and Lighting Switch Terminal Connectivity Rectif

Family: Lancer

Year: 2009

PRA: 2016/15466

The turn signal and lighting switch connector terminals may become worn during switch operation due to insufficient rigidity. This may result in an accumulation of oxidised dust on the connector terminals. Excessive dust accumulation can act as an insulator, affecting proper terminal conductivity.

Continued usage under this condition, could cause conduction failure resulting in head lamp, turn signal lamps, parking lamp, front/rear fog lamp, tail lamp, number plate lamp and room lamp failing to operate or to operate intermittently.

Status: Active

If your vehicle is not COMPLETED for the recall(s) above, please contact your nearest dealer or call Mitsubishi Motors Australia 1300 13 12 11 to book an appointment (Select Option 2 > Option 2) and have this rectified.