

Stock No: APH00584

Caterpillar 329DL 30 Tonne Excavator

Serial No: CAT0329DJTZL00552

Reg No: 14704E

Cat: EXC30

Year: 2014

Provisional?:

Supplier:

Model: Caterpillar 329DL

Under Repair?

**Log**

<i>Date</i>	<i>Type</i>	<i>Description</i>	<i>Meter</i>	<i>Labour</i>	<i>Parts</i>
1/07/2024	REPAIR	TG: Fit 2 new batteries in machine. Clean up terminals and leads. Test OK (@ 9730 Hours)	9730		\$125.00
17/04/2024	OTHER	Next REGISTRATION RENEWALS - date postponed from 13-Apr-24			
8/03/2024	OTHER	Next REGISTRATION RENEWALS - brought forward from 13-Apr-25			
4/09/2023	OTHER	DCT: Water pump hyd		\$639.00	
1/09/2023	REPAIR	DC: Travel to site, remove engine coolant pump, fit new pump from Don Clarks, fill with coolant and test OK (@ 9727 Hours)	9727	\$450.00	
22/08/2023	SERVICE	Harris Heavy Mechanical: Compete 500hr service. Change engine oil and filter. Check over machine (@ 9657 Hours)	9657	\$412.50	
11/08/2023	OTHER	Westrac: Supply Lube filter, filter as, seal, fuel filter			\$103.71
9/08/2023	REPAIR	DC: Diagnose faulty quick hitch solenoid valve		\$425.00	
9/08/2023	OTHER	Westrac: Supply valve gp-mtg			\$599.31
8/08/2023	REPAIR	DC: Remove arm cylinder from APH00234 and fit to this machine. Weld up crack in tilt hitch didnt work. Diagnose quick hitch not functioning		\$475.00	
8/08/2023	OTHER	Westrac: Supply Seal Kit			\$579.79
18/04/2023	OTHER	Next REGISTRATION RENEWALS - date postponed from 13-Apr-23			
9/03/2023	OTHER	SCH: Hose assembly supplied			\$315.38
13/02/2023	REPAIR	Harris Heavy Mechanical: Fit new a/c condensor fan		\$137.50	

Stock No: APH00584

Caterpillar 329DL 30 Tonne Excavator

Serial No: CAT0329DJTZL00552

Reg No: 14704E

8/02/2023	OTHER	Westrac: Motor As-fan		\$439.97	
6/02/2023	REPAIR	Acemec: Test a/c fault, found needs new condensor		\$110.00	
11/01/2023	SERVICE	TG: Completed Service As Per Manufacture Specs (@ 9290 Hours)	9290		
7/09/2022	OTHER	Westrac" Element as, lube filter, fuel filter, filter as		\$202.74	
6/09/2022	SERVICE	TG: Completed 250 Hour Service As Per Manufacturer Specifications (@ 8975 Hours)	8975		
6/09/2022	REPAIR	Acemec: Test stereo fault, test supply, dismantle cab to find plug off supply switch		\$220.00	
9/06/2022	OTHER	Westrac: Cap as-fuel		\$159.90	
1/06/2022	OTHER	PH Jennings: Supply Lower front glass and ROPS cab windscreen		\$471.65	
20/04/2022	OTHER	Next REGISTRATION RENEWALS - date postponed from 13-Apr-22			
3/03/2022	SERVICE	JB: Carry out 250hr service as per manufactures specifications. Repair fuel water sepearator sensor wiring fault. Fit missing bolt on radiator bracket (@ 8686 Hours)	8686	\$450.00	
3/03/2022	OTHER	Westrac: Fuel filters, lube filter, filter assembly		\$153.76	
11/11/2021	OTHER	ADVANCE: Manifold lagging, turbo laggin, fittings		\$1,432.00	
2/06/2021	REPAIR	KOMMAND: Travelled to site and inspected machine, Found AS456 Tilt sensor and cable missing. Installed AS456 and tilt extension cable. Measured up to GP bucket. Tested operation with base station. Programmed site freq into TDL radio. Loaded machine file onto USE so that A-Plant system onsite can be swapped into machine2		\$360.00	\$2,417.00
1/06/2021	OTHER	HASTINGS: replacement windscreen		\$2,038.40	

---

Stock No: APH00584

Caterpillar 329DL 30 Tonne Excavator

Serial No: CAT0329DJTZL00552

Reg No: 14704E

---

12/04/2021	REPAIR	HEAVYQUIP: Tested and confirmed operator complaint of low hydraulic power. Operated machine up to operating power. Carried out testing once machine was at normal operating temperature. Inspection carried out found main relief valve had slight contamination allowing valve seat to close correctly. Installed replacement seals onto relief valve, checked hydraulic pressures and confirmed now operating within OEM specifications	\$625.00
31/03/2021	REPAIR	DH: Fit 2 x top cab work lights, 1 x boom work light and 1 x final drive drain plug	\$35.00
24/03/2020	SERVICE	2000hr Service (@ 7979 Hours)	7979
20/03/2020	OTHER	Turning Cutting Edge (@ 7979 Hours)	7979
3/03/2020	OTHER	Inspect Oil Leak (@ 7888 Hours)	7888
22/01/2020	OTHER	Inspect Engine (@ 7832 Hours)	7832
18/09/2019	SERVICE	500hr Service (@ 7448 Hours)	7448
9/05/2019	OTHER	Cylinder Reseal (@ 6586 Hours)	6586
27/02/2019	OTHER	Replace Compressor (@ 6582 Hours)	6582
15/02/2019	SERVICE	500hr Service (@ 6528 Hours)	6528
14/01/2019	OTHER	Replace Relief Valve (@ 6322 Hours)	6322
4/10/2018	SERVICE	6000hr Service (@ 5986 Hours)	5986
10/07/2018	SERVICE	500hr Service (@ 5538 Hours)	5538
4/04/2018	SERVICE	1000hr Service (@ 5062 Hours)	5062
14/12/2017	SERVICE	500hr Service (@ 4544 Hours)	4544
4/09/2017	SERVICE	2000hr Service (@ 3956 Hours)	3956
3/07/2017	SERVICE	500hr Service (@ 3552 Hours)	3552
2/03/2017	SERVICE	3000hr Service (@ 3103 Hours)	3103
9/05/2016	SERVICE	500hr Service (@ 2568 Hours)	2568
8/02/2016	SERVICE	2000hr Service (@ 2084 Hours)	2084
28/09/2015	SERVICE	500hr Service (@ 1499 Hours)	1499

