

Make: Isuzu Yr: 2007 Rego Plate: - CI37WH
 Model: NPR400 Serial Num: JAANPR75P67100205

Maintenance Record - Street Sweeper (W71)

Date	Repair Description	Repaired By	Comments	Invoice #	Cost
05.08.2016	Inspect movement in suction fan bearings. Grease. Tighten rear engine mounts	On Trak Earthmoving		00000897	\$506.00
09.08.2016	Check acuator for vent, finding broken fuse. Flap is seized needs to be repaired by a mechanic	Enzo's Auto Electrics	Service call	94969	\$165.00
12.08.2016	Close seized air vent on sweeper	On Trak Earthmoving		00000910	\$297.00
18.08.2016	Supply and deliver brushes for sweeper	On Trak Earthmoving		00000939	\$759.00
05.09.2016	Diagnose starting issue on rear engine. Battery found to be flat due to ignition being left on.	On Trak Earthmoving		00000962	\$192.50
24.09.2016	Check A/C system. Hole was found in condenser pipe and requires recevier dryer. Install new pipe and dryer. Regas system.	On Trak Earthmoving		00001007	\$713.85
28.09.2016	Remove sweeper blower fan and drive assembly. Balancing and reassemble with new bearings, bearing blocks, taper locks, shaft and keys away, pulley and belts. Carry out service, sweeper and truck engines. Repair water spray system	On Trak Earthmoving		00001016	\$8,417.50
15.12.2016	Diagnosed cause of truck not selecting gears. Replace brake light fuse.	On Trak Earthmoving		00001088	\$270.00
10.02.2017	Supplied and delivered 2 x Brush sets as requested.	On Trak Earthmoving		00001175	\$1,380.00
14.02.2017	Machine hours 6003. Carried out service. Inspect drive issues. Replaced broken wheel studs.	On Trak Earthmoving		00001175	\$590.86
22.02.2017	Supplied and fit 2 x auxiliary hoses to boom of bobcat as requested by stephan.	On Trak Earthmoving		00001175	\$464.82
11.04.2017	2 x sets of brushes for sweeper	On Trak Earthmoving		00001276	\$360.00
16.05.2017	Position truck on ramps. Adjust and test park brake.	On Trak Earthmoving		00001304	\$412.50

Make: Isuzu Yr: 2007 Rego Plate: - CI37WH
 Model: NPR400 Serial Num: JAANPR75P67100205

23.05.2017	Inspect engine oil leak as requested. Top up engine oil.	On Trak Earthmoving		00001304	\$142.50
29.05.2017	Service truck and sweeper engine. Replaced all filters, engine oil and v belts and both.	On Trak Earthmoving		00001366	\$1,014.42
05.06.2017	Programme odometer on new instrument cluster from zero to 43,363 KLMS as requested	Attsspeed Auto Instruments		10209	\$400.00
25.11.2017	Vehicle signage 2 x sides	Signwave		80520265	\$2,035.00
03.01.2018	New tyre fitted	West City Tyres		43536	\$264.00
06.02.2018	Remove rear engine radiator due to coolant leak	On Trak Earthmoving		00001690	\$460.00
15.02.2018	Install rear engine radiator which required a new core and mounts. Refill with coolant	On Trak Earthmoving		00001690	\$3,178.41
13.06.2018	Inspect starting fault.Remove fuel lines. Check fuel flow, refit lines and prime system. Start and test	On Trak Earthmoving		00001925	\$190.00
21.06.2018	Inspect engine fault (engine stopping intermittently), coolant switch found to be faulty	On Trak Earthmoving		00001925	\$190.00
28.06.2018	Inspect cause of rear engine stopping intermittently. Electrical fault found	On Trak Earthmoving		00001925	\$270.00
04.07.2018	Klms 44419. Pink Slip	Clancy's Truck &L Trailor Repairs		350082	\$82.00
04.07.2018	Klms 44419. Repair exhaust. Weld broken support arm at R/H side behind R/H axle 1. Repair broken work light on R/H side	Clancy's Truck &L Trailor Repairs		350604	\$1,047.60
10.07.2018	New tyre	West City Tyres		46087	\$385.10
09.07.2018	44162 kms. New front tyre.	West City Tyres		47378	\$385.10
16.07.2018	Inspect fuel leak on rear engine. Replace section of fuel return line.	On Trak Earthmoving		00001944	\$233.82
08.08.2018	Hours 3783. Remove fuel lines. Remove seized fuel injector. Install new injector and return lines.	On Trak Earthmoving		00001996	\$1,002.18
12.08.2018	Remove rusted out front section of fan and replace. Desize air vent bleed off on fan & reconnect activator	Belgenny Engineering		1007	\$1,591.70

Make: Isuzu Yr: 2007 Rego Plate: - CI37WH
 Model: NPR400 Serial Num: JAANPR75P67100205

17.10.2018	Locate brake fluid leak, remove left hand side rear brake lines. Prepare and fit brake lines and clamps. Clean bleed nipples. Bleed brakes and test.	On Trak Earthmoving		00002082	\$1,262.73
23.11.2018	Oil pressure switch	Garwood International		00004529	\$62.57
16.01.2019	Supplied oil switch and brooms	B.S.B Brushes & Sign		48233	\$737.00
29.01.2019	44635 KMS. A/C inoperative, faulty pressure switch, supply and fit new receiver drier and switch.	S&S Auto Electrical Services		44598	\$1,076.79
18.03.2019	Remove and replace main engine sump due to corrosion	On Trak Earthmoving		00002256	\$615.00
03.04.2019	Exhaust bend	M&M Mufflers		1579	\$55.00
12.08.2019	Repaired false warning low oil pressure vacuum engine.	In house (Stef)		n/a	n/a
02.03.2020	replaced fitting hydraulics	In house (Stef)		n/a	n/a
16.03.2020	Fitted new windscreen wipers and beacon repaired	In house (Stef)		n/a	n/a
20.05.2020	New Battery for sweeper	RJ Batteries		17a013126	504.31
27.11.2021	5 x drive belts, adjust & grease, remove right hand side water tank	On Trak Earthmoving		00003351	1896.14
1.07.2022	Removed tank for access. Reinstalled suction fan drive belts and adjust. Cut off one belt due to damage and ordered new part.	On Trak Earthmoving		3699	\$460
13.07.2022	Removed water tank, installed new suction fan belts and adjusted. Installed tank and test. Labour x 8 hours	On Trak Earthmoving		3699	\$1,020
20.07.2022	Supplied 5 x vee belts for fan drive	On Trak Earthmoving		3678	\$228.87
25.07.2022	Removed and replaced right hand side brush motor. Removal required heating and grinding as items were seized. 4 x hours labour	On Trak Earthmoving		3717	\$560
22.11.2022	1X PUNCTURE REPAIR	West City Tyres		76826	189.26
25.01.2023	The control module for the gearbox was burnt out-TCM FAILED. Connected. Towed into workshop as truck was stuck in gear. Checked sensors.	Isuzu Trucks		iscsn15717	\$8,129

Make: Isuzu Yr: 2007 Rego Plate: - CI37WH
 Model: NPR400 Serial Num: JAANPR75P67100205

09.02.2023	Carry Out Service. Replace Filter and Engine Oil on both front and rear engines	On Trak Earthmoving	5.5 hours Labour and parts	00003985	\$1,018
10.03.2023	Bypass air dryer and repair air leak	On Trak Earthmoving	4.75 hours	0004003	\$731
18.04.2023	Remove rear engine water pump. Sourced parts and removed pulley from pump. 26/4- Installed used water pump on rear engine. Fill with coolant, run and test	On Trak Earthmoving	16 x hours labour	00004081	\$2,120
13.7.23	remove radiator lines and water pump 19/7/23 pickup new belts and hoses and travel to site .install new water pump an belts	on Trak Earthmoving	labour x2 hours service call an parts	00004220	\$ 1.192.00
01.08.2023	TRAVEL TO SITE, PREPARE AND FIT RADIATOR TO SWEEPER ENGINE AND TEST. FILL WITH COOLANT AND TEST.	ON TRAK EARTHMOVING	HOURS 4181, LABOUR X 5 HOURS AND SERVICE CALL	00004284	\$770.00
06.02.2024	ROAD SERVICE, TYRE REPAIR	West City Tyres		92088	\$231
15.02.2024	TRAVEL TO LONG STREET. FILL BRAKE RESERVOIR. LOCATE LEAK FROM CORRODED BRAKE LINES.	On Trak Earthmoving	LABOUR X4 HOURS, SERVICE CALL	00004608	\$682
19.02.2024	REMOVE AND INSTALL NEW BRAKE LINES AS REQUIRED IN LHS CHASSIS RAIL. BLEED BREAKS AND TEST SYSTEM	On Trak Earthmoving	LABOUR X4 HOURS, SERVICE CALL	00004608	\$682
17.04.2024	Inspected transmission oils and found level ok and no contamination. Inspected sensor and solenoid, sensor ok, solenoid seized and unable to select maunally. Connected and found fault codes relating to shift/ select sensors, solenoid and TCM. Removed and replaced shift lid. operated vehicle and no responce, unable to talk to TCM. Carried out gear learn. road testes and passed.	IZUZU TRUCKS	BOX ASM; SHIFT, CONTROL UNIT N, WORKSHP SUPPLIES	ISSN36327	\$7,597.5
30.04.2024	travel to site, replace blown right side brush cylinder hose.	On Trak Earthmoving	labour x1.5 hours, service call, parts hose and fittings	4799	\$562
30.04.2024	tavel to site, replace blown right side brush cylinder hose	On Trak Earthmoving	labour x1.5 hours, service call, parts hose and fittings	4785	\$562