



Profix Industries Pty Ltd

Logan Village QLD 4207

0424 176 440 | leyton@profixindustries.com.au | profixindustries.com.au



Tax Invoice #105682

Issued	19/12/2025
Due	03/01/2026
ABN	87 607 916 129
Date of work	25 Nov to 12 Dec 2025
Order #	Q452
Job Title	MCC Darra / Remondis, Repairs to Compactor
Total	\$8,690.88

MCC Darra / Remondis, Repairs to Compactor, 25 Nov to 12 Dec 2025

Product/Service	Description	Qty.	Unit Price	Total
Contractor Call Out (Elec)	ELECTRICIAN Remondis Darra MCC 28 Limestone St, Darra QLD Ref: Quote 452 dated 13-11-2025, Issues: - Power supply failure - Auxiliary contactor failure - Motor start contactor and overload failure	1	\$130.00	\$130.00
Contractor Labour (Elec)	ELECTRICIAN Attend site to fix the following failed issues: - Power supply failed. - Auxiliary contactor has failed. - Motor start contactor and overload have failed. - Motor has failed short between windings and earth. - Inlet plug has burnt pins. - Both 32A outlets on site have burnt contacts. **Noted 13-11-2025; Unable to test fully, until the main repairs are completed to enable testing of further components**. - Replaced the faulty parts as per the quote and conducted tests to ensure all systems were functioning correctly. - On return to site to fix the above listed, the pump/motor had burnt out. Leyton to source pump/motor and install. Return to site on 05 Dec with Leyton to assist with final electrics.	9	\$130.00	\$1,170.00



Profix Industries Pty Ltd

Logan Village QLD 4207

0424 176 440 | leyton@profixindustries.com.au | profixindustries.com.au

Product/Service	Description	Qty.	Unit Price	Total
Parts (Electrician)	ELECTRICIAN -Schneider 24VDC 1.25 A power supply x 1 -New motor contactor and overload x 1 -Schneider CA2KN223m7 contactor x 1 -32A 5pin plug top x 1 -32A 5pin outlet x 2	1	\$1,387.50	\$1,387.50
Call Out Standard W.I.	LEYTON	4	\$130.00	\$520.00
Labour Standard W.I.	LEYTON; 25 Nov to 12 Dec 2025	19	\$130.00	\$2,470.00
	TUE 25 Nov, attend site with Electrician, check power pack once motor was removed. -Found hydraulic drive coupler cracked. -Order new drive coupler.			
	WED 26 Nov, install new drive coupler. -Test run pump from battery drill. -Pump won't prime up due to being worn out. -Order new pump.			
	WED 03 Dec, install new pump. -Re-install motor. Check return filter and found full of plastic and rubber particles. -Source and install new return filter. -Organise for compactor to be put back into position.			
	THU 04 Dec, plug machine back in and test run. -Noted pressure switch leaking oil.			
	FRI 05 Dec, compactor had tripped out. -Inspect and reset overload. Talk to Callan for approval to install 2 x new pressure switches. -Only 1 x available in Brisbane. Install 1 x switch and order 2nd from interstate.			
	FRI 12 Dec, install 2nd pressure switch.			
	No issues as of 18-12-2025.			
Parts (Leyton)	LEYTON -Motor \$830 ex gst -Pump and freight \$580 ex gst -Coupling \$77.30 ex gst -Return Filter \$70 ex gst - 2 x pressure switches \$616 ex gst (308ea)	1	\$2,173.30	\$2,173.30
Consumables		1	\$50.00	\$50.00



Profix Industries Pty Ltd

Logan Village QLD 4207
0424 176 440 | leyton@profixindustries.com.au | profixindustries.com.au

Thank you for your business.
Send REMITTANCE to admin@profixindustries.com.au

Bank Account Details for EFT Payment:
Commonwealth Bank
Profix Industries PTY LTD
BSB: 064-184 Account: 10947924
PARTS REMAIN THE PROPERTY OF PROFIX INDUSTRIES P/L,
UNTIL INVOICE IS PAID IN FULL.

Tax Invoice 87 607 916 129

Subtotal	\$7,900.80
GST (10.0%)	\$790.08
Total	\$8,690.88



Profix Industries Pty Ltd

Logan Village QLD 4207
0424 176 440 | leyton@profixindustries.com.au | profixindustries.com.au

Quote #452

Sent on 13/11/2025

ABN 87 607 916 129

Job Title MCC Darra / Remondis, Repairs Required

Total \$2,785.75

Product/Service	Description	Qty.	Unit Price	Total
Contractor Call Out	Remondis Darra MCC 28 Limestone St, Darra QLD Jim Fronis (Remondis) 0419 988 538	1	\$140.00	\$140.00
Inspection to be invoiced separately				
Issues found 13-11-2025 as follows:				
Contractor Labour	Attended site and found the following items have failed when the machine malfunctioned: - Power supply failed - Auxiliary contactor has failed - Motor start contactor and overload have failed - Motor has failed short between windings and earth - Inlet plug has burnt pins - Both 32A outlets on site have burnt contacts	7	\$140.00	\$980.00
Unable to test fully until the main repairs are completed to enable testing of further components				
Quote to be used as a guide only				
Parts	-Schneider 24VDC 1.25 A power supply x 1 -New motor contactor and overload x 1 -Schneider CA2KN223m7 contactor x 1 -32A 5pin plug top x 1 -32A 5pin outlet x 2	1	\$1,387.50	\$1,387.50
Consumables		1	\$25.00	\$25.00

Subtotal	\$2,532.50
GST (10.0%)	\$253.25
Total	\$2,785.75



Profix Industries Pty Ltd

Logan Village QLD 4207
0424 176 440 | leyton@profixindustries.com.au | profixindustries.com.au

This quote is valid for the next 30 days, after which values may be subject to change.
Please contact us with any questions regarding this Quote.
Send deposit REMITTANCE to admin@profixindustries.com.au

Bank Account Details for EFT Payment
Commonwealth Bank
Profix Industries PTY LTD
BSB: 064-184 Account : 10947924