

BK Civil - Work Order Summary

Asset:
EX3002 BK164 - 2018 Hitachi ZX360LCH-5
Excavator

Location:

Current Tracker Hours:

Current Tracker Kms:

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
30011	7000 hours service	07/03/2023	6948	0		Routine Service	Open	Joseph Giles
29739	checkover weld track link pins in	17/02/2023	6924	0	20/02/2023	Ask Supervisor		Joseph Giles Samuel Sparkes
29431	bucket repairs	25/01/2023	6895	0	25/01/2023	Ask Supervisor		Jordan Humberdross
29389	kogan power station check over	22/01/2023	6893	0	21/01/2023	Ask Supervisor		David Wood
29152	Broken grease line	05/01/2023			24/01/2023	Ask Supervisor		Samuel Sparkes
29048	Htch pin shims please and thankyou	17/12/2022				Ask Supervisor	Open	Samuel Sparkes
28819	250 service due	30/11/2022			01/12/2022	Repair Next Service		Samuel Sparkes
28812	Loose grouser right side	29/11/2022			06/12/2022	Ask Supervisor		Samuel Sparkes
28796	6750 hours service	28/11/2022	6696	0	05/12/2022	Routine Service		Samuel Sparkes
28377	Service due	20/10/2022			24/10/2022	Repair Next Service		
28358	Carry roller	18/10/2022			05/12/2022	Ask Supervisor		Samuel Sparkes
28332	6500 hours service	14/10/2022	6445	0	28/09/2022	Routine Service		Samuel Sparkes
28195	Mssing grease line	27/09/2022			17/10/2022	Routine Service		Samuel Sparkes
27837	6250 hours service	24/08/2022	6195	0	02/09/2022	Routine Service		Samuel Sparkes
27449	6000 hours service	13/07/2022	5951	0	21/07/2022	Routine Service		DMS Cobar
27007	5750 hours service	30/05/2022	5691	0	17/06/2022	Routine Service		DMS Cobar
26759	Change fuel filters and top up auto greaser	30/04/2022	5506	0	30/04/2022	Ask Supervisor		
26727	Requires new fan belts	28/04/2022	5494	0	29/05/2022	Ask Supervisor		Morgan Hblcombe
26643	Wipers not working	19/04/2022	5468	0	20/04/2022	Ask Supervisor		
26616	5500 hours service	16/04/2022	5449	0	28/04/2022	Routine Service		Mrgan Hblcombe
26593	A/C not getting cold and a belt squeak	12/04/2022	5416	0	12/04/2022	Ask Supervisor		
26374	Repair grease lines	20/03/2022	5276	0	20/03/2022	Ask Supervisor		
26273	Autogreaser	09/03/2022	5243	0	09/03/2022	Ask Supervisor		
26231	5250 hours service	04/03/2022	5205	0	19/03/2022	Routine Service		Morgan Holcombe
26215	A/C issue	02/03/2022	5186	0	02/03/2022	Ask Supervisor		Mrgan Hblcombe
25736	Peak check lists	12/01/2022	5102	0	06/01/2022	On/Off Hre Inspection		Clay Baran
25720	Engine light	11/01/2022	5102	0	05/01/2022	Repair Next Service		
25538	R/HAND travel motor break not operating correctly.	09/12/2021			24/01/2022	Ask Supervisor		Saul Whiley
25108	remove tilt head for repairs	20/10/2021	5016	0	20/10/2021	Routine Service		Clay Baran

25109 Work Order	Car out CS Energy site check	20/10/2021 Created	5016 Created Hours	0 Created Km	20/10/2021 Completed	On/Off Fire Inspection Priority	Item Status	Clay Baran Assigned To/Completed By
24835	5000 hours service	16/09/2021	4943	0	19/10/2021	Routine Service		Clay Baran
24613	Replace GET , New teeth and weld cutting edges x 2	24/08/2021	4782	0	03/05/2021	Repair Next Service		Nicholas Spina
24615	REPLACE GREASE HOSES ON HITCH	24/08/2021	4782	0	24/08/2021	Ask Supervisor		
24628	Replace GET as required	24/08/2021	4782	0	14/06/2021	Repair Next Service		Samuel Sparkes
24592	wiper not working	22/08/2021			13/09/2021	Repair Next Service		Samuel Sparkes
24587	Prestart Defect - broken nipple high	21/08/2021			13/09/2021	Repair Next Service		Samuel Sparkes
24488	4750 hours service	15/08/2021	4699	0	16/08/2021	Routine Service		Samuel Sparkes
24462	Warning Light - Maintenance	12/08/2021	4681	0	07/08/2021	Ask Supervisor		
24468	Replace grease lines and secure grease bank	12/08/2021	4681	0	08/08/2021	Ask Supervisor		Samuel Sparkes
24315	Fire suppression gone off	30/07/2021	4567	0	30/07/2021	Ask Supervisor		Samuel Sparkes
24104	4500 hours service	16/07/2021	4446	0	26/07/2021	Routine Service		Samuel Sparkes
23693	Inspect power headleak	15/06/2021	4193	0	13/06/2021	Ask Supervisor		Samuel Sparkes
23673	4250 hours service	14/06/2021	4193	0	18/06/2021	Routine Service		Samuel Sparkes
23323	4000 hours service	16/05/2021	3955	0	18/06/2021	Routine Service		Adani Plant Branch Fitter
22976	3750 hours service	11/04/2021	3694	0	23/04/2021	Routine Service		Adani Plant Branch Fitter
22424	3500 hours service	11/03/2021	3455	0	22/03/2021	Routine Service		Adani Plant Branch Fitter
21523	Blow out air cleaners, inspect and repair engine oil leak	25/02/2021	3341	0	05/02/2021	Ask Supervisor		Adani Plant Branch Fitter
18982	grease line broken	11/01/2021	3104	0	18/12/2020	Routine Service		Adani Plant Branch Fitter
17437	3000 hours service	02/12/2020	2950	0	13/01/2021	Routine Service		Adani Plant Branch Fitter
15457	2750 hours service	02/11/2020	2699	0	04/11/2020	Routine Service		Adani Plant Branch Fitter
14469	Breakdown n - Auto Greaser Hoses	15/10/2020	2581	0	15/10/2020	Repair Next Service		Toowoomba Branch WSHOP - R
14474	Breakdown n - Cracked windscreen	15/10/2020	2581	0	15/10/2020	Do Not Operate		
13762	Prestart Defect - ac fan is squealing	02/10/2020			07/01/2021	Ask Supervisor		Adani Plant Branch Fitter
13132	2500 hours service Completed SMU 2564	21/09/2020	2445	0	12/10/2020	Routine Service		Toowoomba Branch WSHOP - W
13065	Auto greaser needs refilling	18/09/2020			18/09/2020	Repair Next Service		
10279	250 Hr Service	30/06/2020	2264		17/07/2020	Routine Service		Raymond Strohfeld