



Vehicle History Detail

Fleet #	XJT625
Registration	XJT625
Make	Volvo
Model	
VIN / Chassis #	YV5J4CNDX6D128181

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer	Repairer Notes	Invoice	Cost
R-4389	26/04/2024				0 Lights	Irvines			\$0.00
R-3184	26/04/2024				0 Chassis	L M Diesel	19/5 still waiting on Evan from RRAg to get back to me re warranty claim	332196	\$3,796.53
R-4589	08/11/2023				0 Electrical	Largs Depot			\$0.00
R-4373	22/09/2023				0 Signage	Largs Depot			\$0.00
S-634	23/08/2023	955281		0	B - BASIC/30k	Largs Depot	Carried out Basic service topped up fluids		\$280.00
R-4628	23/08/2023		0	0	0 Brakes	Multispares		5959596	-\$196.35
R-4630	23/08/2023		0	0	0 Engine	Multispares		5957513	\$419.97
R-4264	23/08/2023	955281		0	0 ABS	Largs Depot	Removed all drive wheels and visually inspected brake pad on rearmost axle whilst replacing front drive pads found rear drive pads in bad shape replaced with new and replaced abs sensor on RH rearmost hub all okay cleared fault		\$350.00
R-4625	18/08/2023		0	0	0 Brakes	Multispares		5948616	\$320.34
T-1252	17/08/2023		0	0	0 B FLEET PRESSURE	Bridgestone		187172399	\$23.10

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer	Repairer Notes	Invoice	Cost
R-2878	31/01/2023	0	0	0	Fuel Delivery	Ryan Maintenance Service	hose test	13197	\$237.55
R-1704	06/01/2023	925971	0	0	Lights				\$0.00
T-437	06/01/2023	0	0	0	11R22.5 X 4	Bridgestone		88964702	\$2,669.51
T-330	07/12/2022	0	0	0	REPAIR PUNCTURE	Bridgestone		88822173	\$50.60
T-330	07/12/2022			0		Bridgestone		88822173	\$0.00
T-329	06/12/2022			0		Bridgestone	Has been rectified on Repair Order # T-330		\$0.00
S-330	28/11/2022	0	0	0	E	Ivines	refer jobcard 2204	87814	\$0.00
R-2204	28/11/2022			0	Cooling System	Ivines		87814	\$637.78
R-2160	24/11/2022			0	Steering	Bridgestone	new steer tyre fitted refer #324 in tyres	88748578	\$0.00
T-324	24/11/2022			0	295/80R22.5 X 1	Bridgestone		88748578	\$655.63
R-610	22/11/2022			0	Cooling System	Ivines			\$0.00
R-1710	22/11/2022			0	Hydraulics	Ivines			\$0.00
R-1838	26/09/2022	0	0	0	Parts	Haulmark - ADELAIDE	FILTER KIT MACK	49925	\$155.23
R-1498	13/09/2022	0	0	0	Parts	Multispares	CAP POWER STEERING/RADIATOR MOUNT BOTH UPPER/LOWER/ENGINE MOUNT FRONT/SWAY BAR LINK/MOUNTING BRACKETS/MUDGUARD/CLAMP	5233669	\$2,426.32
S-283	09/09/2022	925600	0	0	B - BASIC/30k	Largs Depot			\$210.00
R-1815	08/09/2022	0	0	0	Fuel system	South Central Trucks	FUEL FILTER	381650	\$154.99
R-1379	07/08/2022	0	0	0	Lights	Ivines	REPLACED LH HEAD LIGHT GLOBES	85938	\$93.17

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer	Repairer Notes	Invoice	Cost
T-136	04/08/2022	0	0	0		Bridgestone	REPLACE DRIVE TYRES X 2	88166624	\$1,015.74
R-714	23/05/2022	0	0	0	Air Conditioner		AIR CONDITIONER REPAIRS - ROCKY RIVER AG	323728	\$2,152.87
T-568	28/03/2022	906246		0	Imported	Bridgestone	EQUAL @ \$ 35.00 EACH		\$0.00
T-569	28/03/2022	906246		0	Imported	Bridgestone	BEAD BALANCE BB12 - 360G		\$70.00
T-570	28/03/2022	906246		0	Imported	Bridgestone	SCRAP TYRES TBR		\$43.34
T-571	28/03/2022	906246		0	Imported	Bridgestone	FIT TBR TYRE		\$39.60
T-572	28/03/2022	906246		0	Imported	Bridgestone	295/80R22.5 152/148M BS R150		\$1,127.13
R-58	18/02/2022			0	Engine	Justin McCredie	gather tools, collect parts from SCT, travel to CrystalBrook depot. replace cam. position sensor, test, truck starts fine. pack up, travel back to Largs depot, unpack tools.		\$490.00
R-117	01/02/2022			0	Cab	Justin McCredie	Washed truck after repairs		\$70.00
R-121	31/01/2022			0	Steering	Justin McCredie	Refit new steering shaft to truck, test drive and realign steering wheel.		\$140.00
R-124	28/01/2022			0	Steering	Justin McCredie	Test drive around yard, jack up and check kingpins & wheel bearings, check all steering ball joints, all ok. jack up and turn steering wheel, fault still there. Remove lower steering joint u/j and find seized, remove steering shaft and order new one.		\$280.00
R-349	22/10/2021			0	Electrical	Justin McCredie	Undo all wiring to LH headlight/parker, repair multiple broken wires, test, all operational		\$420.00
R-356	21/10/2021			0	Electrical	Justin McCredie	replace plug for diff lock		\$70.00

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer	Repairer Notes	Invoice	Cost
R-355	21/10/2021			0	Steering	Justin McCredie	remove and replace worn drag link ball joint		\$280.00
R-353	21/10/2021			0	Air Leaks	Justin McCredie	remove and reseal leaking fitting on RH air tank		\$35.00
R-354	21/10/2021			0	Steering	Justin McCredie	Replace both ball joints on tie rod, refit rod and check alignment		\$280.00
R-352	21/10/2021			0	Chassis	Justin McCredie	Remove and replace RHF guard hanger bracket		\$35.00
R-357	21/10/2021			0	Electrical	Justin McCredie	replace plug for gearbox temp sensor		\$70.00
R-363	20/10/2021			0	Lights	Justin McCredie	replace inop roof clearance light		\$35.00
R-361	20/10/2021			0	Suspension	Justin McCredie	replace 6 leaking drive air bags		\$840.00
R-360	20/10/2021			0	Suspension	Justin McCredie	replace leaking LHF drive shocker		\$70.00
R-359	20/10/2021			0	Brakes	Justin McCredie	Inspect front drive brakes, all ok		\$140.00
R-358	20/10/2021			0	Lights	Justin McCredie	replace RHR number plate light		\$70.00
R-362	20/10/2021			0	Fuel Delivery	Justin McCredie	replace worn earth reel		\$70.00
R-369	15/10/2021			0	Engine	Justin McCredie	replace air filter element		\$35.00
S-4	14/10/2021	890232		0	B - 40k	Justin McCredie	B SERVICE COMPLETED - LIST PAPERWORK RECEIVED - LIST OF JOBS STILL TO BE COMPLETED ATTACHED		\$0.00
53 Records								TOTAL:	\$20,163.05