

## **Vehicle Service Records (VSR Explorer) Repair history D-201942**

**Registration nr:** XQ92AJ **Chassis nr:** D-201942 **VIN nr:** YV5RG40D4FD201942

Market type: FH13A64T Country: AUS Delivery date: 2015-08-04

PC	Туре	Code	Description (Original)	#
٩	202	24-06-13 - Mileage: 14	481555 - Order nr: 8189939	
0	*	М	PLEASE FILL IN	
0	Ø	LO-170	TEAM VIEWER	1.5
	3		CARRY OUT AIR DRIER CALIRBATION - CUSTOMER HAS REPLACED	
	3			
	3		Drove out to Gatton and carried out programming and	
0	Ø	LO-170P40V	Charge for laptop connection	0.5
	Ξ		Connect laptop to vehicle and conduct	
	3		diagnostic test.	
	Ξ		Mileage:1481555	
	Ξ		Hrs:22806	
	Ξ		calibration.	
	Ξ		DRIER @ THEIR WORKSHOP	
0	*	91	WORKSHOP CONSUMABLES	
9	202	24-05-15 - Mileage: 14	479322 - Order nr: 4088772	
0	*	М	PLEASE FILL IN	
	3			
0	Ø	LO-3000	Program instrument cluster	2
0	*	92	UTE MILEAGE 160 km's @ \$2.50/km.	
	3			
	3		Mileage:1479323	
	3		Hrs:22734	
	3		Next Service:	
	E		Parked:	
	3		DROVE TO SITE, FIND TRUCK WITH SUPERVISOR AND COMMENCE	
	E		WORK, THEY HAVE INSTALLED A NEW INSTRUMENT CLUSTER WHICH	
	E		ELLIOT PREVIOUSLY TRIED TO CONNECT VIA TEAM VIEWER BUT	
	3		TECH TOOL DIDNT GET TRANSFERED INTO OUR SITE SO COULD NOT	
	Ξ		CONNECT. GOT ASKED TO TOUCH ANOTHER TRUCK WHICH AARON KNEW	
	Ξ		ABOUT AND WILL MAKE ANOTHER JOB CARD FOR (XQ11G) FOR APM	
	3		PROGRAMMING ALSO.) CARRY OUT CONNECTING BUT WOULD NOT	

about:blank 1/26

//24, 2:45     PC	Туре	Code	Venicle Service Records (VSR) - Repair history D-201942  Description (Original)	#
	<b>3</b>		CONNECT TO CARRY OUT ANY WORK TO IT. CONSTANT RESTARTING	
	B		CLIENT, DOING REPAIR TOOL AND AUTHENTICATING TO EVENTUALLY	
	3		GET IT TO WORK AFTER LIKE 11 OR 12TH TIME (LOST COUNT	
	3		TBH.) CARRY OUT PROGRAMMING INSTRUMENT CLUSTER, SID	
	B		DISPLAY AND ALSO HMIIOM. ALL WENT THROUGH OK WHICH I COULD	
	3		GET HOURS OFF OF IT. PUT TRUCK TO SLEEP AND TURNED BACK ON	
	Ξ		AND DASH AND SID WORKS GREAT NOW. FINISHED TT AND JOBCARD	
	3		о іт.	
0	*	91	WORKSHOP CONSUMABLES	
8	202	24-05-03 - Mileage: 14	179322 - Order nr: 8188186	
0	*	М	PLEASE FILL IN	
	3			
0	Ø	LO-3000	Program instrument cluster	3.5
0	Ø	LO-170P40V	Charge for laptop connection	0.5
	Ξ		Connect laptop to vehicle and conduct	
	1		diagnostic test.	
0	*	92	UTE MILEAGE 160 km's @ \$2.50/km.	
	B			
	E		Mileage:1479323	
	E		Hrs:22734	
	Ξ		Next Service:	
	Ξ		Parked:	
	3		DROVE TO SITE, FIND TRUCK WITH SUPERVISOR AND COMMENCE	
	3		WORK, THEY HAVE INSTALLED A NEW INSTRUMENT CLUSTER WHICH	
	3		ELLIOT PREVIOUSLY TRIED TO CONNECT VIA TEAM VIEWER BUT	
	Ξ		TECH TOOL DIDNT GET TRANSFERED INTO OUR SITE SO COULD NOT	
	Ξ		CONNECT. GOT ASKED TO TOUCH ANOTHER TRUCK WHICH AARON KNEW	
	Ξ		ABOUT AND WILL MAKE ANOTHER JOB CARD FOR (XQ11GJ FOR APM	
	1		PROGRAMMING ALSO.) CARRY OUT CONNECTING BUT WOULD NOT	
	3		CONNECT TO CARRY OUT ANY WORK TO IT. CONSTANT RESTARTING	
	E		CLIENT, DOING REPAIR TOOL AND AUTHENTICATING TO EVENTUALLY	
	E		GET IT TO WORK AFTER LIKE 11 OR 12TH TIME (LOST COUNT	
	Ð		TBH.) CARRY OUT PROGRAMMING INSTRUMENT CLUSTER, SID	
	E		DISPLAY AND ALSO HMIIOM. ALL WENT THROUGH OK WHICH I COULD	
	E		GET HOURS OFF OF IT. PUT TRUCK TO SLEEP AND TURNED BACK ON	
	E		AND DASH AND SID WORKS GREAT NOW. FINISHED TT AND JOBCARD	
_	E .		О ІТ.	
0	*	91	WORKSHOP CONSUMABLES	

about:blank 2/26

124, 2.40			verticle detrice records (vort) - repair filstory b-201942	
PC	Туре	Code	Description (Original)	#
8	202	20-09-29 - Mileage: 1	165147 - Order nr: 8137251	
0	*	М	PLEASE FILL IN	
	3			
0	Ø	LO-211	Cylinder head, replacement	26
	3		Quoted 4472909	
0	г.	VO-8192804	SCREW	8
0	г.	VO-20538793	SEAL STRIP, R/COVER GASKET	1
0	г.	VO-21510072	CYLINDER HEAD GASK	1
0	г.	VO-20855371	GASKET EXH/MANIFOLD	6
0	г.	VO-21447682	GASKET, UPPER T/COVER	1
0	г.	VO-3979639	GASKET - PREHEATER	2
0	г.	VO-21282255	GASKET	1
0	г.	VO-20479636	SEALING STRIP	1
0	г.	VO-1547254	SEALING RING - BLACK	2
0	г.	VO-975697	O-RING	1
0	5	VO-21503575	SEALING RING - BLACK	1
0	5	VO-22206133	TURBO FEED GASKET	1
0	г.	VO-420643	TURBO DRAIN GKT	1
0	5	VO-469601	O-RING TURBO - GREEN	1
0	5	VO-21940615	SEALING RING - PURPLE	1
0	г.	VO-20784537	GASKET TURBO BASE	1
0	г.	AU2-WUR0673205010	Nylon Power LOC 2I	8
0	6	AU2-9718-240002743	BBC4 BRAKE CLEANER	8
0	6	VO-983472	CABLE TIE, Injector Harness	8
0	5	MK-NARV56310	CABLE TIE 1=10PK (7.6x370mm)	2
0	ď	MK-NARV56306	CABLE TIE 1=25PK (4.8x300mm)	1
0	5	VO-3092340	SILASTIC GREY	1
0	г.	VO-1161277	LINER SILASTIC	1
0	5	VO-85103205	GREEN PAINT	1
0	Γ.	OTH- WUR0674850120/MTR	EMERY CLOTH G120	1
0	г.	AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	1
0	г.	VO-994447	FLANGE BOLT M8 x 25mm Black	6
0	г.	VO-8131393	CAGE	4
0	г.	VO-276948	O-RING KIT	6
0	г.	VO-20852765	DOWTY WASHER O.D. 24mm	4
0	г.	VO-20852764	DOWTY WASHER O.D. 22mm ID 14mm	4
0	г.	AU2-PERM84101	PX EPOXY 5 MIN GENP	1

about:blank 3/26

ion (Original)	#
G RING - PURPLE	1
G RING - PURPLE	2
AMP 12-22mm	1
BOLT M8 x 40mm Black	2
NMENTAL CHARGE	
TO BE RETURNED TO WHEN COMPLETE	
OITIONAL PARTS MUST BE ON SEPERATE LINE	
al parts	
BOLT M12 x 45mm	6
BOLT M10 x 50mm ENG	6
BOLT M8 x 50mm Black	1
NUT M8 CRIMP	1
/L HEAD - D13C/D	1
INJ HARNESSD9B/D12D/D13	1
- Order nr: 8131286	
03294	
parts warranty	
	1
- Order nr: 8130457	
ndersen Truck & Tractor	
LOSS OF ALL LIGHTS: MISSION CONFIRMATION NUMBER:	
0124	
O124 OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND	
+	
IOURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER  THROUGH AND BLOWING FUSE. REPLACE FUSE AND REPLACE	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER  THROUGH AND BLOWING FUSE. REPLACE FUSE AND REPLACE  TH DRIVERS SPARE SUZI COIL. CHECK OPERATION, OKAY.	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER  THROUGH AND BLOWING FUSE. REPLACE FUSE AND REPLACE  TH DRIVERS SPARE SUZI COIL. CHECK OPERATION, OKAY.  VEHICLE TO SERVICE, TRAVEL BACK TO WORKSHOP	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER  THROUGH AND BLOWING FUSE. REPLACE FUSE AND REPLACE  TH DRIVERS SPARE SUZI COIL. CHECK OPERATION, OKAY.  VEHICLE TO SERVICE, TRAVEL BACK TO WORKSHOP  Order nr: 8114283	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER  THROUGH AND BLOWING FUSE. REPLACE FUSE AND REPLACE  TH DRIVERS SPARE SUZI COIL. CHECK OPERATION, OKAY.  VEHICLE TO SERVICE, TRAVEL BACK TO WORKSHOP  Order nr: 8114283	
OURS CALL OUT SATURDAY 11-04-20 19:00 HRS TO ATTEND  WITH COMPLAINT OF LOSS OF ALL LIGHTS. TRAVEL TO  OOWN SITE AT SHELL ROADHOUSE BOGGABILLA AND CARRY  SPECTION OF VEHICLE. INSPECT POWER SUPPLY AND WIRING  ATE SUZI COIL FROM PRIME MOVER TO FIRST TRAILER  THROUGH AND BLOWING FUSE. REPLACE FUSE AND REPLACE  TH DRIVERS SPARE SUZI COIL. CHECK OPERATION, OKAY.  VEHICLE TO SERVICE, TRAVEL BACK TO WORKSHOP  Order nr: 8114283  FILL IN	
THOUGH AND BLOWING FUSE. REPLACE FUSE AND REPLACE  TH DRIVERS SPARE SUZI COIL. CHECK OPERATION, OKAY.  VEHICLE TO SERVICE, TRAVEL BACK TO WORKSHOP  Order nr: 8114283  FILL IN	7.6
	GRING - PURPLE  LAMP 12-22mm  BOLT M8 x 40mm Black  NMENTAL CHARGE  GTO BE RETURNED TO WHEN COMPLETE  DITIONAL PARTS MUST BE ON SEPERATE LINE  all parts  BOLT M12 x 45mm  BOLT M10 x 50mm ENG  BOLT M8 x 50mm Black  NUT M8 CRIMP  YL HEAD - D13C/D  INJ HARNESSD9B/D12D/D13  - Order nr: 8131286  03294  parts warranty  - Order nr: 8130457  Andersen Truck & Tractor  I LOSS OF ALL LIGHTS: MISSION CONFIRMATION NUMBER:

about:blank 4/26

1124, 2.40			vehicle dervice Records (Volv) - Repair filstory D-201342	
PC	Туре	Code	Description (Original)	#
	Ξ		The engine was stripped by the customer. Inspected the min	
	3		bearings. Found they were worn. Removed all main bearings	
	3		and trust washers. Replaced the bearings and reassembled	
	3		with the parts listed.	
0	*	91	WORKSHOP CONSUMABLES	
8	<b>₩</b> 201	19-03-11 - Mileage: 89	94598 - Order nr: 8114087	•
<b>Ø</b>	Ø	VO-2112600	Cylinder head, replace	13.7
	3		S0914 DACU, SW UPDATE. FH/FM (4)	
0	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
<b>Ø</b>	Ø	VO-3608300	DACU, SW update. Campaign only	0.2
0	г.	VO-21510072	CYLINDER HEAD GASK	1
8	г.	VO-21253770	CYLINDER LINER KIT	3
0	г.	VO-21253770	CYLINDER LINER KIT	2
8	г.	VO-85013933	CYL HEAD, EXC - FM(4) / FH(4)	1
<b>@</b>	г.	VO-20538793	SEAL STRIP, R/COVER GASKET	1
0	г.	VO-22584597	CAMSHAFT AND BEARING KIT	1
8	г.	VO-8192804	SCREW	8
0	г.	VO-990810	FLANGE BOLT M12 x 45mm	6
8	г.	VO-994447	FLANGE SCREW	6
0	г.	VO-21447682	GASKET	1
8	г.	VO-21344774	FLANGE BOLT M10 x 50mm Grey	6
8	г,	VO-276948	O-RING KIT	6
0	6	VO-21261987	GASKET	6
0	5	VO-85136742	FILTER KIT	1
0	5	MK-NARV56306	CABLE TIE 1=25PK	2
8	5	VO-990861	FLANGE BOLT M10 x 30mm Grey	24
<b>®</b>	г.	VO-20541940	SEALING STRIP	1
0	г.	VO-21532258	SEALING RING	1
<b>®</b>	г.	VO-21637266	ROCKER ARM - INLET	2
0	г.	VO-21881195	ROCKER ARM INJECTION	1
0	г.	VO-85020372	TURBOCHARGER, EXCH	1
0	г.	UNK-STH625115AK	21460261 Rocker Arm Ex Br	3
0	г.	UNK-STH625115AK	21881195 Rocker Arm	4
0	r.	VO-21637266	ROCKER ARM - INLET	1
0	г.	VO-21610676	BEARING SHELL	4
0	г.	VO-22275838	SEALING RING	2
<b>Ø</b>	г.	VO-21092243	SEALING RING	7
0	г.	VO-994445	FLANGE BOLT M8 x 16mm Black	6

about:blank 5/26

7/24, 2:45	) FIVI		venicle Service Records (VSR) - Repair history D-201942	
PC	Туре	Code	Description (Original)	#
0	г.	VO-21948261	THRUST WASHER KIT	2
0	-	VO-21834205	Air Fliter - Outer	1
0	г.	VO-23294956	AIR FILTER - INNER	1
0	г.	VO-21503575	SEALING RING	1
0	г.	VO-20479636	SEALING STRIP	1
0	г.	VO-1547254	SEALING RING	2
<b>®</b>	г.	VO-20784537	GASKET TURBO BASE	1
0	г.	VO-20855371	GASKET EXH/MANIFOLD	6
0	г.	VO-21282255	GASKET	1
0	г.	VO-20573472	SPACER 10mm x 20mm x 16mm	4
0	г.	AU2-9718-240002743	BBC4 BRAKE CLEANER	4
0	г.	VO-22206133	TURBO FEED GASKET	1
0	г.	VO-420643	TURBO DRAIN GKT	1
0	г.	VO-469601	TURBO O-RING	1
0	г.	VO-21940615	SEALING RING	1
0	г.	VO-20526428	SEALING RING	1
0	г.	VO-22422785	BOOST TEMP SENSOR - FE FM/FH(4	1
0	г.	VO-21253763	PISTON RING KIT	1
0	г.	VO-990861	FLANGE BOLT M10 x 30mm Grey	5
0	г.	VO-994441	FLANGE BOLT M8 x 50mm	1
0	г.	VO-22422785	BOOST TEMP SENSOR - FE FM/FH(4	1
0	г.	UNK-STH625081KE	21253770 CYLINDER LINER KIT	1
0	г.	AU2-CAL85121795	ENGINE OIL BULK*	33
0	г.	VO-20852765	DOWTY WASHER O.D. 24mm	4
0	г.	VO-1075753	CLAMP	1
0		OTH- WUR0674850240/MTR	EMERY CLOTH G240	1
0	г.	VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
0	г.	AU2-PERM84101	PX EPOXY 5 MIN GENP	1
0	г.	AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	3
<b>®</b>	г.	VO-1677370	SEALING RING	1
0	Ø	LO-210	3 PISTONS AND LINERS JOE W	3.3
0	-	VO-995906	HEXAGON SCREW	4
<b>@</b>	Б.	VO-25339078	HEX NUT - M14 FINE (11MM)	4
0	*	20	Sublet tow truck	
0	Ø	VO-2130000	Cylinder liner and piston. Secondary ope	2.6
Ø	Ø	VO-2562400	Filter insert, air cleaner, replace. Onl	0.2
0	Ø	VO-2562500	Secondary air filter, replace. Air filte	0.2

about:blank 6/26

1124, 2.40	. IVI	_	verifice dervice records (vort) - repair filstory b-201342	_
PC	Туре	Code	Description (Original)	#
0	0	LO-255	TURBO COMPRESSOR	0.01
	Ð		Old Serial number:TW1804210375	
8	0	VO-2170800	Oil sump, install	0.6
<b>Ø</b>	0	VO-2170600	Oil sump, remove	0.3
0	0	VO-2144400	Rocker arms, replace (all)	0.8
0	*	213	Piston rings	
0	Ø	VO-4510000	Propeller shaft. Secondary operation num	0.2
	Œ		New Serial Number:TW1807172917	
0	*	19400	Breakdown Taree	
№ 2018-09-21 - Mileage: 787123 - Order nr: 8106984				
	1		AIRBAG MODULE, REPLACE. FH/FM (4)	
0	0	VO-8842000	Airbag module, replace	0.3
0	Ø	LO-7000	RIDE HEIGHT DRIVE	1.4
	3		AIR BAG PROBS.	
<b>Ø</b>	r.	VO-84433698	AIRBAG MODULE	1
	Œ		Checked the codes. Checked operation. Checked under the	
	<b>E</b>		trailer. Found no issues. Took the truck for a run and	
	æ		could not fault.	
0	*	91	WORKSHOP CONSUMABLES	
8	201	.8-05-04 - Mileage: 68	33975 - Order nr: 8101435	
0	*	352	LIGHTING - FRONT LIGHTS	
	Œ		Supply RH & LH Headlight panels	
	E			
0	5	VO-82884084	AIR DUCT	1
0	Ľ	VO-82884080	AIR DUCT	1
0	r.	VO-21874450	PANEL H/LAMP LH	1
0	ď	VO-21874457	PANEL H/LAMP RH	1
8	201	.8-03-26 - Mileage: 60	99058 - Order nr: 7579846	
0	*	20	Sublet tow	
	Ξ		tow combination from Armidale to Beresfield, drop trailers	
	1		tow truck to Sydney West	
8	201	.8-03-26 - Mileage: 60	99058 - Order nr: 2383445	
0	*	20	Sublet tow	
	Œ		tow combination from Armidale to Beresfield, drop trailers	
	Ξ		tow truck to Sydney West	
8	₩ 201	.8-03-07 - Mileage: 60	99058 - Order nr: 7579269	
0	*	20	Sublet tow	
0	*	20	sublet tow	

about:blank 7/26

1124, 2.4	-	-	verilide Service Records (VSR) - Repair History D-201942	_		
PC	Туре	Code	Description (Original)	#		
	E		tow combination from Armidale to Beresfield, drop trailers			
	3		tow truck to Sydney West			
	E		200427792			
9	201	.8-03-07 - Mileage: 60	09058 - Order nr: 2383426			
0	*	40	SUBLET ONEILLS			
	E		got po from jim			
	3		he will pursue goodwill on his end			
	Ξ					
	Ξ					
	3		tow combination from Armidale to Beresfield, drop trailers			
	3		tow truck to Sydney West			
9	201	.8-02-21 - Mileage: 60	09058 - Order nr: 7578500	•		
0	*	40	SUBLET ONEILLS			
	3		got po from jim			
	3		he will pursue goodwill on his end			
	3					
	Ξ					
	3		tow combination from Armidale to Beresfield, drop trailers			
	3		tow truck to Sydney West			
8	₩ 201	.8-02-08 - Mileage: 63	36679 - Order nr: 8092995	•		
0	Ø	VO-4132000	Clutch cylinder, replace. Gearbox remove	0.2		
0	Ø	LO-818	Check if rear cab airbags have covers	1.5		
0	Ø	LO-371	Carry out battery lug inspection	1		
0	5	VO-85013166	CYLINDER	1		
0	5	MK-9739-16488479	CAB AIR BAG ISULAT	2		
0	г.	VO-990073	CABLE TIE	2		
0	г.	VO-22485772	SEALING KIT	1		
0	г.	VO-995906	HEXAGON SCREW	4		
0	г.	VO-25339078	HEXAGON NUT	4		
<b>®</b>	г.	VO-20860677	SEALING RING	1		
	3		Clutch actuator not working properly.			
0	Ø	VO-4317000	Gearbox, remove	0.9		
0	Ø	VO-4317200	Gearbox, install	1.5		
8	₩ 201	.8-02-01 - Mileage: 60	)9058 - Order nr: 7240190			
0	г.	VO-22343361	CABLE HARNESS	1		
<b>®</b>	*	3712000	Cable harness, engine control unit,			
	Ξ		replace			
8	201	.8-01-31 - Mileage: 60	09058 - Order nr: 2881281	-		

about:blank 8/26

1	1	ı	I	
PC	Туре	Code	Description (Original)	#
0	ď	VO-22343361	CABLE HARNESS	1
0	*	370	Crediting engine harness	
	3		Refer invoice 7239212	
8	201	.8-01-17 - Mileage: 60	09058 - Order nr: 7239714	
	æ			
0	Ø	LO-100	CHECK AND QUOTE FOR ACCIDENTAL DAMAGE	24
	1		DONE BY TOW COMPANY (	
	æ			
0	ď	VO-84210166	UNDERRUN GUARD	1
0	Ľ	VO-22542233	PIPE	1
0	ď	VO-21519078	BRACKET	1
0	ď	VO-22282775	HOSE	1
0	ď	VO-22282785	HOSE	1
0	r.	VO-1626139	RUBBER SPACER	1
0	ď	VO-21919316	PIPE	1
	<b>E</b>		VO/21919316 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	Ľ	VO-21312237	CHARGE AIR HOSE	1
	3		VO/21312237 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8086589 - DATE 2017-05-09 MILEAGE - 445432	
0	Ľ	VO-8131393	CAGE	15
0	5	MK-NARV56310	CABLE TIE 1=10PK	2
0	r.	MK-NARV56306	CABLE TIE 1=25PK	2
0	r.	VO-21177272	SOCKET	2
	3		VO/21177272 WAS FITTED BY BRANCH 4000	
	Ð		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	r.	VO-85122800	TRANSMISSION OIL	4
0	r.	VO-22325247	ARM	2
0	ď	VO-1626139	RUBBER SPACER	1
0	ď	VO-25097329	BOLT	4
0	r.	VO-25089744	NUT	4
	<b>3</b>		POWER STEERING PIPES RUNNING UNDER RADIATOR	
	Œ		LOWER BOOST PIPE	
	<b>3</b>		LOWER FRONT BUMPER APRON	
	Œ		INSPECT FOR OTHER DAMAGES	
	3		Removed front grille, headlight surrounds panels, brackets &	
	Œ		headlights, remove wiring, sensors & ECU's, remove steps &	
	Ð		cab hydraulics, washer bottle & fups bar, remove both front	

about:blank 9/26

I /	ſ	1	, , , , , , , , , , , , , , , , , , ,	Ī
PC	Туре	Code	Description (Original)	#
	Ξ		wheels & remove both sides link rods, remove front sway bar	
	Ξ		for access, remove front U-bolts (had to heat them to	
	E		remove), reassemble with new parts as listed below,	
	Ξ		tensioned U-bolts & wheels, removed fan belt & tensioner,	
	Ξ		remove boost pipe bracket & R&R boost pipe found power	
	E		steering hoses damaged, drain power steering oil & replace	
	E		power steering hoses reassemble removed parts & refilled	
	<b>3</b>		power steering oil, jack up steer axle & bleed power	
	3		steering, wash down & checked for power steering & boost	
	Ξ		system leaks after road test all ok.	
	3		VO/22282775 WAS FITTED BY BRANCH 2000	
	Ξ		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/22282785 WAS FITTED BY BRANCH 2000	
	E		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/84210166 WAS FITTED BY BRANCH 2000	
	3		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/22542233 WAS FITTED BY BRANCH 2000	
	E		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/21519078 WAS FITTED BY BRANCH 2000	
	E		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/1626139 WAS FITTED BY BRANCH 2000	
	E		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	E		VO/22325247 WAS FITTED BY BRANCH 2000	
	<b>3</b>		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/1626139 WAS FITTED BY BRANCH 2000	
	Ξ		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
0	*	91	WORKSHOP CONSUMABLES	
8	201	18-01-16 - Mileage: 60	09058 - Order nr: 2881272	
	3			
0	Ø	LO-100	CHECK AND QUOTE FOR ACCIDENTAL DAMAGE	24
	B		DONE BY TOW COMPANY	
	Ξ			
<b>®</b>	г.	VO-84210166	UNDERRUN GUARD	1
0	г.	VO-22542233	PIPE	1
0	г.	VO-21519078	BRACKET	1
0	г.	VO-22282775	HOSE	1
0	г.	VO-22282785	HOSE	1
0	г.	VO-1626139	RUBBER SPACER	1
		a.		

about:blank 10/26

7/24, 2:45	D PIVI		venicie Service Records (VSR) - Repair history D-201942	
PC	Туре	Code	Description (Original)	#
0	η,	VO-21919316	PIPE	1
	3		VO/21919316 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	2	VO-21312237	CHARGE AIR HOSE	1
	3		VO/21312237 WAS FITTED BY BRANCH 4000	
	Ξ		ON REPAIR ORDER 8086589 - DATE 2017-05-09 MILEAGE - 445432	
0		VO-8131393	CAGE	15
0	5	MK-NARV56310	CABLE TIE 1=10PK	2
0	г.	MK-NARV56306	CABLE TIE 1=25PK	2
0	г,	VO-21177272	SOCKET	2
	3		VO/21177272 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	г.	VO-85122800	TRANSMISSION OIL	4
0	г.	VO-22325247	ARM	2
0	г.	VO-1626139	RUBBER SPACER	1
0	г.	VO-25097329	BOLT	4
0	η,	VO-25089744	NUT	4
	3		POWER STEERING PIPES RUNNING UNDER RADIATOR	
	3		LOWER BOOST PIPE	
	3		LOWER FRONT BUMPER APRON	
	3		INSPECT FOR OTHER DAMAGES	
	3		Removed front grille, headlight surrounds panels, brackets &	
	3		headlights, remove wiring, sensors & ECU's, remove steps &	
	3		cab hydraulics, washer bottle & fups bar, remove both front	
	Ξ		wheels & remove both sides link rods, remove front sway bar	
	3		for access, remove front U-bolts (had to heat them to	
	3		remove), reassemble with new parts as listed below,	
	<b>3</b>		tensioned U-bolts & wheels, removed fan belt & tensioner,	
	Ξ		remove boost pipe bracket & R&R boost pipe found power	
	<b>3</b>		steering hoses damaged, drain power steering oil & replace	
	Ξ		power steering hoses reassemble removed parts & refilled	
	3		power steering oil, jack up steer axle & bleed power	
	3		steering, wash down & checked for power steering & boost	
	3		system leaks after road test all ok.	
	3		VO/22282775 WAS FITTED BY BRANCH 2000	
	Ξ		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	<b>3</b>		VO/22282785 WAS FITTED BY BRANCH 2000	
	3		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	-	•	*	-

about:blank 11/26

	-	_	venicle dervice records (vort) - repair filstory D-201942	_
PC	Туре	Code	Description (Original)	#
	E		VO/84210166 WAS FITTED BY BRANCH 2000	
	3		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/22542233 WAS FITTED BY BRANCH 2000	
	E		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	3		VO/21519078 WAS FITTED BY BRANCH 2000	
	B		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	B		VO/1626139 WAS FITTED BY BRANCH 2000	
	B		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	Ξ		VO/22325247 WAS FITTED BY BRANCH 2000	
	E		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
	E		VO/1626139 WAS FITTED BY BRANCH 2000	
	Ξ		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058	
0	*	91	WORKSHOP CONSUMABLES	
9	201	18-01-11 - Mileage: 60	09058 - Order nr: 7239531	•
	B			
0	Ø	LO-100	CHECK AND QUOTE FOR ACCIDENTAL DAMAGE	24
	E			
	B			
0	5	VO-84210166	UNDERRUN GUARD	1
0	5	VO-22542233	PIPE	1
0	5	VO-21519078	BRACKET	1
0	5	VO-22282775	HOSE	1
0		VO-22282785	HOSE	1
0	г.	VO-1626139	RUBBER SPACER	1
0	6	VO-21919316	PIPE	1
	3		VO/21919316 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	5	VO-21312237	CHARGE AIR HOSE	1
	3		VO/21312237 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8086589 - DATE 2017-05-09 MILEAGE - 445432	
0	5	VO-8131393	CAGE	15
0	5	MK-NARV56310	CABLE TIE 1=10PK	2
0	5	MK-NARV56306	CABLE TIE 1=25PK	2
0	5	VO-21177272	SOCKET	2
	Ξ		VO/21177272 WAS FITTED BY BRANCH 4000	
	<b>E</b>		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	5	VO-85122800	TRANSMISSION OIL	4
0	5	VO-22325247	ARM	2

about:blank 12/26

PC	Туре	Code	Description (Original)	#			
0	г.	VO-1626139	RUBBER SPACER	1			
0	г,	VO-25097329	BOLT	4			
0	г,	VO-25089744	NUT	4			
	E		POWER STEERING PIPES RUNNING UNDER RADIATOR				
	3		LOWER BOOST PIPE				
	3		LOWER FRONT BUMPER APRON				
	3		INSPECT FOR OTHER DAMAGES				
	3		Removed front grille, headlight surrounds panels, brackets &				
	3		headlights, remove wiring, sensors & ECU's, remove steps &				
	3		cab hydraulics, washer bottle & fups bar, remove both front				
	3		wheels & remove both sides link rods, remove front sway bar				
	B		for access, remove front U-bolts (had to heat them to				
	3		remove), reassemble with new parts as listed below,				
	3		tensioned U-bolts & wheels, removed fan belt & tensioner,				
	3		remove boost pipe bracket & R&R boost pipe found power				
	B		steering hoses damaged, drain power steering oil & replace				
	Ð		power steering hoses reassemble removed parts & refilled				
	3		power steering oil, jack up steer axle & bleed power				
	Ξ		steering, wash down & checked for power steering & boost				
	3		system leaks after road test all ok.				
	E		VO/22282775 WAS FITTED BY BRANCH 2000				
	Ξ		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
	Ξ		VO/22282785 WAS FITTED BY BRANCH 2000				
	Ξ		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
	Œ		VO/84210166 WAS FITTED BY BRANCH 2000				
	3		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
	E		VO/22542233 WAS FITTED BY BRANCH 2000				
	3		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
	Ξ		VO/21519078 WAS FITTED BY BRANCH 2000				
	Ξ		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
	Ξ		VO/1626139 WAS FITTED BY BRANCH 2000				
	<b>3</b>		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
	3		VO/22325247 WAS FITTED BY BRANCH 2000				
	B		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
	B		VO/1626139 WAS FITTED BY BRANCH 2000				
	B		ON REPAIR ORDER 7239213 - DATE 2018-01-11 MILEAGE - 609058				
0	*	91	WORKSHOP CONSUMABLES				
٩	2018-01-11 - Mileage: 609058 - Order nr: 2881270						

about:blank 13/26

PC	Туре	Code	Description (Original)	#
PC		Code	Description (Original)	#
_	3			
0	Ø	LO-100	CHECK AND QUOTE FOR ACCIDENTAL DAMAGE	24
	3			
	Ξ			
0	5	VO-84210166	UNDERRUN GUARD	1
0	г.	VO-22542233	PIPE	1
0	5	VO-21519078	BRACKET	1
0	r,	VO-22282775	HOSE	1
0	г.	VO-22282785	HOSE	1
0	5	VO-1626139	RUBBER SPACER	1
0	5	VO-21919316	PIPE	1
	3		VO/21919316 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	5	VO-21312237	CHARGE AIR HOSE	1
	3		VO/21312237 WAS FITTED BY BRANCH 4000	
	B		ON REPAIR ORDER 8086589 - DATE 2017-05-09 MILEAGE - 445432	
0	г.	VO-8131393	CAGE	15
0	5	MK-NARV56310	CABLE TIE 1=10PK	2
0	6	MK-NARV56306	CABLE TIE 1=10PK	2
0	5	VO-21177272	SOCKET	2
	E		VO/21177272 WAS FITTED BY BRANCH 4000	
	3		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	г.	VO-85122800	TRANSMISSION OIL	4
0	5	VO-22325247	ARM	2
0	6	VO-1626139	RUBBER SPACER	1
0	г.	VO-25097329	BOLT	4
0	5	VO-25089744	NUT	4
	3		POWER STEERING PIPES RUNNING UNDER RADIATOR	
	3		LOWER BOOST PIPE	
	3		LOWER FRONT BUMPER APRON	
	3		INSPECT FOR OTHER DAMAGES	
	3		Removed front grille, headlight surrounds panels, brackets &	
	3		headlights, remove wiring, sensors & ECU's, remove steps &	
	3		cab hydraulics, washer bottle & fups bar, remove both front	
	3		wheels & remove both sides link rods, remove front sway bar	
	<b>3</b>		for access, remove front U-bolts (had to heat them to	
	3		remove), reassemble with new parts as listed below,	
	Ξ		tensioned U-bolts & wheels, removed fan belt & tensioner,	
		4	1	-

about:blank 14/26

7/24, 2:45	. LINI		venicie Service Records (VSR) - Repair history D-201942	
PC	Туре	Code	Description (Original)	#
	Œ		remove boost pipe bracket & R&R boost pipe found power	
	3		steering hoses damaged, drain power steering oil & replace	
	Ð		power steering hoses reassemble removed parts & refilled	
	Ш		power steering oil, jack up steer axle & bleed power	
	E		steering, wash down & checked for power steering & boost	
	E		system leaks after road test all ok.	
0	*	91	WORKSHOP CONSUMABLES	
9	201	.8-01-02 - Mileage: 60	09058 - Order nr: 7239213	<del>-</del>
	Ш			
0	Ø	LO-100	CHECK AND QUOTE FOR ACCIDENTAL DAMAGE	24
	E			
	E			
0	r	VO-84210166	UNDERRUN GUARD	1
0	r.	VO-22542233	PIPE	1
0	r	VO-21519078	BRACKET	1
0	ď	VO-22282775	HOSE	1
0	ď	VO-22282785	HOSE	1
0	ď	VO-1626139	RUBBER SPACER	1
0	Ľ	VO-21919316	PIPE	1
	E4		VO/21919316 WAS FITTED BY BRANCH 4000	
	Œ		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	Ľ	VO-21312237	CHARGE AIR HOSE	1
	3		VO/21312237 WAS FITTED BY BRANCH 4000	
	Œ		ON REPAIR ORDER 8086589 - DATE 2017-05-09 MILEAGE - 445432	
0	r.	VO-8131393	CAGE	15
0	r.	MK-NARV56310	CABLE TIE 1=10PK	2
0	r.	MK-NARV56306	CABLE TIE 1=10PK	2
0	5	VO-21177272	SOCKET	2
	Ξ		VO/21177272 WAS FITTED BY BRANCH 4000	
	Ð		ON REPAIR ORDER 8088979 - DATE 2017-08-02 MILEAGE - 505039	
0	5	VO-85122800	TRANSMISSION OIL	4
0	r.	VO-22325247	ARM	2
0	Γ.	VO-1626139	RUBBER SPACER	1
0	г.	VO-25097329	BOLT	4
0	г.	VO-25089744	NUT	4
	Ξ		POWER STEERING PIPES RUNNING UNDER RADIATOR	
	3		LOWER BOOST PIPE	
	3		LOWER FRONT BUMPER APRON	
1				

about:blank 15/26

1/24, 2.40	-	_	verifice Service Necords (VSN) - Nepair History B-201942	_		
PC	Туре	Code	Description (Original)	#		
	E		INSPECT FOR OTHER DAMAGES			
	Ξ		Removed front grille, headlight surrounds panels, brackets &			
	3		headlights, remove wiring, sensors & ECU's, remove steps &			
	3		cab hydraulics, washer bottle & fups bar, remove both front			
	3		wheels & remove both sides link rods, remove front sway bar			
	3		for access, remove front U-bolts (had to heat them to			
	3		remove), reassemble with new parts as listed below,			
	3		tensioned U-bolts & wheels, removed fan belt & tensioner,			
	E		remove boost pipe bracket & R&R boost pipe found power			
	Ξ		steering hoses damaged, drain power steering oil & replace			
	E		power steering hoses reassemble removed parts & refilled			
	Ξ		power steering oil, jack up steer axle & bleed power			
	Ξ		steering, wash down & checked for power steering & boost			
	Ξ		system leaks after road test all ok.			
0	*	91	WORKSHOP CONSUMABLES			
8	☑ 2017-12-29 - Mileage: 609058 - Order nr: 7239212					
8	Ø	VO-2112600	Cylinder head, replace	8.4		
8	г.	VO-85013933	CYLINDER HEAD, EXC	1		
0	г,	VO-21768034	GASKET KIT	1		
<b>®</b>	F.	VO-990810	FLANGE SCREW	6		
0	г.	VO-994447	FLANGE SCREW	6		
0	5	VO-8192804	SCREW	8		
8	5	VO-85020372	TURBOCHARGER, EXCH	1		
0	5	VO-21253770	CYLINDER LINER KIT	1		
0	г.	VO-22343361	CABLE HARNESS	1		
0	5	VO-20541940	SEALING STRIP	1		
8	r	VO-990861	FLANGE SCREW	24		
8	F.	VO-20486228	SCREW	4		
0	г.	MK-9718-BBC4	CLEANER 400G BRAKE	2		
0	г.	MK-342SX33	SILICOM DOW	2		
0	5	VO-983472	CABLE TIE	12		
0	г.	VO-22718180	KIT	1		
0	F.	OTH-BUFF200	BUFF	2		
0	г.	VO-8131393	CAGE	6		
0	г.	MK-NARV56306	CABLE TIE 1=10PK	1		
8	г.	VO-21344774	FLANGE SCREW	6		
	Ð		S/N P21995290			
0	г.	VO-20541940	SEALING STRIP	1		
1 -						

about:blank 16/26

1124, 2.4	O I IVI		vehicle dervice records (vort) - repair filstory b-201942	
PC	Туре	Code	Description (Original)	#
0	Ø	LO-370	ENGINE WIRING HARNESS PERISHED	4
0	6	VO-FK18B	FILTER KIT	1
0	г.	AU2-CAL85121795	VDS4 BULK ENGINE O	6
0	5	AU2-CAL85121795	VDS4 BULK ENGINE O	30
0	6	VO-85013271	UNIT INJECTOR, EXC	1
0	г.	VO-22241727	PIPE	1
0	5	VO-21488099	CONNECTOR	1
0	г.	VO-3979639	GASKET	1
0	5	MK-NARV56306	CABLE TIE 1=10PK	1
0	5	VO-994441	FLANGE SCREW	1
0	5	VO-990950	FLANGE LOCK NUT	1
0		AU2-CAL8394800	VOLVO VCS 20L COOLANT	2
8	5	VO-21834205	FILTER	1
8	5	VO-21115501	FILTER	1
0	г.	VO-995906	HEXAGON SCREW	4
8	5	VO-25339078	HEXAGON NUT	4
•	г.	AU2-CAL85121795	VDS4 BULK ENGINE O	2
0	r,	MK-9718-BBC4	CLEANER 400G BRAKE	1
•	Ø	VO-2140500	Valves, remove and install (one cylinder	0.01
	3		cylinder). Cylinder head removed	
0	Ø	VO-2117700	Cylinder head, transfer parts	0.5
0	Ø	VO-2100600	Cylinder Compression, test	0.2
0	Ø	VO-2135700	Piston and liner, replace (one). Cylinde	1.9
	E		Cylinder head and sump removed	
0	Ø	VO-2170100	Oil sump, replace	1
0	Ø	VO-2562400	Filter insert, air cleaner, replace. Onl	0.2
0	Ø	VO-2562500	Secondary air filter, replace. Air filte	0.2
	3		Remove and repalce engine harness - insulation worn and	
	Ξ		cracking	
0	Ø	LO-873	Coolant loss	0.5
	Ξ		Remove and replace split heater hose.	
	Ξ		S/L F26055	
0	*	91	WORKSHOP CONSUMABLES	
8	201	17-12-01 - Mileage: 58	39073 - Order nr: 8095186	1
	3		Repair without detail info	
8	₩ 201	17-09-29 - Mileage: 54	19060 - Order nr: 7574459	
0	Ø	VO-2551800	Engine turbocharger, replace. Chassis mo	1.6
0	г.	VO-85020372	TURBOCHARGER, EXCH	1
•				Į.

about:blank 17/26

1124, 2.4	J I IVI		verifice dervice Records (VSR) - Repair filstory D-201942	
PC	Туре	Code	Description (Original)	#
<b>®</b>	г,	VO-21634017	PRESSURE SENSOR, CRANKCASE	1
0	5	VO-993811	REPLC BY 984756	4
0	г.	VO-20573472	SPACER SLEEVE	4
0	г,	VO-1543499	FLANGE NUT	4
0	г,	VO-20784537	GASKET - TURBO BASE	1
<b>®</b>	г,	VO-22206133	GASKET	1
0	г,	VO-420643	GASKET - OIL RETURN TURBO	1
0	г,	VO-469601	SEALING RING TURBO OIL DRAIN	4
0	г,	VO-20526428	SEALING RING-VEB	1
0	5	VO-21940615	SEALING RING	1
0	г.	VO-21211715	V-CLAMP	1
0	5	VO-994441	BOLT M8*50 FLANGE	1
8	r.	VO-990950	NUT M8 FLANGED LOCKING	1
0	г.	VO-21312238	CHARGE AIR HOSE	1
0		VO-20592787	CLAMP	2
	3		New Serial Number:	
	B		Old Serial number:	
	1		LOW ON POWER	
	3		HIGH CRANKCASE PRESSURE FAULT	
	B		TURBO REPLACED YESTERDAY	
0	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
0	Ø	VO-1701200	Fault codes, reading	0.2
0	*	255	TURBO COMPRESSOR	
	3		Old Serial number: F24006	
	Ξ		New Serial Number: F27087	
9	₩ 201	.7-09-22 - Mileage: 51	8000 - Order nr: 8089636	
0	*	352	LIGHTING - FRONT LIGHTS	
0	г.	VO-21874457	PANEL H/LAMP RH	1
•	η,	VO-21874450	PANEL H/LAMP LH	1
0	г.	VO-82884080	AIR DUCT	1
0	г.	VO-82884084	AIR DUCT	1
	<b>3</b>		SUPPLY LH & RH HEADLIGHT PANELS- GOODWILL REFER	
	<b>3</b>			
2	₩ 201	.7-08-07 - Mileage: 51	.7505 - Order nr: 8090386	1
0	Ø	VO-2580700	Pump unit, replace	0.8
0	η.	VO-22851845	PUMP UNIT- ADBLUE	1
0	г.	VO-980464	CABLE TIE 350MM	20
0	Ε.	VO-948211	STRIP CLAMP	20
-				

about:blank 18/26

1124, 2.40	J 1 IVI		vehicle dervice records (Vort) - repair filstory D-201942	
PC	Туре	Code	Description (Original)	#
0	г,	VO-3944785	AIR FILTER - COMP/ ADBLUE	1
8	5	VO-22679934	T-PIPE	1
8	г.	VO-22681764	MANIFOLD - ADBLUE	1
0	5	VO-20915849	HOSE CLAMP 16-27mm	2
8	г.	VO-21032572	CLAMP	2
<b>®</b>	г.	VO-21429181	HOSE	3
8	5	VO-4803748	HOSE - CORRUGATED	3
0	5	VO-3092340	SILASTIC GREY	1
0	5	VO-22406383	KIT - ADBLUE GAUZE FILTER	1
0	г.	VO-990413	HEX SOCKET BOLT M6 x 40mm	3
0	5	AU2-PERM84101	PX POXY 5 MIN GENP	1
8	*	2580700	Pump unit, replace.	
	3		Ad-blu fault possible ad-blu pump.	
0	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
0	Ø	VO-2584600	SCR system, test	0.5
0	*	2580700	Pump unit, replace	
•	Ø	VO-2580300	AdBlue tank, replace	1.3
0	Ø	VO-2582800	Combined tank unit, replace. AdBlue tank	0.2
	3		removed	
0	Ø	LO-258	AD-BLU Breather Modification	1.5
0	Ø	VO-2585800	AdBlue tank, clean. Urea tank removed	0.5
<b>Ø</b>	Ø	VO-2580000	Emissions after-treatment. Secondary ope	0.2
0	*	91	AdBlu 80 ltrs	
8	201	.7-08-01 - Mileage: 12	234 - Order nr: 8091215	
0	Ø	LO-820	REINFORCE HEADLIGHT PANELSAND PAINT	7.77
	3		BONDING MATERIALS TO INNER FRAME WITH STIFFENERS TO SUIT	
	3		Å400.00	
	3		PAINT TWO HEADLIGHT PANELS BLACK Å300.00	
8	₩ 201	.7-07-04 - Mileage: 50	05039 - Order nr: 8088979	
0	*	М	PLEASE FILL IN	
	B			
<b>®</b>	Ø	VO-6452600	Hydraulic hose power steering, replace	1
0	Ø	LO-260	LEAKING COOLANT LINE	0.6
0	Ø	LO-261	RADIATOR AND INTERCOOLER HOSES RUBBING	5
	3		CAB, INTERIOR LIGHTS, CABLE HARNESS, INSTALL. FH (4)	
0	Ø	VO-3540800	Interior lights, cable harness, install.	0.5
0	г.	VO-22935545	WIRES	8
	E		EMS AND ACM, SW UPDATE. EU4/5. FH/FM (4)	
•				

about:blank 19/26

7/24, 2:45	) F IVI	_	venicle Service Records (VSR) - Repair history D-201942	_
PC	Туре	Code	Description (Original)	#
0	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
<b>®</b>	Ø	VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
	3		ACM, SW UPDATE. FH/FM (4)	
0	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
0	Ø	VO-2549400	ACM, SW, update. only campaign	0.2
	B		Next Service:	
	3		Mileage:505039	
	<b>3</b>		Hrs:6426	
	3		Name:Jim	
	3		PLEASE TALK TO RODNEY ABOUT THIS TRUCK.	
0	г,	VO-21484087	SERVO PIPE	1
0	г,	VO-21349444	SOCKET	1
<b>Ø</b>	г.	VO-85122800	ATF DEX3 1LTR	3
8	5	MK-5166-56747	LOCTITE, 567 PIPE	1
0	г.	VO-21950340	PIPE - HEATER FM/FH(4)	1
<b>®</b>	г,	VO-21919316	PIPE	1
0	г.	VO-471708	SEALING RING	1
0	г.	VO-992065	O-RING	1
0	г.	VO-85013941	COMPRESSOR, EXCH	1
0	г.	VO-8131848	GEAR	1
0	г.	MK-5166-56747	LOCTITE, 567 PIPE	1
0	г,	AU2-WUR0674850240	EMERY CLOTH 240 GRIT	1
0	6	MK-9718-BBC4	CLEANER 400G BRAKE	1
0	г.	VO-22060521	FAN SHROUD - FH(4)	1
0	6	VO-21177272	SOCKET	3
0	г,	AU2-WUR0674850120	EMERY CLTH-ROLL-120	0.5
0	г.	AU2-WUR0674850240	EMERY CLOTH 240 GRIT	0.5
0	г.	VO-980881	CABLE TIE	4
0	г,	VO-20840154	HOSE CLAMP 60-80mm	1
0	F.	VO-20938686	CONNECTOR	1
0	г.	AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	1
8	Ø	VO-5611100	Compressor, replace	1.7
	Ξ		Leaking power steering pump, & power lines.	
8	Ø	VO-1820200	Localised wash for fault tracing	0.3
8	Ø	VO-5610000	Compressor, regulator, anti-freeze unit.	1.2
8	<b>W</b> 201	7-05-05 - Mileage: 4	45432 - Order nr: 8086589	
0	*	2650000	Charge air cooler hose chaffed	
0	г.	VO-22560373	HOSE BOTTOM RAD - FM/FH(4)	1

about:blank 20/26

1124, 2.4	. IVI	_	- verilide Service Records (VSR) - Repair History D-201942	_
PC	Туре	Code	Description (Original)	#
0	г,	VO-21312237	CHARGE AIR HOSE - BOTTOM FH (4	1
8	₩ 201	17-04-10 - Mileage: 44	12970 - Order nr: S200518	-
0	3	VO-85020789	STARTER MOTOR, EXC	1
0	Ø	VO-3310600	Starter motor, replace	0.4
0	<b>3</b>		TRUCK NOT STARTING, BROKEN DOWN	
0	Ø	VO-1940100	Action service fee. national BREAK DOWN FUND	2.6
0	E		TRUCK BROKEN DOWN BETWEEN DUBBO AND GILGANDRA	
9	₩ 201	.6-08-26 - Mileage: 27	74905 - Order nr: R08001184	
0	3	AU2-CAL8394800	VOLVO VCS COOLANT	2
0		VO-20915849	HOSE CLAMP	2
0	г.	VO-21313188	CONNECTOR	2
0	Ø	VO-4910000	REPLACE HOSE AND FITTINGS	2
0		AU2-CAL85108913	VOLVO VCS COOLANT	1
0	E		AFTER HOURS CALL OUT COOLANT LEAK	
0	Ø	1940000	travel labour	1.16
0	E		TRAVEL TO AND FROM BREAKDOWN AT HUME HIGHWAY BARNAWARTHA	
9	₩ 201	16-07-21 - Mileage: 24	19806 - Order nr: 8075708	-
	Ξ		C3538 Cab tilt pump, filler plug, replace. FH (4)	
•	Ø	LO-8600100	C3538 campaign due	0.5
	3		S3485 Instrument cluster, SW update. FH/FM (4)	
0	Ø	VO-3815800	IC, SW update. Campaign only	0.3
	B		S3594 HMIIOM, parameter (ESP telltale), change. FH/FM (4)	
0	Ø	VO-5604400	Pressure pipe, replace. Only campaign	0.1
0	Ø	VO-1774600	Annual service. Chassis lubrication and	2.4
0	Ø	VO-1706400	12 Months ECU download and oil sample. O	0.9
<b>Ø</b>	Ø	VO-8100300	12 Months cab inspection	0.4
Ø	Ø	VO-2510400	Gaskets, exhaust manifold, replace	1.8
0	*	1753100	Brake fault codes.	
<b>Ø</b>	г.	VO-22861085	REPAIR KIT	1
0	5	VO-8394887	OIL TEST KIT	4
0	r.	VO-82354791	VENTILATION FILTER, V4	1
0	г.	VO-82348995	VENTILATION FILTER	1
0	Γ.	VO-22223804	KIT	1
Ø	г.	VO-22074730	FLANGE SCREW	1
0	г.	VO-20855371	GASKET EXH/MANIFOLD	6
<b>Ø</b>	г.	VO-20883450	SEALING RING	2
0	г.	VO-20784537	GASKET TURBO BASE	1
0	r.	VO-420641	TURBO FEED GKT	1
_				

about:blank 21/26

1124, 2.40	) I IVI		verticle dervice Records (VOR) - Repair history D-201942	
PC	Туре	Code	Description (Original)	#
0		VO-420643	TURBO DRAIN GKT	1
0	Ε.	VO-21940615	SEALING RING	1
0		VO-22718180	KIT ,, HI -TEMP TURBO MTG	1
0		VO-469601	TURBO O-RING	1
0		MK-9718-BBC4	CLEANER 400G BRAKE	1
0		AU2-WURNBB0000853	NYLON POWER LOC 2I	4
0		VO-22321908	EXHAUST PIPE	1
0		VO-1629499	EXH CLAMP FH	2
0		VO-990941	FLANGE NUT M10	2
0	r	VO-994195	FLANGE SCREW	2
0	*	20	Engine Engineering	
8	0	VO-1701000	Connect-disconnect of diagnostic tool	0.2
8	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
0	Ø	VO-2511600	Gasket kit, exhaust manifold, replace. E	0.3
0	Ø	VO-8720800	Air conditioning air filter, replace	0.1
0	0	VO-8721400	Air filter air conditioning, replace (in	0.1
0	Ø	VO-5612600	Air drier, drier insert, replace	0.4
0	Ø	VO-2522800	Flexible exhaust pipe, replace	0.2
0	*	91	WORKSHOP CONSUMABLES	
Δ.	₩ 201	.6-06-28 - Mileage: 23	32502 - Order nr: T54746	
0	Ø	VO-1703000	Parameter, programming	0.2
<b>Ø</b>	Ξ		BREAKDOWN , TRAILER LIGHTS NOT WORKING	
8	0	VO-3720000	INSPECT CIRCUIT BREAKER BOX FOR FAULTS , SECURE TERMINALS & TEST	0.8
0	Ø	VO-1701200	Fault codes, reading	0.2
0	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
0	Ø	1940000	TRAVEL FROM QTC TOOWOOMBA TO MILLMERRAN - RETURN	2.1
<b>Ø</b>	3		BREAKDOWN , MILLMERRAN , TRAILER LIGHTS NOT WORKING	
9 🕒	201	.6-02-01 - Mileage: 6	- Order nr: 201942	
Θ	Ø	96000		0
9 6	201	.6-01-01 - Mileage: 5	- Order nr: 201942	
G	Ø	96000		0
9	₩ 201	.5-12-11 - Mileage: 87	7226 - Order nr: 8067581	
0	Ø	LO-510	TYRES SCRUBBING - ROTATED AT 68,000	1.6
0	Ø	VO-5936100	Sensor yaw rate, calibration	0.2
0	ď	OTH-FAB26S	RIVET 3/16X7/16	3
0	Ø	VO-1701000	Connect-disconnect of diagnostic tool	0.2
<b>Ø</b>	Ø	VO-1701200	Fault codes, reading	0.2
i				

about:blank 22/26

/24, 2.40	-	_	verificie dervice records (vort) - repair filstory D-201942	_
PC	Туре	Code	Description (Original)	#
	2		Deliver and pick up vehicle from Fortuna, results came back	
	E		satisfactoty, no adjustment required	
0	Ø	VO-5930000	Anti-lock brake (anti-skid). Secondary o	2
0	Ø	VO-5930000	Anti-lock brake (anti-skid). Secondary o	2
8	*	WTY-NONGEN	WTY-Non Genuine Parts-SUBLET	
8	Ø	VO-1702600	Program control unit	0.1
9	201	5-12-01 - Mileage: 4	- Order nr: 201942	
•	Ø	96000		0
9 6	201	.5-11-01 - Mileage: 3	- Order nr: 201942	-
Θ	Ø	96000		0
9 6	201	.5-10-01 - Mileage: 2	- Order nr: 201942	<u>-</u>
Θ	Ø	96000		0
<b>Q</b> []	201	.5-09-01 - Mileage: 1	- Order nr: 201942	
Θ	0	96000		0
8	201	.5-08-25 - Mileage: 12	2771 - Order nr: 8063376	
0	Ø	LO-885	REFRIGERATOR	0.5
	E		Remove and install fridge in stock truck,	
	Ш		Replacement fridge has been ordered on 8063328,	
	Œ		should arrive 26.8.15	
8	₩ 201	.5-08-24 - Mileage: 12	2771 - Order nr: 8063328	
8	0	VO-1721000	Warranty service. After 4 weeks or maxim	2
8	Ø	VO-8410000	Outside trim parts, emblem, reflector	0.4
0	Ø	VO-3661500	Load indicator, calibration	3.63
0	Ø	VO-8850300	Refrigerator, replace	0.2
8	r.	VO-9130476	SPLICE BLUE, HEAT SHRINK	2
8	Γ.	VO-82174077	REFRIGERATOR	1
0	Ø	VO-3710200	Electric wires and connections, check	0.4
0	Ø	VO-3711700	Connector, replace (1-8 cables)	0.3
8	201	.5-08-03 - Mileage: 75	5 - Order nr: 8062508	
0	*	10	FUEL TANK POLISH	
8	201	.5-08-03 - Mileage: 10	00 - Order nr: 8062640	
0	Ø	LO-170	REGISTRATION	2.5
93	201	.5-07-23 - Mileage: 43	321 - Order nr: 8062260	
0	Ø	LO-820	PAINT T/TABLE BLACK	1
	Ð		- GENERAL	
0	*	MTPAINT	PANELSHOP PAINT	
0	*	91	PANELSHOP CONSUMABLES	

about:blank 23/26

1124, 2.4	•	-	verilicie del vice (voit) - (voit) - (voit)			
PC	Туре	Code	Description (Original)	#		
	3		REFER N/T FIT UPS			
	3		ORDER NO;4013836			
9	₩ 201	15-07-20 - Mileage: 17	78 - Order nr: 8062082	•		
0	*	М	PLEASE FILL IN			
	E		Mileage:			
	3		Hrs:			
	E		Name:			
	E		Phone:			
0	Ø	LO-856	BUNK BED MOUNTING BRACKET	1		
	E		FST 85 201			
0	г.	VO-82378986	HINGE FITTING	1		
0	г.	VO-82328298	HINGE FITTING	1		
8	<b>S</b> 2015-07-03 - Mileage: 68 - Order nr: 8059440					
0	0	LO-171	PRE DELIVERY WITH PLATES	6.5		
0	*	MTELEC186	RIVETS			
0	*	10	VEHICLE DETAIL			
0	*	10	TARE WEIGHT			
0	Ø	LO-810	FIT AEROFOIL	3		
0	*	10	CUSTOM BADGE			
0	Ø	LO-350	3 X LED LIGHTS TO EACH MIRROR600	3.8		
0	Ø	LO-350	3 X LED LIGHTS TO EACH SIDE OF CAB600	3.8		
0	Ø	LO-852	DRIVERS SHEEP SKIN SEAT COVER250	0.6		
	3		NOLANS LOGO			
0	*	860	NOLANS PARTS KIT			
	3		BELTS, RADIATOR HOSES, FILTERS N O AIR			
0	Ø	LO-843	LEFT & RIGHT WEATHERSHIELDS363	1.6		
0	Ø	LO-360	CALIBRATE LOAD SCALES SOFTWARE	1		
	E		IN TRUCK FROM FACTORY			
0	Ø	LO-350	RELOCATE EXISTING REASR OF CAB WORK300	3		
	3		LIGHTS TO THE AERO KIT SIDE WINGS			
0	Ø	LO-610	IMEX FULL STAINLESS STEEL DRESS RING492	1.35		
	Ξ		TO STEER AXLE			
0	Ø	LO-360	PROGRAM 4 MINUTE IDLE SHUT DOWN	1		
0	Ø	LO-360	ENSURE 12 & 24 VOLT PLUTS ARE LED OK	1		
0	Ø	LO-712	S&F JOST JSK37 CZ GREASE TOP 185 2750.75	3		
	B		DRILL Ö CENTRE + 50 + 100			
0	Ø	LO-826	CHANGE REAR GUARDS TO SMOOTH 1500	5		
	2		STAINLESS STEEL WITH ALLOY MOUNT CLAMPS			
				· ·		

about:blank 24/26

7/24, 2:4:	) FIVI	Ī	venicie Service Records (VSR) - Repair nistory D-201942	1
PC	Туре	Code	Description (Original)	#
0	Ø	LO-360	CHECK K FACTOR WITH LOADED TEST TRAILER	1
	Ξ		100KMH	
0	Ø	LO-250	REPLACE EXHAUST TAIL PIPE 1004.06	1.5
	<b>3</b>		SAME AS 200397	
0	*	10	WINDOW TINT	
0	*	610	VOLVO POLISHED DURABRITE 1309.63	
0	*	60	R150 STEER TYRE	
0	0	LO-712	front alloy deck plate 750	3.8
0	*	20	supply exhaust	
0	r.	MK-9711- 4017RSVVS6S	DRESS DISC H/CAP	1
0	ď	VO-8394442	CLIPS, HUBCAP FIT	12
0	r.	OTH-26260CK	LUCIDITY MARKER WHITE STAINLES	6
0	r,	VO-25087755	TORX SCREW M4 x 16mm Silver	12
0	5	VO-990976	LOCK NUT	12
0		MK-NARV56707	TUBING 7MM 1=10M	1
0	5	OTH-AMB25B	STICKY PAD	8
0	5	OTH-26260AK	LUCIDITY MARKER AMBER STAINLES	6
0	5	VO-25171459	TORX SCREW M4 x 18mm	12
0	5	MK-NARV56600	HEATSHRINK 1=1 150	1
0		VO-25392050	RELAY RETAINER	1
0	5	VO-979002	TERMINAL FEMALE	5
0		VO-21244697	RELAY	1
0	ď	VO-949597	SLEEVE LOCKING	5
0	г.	VO-949211	TERMINAL FEMALE SPADE	5
0	г.	OTH-NPNC/PLATCH	E3-15-25 LATCH KEYLO	2
0	r.	OTH-NPNC/PCOVER	90-3 COVER KEYLOCK	2
0	r	OTH-NPNC/PKEY	E3-5-15 KEY KEYLOCK	1
0	ď	OTH-UES32752	ANTILUCE FASTENER 50MM THREAD	2
0	г.	OTH-25060	WEAR PLATE ANTI-VIB CLIP S/S	2
0	г.	VO-20393237	RUBBER MOULDING	2
0	г.	OTH-VSHEEPNOLANSRH	SHEEPSKIN NOLANS	1
0	r.	VO-84165756	WEATHERSHIELD (FH4)	1
0	г.	VO-20464675	V-RIBBED BELT	1
0	5	VO-22275091	V-RIBBED BELT	1
0	г.	VO-22273743	HOSE	1
0	г.	VO-21133830	HOSE	1
0	г,	VO-FK18B	FILTER KIT	1
		<del>-</del>		

about:blank 25/26

7/24, 2:4	5 PM		Vehicle Service Records (VSR) - Repair history D-201942	
PC	Туре	Code	Description (Original)	#
0	5	VO-21708450	FMS PREPERATION KI	1
0	*	MTELEC6	4000-3mm Twin Core Cable	
0	*	MTELEC6	3mm Twin Core Cable	
0	*	MTELEC26	4000- 7mm conduit	
0	*	MTELEC6	4000- Twin Core Cable	
0	г.	VO-85135865	CONVERSION KIT	1
0	6	MK-9750-SS11SINCNG	S/STEEL GRD NO RIB	4
0	Ø	LO-810	FMS GATEWAY 436.44	3
0	5	VO-990060	CABLE TERMINAL	6
0		VO-20378934	FUSE, BLADE MINI 10 AMP	1
0	*	MTELEC100	5" Flat Cutting EHT125-2.4A4	
0		AU2-9703- JSK37CZ201TO	.JSK 37 CZ/185 C/W	1
0	5	AU2-20572280	WHEEL 22.5 X 8.25 DURA BRITE	1
0	*	70	PAINT TURNTABLE	
0	г.	MK-9750-MMABPOL	BRACKET	16
0	*	70	MOD PLATE	
0	*	MTELEC187	WALK PLATE CHECKER PLATE	
	B		CHROME NUT COVERS ALL AXLES	
	E		HUBCAPS TO REAR AXLES	
	3		MOUNT Ö 50MM FORWARD OF CENTRE	
	3		ADD RUBER LOOP BETWEEN THE NEW GUARDS	
	3		NO HAIR REQUIRED	

about:blank 26/26