

2017 MB 3200 444 CAP

199185

Component Serial Number
473909C0431672

VIN
WDB96342620291802

YEAR	MAKE	MODEL	IN SERVICE
2019	MB	ACTROS	28/03/2019

Sold Operations

OpsId : 3 Job : 01 CARRY OUT ENGINE REPLACEMENT - TREAT AS WARRANTY - COVER
Cause : MATERIAL FAILURE IN OIL SUCTION MANIFOLD PLASTIC CAUSING THE ENGINE TO SPIN AI
Correction : CARRIED OUT REMOVAL OF ENGINE, NOTED ADDITIONAL DEFECTS

45.00	COOLANT - ALLIANCE PRIMECOOL GP P-40 (1000L) - QABP AFM46041000	6.47	291.15
1.00	ENGINE 580HP	39,312.34	39,312.34
1.00	CORE DEPOSIT	11,252.23	11,252.23
1.00	CORE MUST BE CLEANED AND RETURNED IN ORGINAL PACKAGING	0.00	0.00
1.00	CABLE TIE 7.6 X 370 100	25.99	25.99
1.00	GASKET	155.14	155.14
1.00	STARTER	1,307.97	1,307.97
1.00	CORE DEPOSIT	230.82	230.82
1.00	CORE MUST BE CLEANED AND RETURNED IN ORGINAL PACKAGING	0.00	0.00
1.00	PROFILE SEAL	27.31	27.31
1.00	COOLANT LINE	589.50	589.50
1.00	SINGLE-EYE CLAMP	17.77	17.77
0.00	bay 6	0.00	0.00
-1.00	CORE DEPOSIT	11,252.23	-11,252.23
0.00	A0019970845 X1 is given, one come in will go on shelf	0.00	0.00
-1.00	CORE - STARTER	230.82	-230.82

SIId : RA960015327:01 Total : \$2,478.95 Date Invoice : 06/07/2023 OdomIn: 314,693 OdomOut: 314,693

Sold Operations

OpsId : 1 Job : 20 Engine Cooling - COOLANT LEAK LHS OF ENGINE
Cause : DIAGNOSTIC REPORT
Correction : - Carry out inspection of customer concern

OpsId : 3 Job : 13 Air Compressor coolant lines leaking and injector line seals 3 & 4 leaking.
Cause : Carried out Quoted Repairs.
Correction : - Replaced the defective coolant lines as required.

45.00	COOLANT - ALLIANCE PRIMECOOL GP P-40 (1000L) - QABP AFM46041000	6.47	291.15
1.00	HIGH-PRESSURE LINE	119.31	119.31
2.00	GASKET	17.47	34.94
1.00	COOLANT LINE	49.67	49.67
1.00	COOLANT LINE	98.51	98.51
1.00	HIGH-PRESSURE LINE 4-5-6	211.37	211.37
0.00	kieren desk ewx warehouse-a4700783210-ex dandenong	0.00	0.00

SIId : RA960013370:02 Total : \$2,677.29 Date Invoice : 03/30/2023 OdomIn: 314,692 OdomOut: 314,692

199185

473909C0431672

WDB96342620291802

YEAR	MAKE	MODEL	IN SERVICE
2019	MB	ACTROS	28/03/2019

Sold Operations

OpsId : 14 Job : 01 CARRY OUT ENGINE MOUNT REPLACEMENT
Cause : WORN
Correction : WHILE ENGINE OUT:

2.00 ENGINE SUPPORT	534.41	1,068.82
---------------------	--------	----------

OpsId : 15 Job : 20 REPLACE DRIVE BELTS, MAIN DRIVE PLATE PULLEY AND FAN HUB E
Cause : CONSEQUENTIAL DAMAGE DUE TO ENGINE SEIZING
Correction : WHILE ENGINE OUT :

1.00 V-RIBBED BELT	69.43	69.43
1.00 V-RIBBED BELT 1635MM	69.43	69.43
1.00 V-RIBBED BELT 2642MM	144.32	144.32
1.00 FAN BRACKET	2,845.52	2,845.52
1.00 DRIVE PLATE	1,415.44	1,415.44

OpsId : 16 Job : 25 CARRY OUT CLUTCH AND RELEASE BEARING REPLACEMENT
Cause : WORN
Correction : WHILE ENGINE OUT:

1.00 RELEASE BEARING CLUTCH	2,056.18	2,056.18
1.00 SEAL RING	9.00	9.00
1.00 DUAL-PLATE DRY CLUTCH	5,176.91	5,176.91
1.00 CORE DEPOSIT	913.73	913.73
1.00 CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
12.00 SCREW	14.87	178.44
-1.00 CORE - DUAL-PLATE DRY CLUTCH	913.73	-913.73

OpsId : 17 Job : 13 RECTIFY EAPU HAS OIL DUE TO FAIL AIR COMPRESSOR
Cause :
Correction :

1.00 CONTROL UNIT, EAPU	2,134.91	2,134.91
1.00 MUFFLER	164.45	164.45
7.00 UNION SCREW	7.67	53.69
1.00 CONNECTING PIECE	28.86	28.86
1.00 HOSE ASSEMBLY	341.02	341.02
1.00 COMPRESSED AIR LINE	105.77	105.77
1.00 SUCTION LINE	112.80	112.80
0.00 eapu ex-perth	0.00	0.00

OpsId : 18 Job : 60 RECTIFY UNDER CHASSIS CROSS OVER BRACKET SNAPPED
Cause : BROKEN
Correction : WHILE ENGINE OUT

2.00 STRUT	459.40	918.80
1.00 CABLE TIE 7.6 X 370 100	29.92	29.92

OpsId : 19 Job : 20 RECTIFY FAN SHROUD BROKEN
Cause : IMPACT DAMAGE
Correction : WHILE ENGINE OUT

199185

473909C0431672

WDB96342620291802

YEAR	MAKE	MODEL	IN SERVICE
2019	MB	ACTROS	28/03/2019

Sold Operations

OpsId : 1 Job : 20 CHECK AND REPORT - TRUCK IS USING EXCESSIVE COOLANT - NO
Cause :
Correction : CONCERN: CHECK AND REPORT - TRUCK IS USING EXCESSIVE COOLANT - NO VISABLE L

OpsId : 3 Job : 20 CARRY OUT RADIATOR REPAIR
Cause :
Correction : Complaint: CARRY OUT RADIATOR REPAIR

1.00	COOLANT - ALLIANCE PRIMECOOL GP P-40 (1000L) - QABP AFM46041000	200.00	200.00
1.00	MOLDED HOSE - warehouse	177.75	177.75
1.00	COOLANT LINE	742.71	742.71
1.00	ONE EAR CLAMP	24.57	24.57
0.00	backcounter-now bay 12	0.00	0.00
1.00	COOLANT RADIATOR	2,123.06	2,123.06
0.00	Radiator used out of stock, put transfer back to stock on arrival	0.00	0.00

OpsId : 4 Job : 42 CHECK AND REPORT - BRAKE WARNING ON DASH - QUOTE BRAKES
Cause :
Correction : Complaint: CHECK AND REPORT - BRAKE WARNING ON DASH - QUOTE BRAKES IF NEEDED

OpsId : 5 Job : 00 CARRY OUT SERVICE DUE B+ SERVICE

Cause :
Correction : - CARRY OUT QUICK TEST ON XENTRY, CHECK AND CLEAR ALL STORED FAULT CODES AND

1.00	SCREW PLUG	43.52	43.52
1.00	PARTS KIT FILTER ELEMENT	87.42	87.42
1.00	PARTS KIT FUEL FILTER	252.42	252.42
2.00	AIR RELEASE FILTER	80.03	160.06
1.00	AIR FILTER ELEMENT	174.90	174.90
1.00	PARTS KIT WIPER BLADE	80.52	80.52
1.00	DUST FILTER	118.48	118.48
0.00	bay25	0.00	0.00
1.00	BULB	4.49	4.49
0.00	bay20	0.00	0.00

OpsId : 7 Job : 43 CARRY OUT BRAKE REPLACEMENT

Cause :

Correction : CONCERN: CARRY OUT BRAKE REPLACEMENT

1.00	DISK BRAKE PAD	340.51	340.51
2.00	DISK BRAKE PAD	340.51	681.02
1.00	PARTS KIT GUIDE PIN	794.10	794.10
1.00	BRAKE CALIPER	2,867.93	2,867.93
1.00	CORE - BRAKE CALIPER	506.10	506.10
0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
0.00	backcounter-now bay 23	0.00	0.00
0.00	bay 23	0.00	0.00
1.00	FIT SCREW	39.50	39.50