



Your recall status

Please be sure to read the entire page and follow our advice carefully. To book a Toyota service, please [click here](#).

Safety Recalls

Campaign Code
[2611H]

Recall Description
Power window master switch operation defect may cause switch to become inoperative and/or switch assembly to over-heat & melt

Recall Number
2012/13327

Recall Status
● Outstanding

Completion Date
—

Vehicle Details

VIN	6T153BK400X010031
Model	Camry L4
Colour	Blue Mica Metallic
Trim	FORGE - BLACK
Series	Sedan 5A 2.4 Altise
Production year/month	2006-09
Time/Date	01:35:27 02/06/2023

This search is provided for information purposes to assist Toyota guests and should not be solely relied upon. The Toyota VIN search tool is available for Toyota vehicles only that are supplied through authorised networks (i.e. it does not include 'grey imports'). The search results contain the best information currently available to Toyota.

*Recall Number (REC) is a unique identifier assigned to vehicle recalls by the Department of Infrastructure, Transport, Regional Development and Communications. Previously, Product Recall Australia (PRA) numbers were assigned by the Australian Competition and Consumer Commission (ACCC), therefore the Toyota Safety Recall Website may display REC number or PRA number formats.

For more detail about REC numbers and/or PRA numbers, please visit
<https://www.vehicle recalls.gov.au/> or <https://www.productsafety.gov.au/>

Note: Takata airbag mandatory safety recalls are controlled/monitored by the ACCC and will display the PRA Number only.