W/O No	Plant No	Asset Descriptic	Finished Date/Time 🕴 🚺	Job Type 🚺	Description	<u>.</u> Downtime	Repair Time	Component Code	Department	Parent Asset	Labour Costs	Material Costs	<u>·</u> Other Costs _	Account Code Risk Type
279370	HV827	Truck, water	5/05/2023	Inspection	HV827 - demode ***Complete Mech check, fit number plates and remove toolbox, pack parts and send	0	13	Safety	EXSA0017	Obsolete plant	\$650.00	\$0.00	\$0.00	Water Carts 455>473
274466	HV827	Truck, water	15/04/2023	PInd/Maint	HV827 - PTO faults ***Completed	0	0.5	Hydraulic	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
271380	HV827	Truck, water	4/04/2023	PInd/Maint	HV827 - yoke nut loose * Waiting on Quote* ***Inspected and Completed	0	0.5	Final Drv	EXSA0017	Obsolete plant	\$50.00	\$0.00	\$0.00	Water Carts 455>473
275257	HV827	Truck, water	1/04/2023	PInd/Maint	HV827 - Fit New Reverse Camera Kit *Order Reverse Camera Kit to replace kit used* ***Completed	0	7	Cabin		Obsolete plant	\$735.00	\$0.00	\$0.00	Water Carts 455>473
276086	HV827	Truck, water	28/02/2023	B/dwn Unpl	HV827 - Install New VHF Digital Radio ***Install new VHF radio with mounts, fix door alarm to wor	0	9.5	Electrical	EXSA0017	Obsolete plant	\$1,045.00	\$0.00	\$0.00	Water Carts 455>473
275110	HV827	Truck, water	28/02/2023	PM Service	HV827 - CAT HV CT610 250hr ***service completed	0	5	Servicing	EXSA0017	Obsolete plant	\$275.00	\$0.00	\$0.00	Water Carts 455>473
275228	HV827	Truck, water	17/02/2023	Safety	HV827 - FRC Inspection ***Completed - pass	0	0	Safety	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
268966	HV827	Truck, water	13/02/2023	PInd/Maint	HV827 - Install new PVC pipe ***Install new PVC pipe on RHS of water cart boby, cut to length and	0	1	Hoses	EXSA0017	Obsolete plant	\$100.00	\$251.94	\$0.00	Water Carts 455>473
264986	HV827	Truck, water	12/02/2023	PInd/Maint	HV827 - Rewire electrical control solenoids for water system in rear box ***Reinspect and ok/comp	0	0.5	Electrical	EXSA0017	Obsolete plant	\$50.00	\$176.00	\$0.00	Water Carts 455>473
270389	HV827	Truck, water	11/02/2023	PInd/Maint	HV827 - DOC chamber ***Checked repairs have been carried out by Cavpower, ok.	0	0.5	Engine	EXSA0017	Obsolete plant	\$50.00	\$7,168.22	\$0.00	Water Carts 455>473
275255	HV827	Truck, water	11/02/2023	PInd/Maint	HV827 - To Do List Repairs ***Carry out various repairs, check previous work, secure dash, air le	0	12.58	Cabin		Obsolete plant	\$1,345.00	\$0.00	\$0.00	Water Carts 455>473
268455	HV827	Truck, water	11/02/2023	PInd/Maint	HV827 - Electrical Repairs - Light on Dash/ UHF Bracket/ Reverse Alarm/ Horn ***Carry out electri	0	7	Cabin	EXSA0017	Obsolete plant	\$600.00	\$0.00	\$0.00	Water Carts 455>473
275256	HV827	Truck, water	11/02/2023	PInd/Maint	HV827 - Replace Exhaust Guard ***Weld new brackets to exhaust stack, fit exhaust guard.	0	2	Engine		Obsolete plant	\$200.00	\$0.00	\$0.00	Water Carts 455>473
243792	HV827	Truck, water	9/02/2023	PInd/Maint	HV827 - Interior light ***Inspect light, found door switches U/S, rewire door alarm to door switc	0	5	Cabin	EXSA0017	Obsolete plant	\$0.00	\$37.32	\$0.00	Water Carts 455>473
275136	HV827	Truck, water	9/02/2023	B/dwn Unpl	HV827 - Replace LH Top Spray Gate Valve ***Remove and replace top L/H sprayer gate valve, test ok.	0	1.5	Dust Ctrl	EXSA0017	Obsolete plant	\$150.00	\$0.00	\$0.00	Water Carts 455>473
264357	HV827	Truck, water	9/02/2023	Inspection	HV827 - Onsite (OD) check ***Onsite check completed.	0	11	Safety	EXSA0017	Obsolete plant	\$1,000.00	\$0.00	\$0.00	Water Carts 455>473
266737	HV827	Truck, water	9/02/2023	PM Service	HV827 - Valve adjust from 2000Hr No labour at service to complete ***completed.	0	0.5	Servicing	EXSA0017	Obsolete plant	\$0.00	\$1,987.90	\$0.00	Water Carts 455>473
272056	HV827	Truck, water	8/02/2023	PInd/Maint	HV827 - new fuel tank ***Changed out fuel tank, repaired steps and brackets.	0	14.5	Acc Damage	EXSA0017	Obsolete plant	\$1,520.00	\$2,130.29	\$0.00	Water Carts 455>473
258293	HV827	Truck, water	8/02/2023	PInd/Maint	HV827 - A/C & headlight repairs by Cavpower ***work completed	0	0.5	Air Cond	EXSA0017	Obsolete plant	\$0.00	\$3,183.42	\$0.00	Water Carts 455>473
268676	HV827	Truck, water	8/02/2023	PInd/Maint	HV827 - seat U/S ***new seat has been fitted	0	0.5	Cabin		Obsolete plant	\$0.00	\$2,135.70	\$0.00	Water Carts 455>473
275063	HV827	Truck, water	6/02/2023		Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Fitters First retorque	0	2	Tyres		Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
274366	HV827	Truck, water	21/01/2023	B/dwn Unpl	HV827 - Transmission / PTO Fault ***Check trans fault, found fault was due to excessive load from	0	6.5	Hydraulic	EXSA0017	Obsolete plant	\$690.00	\$0.00	\$0.00	Water Carts 455>473
274363	HV827	Truck, water	20/01/2023	B/dwn Unpl	HV827 - Sprays not working ***Inspecdt and test PTO fault, found faulty flow contral valve, bypas	0	2	Hydraulic	EXSA0017	Obsolete plant	\$210.00	\$0.00	\$0.00	Water Carts 455>473
273124	HV827	Truck, water	19/01/2023	B/dwn Unpl	HV827 - not spraying water correctly + 2 valves not opening. ***Found tap for return open. Closed	0	26.25	Hydraulic	EXSA0017	Obsolete plant	\$2,530.00	\$0.00	\$0.00	Water Carts 455>473
274289	HV827	Truck, water	19/01/2023		HV827: Gain Access to locked Cabin ***Locked cabin and keys left inside, unlock cabin, adjust doo	0	1			Obsolete plant	\$100.00	\$0.00	\$0.00	Water Carts 455>473
273903	HV827	Truck, water	11/01/2023	B/dwn Unpl	HV827 - Belt Tensioner ***Remove tensioner assembly, waiting on parts. Fit new belt and tensioner	0	5	Engine	EXSA0017	Obsolete plant	\$500.00	\$0.00	\$0.00	Water Carts 455>473
267741	HV827	Truck, water	8/11/2022	PM Service	HV827 - CAT HV CT610 500hr ****Completed service as per job sheet. Checked all wheel bearings and	0	7	Servicing	EXSA0017	Obsolete plant	\$700.00	\$579.37	\$0.00	Water Carts 455>473
268556	HV827	Truck, water	30/10/2022	Damage	HV827 head unit U/S ***Remove old head unit, fit new head unit and wire in correct outputs. Tes	0	4	Brakes	EXSA0017	Obsolete plant	\$400.00	\$984.80	\$0.00	Water Carts 455>473
270487	HV827	Truck, water	26/10/2022	B/dwn Unpl	HV827 - Wont move **** Inspect for gauge fault on RHS of dash - gauges not reading. Check gauges/da	0	5	Electrical	EXSA0017	Obsolete plant	\$500.00	\$0.00	\$0.00	Water Carts 455>473
267295	HV827	Truck, water	14/10/2022	Safety	HV827 - FRC inspection ***Completed externally by Cavpower Roxby Downs - failed due to dents in DP	0	0.5	Safety	EXSA0095	Obsolete plant	\$0.00	\$550.98	\$0.00	Water Carts 455>473
268456	HV827	Truck, water	4/10/2022	PInd/Maint	HV827 pos 3 air bag leaking ****Clean off mud and change out Pos 3 air bag.	0	3.5	Air System	EXSA0017	Obsolete plant	\$385.00	\$684.05	\$0.00	Water Carts 455>473
243789	HV827	Truck, water	16/09/2022	PInd/Maint	HV827 - passenger door skin broken	0	0.5	Cabin	EXSA0017	Obsolete plant	\$27.50	\$1,250.37	\$0.00	Water Carts 455>473
268689	HV827	Truck, water	16/09/2022	B/dwn Unpl	HV827 - Leaking Pos 2 hub cover *** Replace LHF hub cap and top up hub oil.	0	1	Final Drv	EXSA0017	Obsolete plant	\$110.00	\$37.61	\$0.00	Water Carts 455>473
267525	HV827	Truck, water	10/09/2022	PInd/Maint	HV827 - Battery isolators	0	1	Electrical	EXSA0017	Obsolete plant	\$0.00	\$339.20	\$0.00	Water Carts 455>473
266907	HV827	Truck, water	10/09/2022	PM Service	HV827 - CAT HV CT610 250	0	5	Servicing	EXSA0017	Obsolete plant	\$140.00	\$357.76	\$0.00	Water Carts 455>473
265110	HV827	Truck, water	10/09/2022	PInd/Maint	HV827 - Pos 6 airbag leaking Replaced air bag	0	3	Suspension	EXSA0017	Obsolete plant	\$84.00	\$586.77	\$0.00	Water Carts 455>473
260146	HV827	Truck, water	10/09/2022	PInd/Maint	HV827 - Replacement hose for hire water truck	0	0.5	Hoses	EXSA0017	Obsolete plant	\$27.50	\$234.92	\$0.00	Water Carts 455>473
252196	HV827	Truck, water	10/09/2022	PInd/Maint	HV827 - replace oils in diff and gearbox when oil arrives, from 1000 hr service. Completed	0	0.5	Servicing	EXSA0017	Obsolete plant	\$27.50	\$1,422.46	\$0.00	Water Carts 455>473
268951	HV827	Truck, water	26/08/2022	PInd/Maint	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Damien Southon First r	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
257157	HV827	Truck, water	3/08/2022	B/dwn Unpl	HV827 - Replace camlok *** 28/5/22 - Spray fault. ****LH spray cam lock broken, centre spray missin	0	16	Cabin	EXSA0017	Obsolete plant	\$1,168.00	\$1,819.25	\$0.00	Water Carts 455>473
259464	HV827	Truck, water	19/07/2022	PM Service	HV827 - CAT HV CT610 2000HR ***Completed Service as per worksheet	0	6	Servicing	EXSA0017	Obsolete plant	\$366.00	\$626.97	\$0.00	Water Carts 455>473
266491	HV827	Truck, water	13/07/2022	B/dwn Unpl	HV827 - Not starting ***Checked, found short.	0	3	Electrical	EXSA0017	Obsolete plant	\$165.00	\$0.00	\$0.00	Water Carts 455>473
265231	HV827	Truck, water	3/06/2022	PInd/Maint	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Shane Tuttelby Firs	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
265233	HV827	Truck, water	3/06/2022	PInd/Maint	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by:Damien Southon First	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
265119	HV827	Truck, water	2/06/2022	B/dwn Unpl	HV827 - Pos 4 brake sezied on ***ACTIONS: Remove wheels & drums, start looking for fault. Found Po	0	9	Brakes	EXSA0017	Obsolete plant	\$585.00	\$0.00	\$0.00	Water Carts 455>473
264358	HV827	Truck, water	11/05/2022	PInd/Maint	HV827 - Rear sprays not working **Found valves sealed and electric solenoids not working. Has air c	0	6	Hoses	EXSA0017	Obsolete plant	\$330.00	\$0.00	\$0.00	Water Carts 455>473
262572	HV827	Truck, water	2/05/2022	B/dwn Unpl	HV827 - Wont select Gears and aircon intermittently playing up. Outsourced to Truck shop Cavpower.	0	0.5	Electrical	EXSA0017	Obsolete plant	\$0.00	\$13,942.20	\$0.00	Water Carts 455>473
255586	HV827	Truck, water	15/02/2022	Inspection	HV827 - FRC Inspection completed by Cavpower Roxby Downs	0	0.5	Safety	EXSA0017	Obsolete plant	\$0.00	\$168.00	\$0.00	Water Carts 455>473
258130	HV827	Truck, water	15/12/2021	PM Service	HV827 - CAT HV CT610 250hr ***ACTIONS: Complete service as per sheet. Diagnose and repair headligh	0	20	Servicing	EXSA0017	Obsolete plant	\$560.00	\$319.22	\$0.00	Water Carts 455>473
258866	HV827	Truck, water	22/11/2021	B/dwn Unpl	HV827 - PTO electric solenoid valve ****ACTIONS - Changed air electrical relay valve. Mounted valv	0	2	Hydraulic	EXSA0017	Obsolete plant	\$200.00	\$0.00	\$0.00	Water Carts 455>473

Stow Gram Normal 164 of 164	Туре 🛓	Hazard Description	W/O Suffix	Risk Score	Risk Rating
Show Graw Show Mark Show Mark Show Mark Show Graw Show Mark Show Mark Show Mark					
Image: section of the section of th					
Image: sector					
Image: Show Brack Im					
Nove Group Show More Keresh					
Show Group Show Group Show Karu Show Karu Show Karu Keresh Show Karu Show Karu Show More Keresh Keresh					
Show Croup Show Croup Show Croup Show Croup Show Kroup Kerest					
Show Croup Show Tarupa					
Show Graup Show Kraup Show Kraup <td></td> <td></td> <td></td> <td></td> <td></td>					
Image: state in the state					
Image: state in the state					
Image: Show Group Show Krocp Show Kropp Show K					
Image: state stat					
Know Group Nowing 164 of 184 Know More Nether					
Констрант Констранt					
Show Group Show 124 of 184 Show More Refresh					
Show Group Show Mare Show Mare Show Mare Secure Action					
Shew Group Show More Show More Refresh					
Show Group Show Mare Show Mare Show Mare Refresh					
Show Group Show Mare Show Mare Show Mare Refresh					
Show Group					
Show Group Show ing 164 of 164 Show More Refresh					
Show Group Show More Refresh					
Show Group Show Light of 164 Show More Refresh					
Show Group Show More Refresh					
Show Group Show arous Show More Refresh					
Show Group Show More Refresh					
Show Group Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Show In 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Show ing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
Show Group Showing 164 of 164 Show More Refresh					
		Show Group Showin	g 164 of 164	Show More	Refresh

W/O No	Plant No	Asset Descriptic	Finished Date/Time 🕴 🛓	Job Type	Description	<u>.</u> Downtime	. Repair Time	Component Code	Department	Parent Asset	Labour Costs	Material Costs	Cther Costs	Account Code Risk Type
258865	HV827	Truck, water	22/11/2021	PInd/Maint	HV827 - Door too high	0	0.5	Cabin	EXSA0017	Obsolete plant	\$14.00	\$0.00	\$0.00	Water Carts 455>473
256375	HV827	Truck, water	5/11/2021	PM Service	HV827 - CAT HV CT610 500hr Service completed by Cavpower	0	8	Servicing	EXSA0017	Obsolete plant	\$0.00	\$2,437.20	\$0.00	Water Carts 455>473
255017	HV827	Truck, water	28/09/2021	B/dwn Unpl	HV827 - Engine warning alarm/fault ACTIONS - Job completed by Cavpower - Drain coolant, remove	0	4	Electrical	EXSA0017	Obsolete plant	\$0.00	\$6,995.36	\$0.00	Water Carts 455>473
253018	HV827	Truck, water	7/09/2021	PM Service	HV827 - CAT HV CT610 250hr ACTIONS: Service carried out by external labour - Cavpower	0	0.5	Servicing	EXSA0017	Obsolete plant	\$50.00	\$1,142.67	\$0.00	Water Carts 455>473
248448	HV827	Truck, water	7/09/2021	PInd/Maint	HV827 - Replace windscreen, cracked ACTIONS: Send out to external labour to have replaced - Ca	0	0.5	Cabin	EXSA0017	Obsolete plant	\$50.00	\$1,177.25	\$0.00	Water Carts 455>473
255974	HV827	Truck, water	5/09/2021	B/dwn Unpl	HV827 - Ehaust pipe cooked grease lines and wiring Checked damage, removed exhaust pipe. Cut ou	0	4	Safety	EXSA0017	Obsolete plant	\$236.00	\$245.41	\$0.00	Water Carts 455>473
255764	HV827	Truck, water	28/08/2021	B/dwn Unpl	HV827 - pos 6 brake booster leaking Actions: Remove and replace Pos. 6 booster as was lieaking	0	1	Brakes	EXSA0017	Obsolete plant	\$100.00	\$0.00	\$0.00	Water Carts 455>473
255763	HV827	Truck, water	27/08/2021	B/dwn Unpl	HV827 - LH headlight n/w Actions: Check connection to headlight, found loose plug. Reconnected	0	0.5	Electrical	EXSA0017	Obsolete plant	\$50.00	\$0.00	\$0.00	Water Carts 455>473
254101	HV827	Truck, water	13/07/2021	B/dwn Unpl	HV827 - Yellow isolator siezed Fitted new isolator	0	1	Electrical	EXSA0017	Obsolete plant	\$55.00	\$60.80	\$0.00	Water Carts 455>473
253640	HV827	Truck, water	12/07/2021	B/dwn Unpl	HV827 - Replace Faulty E- tag	0	1	Electrical	EXSA0017	Obsolete plant	\$0.00	\$180.80	\$0.00	Water Carts 455>473
254079	HV827	Truck, water	12/07/2021	B/dwn Unpl	HV827 - Air tank drains Replaced air tank drains	0	1	Air System	EXSA0017	Obsolete plant	\$55.00	\$0.00	\$0.00	Water Carts 455>473
252795	HV827	Truck, water	5/07/2021	B/dwn Unpl	HV827 - DPF burn off faulty carried out by Cavpower	0	1	Engine	EXSA0017	Obsolete plant	\$0.00	\$1,735.00	\$0.00	Water Carts 455>473
252515	HV827	Truck, water	9/06/2021	PInd/Maint	HV827 - Canon on tank not rotating or turning Traced wiring back. Replaced wire and fuse. Teste	0	5	Tray	EXSA0017	Obsolete plant	\$330.00	\$0.00	\$0.00	Water Carts 455>473
248778	HV827	Truck, water	8/06/2021	PM Service	HV827 - CAT HV CT610 1000hr Carried out 1000hr service as per work order. Repaired LH upper mudg	0	9	Servicing	EXSA0017	Obsolete plant	\$531.00	\$590.00	\$0.00	Water Carts 455>473
252234	HV827	Truck, water	7/06/2021	B/dwn Unpl	HV827 - replace beacon and battery isolator switch Removed old beacon, and rewired and fitted n	0	1	Electrical	EXSA0017	Obsolete plant	\$59.00	\$322.19	\$0.00	Water Carts 455>473
251440	HV827	Truck, water	25/05/2021	B/dwn Unpl	HV827 - A/C not working Replaced HP valve, checked system (pressure OK), cleaned air filter, te	0	4.5	Air Cond	EXSA0017	Obsolete plant	\$330.00	\$0.00	\$0.00	Water Carts 455>473
251422	HV827	Truck, water	21/05/2021	PInd/Maint	HV827 - Reverse alarm not working Reverse alarm was not working due to lack of cleaning. Replace	0	1	Electrical	EXSA0017	Obsolete plant	\$59.00	\$0.00	\$0.00	Water Carts 455>473
248460	HV827	Truck, water	11/05/2021	Safety	HV827 - Fit PTO Sticker No job card but confirmed done by Millsy & Scott	0	0.01	Cabin	EXSA0017	Obsolete plant	\$0.00	\$15.84	\$0.00	Water Carts 455>473
250131	HV827	Truck, water	8/05/2021	B/dwn Unpl	HV827 - Idler pulley seized, replace pulleys and belts removed idler pulley. removed belt tensi	0	3	Engine	EXSA0017	Obsolete plant	\$165.00	\$476.77	\$0.00	Water Carts 455>473
250008	HV827	Truck, water	29/04/2021	B/dwn Unpl	HV827 - DPF light not cancelling Carry out burn off no change. remove & clean temp probs in muff	0	2	Engine	EXSA0017	Obsolete plant	\$118.00	\$0.00	\$0.00	Water Carts 455>473
249253	HV827	Truck, water	25/04/2021	PInd/Maint	HV827 - Replace transmission inc clutch jack truck up. remove cross member. remove hydraulic pum	0	55.5	Trans	EXSA0017	Obsolete plant	\$3,052.50	\$789.43	\$0.00	Water Carts 455>473
248287	HV827	Truck, water	25/04/2021	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: First retorque compl	0	0.01	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
245897	HV827	Truck, water	18/04/2021	PInd/Maint	HV827 - Centre tailshaft bearing - replace unit	0	2	Final Drv	EXSA0017	Obsolete plant	\$110.00	\$523.26	\$0.00	Water Carts 455>473
248090	HV827	Truck, water	18/04/2021	B/dwn Unpl	HV827 - PTO drive overheated - Remove PTO	0	1	Hydraulic	EXSA0017	Obsolete plant	\$55.00	\$2,569.25	\$0.00	Water Carts 455>473
249125	HV827	Truck, water	10/04/2021	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by:	0	3	Tyres	EXSA0005	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
242883	HV827	Truck, water	4/04/2021	Safety	HV827 Signs to be fixed to the side of water truck. Task completed as per lisiting	0	1	Safety	EXSA0017	Obsolete plant	\$55.00	\$32.00	\$0.00	Water Carts 455>473
248288	HV827	Truck, water	1/04/2021	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: First retorque compl	0	0.01	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
247427	HV827	Truck, water	17/03/2021	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: First retorque compl	0	0.01	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
242281	HV827	Truck, water	14/03/2021	B/dwn Unpl	HV827 - Engine oil dipstick tube broken off Remove old dipstick tub. Unbolt mount bracket, fit n	0	5	Engine	EXSA0017	Obsolete plant	\$283.00	\$189.00	\$0.00	Water Carts 455>473
246972	HV827	Truck, water	14/03/2021	B/dwn Unpl	HV827 - UHF hand piece - Replace hand piece	0	1	Electrical	EXSA0017	Obsolete plant	\$55.00	\$78.80	\$0.00	Water Carts 455>473
246306	HV827	Truck, water	14/03/2021	PM Service	HV827 - CAT HV CT610 250hr	0	4	Servicing	EXSA0017	Obsolete plant	\$236.00	\$81.07	\$0.00	Water Carts 455>473
245896	HV827	Truck, water	14/03/2021	PInd/Maint	HV827 - Rear shockers - fit rear shockers	0	3	Suspension	EXSA0017	Obsolete plant	\$165.00	\$786.76	\$0.00	Water Carts 455>473
245898	HV827	Truck, water	14/03/2021	PInd/Maint	HV827 - Air cleaner lid - Fit lid	0	1	Engine	EXSA0017	Obsolete plant	\$55.00	\$0.00	\$0.00	Water Carts 455>473
246910	HV827	Truck, water	2/03/2021	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Lachlan First retor	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
246007	HV827	Truck, water	18/02/2021	PInd/Maint	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Arron Mcgilvary Firs	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
242642	HV827	Truck, water	13/02/2021	PM Service	HV827 - Completed CAT HV CT610 500hr As per service sheet	0	4	Servicing	EXSA0017	Obsolete plant	\$220.00	\$882.47	\$0.00	Water Carts 455>473
228153	HV827	Truck, water	12/02/2021	PInd/Maint	HV827 - Diagnose electrical fault on water cannon/ Tested functions/ Removed all part related to ca	0	15	Electrical	EXSA0017	Obsolete plant	\$1,375.00	\$8,005.19	\$0.00	Water Carts 455>473
244235	HV827	Truck, water	21/01/2021	B/dwn Unpl	HV827 - A/c compressor failed - replace compressor, 1 valve, dryer, belts x2, R&R evaporator & dash	0	29	Air Cond	EXSA0017	Obsolete plant	\$1,595.00	\$2,010.51	\$0.00	Water Carts 455>473
244092	HV827	Truck, water	14/01/2021	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: locki First retorque	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
241339	HV827	Truck, water	21/12/2020	PM Service	HV827 - CAT HV CT610 250hr carry out service as per sheet. Drain sample & refil both rear diffs	0	4	Servicing	EXSA0017	Obsolete plant	\$236.00	\$314.69	\$0.00	Water Carts 455>473
238956	HV827	Truck, water	27/11/2020	PM Service	HV827 - CAT HV CT610 2000HR Actions: carry out service as per sheet.	0	5	Servicing	EXSA0017	Obsolete plant	\$275.00	\$693.37	\$0.00	Water Carts 455>473
240614	HV827	Truck, water	11/11/2020	PInd/Maint	HV827 - replace A/C cab filter ACTIONS: - chang	0	1	Servicing	EXSA0017	Obsolete plant	\$110.00	\$44.38	\$0.00	Water Carts 455>473
240351	HV827	Truck, water	8/11/2020	PInd/Maint	HV827 - carry out DPF cycle ACTIONS: - Ordered decal for windscreen	0	1	Engine	EXSA0017	Obsolete plant	\$55.00	\$33.47	\$0.00	Water Carts 455>473
239702	HV827	Truck, water	8/11/2020	PInd/Maint	HV827 - Passenger seatbelt faulty ACTIONS fit new seat belt (LH side)	0	1	Cabin	EXSA0017	Obsolete plant	\$55.00	\$103.04	\$0.00	Water Carts 455>473
237993	HV827	Truck, water	23/10/2020	PM Service	HV827 - CAT HV CT610 250hr	0	5	Servicing	EXSA0017	Obsolete plant	\$295.00	\$363.18	\$0.00	Water Carts 455>473
222031	HV827	Truck, water	23/10/2020	PInd/Maint	HV827 - Valve clearance adjustment - 6000hr	0	4	Engine	EXSA0017	Obsolete plant	\$236.00	\$36.59	\$0.00	Water Carts 455>473
237826	HV827	Truck, water	4/10/2020	PInd/Maint	HV827 - clearance lights out ACTIONS: Repaired corroded wire for lower LH clearance lights	0	1	Electrical	EXSA0017	Obsolete plant	\$55.00	\$0.00	\$0.00	Water Carts 455>473
237827	HV827	Truck, water	4/10/2020	PInd/Maint	HV827 - Bad samples (Transmission and front diff)	0	2	Trans	EXSA0017	Obsolete plant	\$110.00	\$0.00	\$0.00	Water Carts 455>473
237374	HV827	Truck, water	27/09/2020	B/dwn Unpl	extra accidentally	0	0.01	Cabin	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
237398	HV827	Truck, water	27/09/2020	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: First retorque compl	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473

сТуре 🛓	Hazard Description	W/O Suffix	÷	Risk Score	Risk Rating	_
	Show Group Show	wing 164 of 164		Show More	Refresh	

W/O No	Plant No	Asset Descriptic	Finished Date/Time \downarrow İ	Job Type	Description	Downtime	Repair Time	Component Code	. Department	Parent Asset	Labour Costs	Material Costs	Other Costs	Account Code Risk Type
237081	HV827	Truck, water	24/09/2020	B/dwn Unpl	HV827 - Trans wont find Neutral ACTIONS: -Found broken power wirse which was hidden - s	0	8.5	Trans	EXSA0017	Obsolete plant	\$467.50	\$1,192.55	\$0.00	Water Carts 455>473
236909	HV827	Truck, water	23/09/2020	PInd/Maint	HV827 - Water pump drive coupling	0	5.5	Frame	EXSA0017	Obsolete plant	\$302.50	\$560.73	\$0.00	Water Carts 455>473
235546	HV827	Truck, water	10/09/2020	Inspection	HV827 - FRC Inspection ACTIONS: -Repaired 2x clearance lights -continued wiring repairs f	0	13	Safety	EXSA0017	Obsolete plant	\$735.00	\$618.00	\$0.00	Water Carts 455>473
233783	HV827	Truck, water	8/09/2020	PM Service	HV827 - CAT HV CT610 500hr Carried out service as per sheet. Then started on defects.	0	10	Servicing	EXSA0017	Obsolete plant	\$590.00	\$458.25	\$0.00	Water Carts 455>473
235758	HV827	Truck, water	5/09/2020	PInd/Maint	HV827 - Horn pad fallen off and broken Actions: Replaced horn cover	0	0.5	Cabin	EXSA0017	Obsolete plant	\$29.50	\$518.21	\$0.00	Water Carts 455>473
235582	HV827	Truck, water	30/08/2020	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: First retorque compl	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
235001	HV827	Truck, water	26/08/2020	B/dwn Unpl	HV82 - Alternator Failed ACTIONS: -20/08/2020 checked over and found alternatorsiezed st	0	5	Engine	EXSA0086	Obsolete plant	\$295.00	\$500.74	\$0.00	Water Carts 455>473
234648	HV827	Truck, water	18/08/2020	PInd/Maint	HV827 - Replace siezed battery isolator. Actions: Checked electrics, cleaned battery terminals,	0	2.5	Electrical	EXSA0017	Obsolete plant	\$175.00	\$121.60	\$0.00	Water Carts 455>473
228125	HV827	Truck, water	8/08/2020	PInd/Maint	HV827 - Bumper brakes - cracked Actions: Repaired Mounts	0	1	Frame	EXSA0017	Obsolete plant	\$55.00	\$355.26	\$0.00	Water Carts 455>473
234009	HV827	Truck, water	8/08/2020	B/dwn Unpl	HV827 - ransimssion lost drive Actions: Checked fault codes, (code 19. communication fault), check	0	8	Electrical	EXSA0017	Obsolete plant	\$440.00	\$0.00	\$0.00	Water Carts 455>473
233281	HV827	Truck, water	7/08/2020	PInd/Maint	HV827 - replace PTO hydraulic filter Actions: Removed old filter, cleaned up housing from patch jo	0	0.5	Hydraulic	EXSA0017	Obsolete plant	\$27.50	\$76.94	\$0.00	Water Carts 455>473
228119	HV827	Truck, water	7/08/2020	PInd/Maint	HV827 - Replace steer seal	0	1.5	Servicing	EXSA0017	Obsolete plant	\$82.50	\$148.78	\$0.00	Water Carts 455>473
231718	HV827	Truck, water	26/07/2020	PInd/Maint	HV827 - Hydraulic proportional valve not working Actions: Replaced Solenoid	0	1	Hydraulic	EXSA0017	Obsolete plant	\$55.00	\$173.42	\$0.00	Water Carts 455>473
230380	HV827	Truck, water	26/07/2020	PM Service	HV827 - 250hr service Actions: Carried out service as per sheet. Hydraulic leak at filter for PTO	0	3	Servicing	EXSA0017	Obsolete plant	\$177.00	\$371.53	\$0.00	Water Carts 455>473
228118	HV827	Truck, water	4/07/2020	PInd/Maint	HV827 - Replace diff oil Drained and Fill Diffs	0	2	Final Drv	EXSA0017	Obsolete plant	\$110.00	\$758.67	\$0.00	Water Carts 455>473
228124	HV827	Truck, water	29/06/2020	PInd/Maint	HV827 - Washer motor not working + wiper blades + washer bottle cap Actions: Removed old wiper bla	0	0.5	Cabin	EXSA0017	Obsolete plant	\$27.50	\$113.31	\$0.00	Water Carts 455>473
228123	HV827	Truck, water	29/06/2020	PInd/Maint	HV827 - air horn broken off Actions: Removed broken horn, Fitted new horn	0	0.5	Air System	EXSA0017	Obsolete plant	\$27.50	\$81.04	\$0.00	Water Carts 455>473
228151	HV827	Truck, water	29/06/2020	PInd/Maint	HV827 - LH Window Motor Failed Actions: Removed door trim, removed window regulator, fitted new	0	0.5	Electrical	EXSA0017	Obsolete plant	\$27.50	\$109.69	\$0.00	Water Carts 455>473
228117	HV827	Truck, water	29/06/2020	PInd/Maint	HV827 - Gearbox x member Actions: Removed old cross member, Fitted new cross member	0	1	Frame	EXSA0017	Obsolete plant	\$55.00	\$102.82	\$0.00	Water Carts 455>473
231361	HV827	Truck, water	25/06/2020	B/dwn Unpl	HV827 - Hydraulic PTP pump failed Actions: Fit pump. Fill oil & test. Investigate manuf. settings	0	10.5	Hydraulic	EXSA0017	Obsolete plant	\$577.50	\$1,131.51	\$0.00	Water Carts 455>473
231364	HV827	Truck, water	21/06/2020	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Hayely Randall First	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
231262	HV827	Truck, water	18/06/2020	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Arron McGilvary Firs	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
230566	HV827	Truck, water	8/06/2020	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Balf and Scott First	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
229657	HV827	Truck, water	7/06/2020	PInd/Maint	HV827 - Seat slides Actions: Replaced seat slides	0	0.5	Cabin	EXSA0017	Obsolete plant	\$27.50	\$164.82	\$0.00	Water Carts 455>473
229091	HV827	Truck, water	7/06/2020	PM Service	HV827 - 1000 hr service Actions: Carried out service as per sheet + some defects	0	9	Servicing	EXSA0017	Obsolete plant	\$495.00	\$0.00	\$0.00	Water Carts 455>473
228163	HV827	Truck, water	18/05/2020	PInd/Maint	HV827 - Isolators Siezed Removed and Replaced both isolators	0	1.5	Electrical	EXSA0017	Obsolete plant	\$82.50	\$163.80	\$0.00	Water Carts 455>473
229284	HV827	Truck, water	15/05/2020	B/dwn Unpl	Hv827 - hydraulic hose failed (outlet/pressure hose from pto) Fitted new hose, filled with oil,	0	1	Hoses	EXSA0017	Obsolete plant	\$55.00	\$269.43	\$0.00	Water Carts 455>473
225943	HV827	Truck, water	22/04/2020	PM Service	HV827 - CAT HV CT610 250hr Bracket Bumper RH Broken - work order requested Front horn brachet/hor	0	6	Servicing	EXSA0017	Obsolete plant	\$330.00	\$0.00	\$0.00	Water Carts 455>473
227397	HV827	Truck, water	13/04/2020	B/dwn Unpl	HV827 - blown pos 2 tyre	0	1	Tyres	EXSA0017	Obsolete plant	\$59.00	\$0.00	\$0.00	Water Carts 455>473
227007	HV827	Truck, water	6/04/2020	B/dwn Unpl	-	0	0.01	Cabin	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
226970	HV827	Truck, water	4/04/2020	B/dwn Unpl	HV827 - Faulty cabin earth	0	13	Electrical	EXSA0017	Obsolete plant	\$715.00	\$0.00	\$0.00	Water Carts 455>473
218618	HV827	Truck, water	3/04/2020	PInd/Maint	Diagnostic software for truck No action taken, NAVSTAR will not release system	0	0.01	Electrical	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
227011	HV827	Truck, water	3/04/2020	B/dwn Unpl	HV827 - Burnt wiring loom repair loom	0	2	Electrical	EXSA0017	Obsolete plant	\$110.00	\$0.00	\$0.00	Water Carts 455>473
226196	HV827	Truck, water	29/03/2020	B/dwn Unpl	No rear sprays, PTO pump issues. Replaced pump and PTO	0	10.5	Hydraulic	EXSA0017	Obsolete plant	\$1,050.00	\$3,331.41	\$0.00	Water Carts 455>473
225819	HV827	Truck, water	15/03/2020	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: HR First retorque co	0	1	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
223350	HV827	Truck, water	10/03/2020	B/dwn Unpl	LH front hub cab -replace cap and fill with oil	0	0.25	Final Drv	EXSA0017	Obsolete plant	\$25.00	\$84.32	\$0.00	Water Carts 455>473
223229	HV827	Truck, water	9/03/2020	PM Service	HV827 - CAT HV CT610 500hr Carry out service	0	5	Servicing	EXSA0017	Obsolete plant	\$500.00	\$0.00	\$0.00	Water Carts 455>473
226431	HV827	Truck, water	7/03/2020	PInd/Maint	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Nathan First retorqu	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
225056	HV827	Truck, water	1/03/2020	Damage	HV827 - align front bumper and weld straps.	0	200	Acc Damage	EXSA0017	Obsolete plant	\$200.00	\$0.00	\$0.00	Water Carts 455>473
221134	HV827	Truck, water	10/02/2020	PM Service	HV827 - CAT HV CT610 250hr, replace front tyres, Fix LHS rear beacon, refit wiper blade replace pos	0	5	Servicing	EXSA0017	Obsolete plant	\$500.00	\$595.22	\$0.00	Water Carts 455>473
222081	HV827	Truck, water	5/01/2020	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by:HR First retorque com	0	1	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
222063	HV827	Truck, water	4/01/2020	PInd/Maint	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by:HR First retorque com	0	1	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
219441	HV827	Truck, water	2/01/2020	PM Service	HV827 - CAT HV CT610 2000HR 2 clearnace lights replaced No reverse camera Broken grease line to	0	13	Servicing	EXSA0005	Obsolete plant	\$1,300.00	\$673.70	\$0.00	Water Carts 455>473
218615	HV827	Truck, water	2/01/2020	B/dwn Unpl	Coolant weep RH side engine	0	0.5	Engine	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
218635	HV827	Truck, water	2/01/2020	PInd/Maint	Spare key	0	0.5	Cabin	EXSA0017	Obsolete plant	\$0.00	\$102.96	\$0.00	Water Carts 455>473
219526	HV827	Truck, water	31/12/2019	B/dwn Unpl	LH inner front guard broken - replace	0	1.5	Cabin	EXSA0017	Obsolete plant	\$150.00	\$452.21	\$0.00	Water Carts 455>473
224131	HV827	Truck, water	26/12/2019	B/dwn Unpl	HV827 - POS 9 & 10, Tag# 1498. Job Completed As Per Task Listing. Wheel Removal / Replacement	0	1.25	Tyres	EXSA0005	Obsolete plant	\$62.00	\$0.00	\$0.00	Water Carts 455>473
220055	HV827	Truck, water	26/11/2019	B/dwn Unpl	HV827 - No PTO, blown hydraulic line Replace failed hydraulic hose	0	1	Hoses	EXSA0017	Obsolete plant	\$100.00	\$619.38	\$0.00	Water Carts 455>473
219990	HV827	Truck, water	24/11/2019	B/dwn Unpl	HV827 - engine shut down, turns over but wont start (trans fault) Found wiring issue in e-stop wir	0	6	Electrical	EXSA0017	Obsolete plant	\$600.00	\$0.00	\$0.00	Water Carts 455>473
218417	HV827	Truck, water	24/11/2019	PM Service	HV827 - CAT HV CT610 250hr	0	5	Servicing	EXSA0017	Obsolete plant	\$500.00	\$413.79	\$0.00	Water Carts 455>473

сТуре 🛓	Hazard Description	W/O Suffix	÷	Risk Score	Risk Rating	_
	Show Group Show	wing 164 of 164		Show More	Refresh	

W/O No	Plant No	Asset Descriptic	Finished Date/Time ↓ 🚊	Job Type	Description	D owntime	Repair Time	Component Code	Department _	Parent Asset	Labour Costs	Material Costs	Other Costs	Account Code Risk Type
218617	HV827	Truck, water	10/11/2019	PInd/Maint	Sunvisor clips, mudflaps front, washer bottle	0	2.5	Cabin	EXSA0017	Obsolete plant	\$137.50	\$385.22	\$0.00	Water Carts 455>473
217309	HV827	Truck, water	21/10/2019	PM Service	CAT HV CT610 500hr	0	7	Servicing	EXSA0017	Obsolete plant	\$385.00	\$2,839.77	\$0.00	Water Carts 455>473
217543	HV827	Truck, water	7/10/2019	B/dwn Unpl	HV827 - fuel returning to L/H tank only causing overflow. repaired kinked fuel line	0	2	Engine	EXSA0017	Obsolete plant	\$200.00	\$0.00	\$0.00	Water Carts 455>473
217215	HV827	Truck, water	3/10/2019	PM Service	HV827 - CAT HV CT610 500hr	0	1	Servicing	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
217214	HV827	Truck, water	3/10/2019	PM Service	HV827 - CAT HV CT610 1000hr	0	0	Servicing	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
217213	HV827	Truck, water	3/10/2019	PM Service	HV827 - CAT HV CT610 2000HR	0	0	Servicing	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
217212	HV827	Truck, water	3/10/2019	PM Service	HV827 - CAT HV CT610 250hr	0	0	Servicing	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
217211	HV827	Truck, water	3/10/2019	PM Service	HV827 - CAT HV CT610 500hr	0	0	Servicing	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
217210	HV827	Truck, water	3/10/2019	PM Service	HV827 - CAT HV CT610 1000hr	0	0	Servicing	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
217209	HV827	Truck, water	3/10/2019	PM Service	HV827 - CAT HV CT610 2000HR	0	0	Servicing	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
215777	HV827	Truck, water	30/09/2019	PInd/Maint	HV827 - Prep for site - Heavy vehicle truck inspection attached.	0	10.2	Safety	EXSA0017	Obsolete plant	\$493.50	\$786.80	\$0.00	Water Carts 455>473
217085	HV827	Truck, water	29/09/2019	B/dwn Unpl	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: JR First retorque com	0	2	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
217082	HV827	Truck, water	29/09/2019	PInd/Maint	Wheel Removal / Replacement and Retorque Procedure Wheel / Tyre Replaced by: Clinton H First reto	0	3	Tyres	EXSA0017	Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473
215776	HV827	Truck, water	3/09/2019			0	0			Obsolete plant	\$0.00	\$0.00	\$0.00	Water Carts 455>473

÷	Hazard Description	÷	W/O Suffix	:	Risk Score	<u>.</u>	Risk Rating	:
	Show Group	Showin	g 164 of 164		Show More		Refresh	