

To whom it may concern,

This letter is to confirm that the history of the vehicle with registration CQS150 has presented some discrepancies.

Please keep in mind that the dates in our database are a reflection on when the repair orders were closed/finalized.

This might not necessarily be the same date the vehicle came into the dealership.

Audi
Essendon Fields
Audi Sport ore
Audi e-tron Partner

346 Wirraway Road
Essendon Fields VIC 3041

Tel +61 3 9968 8188


www.audiessendonfields.com.au

ABN 62 315 263 599
LMCT 9479

- We don't have any records of a visit to a dealership on the 3/7/2017 at 15000Km
- The vehicle has come in on the 9/3/2017 with 33944Km instead of the 12/10/2017 that shows in your report
- The vehicle has come in on 10/5/2019 to get the brakes and tyres replaced, instead of getting the new odometer reading, the advisor has used the same reading (50852Km) on the previous service done on 8/11/2018
- On my records there is 2 visits on the 29/3/2021, the first one the vehicle had 69551km and the second one for the same day the vehicle had 73101Km on these visits, the car came in for the service, and we have recommended to do extra work, we have created a repair order on the day to order parts, and the vehicle has come in at a later day to get them installed.

Hope this helps, if there is anything else I can help with please do not hesitate to contact me.

Yours sincerely,



Sebastian Zea

Service Advisor

Audi Essendon Fields
346 Wirraway Road
Essendon Fields VIC 3041
Tel +61 [3 9968 8188](tel:399688188)

www.audiessendonfields.com.au

