

Tool No.	Make	Service Frequency	Service Type	Service Notes
288	Kenworth	14/07/2021 (On Demand)	General Maintenance	check windscreen leaking - ordered new windscreen seals - James Murphy (SOS)
288	Kenworth	13/07/2021 (On Demand)	General Maintenance	D service, adjusted all brakes to achieve 90 degree push rod angle @ 701137kms - James Murphy (SOS)
288	Kenworth	29/06/2021 (On Demand)	Preventive	Carry out A Service - S Collett
288	Kenworth	10/06/2021 (On Demand)	General Maintenance	replaced 1 steering uni and check s-cams - Luke Stanley (SOS)
288	Kenworth	09/06/2021 (On Demand)	General Maintenance	finish putting the front springs back in - Luke Stanley (SOS)
288	Kenworth	08/06/2021 (On Demand)	General Maintenance	removed front spring packs, fitted new ones with new pins, shackles and u-bolts - Luke Stanely (SOS)
288	Kenworth	28/05/2021 (On Demand)	General Maintenance	Brakes dragging, Tested, found brake treddle valve sticking down, cleaned dirt from pedal. Removed brake pedal & cleaned rubbed up piston, re-fitted and tested good, also found 1 booster slow to release - Zen Goldsworthy
288	Kenworth	26/05/2021 (On Demand)	General Maintenance	Clean Truck - Joel Baldwin
288	Kenworth	19/05/2021 (On Demand)	General Maintenance	Put wheel indicators on - Jordon Christian
288	Kenworth	10/05/2021 (On Demand)	General Maintenance	Repair electrical issue with prime mover for tarps, repair marker lamps as wired incorrect, check taps, fit new tema line fitting, fit ring feeder + pick up parts for truck, fit sticker inspect over. Start dissemble of air valve manifold - Ryan Arthur

288	Kenworth	20/04/2021 (On Demand)	General Maintenance	Drain fuel tank on loader to repair leak, help tom do valve set on loader - Jordon Christian
288	Kenworth	16/04/2021 (On Demand)	General Maintenance	Brake Tested - Zen Goldsworthy
288	Kenworth	15/04/2021 (On Demand)	General Maintenance	Heavy Vehicle - Workshop Release Safety & Maintenance Inspection 15 Apr 2021 / 288 / Selena Moore
288	Kenworth	15/04/2021 (On Demand)	Corrective	Wash and degrease truck, start C Service - Jordon Christian
288	Kenworth	15/04/2021 (On Demand)	Preventive	C Service and repairs - Zen Goldsworthy
288	Kenworth	09/04/2021 (On Demand)	General Maintenance	Repair air leaks - Ryan Arthur
288	Kenworth	01/04/2021 (On Demand)	Preventive	a service - shane collett
288	Kenworth	31/03/2021 (On Demand)	General Maintenance	Brown and Hurley- Manifold pass thru x2 & 1x accessory
288	Kenworth	31/03/2021 (On Demand)	General Maintenance	Twin city tyres- 8x Aeolus 11R22.5 ADC53, strip and fit tyre disposal fee
288	Kenworth	26/03/2021 (On Demand)	Preventive	a service - shane collett
288	Kenworth	20/03/2021 (On Demand)	Preventive	a service - shane collett
288	Kenworth	17/03/2021 (On Demand)	General Maintenance	Twin city tyres- Service call, 11R22.5 s/hand drive tyre. Tyre disposal fee
288	Kenworth	15/03/2021 (On Demand)	General Maintenance	Twin City Tyres- Strip & Fit, Tyre disposal fee x1
288	Kenworth	13/03/2021 (On Demand)	Preventive	brake test - matt doyle
288	Kenworth	10/03/2021 (On Demand)	Preventive	i audit inspection - ryan arthur
288	Kenworth	10/03/2021 (On Demand)	General Maintenance	Carry out B Service, replace torque rod v bushes, finish off bushes, carry out I Audit - Ryan Arthur
288	Kenworth	07/03/2021 (On Demand)	General Maintenance	Wash unit - Shane Collett
288	Kenworth	27/02/2021 (On Demand)	General Maintenance	Wash and grease unit - Shane Collett

288	Kenworth	22/02/2021 (On Demand)	General Maintenance	Replaced leaking brake booster at Port access road - James (SOS Diesel)
288	Kenworth	19/02/2021 (On Demand)	Preventive	a service - shane collett
288	Kenworth	13/02/2021 (On Demand)	Preventive	brake test - matt doyle
288	Kenworth	10/02/2021 (On Demand)	General Maintenance	measured cut & made new fuel hoses, fitted hoses with P clamps, intercooler arrived after repair, fitted to radiator, fitted a/c condenser and shrouds, replaced boost hose on RHS @ turbo, primed fuel system, started and ran ok, washed down engine bay @ 686079 - James Murphy (SOS Diesel)
288	Kenworth	09/02/2021 (On Demand)	General Maintenance	Defect repairs and hand overs with James - Luke Stanley (SOS Diesel)
288	Kenworth	09/02/2021 (On Demand)	General Maintenance	sourced and fitted new hub caps, replaced radiator mount rubbers LHS stay, tightened bottom radiator mount nuts, top intercooler mounts cracked, removed intercooler, found evidence of dust in intake pipes, found boost hoses u/s and air filter blocked, replaced air filter, removed rubbing/hard fuel hoses from fuel separator and fuel pump, got new hose, removed fittings from old hose @ 686079kms - James murphy (SOS Diesel)
288	Kenworth	08/02/2021 (On Demand)	General Maintenance	find brake not releasing fault - luke stanley
288	Kenworth	04/02/2021 (On Demand)	General Maintenance	Wash truck & trailers - Rob Leon

288	Kenworth	05/01/2021 (On Demand)	General Maintenance	Continue on repairing overheating issue, replace heater hoses. Fit coolant components, fill up, run truck & replace bonnet rubbers - Ryan Arthur
288	Kenworth	04/01/2021 (On Demand)	General Maintenance	Cooling issue repairs - Drain coolant, start disassemble of components. Change out oil thermostat, remove coolant thermo, clean all components, refit thermo housing, fit new coolant thermostat, check ok, Wash & hose down exterior of truck - Ryan Arthur
288	Kenworth	21/12/2020 (On Demand)	General Maintenance	Supply & fit EGR Cooler - SOS Diesel Inv No 30368
288	Kenworth	14/12/2020 (On Demand)	General Maintenance	replace tensioners for a/c and fan and pullys and belts - ryan arthur
288	Kenworth	12/12/2020 (On Demand)	General Maintenance	replace temp sensor and gauge - tom kerlin
288	Kenworth	10/12/2020 (On Demand)	General Maintenance	replaced bonnet strap and aligned - zen goldsworthy
288	Kenworth	01/12/2020 (On Demand)	Corrective	Twin City Tyres 1 x Strip and fit 1 x second hand tyre
288	Kenworth	30/11/2020 (On Demand)	Corrective	Checked over truck & made sure everything was done - Ryan Arthur
288	Kenworth	27/11/2020 (On Demand)	Corrective	Big Wheels Truck Alignment Carry out drive alignment
288	Kenworth	26/11/2020 (On Demand)	Corrective	Inspect truck. Carry out I-Audit and minor repairs. Brake test - Ryan Arthur

288	Kenworth	26/11/2020 (On Demand)	Preventive	R&M 1298 banging in front end & pull to LHS - R&M 1299 vibration between 70-80km - R&M 1313 using 10L coolant - R&M 1314 check engine light intermittently - completed by Ryan Arthur & SOS diesel
288	Kenworth	11/11/2020 (On Demand)	Preventive	R&M 1297 movement in turntable - completed by Tom kerlin
288	Kenworth	10/11/2020 (On Demand)	Corrective	SOS Diesel Services Replaced front spring bushes and pins. Assist with B-Service
288	Kenworth	26/10/2020 (On Demand)	Corrective	Carried out B-Service as per service sheet. Re- kit air dryer. Replaced Shabel pins/bushes on steer. Replace front engine mounts and adjust clutch free travel Ryan Arthur
288	Kenworth	26/10/2020 (On Demand)	Preventive	R&M 1268 LH hub seal leak - R&M 1269 oil pressure gauge not working - R&M 1270 air leak at gear shift splitter - R&M 1279 a/c leak onto floor - R&M 1285 wiper washer not working - completed by Ryan Arthur
288	Kenworth	26/10/2020 (On Demand)	Preventive	pre workshop release - nick mcclymont
288	Kenworth	13/10/2020 (On Demand)	Corrective	Replace gear knop in truck - Ryan Arthur
288	Kenworth	12/10/2020 (On Demand)	Corrective	Replace side marker lamp LH side. Adjust turntable and replace clutch pad - Ryan Arthur

288	Kenworth	07/10/2020 (On Demand)	Corrective	Check over, overhaul steering shaft from firewall to STR bo. Replace UJ's, refit, grease, adjust brakes, install new right rear mud guards - Steve Clews
288	Kenworth	06/10/2020 (On Demand)	Corrective	Check for noise when turning, replace hub caps, check over - Steve Clews
288	Kenworth	06/10/2020 (On Demand)	Preventive	R&M 1242 front seal hubs leaking oil - R&M 1257 FLH spring clunking - R&M 1258 engine oil pressure gauge reading off scale - R&M 1259 a/c leak - completed by Steve Clews
288	Kenworth	02/10/2020 (On Demand)	Corrective	Mendi Truck & Trailer Brake Test Report Inspected by Ken Wittmann
288	Kenworth	19/09/2020 (On Demand)	Corrective	ATR not building up - Zen Goldsworthy
288	Kenworth	18/09/2020 (On Demand)	Corrective	Mendi - Truck & Trailer Brake Test Report Inspected by Ryan Arthur
288	Kenworth	16/09/2020 (On Demand)	Corrective	Kenny's Auto Electrical Inspect brake lights not working- found no brakes
288	Kenworth	03/09/2020 (On Demand)	Corrective	hook up as road train - scott healing
288	Kenworth	26/08/2020 (On Demand)	Corrective	MAK Diesel & Earthmoving Removed rear axle from roller and found vibration motors to be leaking
288	Kenworth	19/08/2020 (On Demand)	Corrective	Replaced valve - Tom Kerlin
288	Kenworth	10/08/2020 (On Demand)	Corrective	MAK Diesel & Earthmoving Repaired front oil leak behind Cam/ Injector gears
288	Kenworth	30/07/2020 (On Demand)	Corrective	Completed brake test - Tom Kerlin
288	Kenworth	30/07/2020 (On Demand)	Corrective	Truck and Trailer Brake Test report - inspected by Tom Kerlin

288	Kenworth	30/07/2020 (On Demand)	Corrective	Kenny's Auto Electrical Check over all lights - found reverse light, left right rear & right rear indicator, left side indicator and left rood light were faulty
288	Kenworth	30/07/2020 (On Demand)	Preventive	pre workshop release - tom kerlin
288	Kenworth	29/07/2020 (On Demand)	Corrective	repair air leaks, service tank guard, adjusted fuel tank position , repair air leaks, replace air bags - Aaron Pattison (MAK Diesel)
288	Kenworth	27/07/2020 (On Demand)	Corrective	MS Fabrications Weld up cracked engine cover
288	Kenworth	27/07/2020 (On Demand)	Corrective	Kenny's Auto Electrical Remove old fog lights and replace with new LED lights.
288	Kenworth	24/07/2020 (On Demand)	Corrective	Brown and Hurley 2 x hook hood 2 x hubcabs
288	Kenworth	24/07/2020 (On Demand)	Corrective	Bayswater Road Radiator Carried out repairs as requested: - Kenworth cooling pack - Radiator - intercooler
288	Kenworth	24/07/2020 (On Demand)	Corrective	Bayswater Road Radiators Pressure wash and steam clean radiator internally and externally, flush and flow check internally, re-assemble radiator using new gasket and hardware. Carry out repairs
288	Kenworth	23/07/2020 (On Demand)	Corrective	Brown and Hurley 2 x Kit loop
288	Kenworth	23/07/2020 (On Demand)	Corrective	Brown and Hurley 1 x Wind visor cover
288	Kenworth	23/07/2020 (On Demand)	Corrective	Finish off service, refit components - Ryan Arthur (MAK Diesel)
288	Kenworth	23/07/2020 (On Demand)	Corrective	Install radiator and hood, fill with coolant, top up oil and check for leaks - Steve Clews

288	Kenworth	22/07/2020 (On Demand)	Corrective	Predator Remove all signage from unit 288 Supply and install "Mendi" graphics to unit 288
288	Kenworth	22/07/2020 (On Demand)	Corrective	Front oil leak & compressor reseal. Engine/ Truck service - Ryan Arthur (MAK Diesel)
288	Kenworth	22/07/2020 (On Demand)	Corrective	check out radiator to be repaired - zen goldsworthy
288	Kenworth	21/07/2020 (On Demand)	Corrective	Brown and Hurley 2 x Seat Covers
288	Kenworth	21/07/2020 (On Demand)	Corrective	Front oil leak & compressor reseal - Ryan (MAK Diesel)
288	Kenworth	21/07/2020 (On Demand)	Corrective	took radiator to bayswater radiators - zen goldsworthy
288	Kenworth	21/07/2020 (On Demand)	Corrective	Truck Bake 1 X Bonnet - fibreglass repairs to bonnet mount guide areas
288	Kenworth	17/07/2020 (On Demand)	Corrective	Big Boys Super Wash - Acid cab wash sand and polish bumper bar and cab hardware buff cab polish rims internal cab details
288	Kenworth	14/07/2020 (On Demand)	Corrective	Cummins South Pacific 2 x Shaft Rocker Lever
288	Kenworth	10/07/2020 (On Demand)	Corrective	remove exhaust manifold & components prep, reinstall manifold & finish tune up, rekit jake brakes, reinstall rocker cover & all inducting, replace rose joints, radiator support wash - Ryan MAK Diesel
288	Kenworth	09/07/2020 (On Demand)	Corrective	Kenworth valve inspect, adjust, order parts, remove turbo - Ryan MAK Diesel
288	Kenworth	09/07/2020 (On Demand)	Corrective	found air leak, brake light switched - steve clews

				Cummins South Pacific 1 x Harness - wiring 2 x solenoid engine brakes 4x gasket exh manifold 1 x gasket ech manifold 1 x gasket turbocharger 1 x gasket flange 2 x seal grommet 1 x engine brake kit
288	Kenworth	09/07/2020 (On Demand)	Corrective	
288	Kenworth	09/07/2020 (On Demand)	Corrective	Brown and Hurley 4 x Mudguards
288	Kenworth	08/07/2020 (On Demand)	Corrective	remove dash to replace both park brake and trailer supply valves, remove turntable, clean inspect, overhaul, change mount bushes, reinstall turntable and adjust - steve clews
288	Kenworth	08/07/2020 (On Demand)	Corrective	Truckline 1 x lock jaw 1 x pivot foot bush kit 1 x wear pad foot pocket 1 x turntable 2 x repair kit for lock jaw
288	Kenworth	08/07/2020 (On Demand)	Corrective	put new park brake valves in, clean turntable, but new turntable kit in, grease turntable - Lachlan Lurch
288	Kenworth	07/07/2020 (On Demand)	Corrective	D service, check all wheel bearings, adjust all brakes, secure side panels, replace fan belt, replace alternator belt, check all levels, top up oil - Steve Clews
288	Kenworth	07/07/2020 (On Demand)	Corrective	24 Hour Hose Supplied fittings as requested
288	Kenworth	07/07/2020 (On Demand)	Preventive	R&M 1174 - air leaking from park brake buttons - R&M 1178 slow air to trailers - R&M 1179 jake only on stage 2 - R&M 1184 fan shroud cracked - Steve Clews
288	Kenworth	02/07/2020 (On Demand)	Corrective	Truck & Trailer Brake Test Report - Inspected by Tom Kerlin

288	Kenworth	22/06/2020 (On Demand)	Corrective	Twin City Tyres Fit 2 x customer own second hand tyres replaced 4 Power Pro D Powertrac tyres
288	Kenworth	01/06/2020 (On Demand)	Preventive	Modification certificate - GCM 106t - Brown & Hurley
288	Kenworth	29/04/2020 (On Demand)	Corrective	R+M 1181 Turntable feet bushes need replacing and dog bones- Diamond Diesel
288	Kenworth	29/04/2020 (On Demand)	General Maintenance	Mendi Prime Mover / Rigid Tipper & Trailing equipment B-Service - Phil Witten
288	Kenworth	28/03/2020 (On Demand)	Corrective	repaired air leak, repaired two wiring, wipers - scott healing
288	Kenworth	13/03/2020 (On Demand)	Corrective	fit fan hub - ken wittmann
288	Kenworth	07/03/2020 (On Demand)	Corrective	fitted road train sign, repaired air lines - scott healing
288	Kenworth	06/03/2020 (On Demand)	Corrective	Truck Brake test report - Scotty
288	Kenworth	06/03/2020 (On Demand)	Corrective	hooked up road train, tared off and weighed, filled with water, repaired side light, cleaned and washed - scott healing
288	Kenworth	04/03/2020 (On Demand)	Corrective	reline front brakes and change out steer wheel bearings - brendan lariva
288	Kenworth	03/03/2020 (On Demand)	Corrective	repair LHS mirror, repaired RHS tank guards - Scott Healing
288	Kenworth	03/03/2020 (On Demand)	Corrective	clutch needs adjustment R&M 1116 air leak at high split on gear stick R&M 1128 SH 30/1
288	Kenworth	03/03/2020 (On Demand)	Corrective	R+M 1146 RH Exhaust rattling -B. Laviva

288	Kenworth	02/03/2020 (On Demand)	Corrective	Run air lines to cab and fit switches for water tanker Run Airlines for water tanker. Remove Solenoid Bank - Brendan LaRiva
288	Kenworth	24/02/2020 (On Demand)	Corrective	kenny's auto electrical: inspection and repair
288	Kenworth	17/02/2020 (On Demand)	Corrective	Kenny's Auto Electrical Inspect for suspect ac compressor noise.
288	Kenworth	10/02/2020 (On Demand)	Corrective	Remove A/C clutch - Brendan LaRiva
288	Kenworth	30/01/2020 (On Demand)	Corrective	inspection & repairs - scott healing
288	Kenworth	30/01/2020 (On Demand)	Corrective	R+M 1128 Air leak at high split on G/Stick -S. Healing
288	Kenworth	30/01/2020 (On Demand)	General Maintenance	Mendi Mendi Constrcution Limited Pre-Workshop Release Safety & Maintenance Inspection Policy
288	Kenworth	30/01/2020 (On Demand)	Corrective	Clutch needs ADJ. R+M 1116 M-Doyle
288	Kenworth	29/01/2020 (On Demand)	Corrective	needs clutch adjustment. air leak at high split on g/stick R+M 1128
288	Kenworth	16/01/2020 (On Demand)	Preventive	Brake Test
288	Kenworth	02/01/2020 (On Demand)	Preventive	B service - Matt doyle
288	Kenworth	02/01/2020 (On Demand)	Corrective	adjust clutch linkage, front wheel bearings, change coolant aeration hose - Brendan Lariva
288	Kenworth	02/01/2020 (On Demand)	General Maintenance	Mendi Prime Mover / Rigid Tipper & Trailing Equipment B-Service - M. Doyle
288	Kenworth	17/12/2019 (On Demand)	Corrective	Belt squeeling bad. front end knocking when turning gear knob leaking air R&M 1094 - M.DOYLE
288	Kenworth	17/12/2019 (On Demand)	Corrective	Park Brake valve leaking. R&M 1069 - Matt Doyle

288	Kenworth	17/12/2019 (On Demand)	Corrective	LHS Exhaust muffler cracked at top R+M 1067 - M.Doyle
288	Kenworth	17/12/2019 (On Demand)	Corrective	Air horn not working correctly - R+M 1049
288	Kenworth	04/12/2019 (On Demand)	Corrective	Belt slipping, gear knob air leak, front end movement (loud clunk when turning) R+M 1097
288	Kenworth	16/10/2019 (On Demand)	Corrective	oil couplings leaking at rear of trailer R+M 1065
288	Kenworth	03/10/2019 (On Demand)	Corrective	R&M 1051 - check a/c, replaced evaporator fan - ross wise
288	Kenworth	19/09/2019 (On Demand)	Corrective	Twin City Tyres - replace drive tyres
288	Kenworth	16/09/2019 (On Demand)	Corrective	Kennys Auto - alternator inspect and repairs
288	Kenworth	11/09/2019 (On Demand)	Corrective	fault find starting issue - replace batteries and alternator - Tom Kerlin
288	Kenworth	09/09/2019 (On Demand)	Corrective	2 x steer tyres replaced - twin city tyres
288	Kenworth	21/08/2019 (On Demand)	Corrective	Fix mudguard - Tom kerlin
288	Kenworth	14/08/2019 (On Demand)	Preventive	Brake Test 6.9m - Matt Doyle
288	Kenworth	14/08/2019 (On Demand)	Corrective	Clutch adjustment - Tom Kerlin & Calvin Jack
288	Kenworth	12/08/2019 (On Demand)	Corrective	remove all 4 rear shockies, fit new shockies - Calvin Jack
288	Kenworth	09/08/2019 (On Demand)	Preventive	R & M - Gleeman
288	Kenworth	09/08/2019 (On Demand)	Preventive	C Service @ 594820kms - Calvin Jack
288	Kenworth	25/07/2019 (On Demand)	Corrective	R&M 965 - replaced beacon - Matt Doyle
288	Kenworth	16/07/2019 (On Demand)	Corrective	R&M 981 - replace LH spring bolt and bush - Calvin Jack
288	Kenworth	16/07/2019 (On Demand)	Corrective	remove pin from spring hanger front axle and fit new one - Ken Wittmann

288	Kenworth	04/06/2019 (On Demand)	Preventive	Brake Test 9.9m - Salvatore Leonardi
288	Kenworth	04/06/2019 (On Demand)	Preventive	B Service & defects - Salvatore Leonardi & Scott Healing
288	Kenworth	24/05/2019 (On Demand)	Preventive	D Service - Tom Kerlin
288	Kenworth	24/05/2019 (On Demand)	Preventive	D Service - Ross Wise
288	Kenworth	04/05/2019 (On Demand)	Preventive	Service checklist Odometer reading: 576 875
288	Kenworth	02/05/2019 (On Demand)	Corrective	Radiator support rubber - Salvatore Leonardi
288	Kenworth	09/04/2019 (On Demand)	Corrective	Changed light plug - scott healing
288	Kenworth	29/03/2019 (On Demand)	Corrective	R&M 858 - LHS mirror. - Scott Healing
288	Kenworth	27/03/2019 (On Demand)	Corrective	Kenworth Mirror Cover - Paint ice white. - Truck Bake

				<p>Proceed to site/job and inspect air con. Found massive internal failure of compressor. Advice Matt that truck needs to come back to workshop for further inspection as shrapnel has most likely been shot through entire system. Uninstalled the air on systems drier and found the new drier. Remove compressor off of truck and install new compressor. Remove all hoses from system including TX. Flush condenser out - no metal shavings. Flush evaporator. Start making new hose. Install new TX valve with new o-rings. Run new hoses for system. Install new drier/ Flush evaporator. Hook up all the lines. Vac system down. P clamp and cable tie in, Make sure all hoses were secure and put new belt on. Pack up and tidy up. Gas system - all went well accordingly, system was cycling. All good sent truck.</p>
288	Kenworth	18/03/2019 (On Demand)	Corrective	
288	Kenworth	12/03/2019 (On Demand)	Corrective	<p>Proceeded to sit and inspected Navman no working correctly. Checked power supplies and all had power feeds where needed. Faulty Qube unit. Recommend replacement of Navman. - Kenny's Auto Electrical</p>
288	Kenworth	04/03/2019 (On Demand)	Corrective	<p>R&M 863 Adjusted clutch, R&M 870 changed out air switch - Scott Healing</p>

288	Kenworth	27/02/2019 (On Demand)	Corrective	Checked systems and loaded test battery's, removed hold down straps and cleaned all terminals and all start leads, reconnected and rechecked starting system, checked each bank of battery's and checked current draw, battery link lead was faulty so fabricated and installed a new lead and checked operation and charging. Cranston Auto Electrical
288	Kenworth	25/02/2019 (On Demand)	Corrective	4 x new tyres @556849. - Twin City Tyres
288	Kenworth	23/02/2019 (On Demand)	Scheduled	Full greased service Service full truck & clean up. Salvatore Leonardi
288	Kenworth	23/02/2019 (On Demand)	Preventive	B service @556854. Tom Kerlin
288	Kenworth	23/02/2019 (On Demand)	Corrective	R&M 861 - repaired power steering fluid hose leaking - Tom Kerlin
288	Kenworth	13/02/2019 (On Demand)	Corrective	Female & Male Coupling - 24 Hour Hose
288	Kenworth	08/02/2019 (On Demand)	Corrective	R&M 852 - air horn started working again, Jason Drury truck driver reported
288	Kenworth	29/01/2019 (On Demand)	Corrective	Trouble shoot. hard to start fault. changed oil fitting- Scott Healing
288	Kenworth	29/01/2019 (On Demand)	Corrective	Trouble shoot hard to start fault, changed oil fittings - Scott Healing
288	Kenworth	23/01/2019 (On Demand)	Corrective	R&M 847, 848, 849 - RHS indicator repaired, RHS tail light repaired, truck stopped blowing smoke after electrical issues fixed - Scott Healing
288	Kenworth	23/01/2019 (On Demand)	Corrective	Changed out batteries, connected lap top and checked systems. Scott Healing
288	Kenworth	17/12/2018 (On Demand)	Corrective	R&M - Twin City Tyres

288	Kenworth	07/12/2018 (On Demand)	Corrective	R&M Goodyear Bowen
288	Kenworth	01/12/2018 (On Demand)	Corrective	Changed airbag and cab stopper. Matt Doyle
288	Kenworth	31/10/2018 (On Demand)	Preventive	B Service @ 536998 - Scott Healing
288	Kenworth	29/10/2018 (On Demand)	Corrective	Changed tyre. Ken Wittmann
288	Kenworth	20/10/2018 (On Demand)	Corrective	Changed out top torque rod bushes on rear axle. Matt Doyle
288	Kenworth	19/10/2018 (On Demand)	Corrective	Picked up new track rod bushes, removed bottom rack rod beams, removed and installed new bushes, fitted back to truck. Matt Dolye, Ken Wittmann
288	Kenworth	05/10/2018 (On Demand)	General Maintenance	Brake Test - 5.10.18
288	Kenworth	12/09/2018 (On Demand)	General Maintenance	Baxters - Starter motor report claim
288	Kenworth	27/08/2018 (On Demand)	Corrective	Installed fan belt. Scott Healing
288	Kenworth	10/08/2018 (On Demand)	Corrective	Fit new key Barrel, help Matt fit starter motor. Ken Wittmann
288	Kenworth	06/08/2018 (On Demand)	Corrective	Changed out starter motor. Scott Healing
288	Kenworth	10/07/2018 (On Demand)	Corrective	Adjusted brakes and tested. Scott Healing
288	Kenworth	25/06/2018 (On Demand)	Corrective	Kennys Auto - repairs to navman and camera
288	Kenworth	06/06/2018 (On Demand)	Corrective	24hr hose - manufacture and supply compressor hose
288	Kenworth	06/06/2018 (On Demand)	Corrective	Changed air line, belt tensioner, fixed oil pressure gauge, checked power divider works, did oil samples on engine, gearbox and diffs, realigned the steering wheel. Scott Healing

288	Kenworth	06/06/2018 (On Demand)	General Maintenance	R&M 743, 744, 745 - repairs all rectified, power divider, oil pressure, fan belt by Scott Healing
288	Kenworth	06/06/2018 (On Demand)	Preventive	Hastings - trans Oil Sample 12409510
288	Kenworth	06/06/2018 (On Demand)	Preventive	Hastings - Diff Front Oil Sample - 12409534
288	Kenworth	06/06/2018 (On Demand)	Preventive	Hastings - Diff rear oil sample - 12409535
288	Kenworth	06/06/2018 (On Demand)	Preventive	Hastings - Engine oil sample - 12409627
288	Kenworth	31/05/2018 (On Demand)	General Maintenance	R&M 742 - new uhf fitted by Matt Doyle
288	Kenworth	16/05/2018 (On Demand)	Corrective	Fitted battery hold down bracket. Scott Healing
288	Kenworth	14/05/2018 (On Demand)	Corrective	Changed battery. Scott Healing
288	Kenworth	14/05/2018 (On Demand)	Corrective	SOS Diesel - Engine brake fault, replaced engine ECU
288	Kenworth	09/05/2018 (On Demand)	Corrective	Kennys Auto - diagnose why engine brake staying on - faulty ECM
288	Kenworth	04/05/2018 (On Demand)	Preventive	Hastings - trans oil sample - 12294805
288	Kenworth	02/05/2018 (On Demand)	Preventive	Broke up B double unit, Put B trailer onto pit, did full D service, adjusted brakes, changed brake shoes and drum on middle axle. Replaced 3 side lights, rplaced flat tyre on driver side rear axle, changed out kingpin. Changed RHS middle axle brake booster and air lines. Scott Healing
288	Kenworth	01/05/2018 (On Demand)	Preventive	D Service @ 529940 - Scott Healing
288	Kenworth	01/05/2018 (On Demand)	Preventive	Brake Test - Scott Healing
288	Kenworth	01/05/2018 (On Demand)	Preventive	B Service - Scott Healing

288	Kenworth	01/05/2018 (On Demand)	Preventive	Changed Batteries, changed engine and gearbox oils, sampled all oils, did a full checkover, brake test. Scott Healing
288	Kenworth	01/05/2018 (On Demand)	Preventive	Hastings - engine oil sample - 12294734
288	Kenworth	01/05/2018 (On Demand)	Preventive	Hastings - diff rear oil sample - 12294806
288	Kenworth	01/05/2018 (On Demand)	Preventive	Hastings - diff front oil sample - 12294807
288	Kenworth	30/04/2018 (On Demand)	Corrective	Brown & Hurley - repairs as outlined in invoice
288	Kenworth	21/02/2018 (On Demand)	Corrective	Brown & Hurley - inspection after lightning strike
288	Kenworth	21/02/2018 (On Demand)	Corrective	Kenny's - Diagnose truck alarm after truck struck by lightening
288	Kenworth	20/02/2018 (On Demand)	Corrective	Drove to stadium to look at truck with Kenny's, Tyrone reckons truck was struck by lightening. Walked around truck found 4 blown tyres and burn marks on the ground as well as blown sensors on the engine and a few other defects. Truck to be taken to Brown and Hurley. Matt Doyle
288	Kenworth	09/02/2018 (On Demand)	Corrective	Change fan belt and tensioner. Camden Redgrave
288	Kenworth	05/02/2018 (On Demand)	Corrective	Fit new park brake. Ken Wittmann
288	Kenworth	03/02/2018 (On Demand)	Corrective	Diagnose air leak on truck and repair. Tom Kerlin
288	Kenworth	22/01/2018 (On Demand)	Corrective	Remove controlbox for PTO, fit new control lever and fit everything back together and test. Ken Wittmann

288	Kenworth	19/01/2018 (On Demand)	Corrective	Change starter motor, rectify air leak, change cab ari bag, change bump stop on cab. Camden Redgrave
288	Kenworth	17/01/2018 (On Demand)	Corrective	Jump start truck, diagnose air pressure differences, found faulty gauge. Install gauges in truck. Camden Redgrave /Thomas Kerlin
288	Kenworth	16/12/2017 (On Demand)	Preventive	D Service @ 524189kms (Camden Redgrave) changed 2 x leaking pressure protection valves
288	Kenworth	07/12/2017 (On Demand)	Corrective	R & M 655 - Reverse alarm not working (intermittent, comes on while going forward) - Fixed by Camden Redgrave; New reverse switch installed
288	Kenworth	06/11/2017 (On Demand)	Corrective	R & M 641 - Air leak at park brake switch valve in cab - Reinspected air leak has stopped will monitor (Camden Redgrave)
288	Kenworth	18/10/2017 (On Demand)	Corrective	Finished defects and seat arm rest. Matt Doyle
288	Kenworth	17/10/2017 (On Demand)	Corrective	Change front drive axle brakes. Camden Redgrave B Service, removed front drive axle wheels and brakes. Fixed passenger side window switches. Started removing broken bolt from drivers seat arm rest. @511731. Matt Doyle
288	Kenworth	17/10/2017 (On Demand)	General Maintenance	B Service - @511731. Matt Doyle

288	Kenworth	30/09/2017 (On Demand)	Corrective	A/C Compressor wouldnt cut in and was sounding alarm. Found and repaired rubber wire to clutch, stop the alarm but wouldnt engage clutch. By-passed hi low pressure cut out switch and clutch engaged. Changed pressure switch. Matt Doyle
288	Kenworth	25/09/2017 (On Demand)	Corrective	Remove drive shaft and centre bearing to get access to output yolk, changed yolk nut, tightened nut to set preload on output bearings, lifted drive shaft back up. Test drive. Matt Doyle
288	Kenworth	18/09/2017 (On Demand)	Corrective	Remove tailshaft, tighten yoke nut. Refit tailshaft @ 505903 kms (Camden Redgrave)
288	Kenworth	26/08/2017 (On Demand)	Corrective	Adjust brakes on trucks and trailers @ 501900 kms (Camden)
288	Kenworth	17/08/2017 (On Demand)	Corrective	Replaced leaking pressure switch under dash pack up @ 499860 hrs (Camden Redgrave)
288	Kenworth	11/08/2017 (On Demand)	Corrective	Clutch adjustment @ 499860 hrs (Camden Redgrave)
288	Kenworth	13/07/2017 (On Demand)	Preventive	Degrease transmission, fit cover/side guard. Camden Redgrave
288	Kenworth	12/07/2017 (On Demand)	Corrective	Diagnose and repair low oil pressure fault on gear box. Transmission. Camden Redgrave
288	Kenworth	11/07/2017 (On Demand)	Corrective	Continue with gear box install, flywheel housing. @ 492547. Camden Redgrave

288	Kenworth	10/07/2017 (On Demand)	Corrective	Disassemble front of transmission, make tool in lathe to remove and fit cross shaft bushes. Reassemble front of gear box, fit new cross shaft bushes. Remove rear main seal, remove flywheel housing. @492547. Camden Redgrave
288	Kenworth	08/07/2017 (On Demand)	Preventive	Remove transmission, fuel tank and accessories. wash transmission. @492547. Camden Redgrave Remove gearbox. Larry Pegoraro
288	Kenworth	06/07/2017 (On Demand)	Preventive	Started C service (Matt Doyle)
288	Kenworth	12/06/2017 (On Demand)	Preventive	Brake Test. (Camden Redgrave)
288	Kenworth	25/05/2017 (On Demand)	Corrective	Clutch adjustment and brake adjustment(Camden Redgrave)
288	Kenworth	19/05/2017 (On Demand)	Corrective	Put new bush in gear stick (Tom Nugent)
288	Kenworth	24/04/2017 (On Demand)	Corrective	Adjust brakes, diagnose headlight fault. Camden Redgrave
288	Kenworth	21/03/2017 (On Demand)	Preventive	Brake test carried out = stopping distance 10.4 mtrs (Camden Redgrave)
288	Kenworth	20/03/2017 (On Demand)	Preventive	B service carried out @ 472559 kms; Replaced cab airbag, replaced leaking hobbs swithc under dash, bypass the heater valve and turn off the heater taps (Camden Redgrave)

288	Kenworth	07/03/2017 (On Demand)	Corrective	Travel to vehicle, diagnose air not building. found compressor head to have an issue, Got vehicle to depot, changed out compressor, inspect all check valves @ air tanks. All ok. TEst drive okay. @ 470113kms, Camden Redgrave
288	Kenworth	04/03/2017 (On Demand)	Corrective	Clean boost pressure sensor. @469524. Camden Redgrave
288	Kenworth	06/02/2017 (On Demand)	Corrective	Diagnose boost leak, rectify and test - ok @ 465420 kms (Camden Redgrave)
288	Kenworth	03/02/2017 (On Demand)	Corrective	Diagnose why engine won't crank , checked batteries - ok. Found broken wire and starter motor and replay. Replaced wire, test - ok (Camden Redgrave)
288	Kenworth	02/02/2017 (On Demand)	Preventive	Brake test carried out - stopping distance 10.3mtrs (Camden Redgrave)
288	Kenworth	16/01/2017 (On Demand)	Corrective	Replaced A/C belt tensioner, clutch adjustment. Find air leaks @ 463454 kms (Camden Redgrave)
288	Kenworth	13/01/2017 (On Demand)	Corrective	Remove leaking exhaust flex, remove cab skirting replaced 1 x cab mount RH side, removed boost hose at turbo (Camden Redgrave)
288	Kenworth	12/01/2017 (On Demand)	Preventive	Brake Test carried out = stopping distance 11mtrs
288	Kenworth	11/01/2017 (On Demand)	Corrective	Refit exhaust, fit boost hose @ 462394 kms (Camden Redgrave)
288	Kenworth	21/12/2016 (On Demand)	Preventive	D Service carried out @ 462199 kms (Camden Redgrave)

288	Kenworth	21/12/2016 (On Demand)	Corrective	'D' service, RH rear drive wheel seal, RH rear drive brake shoe, brake test. (Camden Redgrave)
288	Kenworth	03/11/2016 (On Demand)	Preventive	B service carried out @ 453657 kms (Brian Ovenden - SOS Diesel) Defects identified to be monitored; Front cab mounts cracked and split. RH front and rear drive brakes low (to be repaired next service)
288	Kenworth	26/10/2016 (On Demand)	Corrective	Fit new mud flaps and rubbers between mudguards @ 453657 kms (Larry Pegoraro)
288	Kenworth	16/09/2016 (On Demand)	Corrective	Travel to broken down truck, remove side step, found rose joint was broken, replace joint with new one, Refit rod and side step, travel back (Camden Redgrave)
288	Kenworth	21/07/2016 (On Demand)	Preventive	Rectify air building issue, replaced D2 Governor @ 436348 kms (Camden Redgrave)

288	Kenworth	26/04/2016 (On Demand)	Corrective	R+M # 528 - Remove fan hub, alternator, Idlers, Horton Solenoid, Disassemble solenoid, Refit solenoid. Disassemble fan hub, fit fan hub with outback kit - test operation. Refit hub, replace idler bearings. Remove crankshaft pulley and inspect - had wear on V-grooves - Replaced crank pulley. Refit alternator. Test operations - minor air leak at fan hub. Remove front of hub and seal thread - refit + test - Ok.
288	Kenworth	29/03/2016 (On Demand)	Corrective	Jump start truck and test batteries, found 2 had no charge at all - order 2 new batteries and fit (Ken Wittmann)
288	Kenworth	29/03/2016 (On Demand)	Preventive	Brake Test Completed - Stopping Distance: 12.8m (Camden Redgrave)
288	Kenworth	24/03/2016 (On Demand)	Corrective	Take off steel plate that holds A/C condenser in place. Workshop weld broke, piece back together & add plate for strength. Drill holes & paint plate. Fit plate back on truck. (Ken Wittmann)
288	Kenworth	24/03/2016 (On Demand)	Scheduled	B Service carried out @ 432897 kms. Repaired broken A/C condensor mounts. Replaced leaking pinion seal on front diff. (Camden Redgrave)
288	Kenworth	09/02/2016 (On Demand)	Preventive	Start removing 2 airlines to governor valves and repair, fit panels back on truck and fix air leak heater control @ 432875 kms (Ken Wittmann)

288	Kenworth	19/01/2016 (On Demand)	Corrective	Replace air line on govenor valve @ 432056 kms (Ken Wittmann)
288	Kenworth	05/01/2016 (On Demand)	Preventive	D Service carried out @ 431884 kms (Sam Previtera)
288	Kenworth	05/11/2015 (On Demand)	Corrective	Fit new hose from AC compressor to condensor. Tidy up harness and lines, help gas a/c @ 424132 kms (Will Nicholas)
288	Kenworth	05/11/2015 (On Demand)	Corrective	C/O A/C compressor and receiver dryer, pressure check found hose u/s, built hose @ 424132 kms (Ross Wise)
288	Kenworth	26/09/2015 (On Demand)	Preventive	B Service carried out @ 414530 kms (Sam Previtera)
288	Kenworth	18/09/2015 (On Demand)	Corrective	R & M 490 - Need new heater hose adaptor on fire wall - Inspected by Camden Redgrave To Be monitored
288	Kenworth	18/08/2015 (On Demand)	Corrective	4 x Tyres @ Advantage Tyres
288	Kenworth	17/07/2015 (On Demand)	Corrective	Repair mirror cover @ 397963 kms (Sam Previtera)
288	Kenworth	16/07/2015 (On Demand)	Corrective	SOS Diesel - Change out pyrometer with unit supplied. Repaired operation of gauge due to bad connector to gauge in dash.
288	Kenworth	16/07/2015 (On Demand)	Corrective	Air dryer and pyrometer sensor installed @ 397695 kms (SOS Diesel)
288	Kenworth	27/06/2015 (On Demand)	Preventive	B & C Service carried out @ 392500 km's (Ken/Sam)
288	Kenworth	25/06/2015 (On Demand)	Corrective	R & M 483 - Front engine Mount needs replacing - Fixed by Ken Wittman & Sam Previtera new engine mount installed

288	Kenworth	09/06/2015 (On Demand)	Corrective	Fit 4 new tyres @ 386188 kms
288	Kenworth	26/05/2015 (On Demand)	Preventive	Carry out B-service @ 381422 kms (Sam Previtera)
288	Kenworth	25/05/2015 (Five Yearly)	Preventive	Noise Survey
288	Kenworth	07/05/2015 (On Demand)	Corrective	Drain air tank and lubricate signal lines for air dryer (Steve Nicol)
288	Kenworth	07/04/2015 (On Demand)	Corrective	Check over and topped up hyd tank, fixed power outlet for fridge, replace steering uni and turn table grease nipples, freed up air coupling @ @ 708609 kms (Steve Nicol)
288	Kenworth	04/02/2015 (On Demand)	Corrective	Several lights require attention for auto leccy (as per D service inspection) - Inspected by Kenny's and lights are working fine
288	Kenworth	31/01/2015 (On Demand)	Corrective	Clutch adjustment @ 360188 kms (Ken & SOS)
288	Kenworth	29/01/2015 (On Demand)	Corrective	B Service carried out; Rear engine mounts fixed, broken mudguard bracket fixed, dash indicator lights fixed, rear torque bushes fixed @ 360188 kms (SOS Diesel)
288	Kenworth	29/01/2015 (On Demand)	Preventive	Adjust brakes and brake percentage @ 359773 kms (Ross)

288	Kenworth	29/01/2015 (On Demand)	Corrective	SOS Diesel - B Service and Roadworthy Check over, engine tune up; Removed air intake system to gain access and remove rocker cover. Carried out full valve injector and engine brake adjustment. Resassembled with new valve cover gsk. B Service and roadworthy check then carried out as per service sheet. Defects repaired: C/O out torn rear engine mounts, C/O belts, Repair R/H dash indicator light not working, replaec broken L/H rear mudguard bracket, c/o all 8 torn torque road bushes.
288	Kenworth	29/01/2015 (On Demand)	Corrective	Windscreen changed out (Instant windscreen), rear engine mounts fixed, broken mudguard bracket fixed, dash indicator lights fixed, rear torque rod bushes fixed @ 360188 kms (SOS Diesel)
288	Kenworth	17/11/2014 (On Demand)	Corrective	Fit plug and repair right front rear guard @ 355614 km's (Ken)
288	Kenworth	09/08/2014 (On Demand)	Corrective	Fit new drive tyres @ 350617 hrs (Ken)
288	Kenworth	19/06/2014 (On Demand)	Preventive	Fit new battery @ 348270 hrs (Ken)
288	Kenworth	28/04/2014 (On Demand)	Preventive	Fit new airbags to cab. Fix exhaust leak at flex pipe. Move clamp around turbo it was pushing on steel plate @ 327465 hrs (Ken)
288	Kenworth	21/04/2014 (On Demand)	Preventive	New turbo fitted by cummins @ 322571 hrs
288	Kenworth	04/04/2014 (On Demand)	Preventive	B Service and check over @ 316347 hrs

288	Kenworth	04/04/2014 (On Demand)	Preventive	Service, change out engine oil, change out oil, fuel, air and diff filters @ 316347 hrs (Ross)
-----	----------	-------------------------------	------------	--