Hazard Register



Type STUMP GRINDER
Make STUMP HUMPER

Model 1800D

Serial Number

LocationSelectSale Number7035552Lot Number0045Vendor118305-8

ID	Hazard Type	Hazard Description
127905.1	Mechanical	ENTANGLEMENT/STRUCK BY POWER TAKE OFF (PTO), LINKAGE AND OR OTHER SPECIFIED HITCHING POINTS
127905.2	Guarding	STRUCK BY WORKPIECES OR PARTS OF THE PLANT EJECTING FROM THE PLANT. ENSURE GUARDING IS ON PLACE AND MEETS AS4024.1.
127905.3	Mechanical	UNINTENDED MOVEMENT OF THE PLANT AND OR MACHINERY
127905.4	Plant Operation	CONTROLS AND MECHANICAL FAILURE OF PLANT AND OR MACHINERY
127905.5	Noise	NOISE. IF LEVEL ABOVE 85dBa HEARING PROTECTION AND SIGNAGE SHOULD BE DISPLAYED.
127905.6	Controls	OBTAIN OCUMENTED INSTRUCTIONS PROVIDED FOR THE PLANT AND OR OPERATOR CONTROLS NOT CLEARLY LABELLED.
127905.7	Plant Structure	MACHINERY TIP-OVER DURING LOADING/UNLOADING ON TRANSPORTER
127905.8	Plant Operation	PLANT OT BE OPERATED BY A TRAINED/COMPETENT OPERATOR.
127905.9	Work Space	CONTACT WITH MOBILE PLANT. CONTACT WITH MOVING TEETH OF MACINE.
127905.10	Plant Access	AN EXCLUSION ZONE SHOULD BE ESTABLISHED AROUND PLANT DURING OPERATIONS.
127905.11	Floor Condition	SLIP/TRIP/FALL DUE TO CLIMATE CONDITIONS AND OR GROUND CONDITIONS IN THE VICINITY OF THE PLANT

Hazard Register



Health and Safety Plant Safety Purchaser Information

This plant health and safety information has been prepared by Grays for the purchaser of the plant item as required by National WHS Legislation. Whilst every effort has been made to identify all of the hazards, it should be recognised that all reasonably practicable hazards have been identified given due consideration to:

- state of knowledge about the plant item
- the availability and suitability of ways to eliminate or control the hazards
- · the cost of evaluating, eliminating or controlling the hazard

Consequently, if this plant item is being purchased for use at a place of work, the purchaser is reminded of their obligations to involve and consult with employees in identifying foreseeable hazards, assess their risks and to take action to eliminate or control the risks.

In order to assess the risk, it is necessary to consider for all the identified hazards, the chance (likelihood) of something happening that would impact (consequence) on health and safety at the workplace. The following guidelines are provided to assist the purchaser in consistently carrying out an assessment of risk:

Likelihood

- Frequency and duration of exposure
- Probability of occurrence of hazard or event (including part history of incidents)
- Possibility to avoid / minimize or limit the damage, impact or harm
- Reliability and effectiveness of existing / established systems of control

Consequences

- Assume "worst case" injury, but also competent follow-up medical and rehabilitation support
- Consider forces or energy levels, highest belt tensions, size of gears, pulleys or other entrapment points and therefore body parts likely to be injured
- Consider sharpness of entrapment points, surrounding parts likely to exacerbate injury, and any give in the entrapment point
- Consider, will entrapment continue until plant is stopped, or can an injured part travel through the entrapment area
- Are temperatures of plant, or chemicals, likely to further injure entrapped person

The outcome of the risk assessment will be a prioritised list of risk control strategies and actions consistent with the following ratings:

Low risk- may be considered acceptable, where the existing controls in place are seen to be effective, requiring periodic monitoring for effectiveness. Medium risk- considered to be unacceptable and requiring additional risk controls within medium to long term. High risk – considered to be unacceptable and requiring action within the short to medium term. Extreme risk – unacceptable, where immediate action required.

In all of these cases employees/operators must be made aware of the risk controls in place to protect them from the hazards.