



Vehicle History Detail



Fleet #	XN67EE
Registration	XN67EE
Make	KENWORTH
Model	K200
VIN / Chassis #	6F5000000JA463586

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1793	06/12/2022	0	0	Callout	Dylan			\$314.24
S-2647	02/11/2022	0	0	A - Fortnightly				\$165.00
S-2657	02/11/2022	871736	0	A - Fortnightly				\$165.00
R-1608	23/09/2022	812262	0	Clutch		truck went to canberra trucks to have clutch replaced Truck presented with clutch problems removed gearbox remove clutch and pressure plate remove flywheel and send for machining clean back of bellhousing and engine fit flywheel fit new clutch kit, spiggot, and throw out bearing fit gearbox test drive _____ Replaced door latch drivers remove front diff and re seal replace x8 torque rod bushes carry out tune up replace exhaust gasket		\$7,977.62
S-2621	06/09/2022	855347	0	C - 150k + RTA Insp.	Dylan			\$1,082.39
R-1702	23/08/2022			Speedometer		FIT NEW SPEEDO CLEAN SPEEDO SENSORS		\$143.00
R-1609	18/07/2022	812262	0	Speedometer		sent speedo away to be repaired then refitted it and clean speed sensors		\$464.92
R-1651	20/06/2022			Lights				\$640.20

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1616	16/06/2022	0	0	Brakes				\$713.35
R-1555	11/05/2022	0	0	Heater Tap		Replaced heater tap grease clutch and remove clutch grease interril No Parts number and no box for part. Part was in stock so no order number.		\$214.50
R-1540	03/05/2022			Electronic Diary	Jack	Removal of Electronic Diary NAVMAN Unit		\$35.75
R-1525	27/04/2022	0	0	blower fan		FIXED TEMPERATURE CONTROL WIRE ON CAB FRIDGE REPLACED BLOWER FAN REPLACED SPEED SENSORS		\$1,366.07
S-2543	02/04/2022	812262	0	B - 50k				\$684.93
R-1463	19/02/2022	0	0	Battery		replace batteries		\$878.80
S-2544	29/01/2022	696798	0	D - 300k	Dylan			\$1,391.87
R-1477	19/01/2022	0	0	Shock Absorbers	Dylan, Jack			\$869.00
O-174	05/10/2021	0	0	CTP				\$1,776.86
O-173	05/10/2021	0	0	Registration			SN-362653136	\$4,703.60
S-2344	29/09/2021	670480	0	B - 50k				
R-1351	07/09/2021	0	0	ad blue	Kobi	replace doser pump		
R-1315	28/07/2021	0	0	Air Compressor	Kobi	REPLACED VALVE built up air releasing correctly		

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1116	08/07/2021			Cab - Step		remove steps and took to muirhead engineering to have repaired then drilled and added extra bolts to prevent this happening again refit steps		\$0.00
S-2308	08/07/2021	645033	60218	A - Fortnightly	Dylan			\$181.90
T-366	06/07/2021	0	0	Recamic		8x recamic cap and case	103796	\$3,753.00
T-357	18/06/2021	0	0	Strip & Fit		1x strip and fit 1x truck tyre disposal	103624	\$88.50
S-2271	18/06/2021	631225		A - Fortnightly	Dylan			\$181.90
S-2234	04/06/2021	621297	0	A - Fortnightly	Dylan	Greased clutch		\$165.00
R-1198	18/05/2021	0	0	Ad Blue Tank	Kobi	replaced ad blue cap		\$81.20
S-2190	17/05/2021	601026	0	B - 50k	Dylan, Kobi			\$576.93
R-1163	06/05/2021	0	0	GPS - Speedo		truck was driven and speedo is fine		\$17.88
S-2154	29/04/2021	594421	0	A - Fortnightly	Dylan			\$165.00
R-1160	29/04/2021	594421		Speed Alert	Jack	Removed old tracking device - blue key		\$71.50
T-313	27/03/2021	0	0	Strip & Fit		1x strip and fit 1x truck tyre disposal	102695	\$88.50
R-1080	22/03/2021	567574	0	Bunk Air Con	Kobi	checked belts both belts loose replace a/c belt with thermo king belt tighten alt belt		\$129.08
S-2037	19/03/2021	569575	0	A - Fortnightly	Dylan, Kobi			\$165.00
T-269	27/02/2021	0	0	New - Steers		2x michelin	102357	
R-1035	22/02/2021			Defect	Yard			\$39.00

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-2006	22/02/2021	551026	0	C - 150k				\$511.85
R-1030	16/02/2021	463586		Doors		Adjusted the door latch pin. Cleaned up	164691	\$37.03
R-997	09/02/2021	541744	0	Cab	Jack	New door card fitted		\$742.39
S-1910	02/02/2021	538236	0	A - Fortnightly	Kobi			\$165.00
R-921	12/01/2021	524975	0	Bunk Air Con	Zane	New bearing fitted Custom Air unit serviced		\$106.39
S-1479	04/01/2021	519837	0	A - Fortnightly	Dylan	Grease turntable		\$165.00
S-948	14/12/2020	510505	0	A - Fortnightly	Dylan			\$147.40
S-938	08/12/2020	507986	0	B - 50k	Jack, Zane			\$719.11
S-853	09/11/2020	489236	0	A - Fortnightly	Dylan			\$93.50
R-646	30/10/2020	483386	0	King Pin	Steve T	close job card cause is dod		\$0.00
R-664	30/10/2020	483386		Steering	Dylan, Kobi	Inspected steering joints, Jacked up front end check for play no play found anywhere, Test drove. Vehicle test driven, no fault found,		\$236.50
O-103	19/10/2020	0	0	CTP				\$1,981.19
O-102	19/10/2020	0	0	Registration				\$4,599.15
S-794	13/10/2020	472066	0	A - Fortnightly	Yard			\$194.77
R-593	30/09/2020			Defect, Wheels	Driver	Took wheel nut covers off		\$35.75
S-740	25/09/2020	462827	0	A - Fortnightly	Yard			\$165.00
R-577	18/09/2020			Speed Alert	Jack	Install Hummingbird Speed alert device		\$224.85
S-610	07/09/2020	442896	0	B - 50k	Kobi, Mick			\$597.19
R-468	28/08/2020	445478		Engine, Exhaust				\$3,708.31
S-558	10/08/2020	425988	0	A - Fortnightly	Yard	Replaced batteries		\$835.16
S-547	29/07/2020	425988	0	B - 50k	Yard	Ad Blue light was on		\$562.45

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
T-108	10/07/2020	0	0	New		2x Michelin 1x truck tyre disposal	141426	\$1,556.50
S-308	06/07/2020	416347	0	A - Fortnightly		centre diff leak through shaft leaking from both seals booked in on 14th of july		\$165.00
R-355	25/06/2020			Electrical	Jack			\$442.59
S-288	24/06/2020	407609	0	A - Fortnightly		Completed A service Check lights, tyres, oil, coolant		\$165.00
R-242	28/05/2020	0	0	Exhaust		Ad blue pump primed with computer		\$71.50
S-245	25/05/2020	387125	0	A - Fortnightly				\$165.00
S-196	18/05/2020	396798	0	D - 300k		duplicated job card created		
S-99	06/05/2020	375851	0	C - 150k				\$881.66
S-172	27/04/2020	371468	0	A - Fortnightly	Yard			\$165.00
S-502	15/04/2020	365693	0	A - Fortnightly		Check for air leaks, coolant level, lights and tyres		\$46.75
S-498	09/04/2020	363859	0	A - Fortnightly		Tightened diff housing bolts 6/4/20		\$174.02
R-151	06/04/2020	361278	0	Differentials, Oil Leak	Dylan, Mick			
R-101	18/03/2020	350554		Bunk Air Con	Jack, Yard	R/R solenoid - done by Jack Part no. 15491-60013 Job card 3466		\$341.49
R-37	17/03/2020	0	0	Engine		repaired		
S-488	16/03/2020	349867	0	A - Fortnightly				\$165.00
T-114	13/03/2020	0	0	New - Drives				
R-84	24/02/2020	355844	0	Safety Equipment	Yard	inspected - no action required		

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-38	11/02/2020	0	0	Brakes	Yard	inspected - no action required		
S-18	07/02/2020	325757	0	B - 50k				\$572.85
S-411	30/01/2020	0	0	A - Fortnightly	Yard	4lt engine oil		\$183.04
T-7	28/01/2020	363859	0	Wear Inspection			140241	\$3,400.00
R-29	28/01/2020	319362	0	Driveline		Refer R-151		
R-28	28/01/2020	319362	0	Suspension	Yard	advised driver no action required - aerodyne		
S-316	02/01/2020	416347	0	A - Fortnightly	Yard	check fan belt pulleys & belt		\$183.04
S-974	17/12/2019	292750	0	A - Fortnightly		rl drive shock		\$165.00
S-1056	22/11/2019	273456	0	B - 50k				\$527.54
S-1057	01/11/2019	258745	0	A - Fortnightly				\$165.00
R-806	28/10/2019			Add Coolant, Add Oil		4ltr cool ELC40 5ltr engine oil - Daniel		\$112.20
S-1053	21/10/2019	253576	0	A - Fortnightly				\$159.50
S-1054	27/09/2019	237684	0	A - Fortnightly				\$165.00
S-1055	02/09/2019	223735	0	A - Fortnightly				\$165.00
S-1255	15/08/2019	213754	0	B - 50k		48ltrs		\$806.65
S-1254	31/07/2019	202613	0	A - Fortnightly				\$165.00
S-1617	19/07/2019	194699	0	A - Fortnightly		4ltrs oil		\$183.04
S-1618	04/07/2019	184698	0	A - Fortnightly		Tighten filler neck hose clamp		\$165.00
S-1718	13/06/2019	169831	0	A - Fortnightly				\$165.00
S-50	23/05/2019	156267	0	C - 150k	Yard	completed		\$914.20
T-225	05/04/2019	0	0	New - Steers		New steers		

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-1616	05/04/2019	125352	0	A - Fortnightly		Top up grease pot, cable tie suzi coils, tighten air blower in cab		\$165.36
S-1657	21/03/2019	115659	0	A - Fortnightly				\$165.00
S-1656	15/03/2019	111287	0	B - 50k				\$646.62
R-1767			0	Windscreen Cracked				\$0.00
100 Records							TOTAL:	\$58,633.03