

VEHICLE DETAILS

VEHICLE IDENTIFICATION NUMBER (VIN): SALCA2AEXFH522329
MODEL: Discovery Sport / L550
ENGINE: 2.2L Diesel
COLOUR: FUJI WHITE
WARRANTY START DATE: 04/06/2015

REGISTRATION COUNTRY:
Not present

Please note that service intervals always represent the maximum time and distance that should exist between servicing. Driving style and conditions may necessitate earlier servicing as indicated by the notifications on your instrument panel.

SERVICE HISTORY

REPAIRER	JOB NUMBER	JOB DATE	ODOMETER	DETAILS
Berwick Jaguar 751 Princes Highway Berwick VIC 3806 Australia	J17515 DISCOVERY	25/09/2023	112,708 km	Work Completed 208,000 km/ 96 months service Related Service Items Not Applicable
Berwick Land Rover 751 Princes Highway Berwick VIC 3806 Australia	J14086 DISCOVERY	19/09/2022	102,218 km	Work Completed 182,000 km/ 84 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter Renewal of Engine Air Filter Renewal of Cam Belt
Berwick Land Rover 751 Princes Highway Berwick VIC 3806 Australia	j240006150 DISCOVERY	07/07/2021	86,924 km	Work Completed 156,000 km/ 72 months service Related Service Items Not Applicable
Berwick Land Rover 751 Princes Highway Berwick VIC 3806 Australia	J240002502 DISCOVERY	30/06/2020	77,377 km	Work Completed 130,000 km/ 60 months service Related Service Items Not Applicable
Berwick Land Rover 751 Princes Highway Berwick VIC 3806 Australia	513059 DISCOVERY	09/07/2019	66,219 km	Work Completed 104,000 km/ 48 months service Related Service Items Not Applicable
Berwick Land Rover 751 Princes Highway Berwick VIC 3806 Australia	508561 DISCOVERY	07/08/2018	55,019 km	Work Completed 78,000 km/ 36 months service Related Service Items Not Applicable

VEHICLE DETAILS

VEHICLE IDENTIFICATION NUMBER (VIN): SALCA2AEXFH522329
MODEL: Discovery Sport / L550
ENGINE: 2.2L Diesel
COLOUR: FUJI WHITE
WARRANTY START DATE: 04/06/2015

REGISTRATION COUNTRY:
 Not present

Please note that service intervals always represent the maximum time and distance that should exist between servicing. Driving style and conditions may necessitate earlier servicing as indicated by the notifications on your instrument panel.

SERVICE HISTORY

REPAIRER	JOB NUMBER	JOB DATE	ODOMETER	DETAILS
Berwick Land Rover Cnr Princes Highway & Clyde Road Berwick VIC 3806 Australia	504781 DISCOVERY	11/08/2017	42,335 km	Work Completed 52,000 km/ 24 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter Renewal of Engine Air Filter Renewal of Fuel Filter
ULR Land Rover 1303 Malvern Road Malvern VIC 3144 Australia	209263 DISCOVERY	25/07/2016	27,106 km	Work Completed 26,000 km/ 12 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter Renewal of Engine Air Filter
ULR Land Rover 1303 Malvern Road Malvern VIC 3144 Australia	200435 DISCOVERY	03/06/2015	16 km	Work Completed Pre-Delivery Inspection Related Service Items Not Applicable