



	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
10/03/2017	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
06/01/2017	RGTWTDCC1CDS119	Dust Suppresn Cannon 1031-01
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	RGTWTDCC1CDS119	Dust Suppresn Cannon 1031-01
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
25/01/2015	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
23/12/2014	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
31/10/2014	MPLHEQTK119	Hino Truck FC Series
03/10/2014	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
	MPLHEQTK119	Hino Truck FC Series
20/02/2014	MPLHEQTK119	Hino Truck FC Series

## **WO Description**

Replace front tyres

12 Monthly service

SEAT AIR ADJUSTMENT. EITHER R

Replace rusted out fuel tank

6 Monthly service

MINOR ISSUES. RHS TAIL LIGHT C

BRAKE FLUID NEEDS TOPPING UP

BRAKE FAULT AND AN ISSUE

12 Monthly Service

EGR fault - P1459/P1458

Brake warning light on dash

BATTERY LIGHT SHOWING ON THE D

CHECK ENGINE LIGHT FLASHING ON

6 Monthly Service

FUEL FILTER LIGHT DISPLAY ON D

WARNING ENGINE LIGHT DISPLAYED

Brake Fluid leak

Remove tow hitch

12 Monthly Service and Inspect

Fit battery isolater/jumpstart

Replace Battery's

Check engine light is on

LOOSING BRAKE FLUID. DONT KNOW

Actuator Status - Not Online

Cab rusty in wheel arches

Tow hitch needs replacing

Replace wiper switch

12 Monthly Service

Replace batteries

WON'T START. POSSIBLE BATTERY

Source parts and service manua

BRAKE ALARM KEEPS APPEARING AT

BROKEN BOLT ON LEFT HAND SIDE

1031-01 Jammed Closing

6 Monthly service

ABS WARNING IN DASH

REAR LEFT TRAFFIC INDICATOR AN

AS PER COI INSPECTION SHEET

LEFT HAND REAR INDERCATOR NOT

12 Monthly service

Repair two way radio fault

Replace a/C belt

12 Monthly service

Replace both front tyres

Possible clutch slipping

FUEL CAP WILL NOT UNLOCK

AIR CON NOT WORKING JUST HOT A

Truck 119 A/C Leaking Water

12 Monthly service

PTO not engaging

6 Monthly Service

Truck 119 A/C Not Cooling

TAIL GATE VERY STIFF AND WILL

EXTERNAL TOOLBOX REQUIRED FOR

AIR CON NOT GETTING COLD

RADIO SPEAKERS REQUIRE CHANGIN

12 Monthly Service

Repair siexed cab stay

Replace RH rear tail lights

REAR BRAKE LIGHTS STAYING ON

RIGHT HAND SIDE TAILGATE PIN R

OVERTAKING SIGN ON TAILGATE TO

replace isolation valve

Truck 119 A/C Not Working

Repair leaking fuel tank

Replace Isolation SW At D/B

Replace battery terminals

Weld up guard back of tray

R/HAND REAR BRAKE LIGHT GUARDI

6 Monthly Inspection

A/C ONLY WORKING WITH FAN ON H

Repair flat tyre

WINDSCREEN WASHERS NOT WORKING

Check clutch adjustment

PTO not disengaging

25000KM SERVICE DUE

Replace drivers side seat belt

REPAIR TRAY AS REQUIRED (SEE N

HOLE IN FUEL TANK

Repair PTO staying on

LHS TAIL GATE LATCH NEEDS WELD

12 monthly service

AIR CON FAN VERY NOISY / LIKE

WATER FOUND IN HYDRAULIC OIL T

Replace batteries

Fire extinguisher bracket in c

Right hand side rear brake lig

## **Description 2**

REPLACE FRONT TYRES

12 MONTHLY SERVICE

SEAT AIR ADJUSTMENT. EITHER RIGHT UP OR ON THE FLOOR, NO IN-BETWEEN

COMPLETED 03/05/23

6 MONTHLY SERVICE

MINOR ISSUES. RHS TAIL LIGHT CONSTANTLY ON. ABS WARNING LIGHT ON (FLUID?).

WORK COMPLETE 16/11/22

HAND BRAKE FAULT AND AN ISSUE WITH THE AIR SYSTEM. (BRAKES/TAILGATE)

COMPLETE - SEE ATTACHMENTS

COMPLETE 31/03/22

SEE ATTACHMENTS

BATTERY LIGHT SHOWING ON THE DASH, ALSO A SMELL LIKE THE BATTERY IS COOKED.

CHECK ENGINE LIGHT FLASHING ON DASH

6 MONTHLY SERVICE

FUEL FILTER LIGHT DISPLAY ON DASH STAYING ON.

WARNING ENGINE LIGHT DISPLAYED ON DASH.

INSPECT / REPAIR

REMOVE TOW HITCH

12 MONTHLY SERVICE AND INSPECT

FIT BATTERY ISOLATER/JUMPSTART

REPLACE BATTERY'S

CHECK ENGINE LIGHT IS ON

LOOSING BRAKE FLUID. DONT KNOW WHERE.

STATUS - CONFIGURATION MODE

CAB RUSTY IN WHEEL ARCHES

TOW HITCH NEEDS REPLACING

REPLACE WIPER SWITCH

12 MONTHLY SERVICE

REPLACE BATTERIES

WON'T START. POSSIBLE BATTERY PROBLEM.

LS

BRAKE ALARM KEEPS APPEARING AT CERTAIN TIMES DURING OPERATION.

BROKEN BOLT ON LEFT HAND SIDE MIRROR MOUNT

NOT MAKING CLOSED LIMIT

6 MONTHLY SERVICE

ABS WARNING IN DASH

REAR LEFT TRAFFIC INDICATOR AND BRAKE LIGHT FAULT

AS PER COI INSPECTION SHEET

LEFT HAND REAR INDERCATOR NOT WORKING

12 MONTHLY SERVICE

REPAIR TWO WAY RADIO FAULT

REPLACE A/C BELT

12 MONTHLY SERVICE

REPLACE BOTH FRONT TYRES

POSSIBLE CLUTCH SLIPPING

FUEL CAP WILL NOT UNLOCK

AIR CON NOT WORKING JUST HOT AIR

A/C UNIT LEAKING WATER INSIDE THE CABIN ON THE FLOOR  
12 MONTHLY SERVICE  
PTO NOT ENGAGING  
6 MONTHLY SERVICE  
AIRCON JUST RUNNING COOL  
TAIL GATE VERY STIFF AND WILL NOT CLOSE PROPERLY  
EXTERNAL TOOLBOX REQUIRED FOR PPE TO GET OUT OF CAB  
AIR CON NOT GETTING COLD  
RADIO SPEAKERS REQUIRE CHANGING  
12 MONTHLY SERVICE  
REPAIR SEIZED CAB STAY  
REPLACE RH REAR TAIL LIGHTS  
REAR BRAKE LIGHTS STAYING ON  
RIGHT HAND SIDE TAILGATE PIN REQUIRES A HANDLE WELDED ON PIN  
OVERTAKING SIGN ON TAILGATE TO BE PUT ON (INSIDE CAB)  
REPLACE ISOLATION VALVE  
A/C NOT GETTING COLD  
REPAIR LEAKING FUEL TANK  
SWITCH WAS USED ON FAULT CC1G D/B SW  
REPLACE BATTERY TERMINALS  
WELD UP GUARD BACK OF TRAY  
R/HAND REAR BRAKE LIGHT GUARDING NEEDS REWELDING  
6 MONTHLY INSPECTION  
A/C ONLY WORKING WITH FAN ON HIGH  
REPAIR FLAT TYRE  
WINDSCREEN WASHERS NOT WORKING  
REPLACE SEIZED THROW OUT BEARING  
PTO NOT DISENGAGING  
25000KM SERVICE DUE  
REPLACE DRIVERS SIDE SEAT BELT  
REPAIR TRAY AS REQUIRED (SEE NOTE BELOW)  
HOLE IN FUEL TANK  
REPAIR PTO STAYING ON  
LHS TAIL GATE LATCH NEEDS WELDING UP. IT IS BROKEN STILL OK TO USE.  
12 MONTHLY SERVICE  
AIR CON FAN VERY NOISY / LIKE IT IS HITTING SOMETHING  
WATER FOUND IN HYDRAULIC OIL TANK (OIL HAS GONE MILKY)  
REPLACE BATTERIES  
FIRE EXTINGUISHER BRACKET IN C  
RIGHT HAND SIDE REAR BRAKE LIG

**Actual Finish Date**

24/07/2023  
16/07/2023  
16/07/2023  
03/05/2023  
27/01/2023  
28/03/2023  
16/11/2022  
26/09/2022  
09/08/2022  
04/04/2022  
29/03/2022  
01/03/2022  
17/01/2022  
16/12/2021  
14/12/2021  
09/11/2021  
07/12/2021  
10/11/2021  
28/06/2021  
28/06/2021  
03/06/2021  
28/04/2021  
09/03/2021  
12/02/2021  
28/06/2021  
16/09/2021  
28/06/2021  
03/06/2021  
02/11/2020  
26/10/2020  
15/09/2021  
17/07/2020  
28/06/2021  
30/06/2020  
13/10/2020  
18/08/2020  
20/04/2020  
06/05/2020  
12/10/2020  
13/05/2020  
11/12/2019  
19/10/2021  
23/05/2019  
28/02/2019  
28/02/2019  
20/02/2019  
23/01/2019

29/11/2018  
10/01/2019  
14/03/2019  
05/05/2020  
07/11/2017  
16/04/2018  
23/09/2019  
04/07/2017  
23/09/2019  
05/05/2020  
28/11/2017  
12/11/2019  
23/09/2019  
12/10/2020  
23/09/2019  
10/01/2017  
16/01/2017  
12/11/2019  
22/06/2018  
16/04/2018  
09/05/2018  
24/01/2017  
25/05/2016  
06/12/2015  
25/05/2016  
25/05/2016  
25/05/2016  
25/05/2016  
25/05/2016  
28/04/2015  
28/04/2015  
07/02/2017  
28/04/2015  
28/04/2015  
28/04/2015  
28/04/2015  
28/04/2015  
16/11/2014  
29/09/2014  
02/10/2014  
25/05/2016  
28/04/2015