



TAX INVOICE

Tax Invoice Number: 1001367

Date: 18/08/2021

Due Date: 18/08/2021


182 Breen Street
 Golden Square Victoria 3555
 ABN: 88514922912
 Tel: 0354414955
 Email: admin@briggsauto.com.au

BILL TO:
Adam Storey
 118 Fitzgibbon Road
 Eppalock Victoria 3551
 Mobile: 0457312910
 Email: adamstorey@bigpond.com

VEHICLE:
 Model: Mazda BT-50
 Reg No: 1UE2DO
 Year: 2012
 Odometer: 197363

Description	Amount
<p>Vehicle came in with engine noise, remove injectors and send for testing, found injectors to be faulty. Replace injectors and code in, remove and replace fuel filter and start vehicle, engine is noisy, suspect internal fault with engine. Prepare vehicle to remove and replace engine. Remove exhaust pipe to engine, undo all wiring, hoses and engine mounts, remove wiper motor assembly, scuttle tray, battery, fuel box, fuel filter, filter bracket, intake pipe, air filter box, alternator, engine fan and de-gas A/C system, undo transmission from engine and remove engine. Place new and old engine together and swap over necessary parts, exhaust manifold and studs, intake manifold/ turbo assembly (replace exhaust manifold gasket and intake manifold seals), replace turbo drain back pipe. Swap high pressure fuel pump and bracketry. Remove fly wheel and machine, replace clutch assembly inc clutch slave cylinder/ release bearing assembly. Remove and replace front diff tube bush. Re fit engine and all parts, including new engine mounts, EGR cooler and EGR valve, water pump assembly, thermostat, drive belt idler pulley and tensioner assembly. Bleed clutch cylinders and re gas A/C system. Flush cooling system and fill with coolant, carry out service on A/C system. Steam clean and road test, check OK.</p>	
Replacement Engine	\$7,250.00
Oil:Synpower FE	\$182.33
Ranger/BT-50 3.2L Fuel Filter	\$32.50
Thermostat	\$34.60
Water Pump	\$373.50
Egr Valve	\$267.36
EGR Cooler	\$395.50
Coolant:G-05 Green	\$50.20
Turbo Drain Back Pipe	\$83.84
Inlet manifold gasket	\$83.70
Exhaust manifold gasket	\$62.64
Gasket	\$32.98
Belt Tensioner Assembly	\$298.93
Idler Pulley	\$89.16
R/H Engine Mount	\$199.62
L/H Engine Mount	\$197.40
Clutch Kit - Heavy Duty	\$958.00
Flywheel	\$90.00
Brake Fluid	\$14.90

Front diff mounting	\$338.69
A/C Regas R134A	\$175.00
Workshop supplies/Waste Disposal	\$20.00
Labour	\$3,850.00
Vehicle requires - Both bottom ball joints. - R/H inner rack end. - Wheel alignment. - Dampener on front of tail shaft. - Front exhaust hanger. - Hand brake needs adjsuting. - Door open light on all the time. - HVAC does not change directions.	



Subtotal	\$13,709.86
GST	\$1,370.99
Total	\$15,080.85
Paid	\$0.00
Balance Due	\$15,080.85

BANK DETAILS

BSB: 083543

Account: 786948142

Name: Briggs Automotive

Book online at www.briggsauto.com.au