Coates Hire Pre Divestment Inspection Checklist			
Air Compressors			
Name AN	MOINE CURTIS		anch MILDURA
	A	Asset #	# 1020053 Service Job #
This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.			
General Information:	*** Copy Data Plate information in this sec	ction ***	1
Make/ Model	X45130	Е	Engine / Motor - Make / Model DEUT2 / D2011 L63
Year	2010	Е	Engine Serial Number 10917602
Serial Number	APP121178	N	Meter Reading 3353
Comments:			
Features:	List features or options for the machine:	_	Comments:
Air Pressure Range	110 PS/ Frame M	_	
Air C.F.M. Rating		∕lount [
Overall Appearance:			
Control Station\Operator Sta Sheet metal\Fiberglass Cond Paint Lights		- -	Comments:
Control Station			
	Operates	C	Comments:
Operator Controls Gauges Operational?	Yes No N/A 21	_	
Engine or Electric Motor:			
Power: Diesel Does it start? Did it need to be jumped? Acceptable Power Unusual Noises	Gas Electric Yes No		Comments:
Chassis	Good Fair Poor I	Inoper N	Missing N/A Comments:
Landing Gear / Outriggers Frame Condition Trailer Lights Trailer Electrical Connection Trailer Brakes Switches Separator Pressure Release Valve Hoses			Comments:
Tyre Condition: Left - Front Left - Rear Comments:			
Brand- HANKOOK	Brand- VITORA		odiline.iie.
Size- 165 8 13 C	Size- 165R 13C		
Condition- FAIR	Condition- FA, R.		
Definium Device fitted?	Yes No		Definium device returned to BU ASM
Issue 1.1		1/	/1/2013 AST-CL-011A Asset Inspection Checklist - Compressor