

Coates Inspection Checklist  
Tools & Equipment (Electric, Pneumatic, Hydraulic or Internal Combustion)

STIHL WHIPPER SNIPPER.

Asset # 1026493

Photos

General Information: \*\*\* Copy Data Plate information in this section \*\*\*

Type of Tool: \_\_\_\_\_  
Make/ Model: FS90  
Year: 2010  
Serial Number: 282 625071

Engine / Motor - Make / Model \_\_\_\_\_  
Engine Serial Number \_\_\_\_\_  
Meter Reading \_\_\_\_\_

☐ Data Plate

Comments:

Features:

List features or options for the machine:

Machine Type:

Frame Mount ☐

Trailer Mount ☐

AC / DC Range \_\_\_\_\_

Engine Horsepower \_\_\_\_\_

Auxiliary Power \_\_\_\_\_

Leads \_\_\_\_\_

Leads Length \_\_\_\_\_

Yes ☐

No ☐

4-Corner Photos

☒ Left-Front Corner  
☒ Left-Rear Corner  
☒ Right-Front Corner  
☒ Right-Rear Corner  
☒ Damage  
☒ Damage  
☒ Damage

Overall Appearance:

Switches/cords ☒ Good ☐ Fair ☐ Poor  
~~Sheet metal/Fiberglass Condition~~ ☐ ☐ ☐  
~~Paint~~ ☐ ☒ ☐  
Fit for Designed Purpose ☐ ☒ ☐

Control Station

Operator Controls ☒ Yes ☐ No ☐ N/A  
Gauges Operational? ☐ ☐ ☒  
Safety Devices ☐ ☐ ☒  
Comments: \_\_\_\_\_

☒ Hour Meter  
☒ Operator Controls  
☒ Safety devices  
☒ Gauges  
☒ Damage  
☒ Damage

Engine or Electric Motor:

Power: Diesel ☐ Petrol ☒ Hydraulic ☐ Electric ☐ Air ☐  
Does it start? ☒ Yes ☒ No  
Did it need to be jumped? ☒ ☐  
Acceptable Power ☒ ☐  
Unusual Noises ☐ ☒  
Comments: \_\_\_\_\_

☒ Right Side  
☒ Left Side

Hydraulics

Operates: Yes ☐ No ☐ N/A ☐  
Leaks: Yes ☐ No ☐ N/A ☐  
Pump ☐ ☐ ☐ ☐ ☐  
Hoses ☐ ☐ ☐ ☐ ☐  
Cylinders ☐ ☐ ☐ ☐ ☐  
Drive Motors ☐ ☐ ☐ ☐ ☐  
Brakes ☐ ☐ ☐ ☐ ☐  
Parking Brakes ☐ ☐ ☐ ☐ ☐  
Comments: \_\_\_\_\_

☐ Pump  
☐ Cylinders  
☐ Drive Motor  
☐ Damage  
☐ Damage  
☐ Damage

Wiring & Lights

Damaged: Yes ☐ No ☐  
Wiring ☐ ☐  
Lights ☐ ☐  
Comments: \_\_\_\_\_

Chassis:

Good Fair Poor Inoper Missing N/A  
Frame Condition ☐ ☒ ☐ ☐ ☐ ☒  
Handles Condition ☐ ☐ ☐ ☐ ☐ ☒  
Lift Points Condition ☐ ☒ ☐ ☐ ☐ ☒  
Guards Condition ☐ ☐ ☐ ☐ ☐ ☒  
Mounting Points ☐ ☐ ☐ ☐ ☐ ☒  
Winching Cable ☐ ☐ ☐ ☐ ☐ ☒  
Comments: \_\_\_\_\_

☐ Frame condition  
☐ Handles/Lifting points  
☐ Guards condition

Tyre Condition:

Left - Front  
Brand- \_\_\_\_\_  
Size- \_\_\_\_\_  
Condition- \_\_\_\_\_  
Left - Rear  
Brand- \_\_\_\_\_  
Size- \_\_\_\_\_  
Condition- \_\_\_\_\_  
Right - Front  
Brand- \_\_\_\_\_  
Size- \_\_\_\_\_  
Condition- \_\_\_\_\_  
Right - Rear  
Brand- \_\_\_\_\_  
Size- \_\_\_\_\_  
Condition- \_\_\_\_\_  
Tire pictures at a 45 degree angle showing the tread and side walls  
☐ Left-Front  
☐ Left-Rear  
☐ Right-Front  
☐ Right-Rear