	Co	pates Inspection Checklis DINGO AND TRAILER	Photos
		Asset # 100105	Tilotos
General Information: Type of Tool: Make/ Model Year Serial Number Comments:	DINGO K9-3 Z012 M0284	Engine / Motor - Make / Model Engine Serial Number Meter Reading 1144	Data Plate
Features:	List features or options for Machine Type: Frame Mount AC / DC Range Engine Horsepower Auxiliary Power	the machine: Trailer Mount Yes No Leads Leads Length	4-Corner Photos Left-Front Corner Left-Rear Corner Right-Front Corner Right-Rear Corner Damage Damage Damage Damage
Overall Appearance: Switches\cords Sheet metal\Fiberglass Condition Paint Fit for Designed Purpose	Good Fair	Poor	
Control Station Operator Controls Gauges Operational? Safety Devices	Operates Yes No N/A	Comments:	Hour Meter Operator Controls Safety devices Guages Damage Damage
Power: Diesel Does it start? Did it need to be jumped? Acceptable Power Unusual Noises	Petrol Yes No	Hydraulic Electric Air Comments: STATOR/FLYWHEEL EXCESSIVE DAMAGE	Right Side Left Side
Hydraulics Oper Yes Pump Hoses Cylinders Drive Motors Parking Brakes Wiring & Lights Dama Yes	No N/A Yes	No N/A Comments: LIHIF BRIVE MOTOR LEAKING Comments:	Pump Cylinders Drive Motor Damage Damage Damage Damage
Wiring	Good Fair	Poor Inoper Missing N/A Comments:	Frame condition Handles/Lifting points Guards condition
Fyre Condition: Left - Front Brand- Size- Condition-	Left - Rear Brand- Size- Condition-	Right-Front Right-Rear Brand- Size- Condition- RIM CRACKED.	Tire pictures at a 45 degree angle showing the tread and side walls Left-Front Left-Rear Right-Front Right-Rear