

Coates Hire Pre Divestment Inspection Checklist

Excavator

Description 12T excavator
2 Buckets

Asset # 1109571

Service Job # 3965684

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information:

*** Copy Data Plate information in this section ***

Make/ Model Cat 312D

Engine/Motor - Make/Model Cat

Year 2012

Engine Serial Number JKH16637

Serial Number RHL00276

Meter Reading 5388

504

Comments:

With 3 Buckets - See Below

Features:

List features or options for the machine:

Cab ☒ Yes ☐ No Front Blade width at the widest point 2400mm
Thumb ☒ Yes ☐ No Rear Bucket width at the widest point NA
Auxiliary Hydraulics ☒ Yes ☐ No
Push Blade ☒ Yes ☐ No

Comments:

Overall Appearance:

Control Station/Operator Station ☐ Good ☒ Fair ☐ Poor
Sheet metal/Fiberglass Condition ☐ Good ☒ Fair ☐ Poor
Paint ☐ Good ☒ Fair ☐ Poor
Lights ☐ Good ☒ Fair ☐ Poor

Comments:

Damage to front of Cabin

Operator Station

Seat Condition ☐ Good ☒ Fair ☐ Poor ☐ N/A
Steering Controls ☐ Good ☒ Fair ☐ Poor ☐ N/A
Control Lock Lever ☐ Good ☒ Fair ☐ Poor ☐ N/A
Powertrain Controls ☐ Good ☒ Fair ☐ Poor ☐ N/A
Hydraulic Controls ☐ Good ☒ Fair ☐ Poor ☐ N/A

Comments:

Operational

Safety Belt ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Gauges ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Air Conditioner ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Heater ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A

Engine

Power: Diesel ☒ Yes ☐ No Gas ☐ Yes ☐ No
Does it start? ☒ Yes ☐ No
Did it need to be jumped? ☒ Yes ☐ No
Acceptable Power ☒ Yes ☐ No
Unusual Noises ☒ Yes ☐ No

Comments:

Drive System

Drive/Propel Motors ☒ Yes ☐ No Operates ☒ Yes ☐ No
Final Drives ☒ Yes ☐ No Operates ☒ Yes ☐ No
Brake and Travel Locks ☒ Yes ☐ No Operates ☒ Yes ☐ No

Comments:

Hydraulics

Pump ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Hoses ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Cylinders ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Drive Motors ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Brakes ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A
Parking Brakes ☒ Yes ☐ No Operates ☒ Yes ☐ No ☐ N/A

Comments:

Quick Hitch v/s High ~~Pressure~~ + replacement Cost.

Chassis

Condition ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Stick ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Boom ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Roller Frame ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Bottom Covers ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Bucket ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Blade ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Wear ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Pin & Bushing Wear at Base Of Boom ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Pin & Bushing Wear on Stick & Bucket ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Turntable Bearing Play ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A

Comments:

Undercarriage

Track Belt (steel / rubber) Width: 550mm Overall Machine Width (Outsides of tracks.) 2400mm
Grouser Height 50mm
Track belt (steel / rubber) ☐ Good ☒ Fair ☐ Poor ☐ N/A
Idlers ☐ Good ☒ Fair ☐ Poor ☐ N/A
Track Rollers ☐ Good ☒ Fair ☐ Poor ☐ N/A
Sprockets ☐ Good ☒ Fair ☐ Poor ☐ N/A
Track Bushings ☐ Good ☒ Fair ☐ Poor ☐ N/A

Comments:

Any other known issues, faults:

includes buckets 1110112, 1110105 1110098