

Tools & Equipment (Electric, Pneumatic, Hydraulic or Internal Combustion)		Photos
Asset # <u>1124972</u> General Information: *** Copy Data Plate information in this section *** Type of Tool: <u>Wrench</u> Make/Model: <u>THORNTON</u> Year: <u>2013</u> Serial Number: _____ Engine / Motor - Make / Model: _____ Engine Serial Number: _____ Meter Reading: _____ Comments: <u>P132-30C-1011</u>		☐ Data Plate
Features: List features or options for the machine: Machine Type: ☒ Frame Mount ☐ Trailer Mount ☐ AC / DC Range: _____ Engine Horsepower: _____ Auxiliary Power: _____ Leads: _____ Leads Length: _____		4-Corner Photos ☐ Left-Front Corner ☐ Left-Rear Corner ☐ Right-Front Corner ☐ Right-Rear Corner ☐ Damage ☐ Damage ☐ Damage
Overall Appearance: Switch/controls: ☐ Good ☒ Fair ☐ Poor <u>Doesn't Start</u> Sheet metal/Fiberglass Condition: ☐ Good ☒ Fair ☐ Poor <u>Case unknown</u> Paint: ☐ Good ☒ Fair ☐ Poor Fit for Designed Purpose: ☐ Good ☒ Fair ☐ Poor		
Control Station Operator Controls: ☐ Yes ☐ No ☒ N/A Gauges Operational?: ☐ Yes ☐ No ☒ N/A Safety Devices: ☐ Yes ☐ No ☒ N/A Comments: _____		☐ Hour Meter ☐ Operator Controls ☐ Safety devices ☐ Gauges ☐ Damage ☐ Damage
Engine or Electric Motor: Power: Diesel ☐ Petrol ☒ Hydraulic ☐ Electric ☐ Air ☐ Does it start? ☐ Yes ☒ No Did it need to be jumped? ☐ Yes ☒ No Acceptable Power: ☐ Yes ☒ No Unusual Noises: ☐ Yes ☒ No Comments: _____		☐ Right Side ☐ Left Side
Hydraulics Operates: ☐ Yes ☐ No ☒ N/A Leaks: ☐ Yes ☐ No ☒ N/A Pump: ☐ Yes ☐ No Hooses: ☐ Yes ☐ No Cylinders: ☐ Yes ☐ No Drive Motors: ☐ Yes ☐ No Brakes: ☐ Yes ☐ No Parking Brakes: ☐ Yes ☐ No Comments: _____		☐ Pump ☐ Cylinders ☐ Drive Motor ☐ Damage ☐ Damage ☐ Damage
Wiring & Lights Wiring: ☐ Yes ☐ No Lights: ☐ Yes ☐ No Comments: _____		
Chassis: Frame Condition: ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A Handles Condition: ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A Lift Points Condition: ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A Guards Condition: ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A Mounting Points: ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A Winching Cable: ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A		☐ Frame condition ☐ Handles/lifting points ☐ Guards condition
Tyre Condition: Left - Front: _____ Left - Rear: _____ Right - Front: _____ Right - Rear: _____		Two pictures at a 45 degree angle showing the tread and side walls ☐ Left-Front ☐ Left-Rear ☐ Right-Front ☐ Right-Rear