Coates Inspection Checklist	
Scissor Lift (Electric or Internal Combustion)	Photos
See Scissor Lift Photo Log for required pictures Asset # 1150841	4
General Information: **** Copy Data Plate information in this section **** Make/ Model N/A Year 2014 Engine / Motor - Make / Model N/A Serial Number B200019114 Meter Reading 285	Data Plate
Comments: Disposla due to Ten year inspection due	
Features: Max Lift Height Flatform size (L x W) Flatform size (L x W) Flatform Extension Platform Extension Flatform Extension Generator Generator	Right-Rear Corner
AC Chord to Platform Air to Platform Outriggers Non-markeing Tires	
Comments:	
Overall Appearance: Good Fair Poor Control Station\Operator Station Sheet metal\Fiberglass Condition Paint Good Fair Poor Good Fair Poor Foor Fo	
Control Station Operates	Hour Meter Ground Controls
Yes No N/A Operator Controls: Platform □ □ Comments: Operator Controls: Ground □ □ □ Gauges Operational? □ □ □	Platform Controls Guages Damage Damage
Engine or Electric Motor:	Right Side hood open
Power: Diesel Gas Dual Fuel Electric Yes No Does it start? Comments: Did it need to be jumped? Acceptable Power Unusual Noises	Left Side hood open
Hydraulics Operates Leaks Yes No N/A Yes No N/A Comments:	Pump
Pump Hoses Cylinders Drive Motors Brakes Parking Brakes Drive Motors Brakes Parking Brakes	Cylinders Drive Motor Damage Damage Damage
Chassis: Good Fair Poor Inoper Missing N/A Comments:	
Frame Condition Scissor Linkage Steering Linkage Work Platform Condition Outriggers and Pads Condition	Scissor Linkage (Extend) Steering Linkage Work Platform
Brand Soildeal Brand Soildeal Brand Brand Soildeal Brand Brand Soildeal Soild	