Coates Inspection Checklist Scissor Lift (Electric or Internal Combustion)				
See Scissor Lift Photo Log for re	equired pictures		Asset #	1153013
Make/ Model JLG Year Serial Number 90003	2015 900035850		* e / Motor - Make / Model e Serial Number Reading	
Comments: Due 10 year inspec	otion			
Orive Syatem 2WD □	4WD 🗍		Max Lift Height Platform size (L x W)	
Platform Extension AC Chord to Platform Air to Platform Comments:	Yes No	Gener Outrig		Yes No  Control  Cont
Overall Appearance:				
Control Station\Operator Station Sheet metal\Fiberglass Condition Paint	Good Fair ■ □ ■ □	Poor		
Control Station				
Operator Controls: Platform Operator Controls: Ground Gauges Operational?	Operates  S No N/A	Comments:		
Power: Diesel  Yes  Does it start?  Did it need to be jumped?  Acceptable Power  Unusual Noises	Gas	Dual Fuel  Comments:	Electric <b>I</b>	
Hydraulics			_	
Operates Yes No Pump		eaks No N/A ■ ■ ■	Comments:	
Chassis:	Good Fair	Poor Inope	er Missing N/A Comm	oente:
Frame Condition Scissor Linkage Steering Linkage Work Platform Condition Outriggers and Pads Condition				rm cage damaged
Tire Condition:				
Left - Front Brand- Size- Condition-	Left - Rear Brand- Size- Condition-		Right- Front  Brand- Size- Condition-	Right - Rear  Brand- Size- Condition-