

# Coates Hire Pre Divestment Inspection Checklist

## Trucks / Motor Vehicles

Description 7000L water cart Asset # 740945 Service Job # 4072582

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at [www.coateshire.com.au](http://www.coateshire.com.au).

General Information: **\*\*\* Copy Data Plate information in this section \*\*\***

Make/Model Mitsubishi Fighter Engine/Motor - Make/Model \_\_\_\_\_  
 Year 2006 Engine Serial Number \_\_\_\_\_  
 Serial Number JLFFM61FH0K00043 Meter Reading 62,502

Comments: \_\_\_\_\_

Features:  
 Pickup  Flat Bed  Dump  Boom  Other  Comments: \_\_\_\_\_  
 Drive System 2WD  4WD  Power Take Off  Yes  No   
 Axle Weights Rating: Front 5100  
 Axle Weights Rating: Rear 9000  
 Registration Information Number \_\_\_\_\_ Year \_\_\_\_\_

Overall Appearance:  

	Good	Fair	Poor	Comments:
Control Station/Operator Station	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>rear bar bent + split, RH mirror broken,</u>
Sheet metal/Fiberglass Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Paint	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Operator Station  

	Good	Fair	Poor	N/A	Comments:
Seat Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Steering Controls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Powertrain Controls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Hydraulic Controls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

  

	Operates			Operates		
	Yes	No	N/A	Yes	No	N/A
Safety Belt	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Gauges	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Warning Alarms	<input type="checkbox"/>	<input type="checkbox"/>
Air Conditioner	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Odometer	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Engine or Electric Motor:  
 Power: Diesel  Gas  Comments: \_\_\_\_\_  
 Does it start?  Yes  No \_\_\_\_\_  
 Did it need to be jumped?  Yes  No \_\_\_\_\_  
 Acceptable Power  Yes  No \_\_\_\_\_  
 Unusual Noises  Yes  No \_\_\_\_\_  
due for service + annual backflow test,  
rocker cover leaking,

Transmission  
 Transmission Auto  Manual  Hydrostatic  No. Speeds \_\_\_\_\_ Comments: \_\_\_\_\_  

	Operates			Operates		
	Yes	No	N/A	Yes	No	N/A
Forward	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Clutch	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Reverse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Parking Brake	<input type="checkbox"/>	<input type="checkbox"/>
Shifting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Chassis  

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Bumpers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>missing battery cover,</u>
Windshield Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Trailer Electrical Connections	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Work Body Function	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

tow point mount bent

Tyre Condition:  

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- <u>Double coin</u>	Brand- <u>Dunlop</u>	Brand- <u>Double coin</u>	Brand- <u>Dunlop</u>
Size- <u>275/70 R22</u>	Size- <u>275/70 R22</u>	Size- <u>275/70 R22</u>	Size- <u>275/70 R22</u>
Condition- <u>good</u>	Condition- <u>Fair</u>	Condition- <u>Fair</u>	Condition- <u>POOR</u>

 Full Name of Employee completing inspection: \_\_\_\_\_ Branch where inspection completed: \_\_\_\_\_

Any other known issues, faults: Front LH tyre ds, RHR tyre damaged side wall.  
Section hose damaged, Fire hose nozzle missing,  
front spray control valve leaking,