

# **CarHistory Dealer Report & PPSR Certificate**

Report generated on 28/08/2024

13317281

VIN	KL3CD2669GB539583
Make	HOLDEN
Model	CAPTIVA
Variant/series	7 LTZ (AWD)CG MY16
Body	4D WAGON
Transmission	6 SP AUTOMATIC
Year (first retail date)	2017
Colour	WHITE



\*Picture provided is a sample only

# **QUICK SUMMARY**



No stolen status reported



Written-off status reported



No financial interests reported



No odometer rollback reported



Vehicle registered

# **VEHICLE DETAILS**



# ✓ Vehicle registered

#### **VEHICLE REGISTRATION**

Registration plate	1YC8FU
Registration state	VIC
Registration expiry date	13-09-2024

### FIRST SALE INFORMATION

First sale date	13-02-2017
Postcode of first sale	3156
First buyer type	NON-PRIVATE

#### **ENGINE DETAILS**

Engine number	Z22D1162850049
Engine size	2.2L
Cylinders/rotors	DT4
Fuel type	DIESEL
Power (KW)	135
Torque (Nm)	400

#### **VEHICLE RATINGS**

ANCAP safety rating	****
Overall green rating	***
Air pollution rating	5.0 out of 10
Greenhouse rating	6.0 out of 10



### **CarHistory notes:**

Vehicle registration information is sourced via the PPSR. Refer to the PPSR Certificate below.

# REPORTED ODOMETER HISTORY



No odometer rollback reported

# LAST REPORTED ODOMETER READING


Kilometres	45,707
Date reported	12/10/2020

# **READING ENTERED BY YOU**

Kilometres	89,573
Date reported	28/08/2024

The odometer history for this vehicle has been supplied to CarHistory by various sources within the automotive industry.

Kilometres	Date reported	Alerts
89,573	28/08/2024	
45,707	12/10/2020	
41,023	18/06/2020	
37,487	11/12/2019	
37,524	10/12/2019	





#### **CarHistory notes:**

CarHistory relies on data received from third parties. We recommend you review the vehicle's log book and service history to determine the accuracy of the vehicle's odometer reading.

# **REPORTED SALES LISTINGS**

No known sales listings for this vehicle.



### **CarHistory notes:**

Reported sales listings are sales advertisements derived from various ecommerce sites and provide an indication of how often the vehicle has been listed for sale.

# **FINANCE CHECK**



### No financial interests reported

PPSR has reported that this vehicle is not encumbered.



#### **CarHistory notes:**

Financial encumbrance information is sourced via the PPSR. Refer to the PPSR Certificate below.

# **WRITTEN-OFF CHECK**



# Written-off status reported

PPSR has reported that this vehicle has been written-off.

Written-off	Impact   Passenger front   Heavy structural Impact   Driver front   Light panel Impact   Suspension (passenger front)   Minor mechanical damage

	Malicious/vandalism/stripped   Interior   Minor vandalism
Date recorded	13 Jun 2023
State recorded	VIC
Туре	Inspected

Written-off	Impact   Passenger front   Heavy structural Impact   Driver front   Light panel Impact   Suspension (passenger front)   Minor mechanical damage Malicious/vandalism/stripped   Interior   Minor vandalism
Date recorded	14 Dec 2022
State recorded	VIC
Туре	Repairable Write-off



#### **CarHistory notes:**

Written-off information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

### STOLEN CHECK



### No stolen status reported

PPSR has reported that this vehicle is not stolen.



#### **CarHistory notes:**

Stolen information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

# **ACCESS YOUR REPORT ONLINE**

To allow an individual to view this report online, simply provide them with the following link: https://secure.carhistory.com.au/vcn?vcn=A1-PCHR

### **GENERAL DISCLAIMERS**

This report has been supplied on the Terms and Conditions set out on the CarHistory website, and accepted by you before you

purchased this report.

The data used to compile this report has been sourced from various independent and Government sources, as a result CarHistory can accept no responsibility for the accuracy or completeness of information.

# **PPSR CERTIFICATE**

The following certificate has been issued by the Australian Financial Security Authority.



28/08/2024

# **Serial Number Search Certificate**

This is a serial number search certificate for a serial number search

This Search certificate is provided under section 174 of the *Personal Property Securities Act* 2009

 Search certificate number:
 5124068914630001

 Search number:
 512406891463

This search certificate reflects the data contained in the PPSR at 28/08/2024 15:18:49 (Canberra Time).

#### Search Criteria Details

Serial number search type: VIN

Motor vehicle: KL3CD2669GB539583

PPSR registration state searched: Current

### **PPSR Registration Details**

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

#### Additional Motor Vehicle Details - NEVDIS

Identifier number:KL3CD2669GB539583Identifier type:VINVehicle type:CAR / SMALLMake:HOLDEN

PASSENGER VEHICLE

Body type: CAR/STATION WAGON Model: CAPTIV

Colour: WHITE Engine number: Z22D1162850049

Registration plate number: 1YC8FU State vehicle registered: VIC

Registration expiry: 13 Sep 2024

Year of manufacture: 2017 Year/Month of compliance: 2017-01

### Important NEVDIS notifications about the Vehicle

#### Written-off:

VIC, 13 Jun 2023, Inspected

- I01C [Impact | Passenger front | Heavy structural]
- I02B [Impact | Driver front | Light panel]
- I34G [Impact | Suspension (passenger front) | Minor mechanical damage]
- M09K [Malicious/vandalism/stripped | Interior | Minor vandalism]

VIC, 14 Dec 2022, Repairable Write-off

- I01C [Impact | Passenger front | Heavy structural]
- I02B [Impact | Driver front | Light panel]
- I34G [Impact | Suspension (passenger front) | Minor mechanical damage]
- M09K [Malicious/vandalism/stripped | Interior | Minor vandalism]

This search certificate reflects the data contained in the PPSR at 28/08/2024 15:18:49 (Canberra Time).

#### Stolen:

Not recorded as stolen.

Tasmanian stolen vehicle information is currently unavailable from this service. For information about the status of Tasmanian vehicles, go to:

https://www.transport.tas.gov.au/MRSWebInterface/public/regoLookup/registrationLookup.jsf (Note: you will need to provide the vehicle registration plate number to search this site).

A stolen vehicle notification, or the absence of one, does not necessarily mean a vehicle is or is not stolen.

If there is a stolen vehicle notification you wish to enquire about, you should contact the police force in the State or Territory indicated immediately after the date in the notification. The reference number at the end of the notification should be quoted as a part of your enquiry.

Please note that there may be multiple stolen notifications shown. A stolen notification can be for a VIN, Plate, Chassis and/or Engine.

Vehicle information is requested from Austroads NEVDIS database for each transaction involving a vehicle VIN or Chassis Number on the PPSR. The data is not part of interests registered on the PPSR and it is presented without any guarantee regarding its accuracy.

The NEVDIS data is intended to assist users with checking that the VIN or Chassis Number they entered, along with information they have about the vehicle from other sources, is accurate and to provide users with any data held on NEVDIS about a vehicle's stolen or written off status.

State and territory road agencies are the main source of NEVDIS data and the primary point of contact for enquiries, errors, and corrections.

Access to and use of data provided through the PPSR is subject to the PPSR General Conditions of Use and applicable third party data conditions (which can be obtained at <a href="https://www.ppsr.gov.au">www.ppsr.gov.au</a>). To the extent permitted by law, all data provided through the PPSR is made available without any representation or warranty of any kind (without limitation in respect to accuracy) and the Commonwealth, and our third party data providers (which includes any person mentioned in the Third Party Data Conditions as providing information through the PPSR), have no liability to you in respect of any loss or damage that you might suffer no matter how arising (including negligence) that is directly or indirectly related to the NEVDIS Data.

#### How to verify this certificate on the PPSR

You can use the search number from an original search (as shown on this certificate) to retrieve the original search results and to issue a copy of the search certificate at <a href="https://transact.ppsr.gov.au/ppsr/Home">https://transact.ppsr.gov.au/ppsr/Home</a>.

There is no fee, however this process will not provide any update to the information in the original search.

#### **Privacy and Terms and Conditions**

The Australian Financial Security Authority is subject to the *Privacy Act 1988* which requires that we comply with the Australian Privacy Principles (APPs) set out in the Act. The APPs set out how Australian Government agencies should collect, use, store and disclose personal information and how individuals can access records containing their personal information.

Access to and use of the PPSR is subject to the General Conditions of Use, as well as other relevant terms and conditions. All relevant terms and conditions can be found at www.ppsr.gov.au.

End of search certificate

EMAIL: enquiries@ppsr.gov.au WEBSITE: www.ppsr.gov.au

GPO Box 1944 Adelaide SA 5001

1300 00 77 77