

Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
10/05/2018	0890085500	3	WD40	\$14.10	\$42.30	\$4.23	\$46.53
06/03/2018	3699094	1	Washer system	\$501.46	\$501.46	\$50.15	\$551.61
06/03/2018	TS-0301-1120	1	Turbo smart - E B/HP	\$948.78	\$948.78	\$94.88	\$1,043.66
10/05/2018	Sublet	1	Tridon Thread File Med	\$64.04	\$64.04	\$6.40	\$70.44
24/08/2018	TTH	1	Tilt Tray Transport - Mlgco to 13	\$160.00	\$160.00	\$16.00	\$176.00
24/07/2018	TTH	1	Tilt Tray Transport - 13 to Migco	\$160.00	\$160.00	\$16.00	\$176.00
06/03/2018	1300558	2	Tilt Pin Bush	\$160.00	\$320.00	\$32.00	\$352.00
06/03/2018	3666736	20	Thrust washer	\$37.70	\$754.00	\$75.40	\$829.40
06/03/2018	3666733	2	Thrust washer	\$469.56	\$939.12	\$93.91	\$1,033.03
06/03/2018	3666727	2	Thrust ring	\$187.60	\$375.20	\$37.52	\$412.72
21/08/2018	Sublet	1	Supply dogman	\$198.00	\$198.00	\$19.80	\$217.80
21/08/2018	Sublet	1	Supply 50t Crane to install Mast	\$770.00	\$770.00	\$77.00	\$847.00
10/05/2018	Sublet	1	Sundry	\$13.20	\$13.20	\$1.32	\$14.52
10/05/2018	124TA1744	1	Strobe Light	\$44.00	\$44.00	\$4.40	\$48.40
10/05/2018	40001613	1	Spring, Hydraulic Tank	\$85.64	\$85.64	\$8.56	\$94.20
10/05/2018	Sublet	1	Spring	\$31.40	\$31.40	\$3.14	\$34.54
10/05/2018	SSG-016BL	1	Spiral Safety Guard 16mm O.D	\$8.40	\$8.40	\$0.84	\$9.24

1229623

Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to:

Account Name
Account Number
Bank
BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
06/03/2018	3666677	2	Spacer Ring	\$980.90	\$1,961.80	\$196.18	\$2,157.98
10/05/2018	FS19732	1	Seperator Filter (R80D)	\$148.00	\$148.00	\$14.80	\$162.80
06/03/2018	3681494	2	Seals - Brake system	\$722.60	\$1,445.20	\$144.52	\$1,589.72
06/03/2018	3666797	1	Seal kit	\$541.33	\$541.33	\$54.13	\$595.46
10/05/2018	3666696	6	Seal	\$2.80	\$16.80	\$1.68	\$18.48
10/05/2018	Sublet	1	Rubber Mount Kit, Headlight	\$565.28	\$565.28	\$56.53	\$621.81
10/05/2018	0890200	1	Rost-Off Plus rust remover - PENTOIL-300ML	\$17.42	\$17.42	\$1.74	\$19.16
06/03/2018	Sublet	1	Refurbish Hydraulic hoses	\$7,500.00	\$7,500.00	\$750.00	\$8,250.00
06/03/2018	Coolant	30	Radiator Coolant	\$7.30	\$219.00	\$21.90	\$240.90
10/05/2018	Sublet	1	Radiator Cap, Mine Spec	\$16.02	\$16.02	\$1.60	\$17.62
06/03/2018	Sublet	1	R/F Windows, tint	\$780.50	\$780.50	\$78.05	\$858.55
10/05/2018	P158324	1	Precleaner Bowl - Donaldson	\$136.80	\$136.80	\$13.68	\$150.48
06/03/2018	3666683	2	Piston	\$4,533.50	\$9,067.00	\$906.70	\$9,973.70
29/08/2018	033	8	Painter - Hernanie Basquina	\$124.00	\$992.00	\$99.20	\$1,091.20
27/08/2018	033	7.5	Painter - Hernanie Basquina	\$124.00	\$930.00	\$93.00	\$1,023.00
18/06/2018	033	3	Painter - Hernanie Basquina	\$124.00	\$372.00	\$37.20	\$409.20
29/06/2018	033	2.5	Painter - Hernanie Basquina	\$124.00	\$310.00	\$31.00	\$341.00

1229623

Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to;

Account Name
Account Number
Bank
BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
30/07/2018	033	8.5	Painter - Hernanie Basquina	\$124.00	\$1,054.00	\$105.40	\$1,159.40
25/06/2018	033	7.5	Painter - Hernanie Basquina	\$124.00	\$930.00	\$93.00	\$1,023.00
24/08/2018	033	4	Painter - Hernanie Basquina	\$124.00	\$496.00	\$49.60	\$545.60
15/06/2018	033	1	Painter - Hernanie Basquina	\$124.00	\$124.00	\$12.40	\$136.40
14/06/2018	033	3	Painter - Hernanie Basquina	\$124.00	\$372.00	\$37.20	\$409.20
22/06/2018	033	7.5	Painter - Hernanie Basquina	\$124.00	\$930.00	\$93.00	\$1,023.00
31/05/2018	033	3.5	Painter - Hernanie Basquina	\$124.00	\$434.00	\$43.40	\$477.40
06/03/2018	PNO004	140	Oil HP Gear 80W/90 1LTR (Per Litre)	\$11.20	\$1,568.00	\$156.80	\$1,724.80
06/03/2018	3666693	2	O'ring Shaft	\$38.60	\$77.20	\$7.72	\$84.92
06/03/2018	3666724	2	O'ring Omega 36DFLT	\$19.50	\$39.00	\$3.90	\$42.90
06/03/2018	3666695	2	O'ring	\$70.43	\$140.86	\$14.09	\$154.95
15/06/2018	223	2.5	Mechanic - Tamen Turner	\$124.00	\$310.00	\$31.00	\$341.00
28/05/2018	107	3.5	Mechanic - Michael Tunbridge	\$124.00	\$434.00	\$43.40	\$477.40
29/08/2018	107	7.5	Mechanic - Michael Tunbridge	\$124.00	\$930.00	\$93.00	\$1,023.00
08/06/2018	107	9.5	Mechanic - Michael Tunbridge	\$124.00	\$1,178.00	\$117.80	\$1,295.80
28/08/2018	107	1.5	Mechanic - Michael Tunbridge	\$124.00	\$186.00	\$18.60	\$204.60
24/05/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20

1229623

Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to:

Account Name
Account Number
Bank
BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



alliedforklifts.com.au

Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
23/05/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
24/08/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
23/08/2018	155	8.5	Mechanic - Kerry Crosby	\$124.00	\$1,054.00	\$105.40	\$1,159.40
16/07/2018	155	4.5	Mechanic - Kerry Crosby	\$124.00	\$558.00	\$55.80	\$613.80
20/07/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
09/07/2018	155	2	Mechanic - Kerry Crosby	\$124.00	\$248.00	\$24.80	\$272.80
22/08/2018	155	3.5	Mechanic - Kerry Crosby	\$124.00	\$434.00	\$43.40	\$477.40
24/07/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
27/08/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
23/07/2018	155	7	Mechanic - Kerry Crosby	\$124.00	\$868.00	\$86.80	\$954.80
27/06/2018	155	3.5	Mechanic - Kerry Crosby	\$124.00	\$434.00	\$43.40	\$477.40
21/05/2018	155	1.5	Mechanic - Kerry Crosby	\$124.00	\$186.00	\$18.60	\$204.60
02/08/2018	155	1	Mechanic - Kerry Crosby	\$124.00	\$124.00	\$12.40	\$136.40
19/07/2018	155	0.5	Mechanic - Kerry Crosby	\$124.00	\$62.00	\$6.20	\$68.20
18/06/2018	155	1.5	Mechanic - Kerry Crosby	\$124.00	\$186.00	\$18.60	\$204.60
07/06/2018	155	2	Mechanic - Kerry Crosby	\$124.00	\$248.00	\$24.80	\$272.80
31/05/2018	155	5.5	Mechanic - Kerry Crosby	\$124.00	\$682.00	\$68.20	\$750.20

1229623

Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to:

Account Name
Account Number
Bank
BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



SALES - SERVICE - REPAIRS - HIRE - SPARE PARTS

Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
10/07/2018	155	2	Mechanic - Kerry Crosby	\$124.00	\$248.00	\$24.80	\$272.80
19/06/2018	155	3	Mechanic - Kerry Crosby	\$124.00	\$372.00	\$37.20	\$409.20
30/05/2018	155	3	Mechanic - Kerry Crosby	\$124.00	\$372.00	\$37.20	\$409.20
28/08/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
12/07/2018	155	3	Mechanic - Kerry Crosby	\$124.00	\$372.00	\$37.20	\$409.20
21/08/2018	155	3.5	Mechanic - Kerry Crosby	\$124.00	\$434.00	\$43.40	\$477.40
25/05/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
01/08/2018	155	1	Mechanic - Kerry Crosby	\$124.00	\$124.00	\$12.40	\$136.40
20/08/2018	155	3	Mechanic - Kerry Crosby	\$124.00	\$372.00	\$37.20	\$409.20
12/06/2018	155	2.5	Mechanic - Kerry Crosby	\$124.00	\$310.00	\$31.00	\$341.00
08/06/2018	155	9	Mechanic - Kerry Crosby	\$124.00	\$1,116.00	\$111.60	\$1,227.60
13/07/2018	155	2.5	Mechanic - Kerry Crosby	\$124.00	\$310.00	\$31.00	\$341.00
22/06/2018	155	3	Mechanic - Kerry Crosby	\$124.00	\$372.00	\$37.20	\$409.20
17/07/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
18/07/2018	155	4.5	Mechanic - Kerry Crosby	\$124.00	\$558.00	\$55.80	\$613.80
22/05/2018	155	8	Mechanic - Kerry Crosby	\$124.00	\$992.00	\$99.20	\$1,091.20
11/06/2018	155	3.5	Mechanic - Kerry Crosby	\$124.00	\$434.00	\$43.40	\$477.40

1229623
Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to:

Account Name
Account Number
Bank
BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
26/06/2018	155	6	Mechanic - Kerry Crosby	\$124.00	\$744.00	\$74.40	\$818.40
29/05/2018	022	2	Mechanic - Geoffrey Pinero	\$124.00	\$248.00	\$24.80	\$272.80
29/08/2018	228	6.5	Mechanic - Bernard Djekic	\$124.00	\$806.00	\$80.60	\$886.60
10/05/2018	51531	1	Master Gasket Loctite 50ML.	\$55.00	\$55.00	\$5.50	\$60.50
06/03/2018	3654314	2	Lined Pad	\$146.00	\$292.00	\$29.20	\$321.20
10/05/2018	Labour	98	Labour	\$0.00	\$0.00	\$0.00	\$0.00
06/03/2018	3635952	1	Hydraulic Filter	\$350.80	\$350.80	\$35.08	\$385.88
10/05/2018	P550148	1	Hydraulic Filter	\$67.48	\$67.48	\$6.75	\$74.23
10/05/2018	0539-116-27	1	Hose Clamp 9mm 16/27	\$3.00	\$3.00	\$0.30	\$3.30
10/05/2018	GC	2	Grease Cartridge	\$14.00	\$28.00	\$2.80	\$30.80
10/05/2018	GC	4	Grease Cartridge	\$14.00	\$56.00	\$5.60	\$61.60
10/05/2018	GC	1	Grease Cartridge	\$14.00	\$14.00	\$1.40	\$15.40
10/05/2018	3657850	1	Gauge - Sight glass	\$215.90	\$215.90	\$21.59	\$237.49
06/03/2018	3666689	2	Gasket Duro outter	\$480.00	\$960.00	\$96.00	\$1,056.00
06/03/2018	3666690	2	Gasket Duro inner	\$435.00	\$870.00	\$87.00	\$957.00
10/05/2018	FF5580	1	Fuel Filter	\$49.72	\$49.72	\$4.97	\$54.69
06/03/2018	Sublet	1	Fire supression refurbish, service system	\$3,170.18	\$3,170.18	\$317.02	\$3,487.20

1229623

Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to;

Account Name
Account Number
Bank
BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
10/05/2018	LF3000	1	Filter, Engine Oil	\$120.64	\$120.64	\$12.06	\$132.70
10/05/2018	897064	1	Filter, Cab Breather	\$118.96	\$118.96	\$11.90	\$130.86
06/03/2018	3681671	1	Filter, Air primary	\$255.38	\$255.38	\$25.54	\$280.92
06/03/2018	3681672	1	Filter air secondary	\$122.18	\$122.18	\$12.22	\$134.40
06/03/2018	4209440	2	Filter-Oil Transmission	\$198.50	\$397.00	\$39.70	\$436.70
10/05/2018	16403-59E0A	1	Filter-Fuel	\$35.30	\$35.30	\$3.53	\$38.83
06/03/2018	2169020	15	Farnplus Hydratrans oil	\$10.31	\$154.64	\$15.46	\$170.10
10/05/2018	Sublet	1	Fan Belts	\$222.88	\$222.88	\$22.28	\$245.16
10/05/2018	3681768	1	Expansion Tank Sight Glass	\$256.22	\$256.22	\$25.63	\$281.85
06/03/2018	EL	1	Environmental waste disposal fee	\$21.00	\$21.00	\$2.10	\$23.10
06/03/2018	Sublet	1	Engineer manufacture, tilt pins	\$1,950.00	\$1,950.00	\$195.00	\$2,145.00
10/05/2018	600050	3	Denso Tape 50mm (per metre)	\$3.40	\$10.20	\$1.02	\$11.22
06/03/2018	600050	50	Denso Tape 50mm (per metre)	\$3.40	\$170.00	\$17.00	\$187.00
10/05/2018	Coolant Red	5	Coolant, red premixed 200L (per Litre)	\$7.30	\$36.50	\$3.65	\$40.15
06/03/2018	CON	1	Consumables	\$220.00	\$220.00	\$22.00	\$242.00
10/05/2018	Sublet	1	Clamps CF3-22	\$10.91	\$10.91	\$1.09	\$12.00
10/05/2018	053911627	4	Clamp Hose 9mm (16-27mm)	\$1.90	\$7.60	\$0.76	\$8.36

1229623

Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to;

Account Name

Account Number

Bank

BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



Tax Invoice

Repair Invoice No. **1236298**
Date **29/08/18**

Make
Model
Serial Number
Engine Hours
Next Service Due
Plant ID

Date	Product	Qty	Description	Unit Price	Total (ex)	GST	Total
10/05/2018	Tac 2	2	Chain Lube	\$24.00	\$48.00	\$4.80	\$52.80
06/03/2018	CANVAS	1	Canvas Seat Cover Suit TCM	\$250.00	\$250.00	\$25.00	\$275.00
06/03/2018	3666676	4	BRG Tappered Roller	\$1,890.80	\$7,563.20	\$756.32	\$8,319.52
06/03/2018	0890117	20	Brake Cleaner 500ML	\$8.00	\$160.00	\$16.00	\$176.00
10/05/2018	0890117	10	Brake Cleaner 500ML	\$8.00	\$80.00	\$8.00	\$88.00
10/05/2018	Sublet	1	Bracket Made	\$544.00	\$544.00	\$54.40	\$598.40
06/03/2018	3693210	2	Bracket door	\$154.00	\$308.00	\$30.80	\$338.80
10/05/2018	Sublet	1	Bolts	\$72.38	\$72.38	\$7.24	\$79.62
10/05/2018	BL1688	20	BL1688	\$185.00	\$3,700.00	\$370.00	\$4,070.00
06/03/2018	3972377	1	Belt, Drive fan	\$219.80	\$219.80	\$21.98	\$241.78
10/05/2018	3974102	1	Belt Tensioner	\$486.16	\$486.16	\$48.62	\$534.78
10/05/2018	31-1000 S4	2	Battery	\$273.60	\$547.20	\$54.72	\$601.92
10/05/2018	Sublet	1	Aircon Brackets	\$544.00	\$544.00	\$54.40	\$598.40
10/05/2018	3666675	4	3666675- Seal	\$427.12	\$1,708.48	\$170.85	\$1,879.33
06/03/2018	RUB745	4	15W40 Diesel Engine Oil 5 Litre Pack	\$49.95	\$199.80	\$19.98	\$219.78

1229623

Onsite transport machine to Allied forklifts workshop, Complete refurbish, carryout full workshop inspection, report faults listed. Remove wheel & planetary's inspect brake friction plates, all ok. Replace Duro cons, seals worn bearings. Reseal hand brake assembly & fit new pads, Replace damaged hydraulic hoses recommend by hose right. Perform major engine, transmission service. refurbish lift cylinders. Complete a hydraulic oil strain, top up hydraulic oil, Remove steer wheels, clean inspect rear bearings repack, Replace door latches, remove windows to repair rust in cab, clean windows tint windows. Full respray of machine & mast, Re-sticker mine spec decals. Fit mast test all functions all ok. Demob machine for transport. Wormald system back into standard. It requires a LVL II + 5 yearly service and discharge test, the cylinder needs to be pressure tested, blasted and painted as it is out of date and LOP tube needs to be replaced. The discharge hose and

Please pay in 7 days to;

Account Name
Account Number
Bank
BSB

Sub Total	\$88,506.26
Total GST	\$8,850.63
TOTAL (inc. GST)	\$97,356.89

Thank you for your business



Onsite Rental Group Operations Pty Ltd

Service History Listing - Details

Date: 10/04/2024

Time: 10:54:20

For Equipment Code From: FL32001 To: FL32001

For Job Category From: All To: All

For Serial No From: All To: All

For Mechanic From: All To: All

For Job Status From: All To: All

For Service Date From: All To: All

For Part No From: All To: All

For Job Type: All

For Owner Option From: All To: All

For Branch Code From: All To: All

For Service Job No. From: All To: All

For Reason Code From: All To: All

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
----------	-------------	----------	--------------	--------------	------------	-------------	----------	------------	---------

Equip Code: FL32001 **Description:** Forklift - 32.0t - 5.5m - Diesel **Registration:** **Registration Expiry:**
Make: Omega **Model:** MFD20 **Serial No:** L533

615222 **CU-DAM ... Cab Rusty / Tyres U.S. / N** **Internal** **Omega** **6/12/2023** **BHPNICKELS** **Repairs & Maintenance** **LSMITH** **3010**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail	Reason	Warranty Expiry	SA Code	PO/TS No
------	-----------------	------	-------------	-----	----------	--------	--------	-----------------	---------	----------

\$0.00

Job Total: \$0.00

559034 **Diagnose and repair no side shift** **Internal** **Omega** **23/05/2023** **BHPNICKELS** **Repairs & Maintenance** **JWALTERS** **3010**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail	Reason	Warranty Expiry	SA Code	PO/TS No
------	-----------------	------	-------------	-----	----------	--------	--------	-----------------	---------	----------

Labour	JWALTERS	23/05/2023	Carry Out General Travel to site	1.00	0	\$0.00	RM		160610RM	1098888
Labour	JWALTERS	23/05/2023	Check/Inspect Electrical general Fuse	0.25	0	\$0.00	RM		160610RM	1098890
Labour	JWALTERS	23/05/2023	Check/Inspect Electrical general Relay	0.25	0	\$0.00	RM		160610RM	1098892
Labour	JWALTERS	23/05/2023	Check/Inspect Electrical general Wiring Harness	1.00	0	\$0.00	RM		160610RM	1098894
Labour	JWALTERS	23/05/2023	Repair Electrical general Wiring Harness	-1.00	0	\$0.00	RM		160610RM	1098896
Labour	JWALTERS	23/05/2023	Repair Electrical general Wiring Harness	1.00	0	\$0.00	RM		160610RM	1098895
Labour	JWALTERS	23/05/2023	Repair Wiring Harness Electrical general	1.50	0	\$0.00	RM		160610RM	1098897

Job Total: \$0.00

Note : Customer stated no side shift, arrived on site to diagnose and repair fault.
 Traced and inspected wiring from joystick to valves, all ok.
 Checked all fuses and relays, all ok.
 Found no voltage at solenoid, diagnose worm/corroded terminals on din plugs for solenoids. Replaced all 4 din plugs on side shift control block. All tested ok.
 Carry Out General Travel to site
 Check/Inspect Electrical general Fuse
 Check/Inspect Electrical general Relay
 Check/Inspect Electrical general Wiring Harness
 Repair Electrical general Wiring Harness

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
558633	Service inspection	Internal	Omega	22/05/2023	BHPNICKELS	Scheduled Maintenance	DSEMPLE	3010	

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Labour	DSEMPLE	22/05/2023	Carry Out Inspection Service Inspection	1.50	0	\$0.00 SM		160610SM	1098179	
Job Total:						\$0.00				

Note : Carry Out Inspection Service Inspection

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
531483	diagnose and repair hydraulic fault.	Internal	Omega	2/02/2023	BHPNICKELS	Repairs & Maintenance	JWALTERS	2985	

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Labour	JWALTERS	15/02/2023	Carry Out General Travel to site	0.40	0	\$0.00 RM		160610RM	1052699	
Labour	JWALTERS	15/02/2023	Check/Inspect Actuator Hydraulics Genera	0.70	0	\$0.00 RM		160610RM	1052697	
Labour	JWALTERS	15/02/2023	Diagnose Accumulator Hydraulics General	0.20	0	\$0.00 RM		160610RM	1052696	
Labour	JWALTERS	15/02/2023	Diagnose Hyd Brake Accumulator Brakes	1.00	0	\$0.00 RM		160610RM	1052698	
Job Total:						\$0.00				

Note : Diagnose Accumulator Hydraulics General

Check/Inspect Actuator Hydraulics General

Diagnose Hyd Brake Accumulator Brakes

Carry Out General Travel to site

customer complained side shift not working. on site diagnostics found brake accumulator constantly recharging which runs the same circuit as the side shift function. there for causing operation fault.

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
443506	Safety Inspection	Inspection	M	2/02/2023		Inspection	JWALTERS	2985	

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
				0.01		\$0.00				
Job Total:						\$0.00				

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
515143	Oil Leak	Internal	Omega	17/11/2022	BHPNICKELS	Repairs & Maintenance	JWALTERS	2940	

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JWALTERS	17/11/2022	Carry Out General Travel to site	0.40	0	\$0.00 RM		160610RM	1017152
Labour	JWALTERS	17/11/2022	Check/Inspect Wiring Harness Electrical	0.50	0	\$0.00 RM		160610RM	1017154
Labour	JWALTERS	17/11/2022	Replace Hydraulic Fitting Hoses	0.30	0	\$0.00 RM		160610RM	1017153
Labour	JWALTERS	17/11/2022	Replace Reverse Alarm Safety Syatems	0.30	0	\$0.00 RM		160610RM	1017155

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
Job Total:						\$0.00			

Note : Carry Out General Travel to site

Replace Hydraulic Fitting Hoses

Check/Inspect Wiring Harness Electrical general

Replace Reverse Alarm Safety Systems

Customer stated oil leak in same area after previous repair. found 1x fitting to not be sealing correctly. changed fitting which was new for old one from failed valve block. re-tested and all ok. replaced reverse hooter/siren.

514499 **Oil Leak,solenoid valve behind front l** **Internal** **Omega** **14/11/2022** **BHPNICKELS** **Repairs & Maintenance** **JWALTERS** **2940**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail	Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JWALTERS	14/11/2022	Carry Out General Equipment Cleaning	0.10	0	\$0.00	RM		160610RM	1015760
Labour	JWALTERS	14/11/2022	Carry Out General Travel to site	0.40	0	\$0.00	RM		160610RM	1015761
Labour	JWALTERS	16/11/2022	Carry Out General Travel to site	0.40	0	\$0.00	RM		160610RM	1016596
Labour	JWALTERS	14/11/2022	Diagnose Control Valve Hydraulics Genera	0.70	0	\$0.00	RM		160610RM	1015762
Labour	JWALTERS	16/11/2022	Labour Other Other	0.30	0	\$0.00	RM		160610RM	1016595
Labour	JWALTERS	16/11/2022	Replace Control Valve Hydraulics General	0.60	0	\$0.00	RM		160610RM	1016597
Job Total:						\$0.00				

Note : Carry Out General Equipment Cleaning

Carry Out General Travel to site

Diagnose Control Valve Hydraulics General

customer stated oil leak from below machine. on inspection found 1x 3-way hydraulic solenoid valve behind front left tyre to be excessively corroded. new valve ordered.

Labour Other Other

Replace Control Valve Hydraulics General

fit new electric over hydraulic controle valve behind front left tyre. carry out function test.

513480 **re-seal hydraualic joystick.** **Internal** **Omega** **9/11/2022** **BHPNICKELS** **Repairs & Maintenance** **JWALTERS** **2940**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail	Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JWALTERS	9/11/2022	Carry Out General Travel to site	0.20	0	\$0.00	RM		160610RM	1013888
Labour	JWALTERS	9/11/2022	Repair Joy Stick Controllers General	2.10	0	\$0.00	RM		160610RM	1013889
Job Total:						\$0.00				

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
----------	-------------	----------	--------------	--------------	------------	-------------	----------	------------	---------

Note : Carry Out General Travel to site

Repair Joy Stick Controllers General

operator stated joystick leaking. stripped and tested found top wiper seals on individual spools leaking. new OEM seal ordered and fitted. tested all ok at time of test.

re-seal hydraulic joy stick.

422962 **Safety Inspection** **Inspection** **M** **9/11/2022** **Inspection** **JWALTERS** **2940**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail	Reason	Warranty Expiry	SA Code	PO/TS No
				0.01		\$0.00				
Job Total:						\$0.00				

499599 **service inspection** **Internal** **Omega** **19/09/2022** **BHPNICKELS** **Scheduled Maintenance** **JWALTERS** **2921**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail	Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JWALTERS	19/09/2022	Carry Out Service Inspection Inspection	2.00	0	\$0.00	SM		160610SM	990116
Job Total:						\$0.00				

Note : Carry Out Service Inspection as per Checklist

carry out service inspection as per checklist. Faults found as bellow. -1x beacon light faulty -1x 4,5 kg fire extinguisher expired. -1x 1kg extinguisher expired. - fire suppression system out of date, needs recharge. -2x engine hood gas struts u/s - airconditioning system u/s -2x 24v horns failed. - front, rear and top wiper blades u/s. machine due for service

499584 **repair left hand rear kingpin bearings** **Internal** **Omega** **19/09/2022** **BHPNICKELS** **Repairs & Maintenance** **JWALTERS** **2921**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail	Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JWALTERS	19/09/2022	Check/Inspect Hub Final Drives	1.00	0	\$0.00	RM		160610RM	990067
Labour	JWALTERS	19/09/2022	Labour Other Other	8.00	0	\$0.00	RM		160610RM	990064
Labour	JWALTERS	19/09/2022	Refit Hub Final Drives	1.00	0	\$0.00	RM		160610RM	990069
Labour	JWALTERS	19/09/2022	Refit King Pin & Bearings Steering	4.00	0	\$0.00	RM		160610RM	990065
Labour	JWALTERS	19/09/2022	Remove Hub Final Drives	1.00	0	\$0.00	RM		160610RM	990068
Labour	JWALTERS	19/09/2022	Remove King Pin & Bearings Steering	10.00	0	\$0.00	RM		160610RM	990066
Labour	JWALTERS	19/09/2022	Repair King Pin & Bearings Steering	4.00	0	\$0.00	RM		160610RM	990070
Labour	JWALTERS	19/09/2022	Replace Steer Linkage Steering	2.00	0	\$0.00	RM		160610RM	990071
Job Total:						\$0.00				

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
----------	-------------	----------	--------------	--------------	------------	-------------	----------	------------	---------

Note : Labour Other Other

Refit King Pin & Bearings Steering

Remove King Pin & Bearings Steering

Check/Inspect Hub Final Drives

Remove Hub Final Drives

Refit Hub Final Drives

Repair King Pin & Bearings Steering

Replace Steer Linkage Steering

previous tech diagnosed left rear kingpin bearing collapsed. arranged bridgstone to remove wheels, stripped, cleaned and inspected assembly and fit new parts. assemble and test. Job required manufacturing special tooling and took a large ammount of hours to repair due to unfamiliarityand rusted/damaged parts.

409313 Safety Inspection Inspection M 19/09/2022 Inspection JWALTERS 2921

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
				0.01		\$0.00			
Job Total:						\$0.00			

409282 Safety Inspection Inspection M 19/09/2022 Inspection JWALTERS 2921

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
				0.01		\$0.00			
Job Total:						\$0.00			

453288 Rear left wheel alignment out of angle Internal Omega 4/03/2022 BHPNICKELS Repairs & Maintenance HThaha 2850

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	HThaha	4/03/2022	Carry Out General Other General	1.50	0	\$0.00 RM		160610RM	907305
Job Total:						\$0.00			

Note : Carry Out General Other General

Wheel Allignment is not good. Same need to be repaired.

357516 Safety Inspection Inspection M 4/03/2022 Inspection HThaha 2850

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
				1.00		\$0.00			
Job Total:						\$0.00			

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
422432	SERVICE INSP + REPAIR OIL LEAK	Internal	Omega	14/10/2021	BHPNICKELS	Scheduled Maintenance	DSEMPLE	2850	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	DSEMPLE	14/10/2021	Carry Out General Travel to site	2.00	0	\$0.00 SM		160610SM	846671
Labour	DSEMPLE	14/10/2021	Carry Out General Travel whilst on job	2.50	0	\$0.00 SM		160610SM	846670
Labour	DSEMPLE	14/10/2021	Repair Hydraulic Fitting Hoses	3.00	0	\$0.00 SM		160610SM	846669
Job Total:						\$0.00			

Note : Repair Hydraulic Fitting Hoses

Carry Out General Travel whilst on job

Carry Out General Travel to site

-TRAVEL TO SITE -LOCATE UNIT -DIAGNOSE OIL LEAK -FOUND O'RINGS REQUIRE REPLACING -TRAVEL TO HOSE REPAIR + GET NEW O'RINGS -TRAVEL TO GET HYD FLUID FOR TOP UP -RETURN TO SITE -REMOVE/REPLACE O'RINGS ON LEAKING HOSES + RE-FIT -COMPLETE SI -MAST STUCK HALF WAY AFTER TESTING -FINALLY GET MAST DOWN + GREASE ROLLERS + SLIDES -FOUND ANOTHER FITTING LEAKING AFTER INSPECTION -REMOVE ALL COVERS AND OBSTRUCTIONS -TIGHTEN FITTINGS AS LOOSE -TEST FOR LEAKS (OK) -RE-FIT ALL COVERS ETC **REQUIRED** SPOOLS IN CAB LEAKING REQUIRE RE-SEAL *LIFT CYLINDER RETURN HOSES REQUIRE RE-SEALING *RHS TILT MAST CYLINDER LEAKING *1X FLASHING LIGHT U/S *BRAKE ERROR LIGHT ON DISPLAY

320392	Safety Inspection	Inspection	M	14/10/2021		Inspection	DSEMPLE	2850	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
				0.10		\$0.00			
Job Total:						\$0.00			

384625	the air intake line between the filter an	Internal	Omega	4/05/2021	BHPNICKELS	Scheduled Maintenance	HThaha	2763	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	HThaha	4/05/2021	Carry Out Service Inspection	1.00	0	\$0.00 RM		160610RM	765794
Labour	HThaha	4/05/2021	Repair Other Engine	2.00	0	\$0.00 RM		160610RM	765793
Job Total:						\$0.00			

Note : the air intake line between the filter and the turbo remains off . The pipe is sitting in bottom of the rear tray of the engine. Dust is bypassing the intake filter and is directly entering the turbo a

Repair Other Engine

Carry Out Service Inspection as per Checklist

LES 2529, Air filter suction hose fallen. Same is refitted. Clamps need to be replaced.

377503	DIAGNOSE NO START	Internal	Omega	30/03/2021	BHPNICKELS	Repairs & Maintenance	DSEMPLE	2750	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	DSEMPLE	30/03/2021	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610RM	749954

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
Labour	DSEMPLE	30/03/2021	Carry Out General Travel whilst on job	0.50	0	\$0.00 RM		160610RM	749952
Labour	DSEMPLE	30/03/2021	Diagnose Wiring Harness Electrical gener	1.00	0	\$0.00 RM		160610RM	749953
Labour	DSEMPLE	30/03/2021	Repair Wiring Harness Electrical general	0.50	0	\$0.00 RM		160610RM	749955
Job Total:						\$0.00			

Note : Carry Out General Travel whilst on job

Diagnose Wiring Harness Electrical general

Carry Out General Travel to site

Repair Wiring Harness Electrical general

-TRAVEL TO SITE -TRY CONTACT SITE CONTACT BUT COULDN'T -DRIVE AROUND TILL LOCATED UNIT -DIAGNOSE NO START -FOUND NO POWER TO IGNITION -CHECK WIRING -FOUND E-STOP WIRE BROKEN -REPAIR WIRING + RE-FIT -TEST UNIT (OK)

268503	Safety Inspection	Inspection	M	30/03/2021		Inspection	DSEMPLE	2750	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
			91+ days rate	0.10		\$0.00			
Job Total:						\$0.00			

374357	Scheduled Service Job. Service Inspe	Internal	Omega	17/03/2021		BHPNICKELS	Scheduled Maintenance	HThaha	2698
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	HThaha	17/03/2021	Carry Out General Travel whilst on job	1.00	0	\$0.00 SM		160610SM	743077
Labour	HThaha	17/03/2021	Carry Out Service Inspection	2.00	0	\$0.00 SM		160610SM	743076
Job Total:						\$0.00			

Note : Carry Out Service Inspection as per Checklist

Carry Out General Travel whilst on job

363773	Hydraulic leak & replace belt	Internal	Omega	5/02/2021		BHPNICKELS	Repairs & Maintenance	HThaha	2698
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
						\$0.00			
Job Total:						\$0.00			

Note : Hydraulic leak & replace belt

357110	Low on coolant - Fan Belt - Oil Leak	Internal	Omega	6/01/2021		BHPNICKELS	Repairs & Maintenance	DSEMPLE	2529
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	DSEMPLE	6/01/2021	Carry Out General Travel whilst on job	0.50	0	\$0.00 RM		160610RM	707075
Labour	DSEMPLE	6/01/2021	Diagnose Fan Belt Cooling System	0.50	0	\$0.00 RM		160610RM	707074

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
Labour	DSEMPLE	6/01/2021	Diagnose Other Hydraulics General	0.20	0	\$0.00 RM		160610RM	707073
Labour	DSEMPLE	6/01/2021	Repair Other Cooling System	0.30	0	\$0.00 RM		160610RM	707072
Job Total:						\$0.00			

Note : Low on coolant - Fan Belt - Oil Leak

Repair Other Cooling System

Diagnose Other Hydraulics General

Diagnose Fan Belt Cooling System

Carry Out General Travel whilst on job

-LOCATE UNIT -TOP UP COOLANT -CHECK ENGINE OIL - OK -CHECK FOR LEAK AT MAST - FOUNDLIFT CYLINDER STEEL PIPES WEEPING OIL AT FITTINGS REQUIRES REMOVAL REPLACE SEALS AND RE-FIT BUT GOING TO DROP A LOT OF OIL IN THE PROCESS -CHECK FOR FRAYED BELTS - FOUND A/C BELT CRACKED BUT A/C NOT WORKING -INFORM OF REQUIRED REPAIRS

323988	Job Created by FSM technician 500hr	Internal	Omega	9/08/2020	BHPNICKELS	Preventative Maintenance	SNtana	2529	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	SNtana	5/08/2020	Carry Out 500hr Service Preventative Mai	3.00	0	\$0.00 PM		160610PM	630103
Labour	SNtana	6/08/2020	Carry Out 500hr Service Preventative Mai	4.00	0	\$0.00 PM		160610PM	630845
Labour	SNtana	9/08/2020	Carry Out 500hr Service Preventative Mai	10.00	0	\$0.00 PM		160610PM	631842
Labour	SNtana	5/08/2020	Carry Out General Other General	1.50	0	\$0.00 PM		160610PM	630101
Labour	SNtana	5/08/2020	Carry Out General Travel to site	0.30	0	\$0.00 PM		160610PM	630102
Labour	SNtana	6/08/2020	Carry Out General Travel to site	0.30	0	\$0.00 PM		160610PM	630844
Job Total:						\$0.00			

Note : Job Created by FSM technician

Carry Out General Other General

Carry Out General Travel to site

Carry Out 500hr Service - Oil & Filter Change - Complete Service Inspection Checklist.

- Prepair for the service at the workshop - Clear up vehicle - load up parts and hookup service trailer. - Travel to site. - Machine was moved to another location. - Set up - Take oil samples and carry on with the service - Pack up

- Travel to site - Set up - Carry on with service - Pack up

7/8/2020 - Travel to site - set up - Drain/fill engine oil, Transmission oil, LH,RH final drive oil. - Remove/replace fuel filters, Transmission filter, Air cleaner filters, hydraulic filters, hyd breather. - Topped up coolant. - Diff oil not changed it will need to be arranged for other time - Start and test run - Pack up - RH Lift cyl pipe leaks oil - RH Tilt cyl pipe fitting leaks oil.

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
295311	LOW HYDRAULIC OIL	Internal	Omega	24/03/2020	BHPNICKELS	Repairs & Maintenance	SNTana	2400	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	SNTana	24/03/2020	Repair Other Hydraulics General	1.50	0	\$0.00 RM		160610SI	559394
Job Total:						\$0.00			
Note : Repair Other Hydraulics General									
187913	Safety Inspection	Inspection	M	24/03/2020		Inspection	SNTana	2400	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
			91+ days rate	1.00		\$0.00			
Job Total:						\$0.00			
186958	Safety Inspection	Inspection	M	19/03/2020		Inspection	SNTana	2396	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
			91+ days rate	1.00		\$0.00			
Job Total:						\$0.00			
294279	Hydraulic oil low	Internal	Omega	18/03/2020	BHPNICKELS	Repairs & Maintenance	SNTana	2396	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	SNTana	19/03/2020	Carry Out General Travel to site	1.00	0	\$0.00 RM		160610SI	556838
Labour	SNTana	19/03/2020	Repair Other Hydraulics General	1.00	0	\$0.00 RM		160610SI	556839
Job Total:						\$0.00			
Note : Carry Out General Travel to site									
Repair Other Hydraulics General									
293751	Replce : Wipers front and rear, Precl	Internal	Omega	16/03/2020	BHPNICKELS	Repairs & Maintenance	SNTana	2394	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	SNTana	17/03/2020	Repair Air Filter Outer Engine	0.50	0	\$0.00 RM		160610SI	555474
Labour	SNTana	17/03/2020	Repair Other Electrical general	1.50	0	\$0.00 RM		160610SI	555473
Labour	SNTana	17/03/2020	Repair Other Hydraulics General	1.00	0	\$0.00 RM		160610SI	555476
Labour	SNTana	17/03/2020	Replace Other Engine	0.50	0	\$0.00 RM		160610SI	555478
Labour	SNTana	17/03/2020	Replace Wiper Motor Front Wipers	0.50	0	\$0.00 RM		160610SI	555475
Labour	SNTana	17/03/2020	Replace Wiper Motor Rear Wipers	0.50	0	\$0.00 RM		160610SI	555477

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
Job Total:						\$0.00			

Note : Repair Other Electrical general

Repair Air Filter Outer Engine

Replace Wiper Motor Front Wipers

Repair Other Hydraulics General

Replace Wiper Motor Rear Wipers

Replace Other Engine

Forklift is due for service

186355 **Safety Inspection** **Inspection** **M** **16/03/2020** **Inspection** **SNTana** **2394**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
			91+ days rate	1.00		\$0.00			
Job Total:						\$0.00			

284857 **Fix Hydraulic Leak** **Internal** **Omega** **6/02/2020** **BHPNICKELS** **Repairs & Maintenance** **SNTana** **2361**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	SNTana	7/02/2020	Repair Other Hydraulics General	2.50	0	\$0.00 RM		160610SI	535031
Job Total:						\$0.00			

Note : Repair Other Hydraulics General

268871 **Not Starting** **Internal** **Omega** **20/11/2019** **BHPNICKELS** **Repairs & Maintenance** **DSEMPLE** **2283**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	DSEMPLE	20/11/2019	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	497546
Labour	DSEMPLE	20/11/2019	Carry Out General Travel whilst on job	0.20	0	\$0.00 RM		160610SI	497544
Labour	DSEMPLE	20/11/2019	Diagnose Other Electrical general	0.50	0	\$0.00 RM		160610SI	497545
Labour	DSEMPLE	20/11/2019	Repair Other Electrical general	1.00	0	\$0.00 RM		160610SI	497547
Job Total:						\$0.00			

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
----------	-------------	----------	--------------	--------------	------------	-------------	----------	------------	---------

Note : Not Starting

Carry Out General Travel whilst on job

Diagnose Other Electrical general

Carry Out General Travel to site

Repair Other Electrical general

-TRAVEL TO SITE -LOCATE UNIT -DIAGNOSE NO STARTING FAULT -INSPECT STARTER + TEST SUPPLIED VOLTAGE -FOUND SIGNAL WIRE TO STARTER FITTED TO EARTH TERMINAL AND MELTED 1X WIRE -REMOVE DAMAGED EARTH WIRE + REPLACE -WIRE POSITIVE SIGNAL CORRECTLY -TEST UNIT (OK)

267440 **Replace starter motor** **Internal** **Omega** **14/11/2019** **BHPNICKELS** **Repairs & Maintenance** **TMAARSSSEN** **2283**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Labour	TMAARSSSEN	14/11/2019	Replace Other Electrical general	14.00	0	\$0.00 RM		160610SI	494092	
Job Total:						\$0.00				

Note : Job Created by FSM technician

Replace Other Electrical general

replace starter motor

255549 **SERVICE INSP** **Internal** **Omega** **27/09/2019** **BHPNICKELS** **Scheduled Maintenance** **DSEMPLE** **2283**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Labour	DSEMPLE	27/09/2019	Carry Out General Travel whilst on job	0.20	0	\$0.00 SM		160610SI	467452	
Labour	DSEMPLE	27/09/2019	Carry Out Service Inspection Inspection	1.50	0	\$0.00 SM		160610SI	467451	
Job Total:						\$0.00				

Note : Carry Out Service Inspection as per Checklist

Carry Out General Travel whilst on job

-L.E.S=1807 -LOCATE UNIT -COMPLETE S.I **REQUIRED** -PRE CLEANER BOWL -2X BEACONS -TRANS FLUID FOR TOP UP -1X 1KG FIRE EXT -500HR DUE

154359 **Safety Inspection** **Inspection** **M** **27/09/2019** **Inspection** **DSEMPLE** **2283**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
				0.10		\$0.00				
Job Total:						\$0.00				

203273 **Function test Service Inspection** **Internal** **Omega** **15/02/2019** **BHPNICKELS** **Scheduled Maintenance** **TMAARSSSEN** **1952**

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
------	-----------------	------	-------------	-----	----------	---------------	-----------------	---------	----------

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
Labour	TMAARSEN	15/02/2019	Carry Out Service Inspection Inspection	2.00	0	\$0.00 RM		160610SI	353424
Job Total:						\$0.00			

Note : Carry Out Service Inspection as per Checklist

199715	Tines not going in & out	Internal	Omega	31/01/2019	BHPNICKELS	Repairs & Maintenance		1952	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Job Total:						\$0.00			

Note : Tines not going in & out

192417	SERVICE INSPECTION	Internal	Omega	18/12/2018	BHPNICKELS	Scheduled Maintenance	DSEMPLE	1952	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	DSEMPLE	18/12/2018	Carry Out General Travel to site	0.50	0	\$0.00 SM		160610SI	329803
Labour	DSEMPLE	18/12/2018	Carry Out Service Inspection Inspection	1.50	0	\$0.00 SM		160610SI	329804
Job Total:						\$0.00			

Note : Carry Out General Travel to site

Carry Out Service Inspection as per Checklist

-L.E.S=1807 -FAULT ICON ON DISPLAY NOT SURE HOW TO ERASE (ALL SYSTEMS FUNCTIONING DURING TESTS)

103478	Safety Inspection	Inspection	M	18/12/2018		Inspection	DSEMPLE	1952	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Job Total:						\$0.00			

189110	Check/rectify oil leak	Internal	Omega	5/12/2018	BHPNICKELS	Repairs & Maintenance	JPRINCE	1944	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JPRINCE	5/12/2018	Carry Out General Travel to site	1.00	0	\$0.00 RM		160610SI	323741
Labour	JPRINCE	5/12/2018	Carry Out General Travel to site	1.00	0	\$0.00 RM		160610SI	323742
Labour	JPRINCE	5/12/2018	Repair Hose High Pressure Hoses	1.00	0	\$0.00 RM		160610SI	323740
Job Total:						\$0.00			

Note : Check/rectify oil leak

Repair Hose High Pressure Hoses

Carry Out General Travel to site

Check fault with oil leaking under forklift. Found loose hose connection. Tighten fitting and recheck, all o.k

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
183763	STARTING FAULT	Internal	Omega	15/11/2018	BHPNICKELS	Repairs & Maintenance	JPRINCE	1924	

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JPRINCE	15/11/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	314263
Labour	JPRINCE	15/11/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	314264
Labour	JPRINCE	15/11/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	314267
Labour	JPRINCE	15/11/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	314268
Labour	JPRINCE	15/11/2018	Diagnose Wiring Harness Electrical gener	6.00	0	\$0.00 RM		160610SI	314265
Labour	JPRINCE	15/11/2018	Repair Wiring Harness Electrical general	4.00	0	\$0.00 RM		160610SI	314266
Job Total:						\$0.00			

Note : STARTING FAULT

Carry Out General Travel to site

Diagnose Wiring Harness Electrical general

Repair Wiring Harness Electrical general

Check fault with engine not starting. Found fuses 2F09 and 2F10 blown in fuse box. Cause of fuses blowing is a dead short circuit in the harness. Locate short in harness and repair. Test circuit, all working o.k

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
173228	Engine not starting.	Internal	Omega	3/10/2018	BHPNICKELS	Repairs & Maintenance	JPRINCE	1894	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JPRINCE	3/10/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	294496
Labour	JPRINCE	3/10/2018	Carry Out General Travel whilst on job	1.50	0	\$0.00 RM		160610SI	294494
Labour	JPRINCE	3/10/2018	Diagnose Starter Motor Engine	4.00	0	\$0.00 RM		160610SI	294495
Labour	JPRINCE	3/10/2018	Replace Starter Motor Engine	4.00	0	\$0.00 RM		160610SI	294493
Job Total:						\$0.00			

Note : Engine not starting.

Replace Starter Motor Engine

Carry Out General Travel whilst on job

Diagnose Starter Motor Engine

Carry Out General Travel to site

Travel to site. Diagnose engine not starting fault. Found starter motor has failed. Travel to Kalgoorlie. Pick up new starter motor. Travel back to site. Fit new starter motor and test. All working o.k Travel to Kalgoorlie

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
167747	Fit mast after transport	Internal	Omega	31/08/2018	ONSITE	Repairs & Maintenance	JPRINCE	1890	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JPRINCE	20/09/2018	Carry Out General Technical Support	0.50	0	\$0.00 RM		160610SI	289710
Labour	JPRINCE	3/09/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	281135
Labour	JPRINCE	3/09/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	281136
Labour	JPRINCE	3/09/2018	Refit Other Mast	9.50	0	\$0.00 RM		160610SI	281134
Labour	PRAPADA	31/08/2018	Carry Out General Other General	5.50	0	\$0.00 RM		160610SI	280849
Labour	PRAPADA	31/08/2018	Carry Out General Travel to site	0.40	0	\$0.00 RM		160610SI	280848
Job Total:						\$0.00			

Note : Fit mast after transport

Carry Out General Travel to site

Carry Out General Other General

ASSIST JAYSON AND KERRY TO FIT MAST ON 32 TON FORKLIFT.

Refit Other Mast

Unload machine and mast from trucks. Set up job site and install mast onto machine. Carry out operational checks and tests. Found machine has a fault with the accumulator charge valve. Allied Forklifts are sourcing parts to repair fault.

Carry Out General Technical Support

125146	1606 Customer repairs and general work	Internal	Omega	28/08/2018	BHPNICKELS	Repairs & Maintenance	1601OOS	1880	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
						\$0.00			
Job Total:						\$0.00			

Note : sent to Perth for a birthday on equipment

19/3/18 Nath to get the quote for the reairs list out of Allied forklifts Perth TT

16/4/2018 2 invoices split between customer damage and fair wear and tear.

CD Invocie 1227427 \$56194.27

W&T Invoice 1226126 \$89848.52

25/7/2018 machine should be ready by end of month, testing is taking place as of 18/7

121682	repair mast	Internal	Omega	10/02/2018	BHPNICKELS	Repairs & Maintenance	PRAPADA	1880	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	PRAPADA	10/02/2018	Carry Out General Travel to site	0.50	0	\$0.00 RM		160610SI	179742
Labour	PRAPADA	10/02/2018	Repair Other Attachments	3.00	0	\$0.00 RM		160610SI	179743

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
Job Total:						\$0.00			

Note : Job Created by FSM technician

Carry Out General Travel to site

Repair Other Attachments

DISSASSEMBLE OF MAST AND CYLINDERS.

95913	service inspection	Internal	Omega	29/11/2017	BHPNICKELS	Scheduled Maintenance	JLIMPAG	1832	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JLIMPAG	29/11/2017	Carry Out General Travel whilst on job	1.50	0	\$0.00 SM		160610SI	146539
Labour	JLIMPAG	29/11/2017	Carry Out Service Inspection Inspection	1.00	0	\$0.00 SM		160610SI	146540
Labour	JLIMPAG	29/11/2017	Diagnose Air Conditioning Aircon/Heating	1.00	0	\$0.00 SM		160610SI	146542
Labour	JLIMPAG	29/11/2017	Diagnose Park Brake Caliper Brakes	0.50	0	\$0.00 SM		160610SI	146543
Labour	JLIMPAG	29/11/2017	Replace Fuse Box Electrical general	1.00	0	\$0.00 SM		160610SI	146541
Job Total:						\$0.00			

Note : Job Created by FSM technician

Carry Out General Travel whilst on job

Carry Out Service Inspection as per Checklist

Replace Fuse Box Electrical general

Diagnose Air Conditioning Aircon/Heating

Diagnose Park Brake Caliper Brakes

repair machine won't start issue, replace corroded fuse box, troubleshoot A.C cool issue, repair door latch, check park brake issue, function test. last engine svc 1807.

89445	Machhne needs hyd repairs and new I	Internal	Omega	2/11/2017	BHPNICKELS	Repairs & Maintenance	1606SCE	1807	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	TTIMU	11/01/2018	Carry Out General Travel whilst on job	1.00	0	\$0.00 RM		160610SI	163840
Labour	TTIMU	11/01/2018	Labour Other Other	1.00	0	\$0.00 RM		160610SI	163839
Job Total:						\$0.00			

Note : Machhne needs hyd repairs and new header tank for coolant

Labour Other Other

Carry Out General Travel whilst on job

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
89444	500hr service	Internal	Omega	2/11/2017	BHPNICKELS	Preventative Maintenance	1606SCE	1807	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
							\$0.00		
						Job Total:	\$0.00		

Note : 500hr service dne

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
33071	Safety Inspection	Inspection	M	2/11/2017		Inspection	1606SCE	1807	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
			Rate change as from 27/7/2016	2.00			\$0.00		
						Job Total:	\$0.00		

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
75131	service Insp	Internal	Omega	26/08/2017	BHPNICKELS	Scheduled Maintenance	JLIMPAG	1744	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Labour	JLIMPAG	26/08/2017	Carry Out General Travel to site	0.40	0	\$0.00 SM		160610SI	94822
Labour	JLIMPAG	26/08/2017	Carry Out Service Inspection Inspection	1.00	0	\$0.00 SM		160610SI	94823
						Job Total:	\$0.00		

Note : Job Created by FSM technician

Carry Out General Travel to site

Carry Out Service Inspection as per Checklist

top-up hydraulic oil, function test.

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
59881	Service Job for recording last service	Internal	Omega	10/04/2017	ONSITE	Scheduled Maintenance	JGLOVER	1566	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Part	NPN	10/04/2017	Service Job created (Data Converted) from last meter reading.	1.00	0	\$0.00 SM		160610PD	
						Job Total:	\$0.00		

Note : Service Job created (Data Converted) from last meter reading.

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
59519	Service Job for recording last service	Internal	Omega	10/04/2017	ONSITE	Scheduled Maintenance	JGLOVER	1566	
Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No
Part	NPN	10/04/2017	Service Job created (Data Converted) from last meter reading.	1.00	0	\$0.00 SM		160610PD	
						Job Total:	\$0.00		

Note : Service Job created (Data Converted) from last meter reading.

Job Code	Description	Job Type	Job Category	Service Date	Cust. Code	Call Reason	Mechanic	Hour Meter	Inv. No
59183	Service Job for recording last service	Internal	Omega	10/04/2017	ONSITE	Scheduled Maintenance	JGLOVER	1566	

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Part	NPN	10/04/2017	Service Job created (Data Converted) from last meter reading.	1.00	0	\$0.00 SM		160610PD		
Job Total:						\$0.00				

Note : Service Job created (Data Converted) from last meter reading.

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Part	NPN	10/04/2017	Service Job created (Data Converted) from last meter reading.	1.00	0	\$0.00 SM		160610PD		
Job Total:						\$0.00				

Note : Service Job created (Data Converted) from last meter reading.

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Part	NPN	16/11/2016	Service Job created (Data Converted) from last meter reading.	1.00	0	\$0.00 SM		160610PD		
Job Total:						\$0.00				

Note : Service Job created (Data Converted) from last meter reading.

Type	Parts/Mechanics	Date	Description	Qty	Discount	Retail Reason	Warranty Expiry	SA Code	PO/TS No	
Part	NPN	16/11/2016	Service Job created (Data Converted) from last meter reading.	1.00	0	\$0.00 SM		160610PD		
Job Total:						\$0.00				

Note : Service Job created (Data Converted) from last meter reading.

Grand Total: **\$0.00**