



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report.

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly.

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich



De-Hire Inspection Check

07/06/2025 / 383726 / Sydney / UE / Battery Electric / Fn945487 / Bal Krishna

Complete

Serial Number Fn945487



Photo 1

Hour Meter Read 5314 hr



Photo 2

Service Job No. 383726

Location Sydney

Conducted on 07/06/2025 6:03 AM ACST

Conducted By Bal Krishna

Truck Category UE

Truck Make Battery Electric



Photo 3

Equipment Exterior

General Appearance / Paintwork



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9

WEAR & TEAR

Include Images of the Front, Rear & Sides of the Unit



Photo 10



Photo 11



Photo 12



Photo 13

Wheels/Tyres

Front Wheels / Tyres

OK



Photo 14



Photo 15



Photo 16

Rear Wheels / Tyres

OK

Wheel Bearings

OK

Chassis/Structure

Overhead Guard

OK



Photo 17



Photo 18



Photo 19

Chassis

OK



Photo 20



Photo 21

Battery Cover

OK



Photo 22

Driver Seat & Fixing

WEAR & TEAR



Photo 23



Photo 24

Panels and Covers (Left & Right)

OK



Photo 25



Photo 26

Accessories (Mirrors, Blue Lights)

OK



Photo 27

Windscreen

N/A

Rear Screen

N/A

Arm Rest

OK




Photo 28

Connection Elements

OK




Photo 29

Drive Unit

Transmission Operation

OK

Transmission Noise & Leaks

OK

Drive Motor Condition

OK

Brake

Brake Function & Adjustment

OK

Steering		
Steer Motor Operation/Noise		OK
Steering Cylinder		N/A
Steer Axle		OK
Steering Wheel/Controls		OK
Hoist Frame/Load Lifting Device		
Mast To Full Height & Bearings		OK
Forks & Fork Carriage		OK
   Photo 30 Photo 31 Photo 32		
  Photo 33 Photo 34		
Lift Chains Free & Secondary		OK
  Photo 35 Photo 36		
Hydraulic Cylinder Free Lift		OK



Photo 37

Hydraulic Cylinders Secondary Light Right & Left

OK



Photo 38



Photo 39

Hydraulic Hoses Conditions

OK



Photo 40



Photo 41



Photo 42



Photo 43

Reach Carriage & Cylinder

OK



Photo 44



Photo 45

Sideshift Carriage & Cylinder

OK



Photo 46



Photo 47

Tilt Function & Cylinders

OK

Hydraulic System

Valve Block

OK

Pump Motor Operation

OK

Pump Operation

OK

Hydraulic Function Levers

OK

Electric System

Multi-pilot & Solo-pilot

OK

Strobe & Working Lights / Alarms

OK



Photo 48

Drive Display, Console & Instruments

OK

Lines in the display



Photo 49



Photo 50

Main Contactor & Connectors

OK

Charger Condition & Operation

OK



Photo 51



Photo 52

Battery

Battery Condition & Cables

OK



Photo 53



Photo 54

Battery Carriage

OK



Photo 55

Battery Lock System

OK




Photo 56

Additions or Attachments

Any other related attachments

No

Were any issues identified?

Wear & Tear

(Internal) Parts required - BE

Seat cover

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27




Photo 28




Photo 29



Photo 30




Photo 31



Photo 32




Photo 33



Photo 34



Photo 35



Photo 36




Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55




Photo 56