



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

Incoming Inspection Check

27/11/2024 / FN950985 / 364620 / Sydney / UE / Battery Electric

Complete

Serial Number

FN950985
14 - EFG - ELECTRIC
COUNTERBALANCE FORKLIFT
TRUCKS

Hour Meter Read

1753 hr

Service Job No.

364620

Location

Sydney

Conducted on

27/11/2024 12:00 PM ACDT

Conducted By

Lucas's skinner

Truck Category

UE

Truck Make

Battery Electric

Equipment Exterior

General Appearance / Paintwork

DAMAGE

Unit will need to be painted on the rear end



Photo 1



Photo 2



Photo 3

Include Images of the Front, Rear & Sides of the Unit



Photo 4



Photo 5



Photo 6



Photo 7

Wheels/Tyres

Front Wheels / Tyres

Front tyres need replacing

WEAR & TEAR



Photo 8



Photo 9

Rear Wheels / Tyres

Rear tyres need replacing

WEAR & TEAR



Photo 10



Photo 11

Wheel Bearings	OK
Chassis/Structure	
Overhead Guard	OK
Chassis	OK
Battery Cover	OK
Driver Seat & Fixing	OK
Panels and Covers (Left & Right)	OK
Accessories (Mirrors, Blue Lights)	OK
Windscreen	N/A
Rear Screen	N/A
Arm Rest	N/A
Connection Elements	OK
Drive Unit	
Transmission Operation	OK
Transmission Noise & Leaks	OK
Drive Motor Condition	OK
Brake	
Brake Function & Adjustment	OK
Steering	
Steer Motor Operation/Noise	OK
Steering Cylinder	OK
Steer Axle	OK
Steering Wheel/Controls	OK
Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	OK
Forks & Fork Carriage	WEAR & TEAR
Forks are undersized, require replacing	



Photo 12



Photo 13

Lift Chains Free & Secondary	WEAR & TEAR
Free lift chain requires replacing	
Hydraulic Cylinder Free Lift	OK
Hydraulic Cylinders Secondary Light Right & Left	OK
Hydraulic Hoses Conditions	OK
Reach Carriage & Cylinder	OK
Sideshift Carriage & Cylinder	OK
Tilt Function & Cylinders	OK
Hydraulic System	
Valve Block	OK
Pump Motor Operation	OK
Pump Operation	OK
Hydraulic Function Levers	OK
Electric System	
Multi-pilot & Solo-pilot	N/A
Strobe & Working Lights / Alarms	OK
Drive Display, Console & Instruments	WEAR & TEAR
Controls on display don't work, will require replacing	
Main Contactor & Connectors	OK
Charger Condition & Operation	OK
Battery	
Battery Condition & Cables	WEAR & TEAR

Battery is filthy, will require a deep clean

Battery Carriage	OK
Battery Lock System	OK
Additions or Attachments	
Any other related attachments	No
Was any wear & tear identified?	Yes
(Internal) Parts required	
Free lift chain x1	
Tyres x2	
Front tyres x2	
Rear tyres x2	
Was any damage identified?	Yes
(External) Parts Required	
Paint	

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13