



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

De-Hire Inspection Check

13/05/2025 / 381137 / Sydney / STR / Yes / No / Yes / 51143605.

Paper clip. Front hood

Table

Rear cover LH side / 3 / 90648320 / Terrence Pinchin

Complete

Serial Number	90648320
Hour Meter Read	257 hr
Service Job No.	381137
Location	Sydney
Conducted on	13/05/2025 11:29 AM ACST
Conducted By	Terrence Pinchin
Truck Category	STR
Function	
Full function Test & Safety Check	Pass
Truck due for service?	No
Appearance	
Condition of the Unit, Wheels, Paint	Fair

Unit in fair condition very dirty



Photo 1



Photo 2




Photo 3

13/05/2025 / 381137 / Sydney / STR / Yes / No / Yes / 51143605. Paper clip

51343938. Front hood

51319336. Table

51372822. Rear cover LH side / 3 / 90648320 / Terrence Pinchin

Private & confidential



Photo 4

Operation

Test & Tag valid? No

Has damage or repair work been identified? Yes
REFER to customer damage

Was any wear & tear identified? No

Was any damage identified? Yes



Photo 5




Photo 6



Photo 7



Photo 8

(External) Parts Required

Table
Rear cover LH side

Media summary



Photo 1



Photo 2

13/05/2025 / 381137 / Sydney / STR / Yes / No / Yes / 51143605. Paper clip
51343938. Front hood
51319336. Table
51372822. Rear cover LH side / 3 / 90648320 / Terrence Pinchin
Private & confidential




Photo 3



Photo 4

13/05/2025 / 381137 / Sydney / STR / Yes / No / Yes / 51143605. Paper clip
 51343938. Front hood
 51319336. Table
 51372822. Rear cover LH side / 3 / 90648320 / Terrence Pinchin
 Private & confidential



Photo 5




Photo 6

13/05/2025 / 381137 / Sydney / STR / Yes / No / Yes / 51143605. Paper clip
 51343938. Front hood
 51319336. Table
 51372822. Rear cover LH side / 3 / 90648320 / Terrence Pinchin
 Private & confidential



Photo 7



Photo 8