



## **DISCLAIMER: Second-Hand Plant Condition and Safety**

This document is Jungheinrich Australia Pty Ltd's (**Jungheinrich**) official notice that the second-hand plant offered for sale through this transaction (direct sale or auction) may contain faults or deficiencies that could pose risks to health and safety.

### **Important Information**

#### **Safety & Compliance of the Plant**

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The **enclosed** Condition Report sets out the current condition of this plant, including any identified faults.

While all efforts have been made to identify faults, there may be other faults present that did not show up at time of inspection

#### **Operational Safety Notice**

The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use.

By participating in this sale and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

#### **Operating condition of the plant**

Note: this condition report is a safety report only and does not represent overall appearance or operating condition of the plant

For any questions please contact Jungheinrich



## Used Sale Safety & Compliance Check

MHE-000014 / 131004 / Melbourne Service / 01/09/2025 /  
Jungheinrich / EFG 216kn

Complete

Flagged items	0
Report ID	MHE-000014
Technician Name	Melbourne Service
Conducted on	01/09/2025 10:44 AM AEST
Branch	Melbourne
Unit Details	
Equipment No.	131004
Brand	Jungheinrich
Model	EFG 216kn

### Include Images of the Front, Rear & Sides of the Unit



Photo 1



Photo 2



Photo 3



Photo 4

## Observations Summary

### Truck Category

Category 3 - Electric  
Counterbalance

Emergency Stop, Horn/Warning device, lights, reverse alarm and flashing lights operational

Yes

Seat switch and seat belt switch fitted to check presence of operator & working in sequence?

Yes

Seat is secure and seat belt is in serviceable condition?

Yes

Mast switch operation for travel speed reduction to 3kmh above specified height

Yes

Are brakes and park brake functioning correctly?

Yes

Are tyres worn beyond limits or have damages rendering them out of service?

No

Are fork tynes in good condition and within specification?

Yes

Are mast chains in good condition, within specification and working correctly?

Yes

Are all controls inc. lift, tilt & sideshift/auxilliary functions working correctly

Yes

Confirm safety systems not bypassed or malfunctioning?

Yes

## Additional Observations & Actions

### Technician Sign off



Seng Ream  
01/09/2025 11:00 AM AEST

## Media summary



Photo 1



Photo 2



Photo 3



Photo 4