

Coates

Coates

Coates Hire Pre Divestment Inspection Checklist

Air Compressors

Name ANTOINE CURTS Branch MILBORA
Description COMPRESSOR 1400CM Asset # 1149346 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information:

*** Copy Data Plate information in this section ***

Make/ Model INGERSOLL RAND 7/4 Engine / Motor - Make / Model _____
Year 2015 Engine Serial Number _____
Serial Number 432261 Meter Reading 458 (520)

Comments:

NEW METER AT 62 HOURS.

Features:

List features or options for the machine:

Air Pressure Range 110 Frame Mount ☐
Air C.F.M. Rating 140 Trailer Mount ☒

Comments:

Overall Appearance:

	Good	Fair	Poor
Control Station/Operator Station	☐	☒	☐
Sheet metal/Fiberglass Condition	☐	☒	☐
Paint	☐	☒	☐
Lights	☒	☐	☐

Comments:

Control Station

	Operates		N/A
	Yes	No	
Operator Controls	☒	☐	☐
Gauges Operational?	☒	☐	☐

Comments:

E-STOP O/S.

Engine or Electric Motor:

Power: Diesel ☒ Gas ☐ Electric ☐
Does it start? Yes ☒ No ☐
Did it need to be jumped? Yes ☒ No ☐
Acceptable Power ☒
Unusual Noises ☐

Comments:

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A
Landing Gear / Outriggers	☐	☒	☐	☐	☐	☒
Frame Condition	☐	☒	☐	☐	☐	☐
Trailer Lights	☐	☒	☐	☐	☐	☐
Trailer Electrical Connections	☐	☒	☐	☐	☐	☐
Trailer Brakes	☐	☒	☐	☐	☐	☐
Switches	☐	☒	☐	☐	☐	☐
Separator	☐	☒	☐	☐	☐	☐
Pressure Release Valve	☐	☒	☐	☐	☐	☐
Hoses	☐	☒	☐	☐	☐	☐

Comments:

DRAW BAR BENT /
COUPLING.

Tyre Condition:

Left - Front		Left - Rear	
Brand- <u>KARCOMAX</u>	Brand- <u>POWERTRAC</u>		
Size- <u>165.13</u>	Size- <u>165R.13</u>		
Condition- <u>FAIR</u>	Condition- <u>FAIR</u>		

Comments:

Definium Device fitted? Yes No

Definium device returned to BU ASM