

TRANSPORT MAINTENANCE & SERVICE RECORDS











REGO No.	010.069
ENGINE No.	23506944
	RO1605
MAKE IN	TERNATION AL.
YEAR BUILT	1996

ı	PLANT No. 501
	CHASSIS No.
I	DESCRIPTION WASTE BINTRUCK
ı	MODEL 72670. 8×4

VEHICLE SPECIFICATION RECORDS

LINTS	MAKE	MODEL	HORSEPOWER
ENGINE	CUMMINS	410	250
	MAKE	MODEL	RATIO
TRANSMISSION	EATON.		9 SPEED DI
FRONT DIFF	MAKE	MODEL	RATIO
REAR DIFF	MAKE	MODEL	RATIO
SUSPENSION	MAKE	MODEL	
JOSI ENGION			Figure 1
WEIGHTS	25 QQQ	12200	27 900
РТО	MAKE	MODEL	
HYD PUMP	MAKE	MODEL	
TYRE SIZE	FRONT	REAR	
MISCALLANEOUS			CFLEE SC
		6	P\$71.17
- 301			15 mg/l
			354
8			LUCE AND STATE

LUBRICATION & REFILL CAPACITIES

COMPARTMENTS	CAPACITY - LTRS	OIL TYPE
ENGINE		ALL FLEET 15W 40 EXTRA.
TRANSMISSION		HPO 50.
DIFF FRONT	2 11	HLS 90
DIFF REAR		HLS 90.
TRANSFER CASE	p.	N/A.
HYDRAULIC SYSTEM	12200	ULTRAMAX HVI 68.
FILTER LISTING	 	
ENGINE OIL		
TRANSMISSION		N/A.
DIFF FILTER		* 1.4
IN LINE AIR FILTER		N/A.
AIR FILTER INNER	Y	
AIR FILTER OUTER		
FUEL FILTER		
WATER FILTER		
POWER STEERING FILTER		

OF SERVICE	HUB METRE READING	TYPE OF SERVICE	9	OMMENTS	No.
22-7-96	22286	20,000	1	Congress	- 17 FF 36
23.8.96	21974	20,000		-33.0	
22.11.96	11054hrs	20000	Then 26473		
31.1.97	57240	20000		The Cartie	S-15-1 3
3.3.97		OUL CA	MANGED NEW MOTOR		
19.4.97	68/1009	80000	thus 68 110	75. 55	
30.4.97	69877	5000			
14.5-97		20000	pis 12300	==44	
23-8 .97	74465	5000			4747
18.6.97	12605 hs	20000		-0.0	L Name of
9.7.47	82808	5000			V.C.
24-7-97	12890	80000		men.	- PET 1
8.8.47	87856	5000		2333.	They are a
16-8-97	13066	5000		035	5 5 7 7 W W W W W W W W W W W W W W W W
28.8.47	91503	20000	13151	-,30	NO/2N 1%
2.10 47	97415	20000	13442	246.5.55	
11.11.87	13780	20000		0.55%	- 6 × 2 € 1 × 11 ·
27-1147	13933	5000	32.246	100-00 1	RIPH PISTON
11.12.97	14099	80000		300 31	31-11 30036
16-12-91	14091	5000	111865	1 6000	in a line
21.1.48	14396	20 000		Mark Tr. Tr.	The contract
5.3-98	14748	20000	581823	3000	- 43342 Sec. 1
153 98	14807	5000	23.75.55		- 13 E 4 S
84.98	15041	20000		To de traction	Tanada ta
21.248	15393	80000		errie C.I	E
2-7-48	15739	20000		3000	18202 -
24.7.48	15934	20000	The same of the sa	2	erithi e
12-8-68	16/19	10000		-	X3754
7-9-98	16305	20000		-12.31	13512
22-10-48	16566	80000			
6.11.98	16796	10000	169 482	2	the state of the s
26-11-44	16913	20000		3005	= 27 (15) × 10 5
5-12-98	16981	10000	344	0000	15212 6
18:12-98	ניזמניז	100-00	2 12,332	000 .3	7.80 51337
12-1-99	17299	20000	179248	0000	3.40 00 1
29-1-49		(0000			11-15-00-25
11-2-49	17573	(0000	184574	10000	PENS & I
26-2-99	187 030	10000		Chan	rang e
11.3.99	189250	10000	17808	ortol.	255125
18.3.99	1785745	20000	190258 Am	200-1	J775 10.

OF SERVICE	HUB METRE READING	TYPE OF SERVICE		co	MMENTS		
1.4.49	17983hi	10000			33335	77252	
16.4-49	1807Zh	10000			1777		
3.5 99	1821060	80000	197873 May			. 192-0	
14.5.99	18309	10000					
28.5-99	13412	10000	The same	-	(447	-
18.6-99	18281	20 000	7.15				
25-6-99	18647	10000	8		11.45	53.36.5	50
10-7-99	18771	10000		<u></u>	2000		-
23.7.44	18879	10000			7.5 (Total at	
28-7.99	18915	20000			1 20000	-5737	
16.8.99	19061	10000	214624		2002	2 355	
23.9-99	19394	20000			25338	1000	-
1.10.99	19448	10000				Later 5	1 -
15.10.99	19523	10000			acc.	Section	¥-,
3010 99	19631	10000	226404		111111111111111111111111111111111111111	7505	
9-11-99	19695	20 000	2.4	V = V	2000	9700	
26.11-94	19816	10000			C39975	13.787	1
10-12-99	19939	10000	232266		9999	15833	
22-12-44	20026	10 000			SORO	Word	-
6.1.00	20101	80000	235255	111		10041	102 1
22-1-00	20187	(0000			37 000	20271	Rr.
4-2.00	20264	10000	238/37		000-0	2500	7
18.2.00	20351	10000	239626		5000	10841	TO THE
7.3.00	2047	20000	241727		Gang	14001	924
23.3.00	2058	(0000)			The same	15398	
11.4.00	20689	10000	245P45		20000	PETEL	20.7.5
18.4.00	20733	10000	3		Copert.	+550	80
45-00	20788	20000			00001	18119	75 45
16.5.00	20848	10 000			00005	16305	90 - "
7.6.00	20475	10000			000000	975941	80
28.6.00	21016	20000		ge tot	Septiment of the septim	- 100 1 12	-
20.7.00	7/142	10000			20220	5-00-01	11
5-8.00	21201	10000	255928			12001	Pr. 7
1.9.00	2/337	20000	2587/7		00.001	-m-r	you on
25.4.00	21435	10000	7,45	179	Control	17299	4
28.10.00	21572	10000			(0000)	12455	pn-5-05
16-11-00	21679	20000	¥T	5481	00101	51751	Birth Ellin
29-11-00	21729	10000			20-201	187 020	pn
16.12.00	21825	10000	, _ i D	308-1	0.400	083181	PP-5-11
10-1-01	21954	10000	258 Au			1725 74	

DATE OF SERVICE	HUB METRE READING	TYPE OF SERVICE	COMMENTS	11-11-11 11-11-12 11-12-28	
120101	21983	20000			
7.2.01	122075	10000	the second	7	
20201	22074	10000			
83.01	22259	20000		27,2915	
2.401	22397	10000		E. T.	200
17.4-01	22466	10000	3734	COLUM	
4-5-01	225 46	80000	12	7.8255	100
25-5-01	22636	10 000	GE A,		
5.6.01	22685	10000	623.11	2775	
13-7-01	22836	20 000	80,000	27330	
26-7-01	22880	10000	10,660	12825	A.
22-8-01	220187	10000	999,01	27943	
30.8-01	23027	10000	033.0	27961	
139-01	2073	10000		25011	<i>y</i>
26.4.01	23115	20000	20,050	28072	921.52
22-10-01	15877	10000	(0,000	28108	9
29-10-01	23252	10000	Can 31	29273	2
22-11-01	23353	1000	200	281188	2-2-3
7.12.01	23414	20000	California Carlotte	2022	181718
16.1.02	23569	10000		1524 198	- 3
23-1.02	23595	10000	16 250	28415	A
5.202	23680	10000	10,000	28424	100
14.2.02		80000	2000	100000	
	23864	10000	338 (-	335-	
17.4.02	24085	20000	80,000	25838	1 - 1
	21247	10000	16,550	254 0	204-07
24 502	25280	20000	0 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 1 0 0 1 0 1 0 0 1 0 1 0 0 1 0 1 0 0 1 0 1 0 0 1 0 1 0 0 1 0	TANK DE	
B.6.02	24379	10000	20,000	29102	22-2.52
5.7.02		10000	(2,000	24223	1
19-9-02		10000	0000	29284	
14-10-02	24813.	10000	20,000	JASA2	PO-P-08
7-1102		20000	936.01	2र्वात्ता	1-6-10
2.12.02		10000	10000	Tanal	r 32
2412.02	75064	10000	000	01202	
16.1.03	25129	10000	Company Company		
4.2.03		80000	00001	29631	143-12
	325343	10000	10,000	29643	15-10-12
3-6-03		10,000.	CASCAS.	CENTED P	
239-03	- 1	20,000	(Action)	29666	For a M
20-10-03	2589Y	10,000.			

DATE OF SERVICE	HUB METRE READING	TYPE OF SERVICE	COMMENTS	entale e
10-1-04		10,000		CHI S T
	26239	20,000	1837	700234
21-5-04	26753	80,000.	ers = 1	
11-6-04	26878	10,000	6385	7.00
27-07-04	27,123	10,000.	1 218.83	THEFT
9-8-04	/ .	20,000.	2000	33425
	27385	10,000	705	32:25
23-11-04	27700	10,000	28000 m. (
25-1-05	27355	10,000		
30-3-05	27830	80,000		HOLL :
45-05	27871	10,000	96403	02877
25-8-05	27943	10,000	Const. St. 2	
	27961	10,000	men.	TRADE I'M.
21-11-05		10000	0~71	
	28072	20,000		1345
The second secon	28108	10,000	200-01	
21-3-06	29233	10000	James	
	28188	10,000	57/201	200000 2000
7.40	28250	20,000	6900	+x122
59-06	28322	10,000	Cocal	11/202
15-11-06	28413.	10,000.		11:10
24-11-06	28424	10,000	SOUTH SOUTH	D5:16.2 -
13-2-07	28534	20,000.		247.83
2-407.	28602	10,000		
129-07	28838	80,000		TO BALL
20-11-07.	28940.	10,000	00001	2 21247
	28971	10000	0000	0.57.52 - 02
28-5.08	29102	20,000	00001	BLEDE 301-81
29-1-09		10,000	0000	D. Miles
30-6-09		10,000	5000	876 42 2
30-9-09		20,000		21,303
1-6-10	29440	10,000	20000	to yell of
20-10-10		10,000	9000]	ON 1940 To
2-4-11	29570	20,00	1000	200-
5-7-11	29617	10,000	Court	02.50
14-3-12	29631	10,000		
15-10-12	29643	10,000	(800-1	- TUS 113
19-2-16	29666	80,000	- C - CW	13 25437
19-2-16	29 beliefe	80000		32,532
			0.80.4	7 2589Y

INDEX

PAGE NO.	COMPARTMENTS
1.	COOLING SYSTEM
	RADIATOR HOSES YMOUNTS
	WATER PUMP
	FANY FAN HUB. DRIVE BELTS.
2. Cal.	THERMOSTATS. HEATER.
2-4.	ENGINE Y ACCESSORIES
	ENGINE ASSY & MOUNTS.
	STARTER MOTOR. ALTERNATOR.
Till and the second	FUEL PUMP & FILTERS.
	POWER STEERING PUMP
	AIR COMPRESSOR
	TURBO CHARGER
	EXHAUST SYSTEM.
	Charles on an and action Daniellans
5-7.	TRANSMISSION. CLUTCH. P.T.D. DRIVELINE.
	GEARBOX ASSY & LINKACES
-	CLUTCH ASSY & LINKAGES
	P.T.O. PUMP. HOIST HOIST VALVES & HOSES
	TAIL SHAFTS & BEARINGS. UNIVERSALS.
8-10	STEERING Y SUSPENSION.
	STEERING COLUMN.
	STEERING BOX ASSY Y WINKACES
	KING PINS Y FRONT AXLE.
	SPRINCS . SHACKLES . SPRING HANCERS.
	TORQUE ROD BUSHES Y SHOCKS.
11-13	REAR AYLES + BRAKE SYSTEMS.
14-15	CAB. BODY YMISCELLANEOUS EQUIPMENT.
16-17	
-	

OF REPAIRS	Hub or Hour Meter Reading	TYPE OF REPAIRS TO
22.7.96	22286	REPLACED PLL ENGINE WATER HOLES.
23.8.96	27974	REPLACED WATER PLANT
3.3.97	11744 hs	Rangers lizare F
25-9-03	355210.	Change The mostat, Radiate
22-05-04	88445.	Change Thermostat & Radiator cap. Flushed cooling system. + Replace (2) Rad hoses.
13-2-07	28534	Kit engine con hub
7-6-10	29993	Replaced for belt
	~~~	reflected fan belts
¥.		
		the state of the s
3000	44.7	
		El + porting to married assemble
		The same of the same of the same
SNATE	4.8	Market British British British
	1.12.13.13	The state of the s
	7.00	and the state of t
		the state of the second
		AND THE STATE OF T
	1 1 1 1 1 1 1 1	
	2.11.0.2	The state of the s
	4 1	
		The state of the s

OF REPAIRS	Meter Reading	TYPE OF REPAIRS TO
14.12.95		STARTER MOTOR O'HAULED INV. 88633.
3.5.96		OIL LEAK AT COMPRESSOR MOUNT SEALED, WATER LEAK
		AT OIL COOLER SEALED
26.7.96	23327	Repaired fuel Leak at Pump Fuez Pump Fitter
31.1.47	57240	INTERIORS REPLACED & TIME UN DONE
3.3.97	11744 hrs	CRANK SHAFT REMAND, Brown LINE BORED NO ZJ 3
	60421 hus	
	279849 KS	FRONT HAS METTEL SPRAYED, BIG END & MAINE
	ON SPERMO	REMAKED, PLT REMAKED
19.4.97	68110 Hus	The REMOVED, HARMONK BALANCER
	-	Remarko
5/6/	12490 hrs.	Stater Motor replaced
20-1202		Renain Barrer
21-7-03	352809	replaced intercooler hoses
8-1-04	26042.	Removes fit New water pump
26-2-04	3594600.	
5-6-04	86818	Fit new feel sender.
20-8-05	10865	Replace FOR FITTERS
14-3-06	28131	Replaced exhaust gaskets Replaced
	•	oil Pressure switch
5906	28322	Replace Temp sender unit on header Tonk
20-6-07	28730	Replace RAT Isolation switch
22-11-07.	28936	Fit New isolation switch
8-4-08	29651	Resealed of cooled (engine)
28-3-12	29634	Replaced mustle
15-10-12	29643	Replaced of cooles (engine) Replaced muffle Replaced reg & brushes on alternator
		•
4 = 2	-	
		· ·
		Page

OF REPAIRS	Hub or Hour Meter Reading	TYPE OF REPAIRS TO
9.2.96	2	ADJUSTED GLUTCH.
31.1.97	57240	NOI TAILSMET OVER MALLED & UD GARDED
		REPLACED GAME SHIFT UNIS
3.3.97	11744	PTO Uni front REMARTO SEAL KET FITTED
		TO PTO
21.1.98	14396	Replaced any joint in PTO shatt
2.2.98	144771	Overhand gear shift bax
7-9-98	158059	PTO SMAFT REMINEUD
28-7.99	18915	Replaced thru shoft red.
7		i 2 uni jaints
29.7.99	18421	THRY SHAFT BRES REMANDE & PTO SOME
6.10.99	19462	Replace No. 1 universal
11.1.00	456990	NO 2 THURANT ROMAN BOTHEY
3.5.00	20800	Reflored P+O. Shoop.
25-8-00	21207	Chutch replaced.
22-5-00	21419	Replace un in generatide tower.
19.6-01	22738	Rem Compos Some Removes
2-2-02	23699	Contra Rom Resonue
25-7-03	25584	fitted clutch assimply - clutch break
		titled spigot bearing, Changed PTO drive gear
,		swapped counter shates around
8-4-04	,	change Tail shaft cheek all unis
22.5-04	88445	Kitted gear stick control box.
5-6-04	80818	KEMOVE-KEPKER O-BOX MOUNT
6-10-04	27564 Hes	Leplace & Bealing.
7.10.04	27599	replaced # 2 tail Shaft
-12-04	•	Replaced UNI on PTO Shats.
4-9-06	28322	Replace geor pox selector town (ROCO TRUCK THAT
/.		poplar UNIS on gar stick short
3-12-06 :		Replace PTO shaft
25-1-07		Kit fro (Power Acto)
5:2.07		Replace GBOT Mount Kubbals
12-1/07.	24436.	Replace UNI Selfind OfDot
77/07.		leplace 150 staff drive geal.
8308		Replace seal on Front ditt. & Ditt +0Ke+UNI.
5508-	29077	FIT PIO SHAET.
7-7-06	29127	Replace (Reco) PTO
25908 2	29159	Fit C/stick Boot - Re-Bush & Reem C/stick
	2	control Box

OF REPAIRS		TYPE OF REPAIRS TO
9.2.96		REPAIRED G.SHIFT REMOTE. OIL LEAK AT PT.O.
7		
-6-7		
. 0		
		× × ×
	_	
/ 57		
100		
	•	

DATE OF REPAIRS	Hub or Hour Meter Reading	TYPE OF REPAIRS TO
9.2.96.	Rear	FITTED S/E BOGIE BEAMS, TORQUE ROD BUSHES.
		SPRING EYE BUSHES, IDLEA ARM PIN + BUSHES.
4.1.96	DHJ - O	4 BOLT REAM SPRING
7.2.96	Replace	REAR MAINLEAR, I SPRING HANGERS (REAR)
26.7.96	23327	KING Pine fitted To 2nd STeer
8 8 96		w Align. Figtree Eng-
4.3.96	57626	WALTER BURNS PETERSON SADDLES BUILT UP
de	eel cho	& SPRING MINS & BUSINES REPIRED
9.7-97	8 2808	RHF SMING MAIN LENY REPURED
11.11.47	13780	REMINISTO TIX ROS ENO FRONT OF REMIN
,,,,,	> 1	Machina & P/STORA RAM
8.448	15041	RHF BOTH STEEN SMINES REMAKED
24.10.98	1656	Replace near droglish & represejant on end.
16.11.44	16913	TIEVOD ENDS ON PISTEEN RAM & CARELINA
61111	10113	Repenses, Whenen beams Repension
28-7-99	18915	Replaced wheelstud LUR steer
16.8.99	19061	TIEROS END ON SELONO STEER DROG LINE
10.0		FIRSTEN
23.9.49	19386	Replace LHF spring & twin own bush a front of ram.
6. 10.99	19462	Repline LHR Spring
11-2-00	11402	Replace Front the rod + ends
21-3.00	20574	Fit new pin + busies to fivin steerable.
	20788	REPLACE ZEO STEERING RAM
13.400	123419	
24-2-01	22074	Fit rente steer drup ann
16.3.01	278707	Replace LUF of front son stee spring hongor
10 7 01	218201	Replaced walker beauty, near torque rod busles
70 9	22 440	" CH tie rod end front steer
14.702	2499	Replace 2nd steer hanger
19.7.02	24527	for up hing pin hits
	356046.	reflaced front shocks
10-10-03	336040	Replaced RHF Steel spling real bushes a pins
17-10-03	201211	Keplaced Shocks
17-10-03.	356346.	Fit L/H/R hangel & pins, Replaced F/steel sping
		hangeis & Pins, bushes Retit shocks
		Réplaced Two Tie rod ends Replaced and axle
		drag Linka balljoints and rear balljoint on Stea
20	261-	and lam to second axle.
20-10-03		Wheel align (PRO AXLE)
1-9-04	27385HR	
		Bushes in Rew hanger. Page

OF REPAIRS	Hub or Hour Meter Reading	TYPE OF REPAIRS TO
16-10-04	27564	Ry Replace spling pins F/4/4 Reas
30905	27983	Replace RHTierod end
23-206	43447314	FIT RH ROOM SPIING REPLACE LHR SPIING.
		Replace LHF spring (Steer) Replace (2) Pin
31-8-06	28322	Replace bushes on RHS String Hangers
1-9-06	/	Replace LH Side Hangel boshes
5-9-06		Replaced Front drive Torque Rad bosh.
7-2-07.	28533	Replace LHF Second Steel shock
13-1/07.	28946	Kitt RH and Steel King Pin
261101	28946	Fit up last dragtink Front Tie Roder
29.08	29159	Leplace Walker Beams
8-9-68	29159	Replace Reco Steeling box (Newman
26-9-08	1 10	Replace BHZad steel King ping Bearings
est.	S. 180 N. 1	Replace HUB Seed Replace RH 1st Steel
		King giv a Bayings Replace LHR Ster
		Wheel bearings / Reline LHF + R Steel
8-1/-14		0. //1 / 1 / 1 / 1/15
8-11-14		Replaced torque rod bushs (all)
8-11-14		0. //1 / 1 / 1 / 1/15
8-11-14		Replaced torque rod bushs (all)
8-11-14		Replaced torque rod bushs (all)
8-11-14		Replaced torque rod bushs (all)
8-11-14		Replaced forgre rod bushs (all)
8-11-14		Replaced forgre rod bushs (all)
8-11-14		Replaced forgre rod bushs (all)
8-11-14		Replaced forgre rod bushs (all)
8-11-14		Replaced forgre rod bushs (all)
8-11-14		Replaced forgre rod bushs (all)
8-11-14		Replaced forgre rod bushs (all)
		Replaced forgre rod busts (all)
8-11-14		Replaced forgre rod busts (all)
2462-		Replaced forgre rod bushs (all)
2442		Replaced torque rock bushs (all)
21A15A-		Replaced forgre road bushs (all)
		Replaced torque road busts (all)
2.A.S		Replaced torque road busts (all)
		Replaced torque road busts (all)
		Replaced torque rod bushs (all)
		Replaced torque road busts (all)

DATE OF REPAIRS	Hub or Hour Meter Reading	TYPE OF REPAIRS TO
10.2.96		TIGHTENED FRT. DIFF FLANCE.
30 7 96	23623	Replace Rear hub 2006.
26/7/46	13317	Relined Rear Bogie + Rebuilt S/cams
27.8.96		LHF DRIVE HAS SEME REPLACED
16.12.91	111863	FRONT PORT REPURCED
7.9.98	158059	RELINGO BOTH STEEMS
13-2-99	184811	Replace LHF hub read.
9-11-99	19695	Replace slock adjuster
10-11-99	19738	Foor Vans Reamon
10.12-64	_	
13-3-00	20519	RIAR BOOSER FITTUP
29-3-00		Relined LIBR wheel shulsend;
10.6.00	20975	'a" fort doine
5.2-07	23680	heflued LAR drue booster
24.7.02	24516	VEVILLORY WAR ( ) ( ) ( ) ( )
	7	refluced LHR drive booster diaphrum
	B	
2-10-03	355697	Fit new axte to 414 Real wheel.
15-10-03:		replaced -////Booster diaphram
26-2-64	359400.	Replaced hub drum, relived shoes
17-2-04	26239	Reline RHR drive, replace Scam boshes
		Replace hus seal
9-9-04	27385	FITNEW Scam RIHIF drive Fit New
		S can his her + high soul sile
	4	s can bushes + hub seal Fldrise Fit
1.11.04 2	27650 0	efface RHF drive booster
1-12-04	5086.	Replace husb line
	1	RIGHT SPING & Refail
	6	Replace bush + PIN IN spring. + Refail RINK Spring Replace hub seed on RHI-
-5-05 2		Reline LH Steer Replace whole bearing set
1-12-06 2	28472.	Replace LHF drive booster
55-07. 2	06/8	Fit 140 live to booste
5-6-10 2		Leplaced rear diff pinion seul
		pinion seul
ge 11	1	

DATE OF REPAIRS	Hub or Hour Meter Reading	TYPE OF REPAIRS TO
30.11. 95	2 1. 1. 1.	CHECKED BATTERIES CLEANED LUCS INV. 1188.
3.5.96		RIH DOOR LOCK REPAIRED
22.7.96	22286	REBUILT FLASE TANK & BRAKKETS
26.7.96	23327	Repaired Lights + Rewired flashers
2211-96	11054 hrs	26473 Hun Fitten New Sunt Remain LIGHTS
		BULLI CAP SLIDES FOR BIN ROUS FITTED HIS COMS.
		REPAIRED FUEZ TAND LEAR PERMICED LIGHTS
31.1.47	57240	HAZARD SWITCH REPURCED LH MIRROR
010	Josep "	Gins Repinion, Winen Bunners
100	RIPLHO	Romacon
4.2.97	57626	Rena Muccunans REPAIRED & TOOL BOX LID
	1	LICHTS REPRINED
3.3.97	11744	HETTER REMAINED, SUMISOR PAINTED, WAREN
		BERRY FITTED , RH MIRADE GLAS REPLACED
30.4.97	69877	BAU HOOR & LANCHES REMINED
28.8-47	91503	FLASHER SWITCH REPUBLED
5.3.48	14748	Sou Hoor Resurcas
215.98	153 93	Rayano Talugus
2-7-98	15739	Replace can left hydraulic hore.
26-11-44	16913	Conno lan Sons Remover, L'NO Luc
		REMINION & PIN   MOUNTINGS
18-6-99	18581	had a repair fuel tanks.
16.8.99	19061	BIN WEAR RATES MADE & FITTED
28-2-60	20422	Reflece to short.
3.3.00	20452	CLUTEN PERA RUBBER FITTED
\$.3.00	2047	FUEZ TANA STRAP & RUMANA REPLACED
		TIGHTHER SPRENDER AM BARENET
11-4-00	20689	Ban Hood Kimmon, SEAN KERADDED
	2	FITTED HEATER CARLE
	20924	Quehand LU Rom.
	29516	Refluced heater control unit
16703	25,29	Kupinus Sent
	25342	Bon Hoon Kinimun
	35558	FIT new fon motor
20-2-04	2/04/20	Fix new ail tank
26-2-04	359400.	Replace 3 Batteries - Make up new battery abla
01 (00)	ora nui-	Replace falty key switch.
21-5-04	88445.	Fit Ailwcomplessor & Service Ail con
,	86817	Fit new door handle + door trim.
15-6-04		Rewile Real Lights +

Page 14

OF REPAIRS	Hub or Hour Meter Reading	TYPE OF REPAIRS TO
16-6-04	26878	Fix up Lift Rams. (Repaired By Hyrac)
9-8-04	27207	Replace hub mtr.
9-9-04	27385.	Replaced for switch
22-11-04	27699	Replace 4/H Guard
1-12-04	27700.	Fit rams & fuel tank - mud guard.
4-2-05.	27762	Replace spling for beil book
242-05	27784	Service AIC
	10,865 Km	Replace Fuel Filters on fur engine
23-2-06	28168	Fix New door batch Fit New door WID &
		Syrround To RHAND door STRIPLH down.
		Keplace Lovel Hinge.
	28189	Replaced head Light switch
	27385	Replace both cab Lock main bushes
4	28424	Reseal main bail hook Ram
	285 34	Replace RH Air TANK
152-07	. /	Fit New Blockson Rear Rails
12-9-07		Replace Key switch (ignition)
227/07.	28936	FIT New JANK STRAPS Make New
		battery box til so endel pers
	29470	Replaced RH window regulation
15-10-12	29643	Replaced 14 buttery
	29661	Send blust chasses
17-7-15	29662	Fittel 2nd hard cal
5-2-16	29663	Replaced 3x butterie & Terminals
7-2-16 3	29663.	repulled AMIEN & installed ULIF
		Inotalled revolving light
	•	hit new door trims
	Was a base of the	Regas A/C sustem
		Regas A/C supters
		TOTAL BUT Kingday D. W. S. W.
		and the sound harder many in the
	•	To 29 Tenno Son
		125 - 252 42 Em 125 Kindle
		ISSIS Pet men is motion
	X-11	and the same of the same
100 110 11	30 1500	1. 320/12 - 32/6/20 1 Boyles - 1/10/20 14
,		The state of the second st
-1		The second of th
	- X	the state of the s