

Stock No: APH01057

Terex TA30 Watertruck

Serial No: A8681100

Reg No:

Cat: WCART30 Year: 2005

Provisional?:

Supplier:

Model: Terex TA30

Under Repair?

Log

<i>Date</i>	<i>Type</i>	<i>Description</i>	<i>Meter</i>	<i>Labour</i>	<i>Parts</i>
22/05/2024	OTHER	Jennings Glass: Supply Terex windscreen			\$296.90
19/03/2024	REPAIR	DLTL: Check drivers concern truck warming up Carried out inspection Pressure tested coolant system Found blown hose from coolant filter to water pump Removed and replaced hose and fittings Topped up coolant as required Check operation all OK at time of inspection Driver also complained A/C not cold Carried out inspection found belt loose and slipping on compressor Adjusted A/C belt All OK at time of inspection Supplied Heater hose, hose clamp		\$560.00	\$60.00
18/03/2024	REPAIR	DLTL: Got to site Temora Check customer concern machine leaking hydraulic oil and noisy operation Carried out inspection found blown hyd hose to P/S/R sprayer Notified Mitch for course of action Told to fixed Removed hydraulic hose and took down to nearest hydraulic hose shop Made as per original Refitted hose and resecured Topped up with hyd oil as required Check operation all OK at time of inspection Supply hyd oil, hydraulic hose, hyd ferrule, JIC hose tail, JIC fittings		\$560.00	\$819.00

Stock No: APH01057

Terex TA30 Watertruck

Serial No: A8681100

Reg No:

14/03/2024	REPAIR	Harris Heavy Mechanical: Drain engine oil. Pull 3 piece sump off engine, oil pump & pipes. Unbolt middle & sump spacer & big end caps, number & bag. Pull out oil squirters, number & bag. Jack out 1,2,3,6 liner & pistons, clean & pack up		\$780.00	
11/03/2024	REPAIR	DC:: Cap 3 x 1/4 lines in artic. Top up transmission oil 10 litres. Noisy transmission pump. C/O Trans filters. Cut filters, some steel/bronze flecks but serviceable. Grease. Check tyre pressures. N.B Pos 4 and 6 were low. Pumped up to 80PSI and check for leaks. All good (@ 11773 Hours)	11773	\$150.00	
11/03/2024	REPAIR	TG: Install new GPS tracker and wire in. Tidy up wiring behind head unit, check diff oils - all ok. Cap off hoses (@ 11773 Hours)	11773	\$125.00	
21/02/2024	REPAIR	MPL: Check over repair water sprays and electrical.		\$1,668.00	
				<hr/>	
				\$3,843.00	\$1,175.90