Stock No: APH00397 Caterpillar 140M2 Grader Serial No: CAT0140MKM9D01556 Reg No: 98380D

Cat: GRD14 Year: 2014 Provisional?: Supplier: RB Model: Caterpillar 140M Series 2 Under Repair?

Log

Log					
Date	Type	Description	Meter	Labour	Parts
2/08/2024	OTHER	Hastings: Supply Camshaft-gear			\$1,643.81
25/07/2024	REPAIR	Carroll Tyres: stip pos 1, clean oring section, replace oring		\$162.73	
25/07/2024	OTHER	Hastings: Supply 1 x gear-cam			\$949.71
23/07/2024	OTHER	Hastings: Seal, key, gasket, washer			\$104.24
11/07/2024	REPAIR	MPLG: Remove fuel pump		\$712.50	
13/06/2024	OTHER	Hastings: Supply 1 x fuel pump			\$2,304.23
13/02/2024	SERVICE	JE: completed service as per manufacturer specs, sampled tandems (@ 11022 Hours)	11022		
5/02/2024	OTHER	Next REGISTRATION RENEWALS - date postponed from 23-Feb-24			
16/10/2023	SERVICE	JE: Completed service as per manufacturer specs (@ 10512 Hours)	10512		
11/05/2023	SERVICE	JE: Completed onsite service as per manufacturer specs, circle shims added and adjusted as moving onto UTS work (@ 10011 Hours)	10011		
14/02/2023	OTHER	Next REGISTRATION RENEWALS - date postponed from 23-Feb-23			
20/01/2023	SERVICE	JE: Completed Onsite Service, Tandems Checked, Circle adjusted (@ 9507 Hours)	9507		
31/10/2022	SERVICE	JE: Completed Onsite Service (@ 9001 Hours)	9001		
30/06/2022	REPAIR	JB: Remove shims from lower blade lift cylinder burmes. Remove shims from circle sideshaft cylinder, remove shim from A- frame bearing (@ 8533 Hours)	8533	\$350.00	
31/05/2022	OTHER	Westrac: Kit-seal-h.g			\$276.99
28/05/2022	OTHER	Westrac:Motor G Elec			\$1,188.48

Orange Truck & Ag

Stock No: APH00	Caterpillar 140M2 C	Grader			Serial No: CAT0140MKM9D01556	Reg No: 98380D
0/05/2022 OTHER	Westrac: Valve GP-Sol			\$259.10		
/05/2022 REPAIR	PC Diesel: Diagnose fault and replace solenoid		\$240.00			
2/04/2022 OTHER	P&H Jennings: New entry glass door			\$265.00		
3/04/2022 REPAIR	JB: Fit new seal and glass to LHS door then refit LHS door (@ 8419 Hours)	8419	\$150.00			
2/04/2022 OTHER	Westrac: Seal-Bulk			\$81.00		
1/04/2022 REPAIR	JB: Fit belly guard, fit turbo heat shield. Tighten loose boost pipe bracket. Connect EGR valve solenoid plugs, connect ET and set transmission to start in 1st gear and reverse. Run and test, check for leaks. Remove LHS door start to fit new glass (@ 8419 Hours)	8419	\$400.00			
/04/2022 REPAIR	PC Diesel: Reassemble machine and testing		\$960.00			
/04/2022 REPAIR	JB: Fit engine pipes, hose and electrical. Fit AC compressor and alternator and bracket, fit AC alternator belt. Fit engine frame and covers, replace entine oil and filter. Flush coolant and replace. Run and check (@ 8417 Hours)	8417	\$575.00			
/04/2022 REPAIR	PC Diesel: Reinstall engine		\$880.00			
/04/2022 REPAIR	JB: Fit rockers and push rods, carry out valve set, refit engine (@ 8417 Hours)	8417	\$525.00			
/04/2022 REPAIR	JB: Clean up new camshaft, fit new. Fit 5 new cam followers. Refit cylinder head with new gasket. Fit 2 new transmission hoses (@ 8417 Hours)	8417	\$550.00			
/04/2022 REPAIR	PC Diesel: install head on engine		\$400.00			
/04/2022 REPAIR	JB: Replace broken springs in tension damper (@ 8417 Hours)	8417	\$200.00			
/04/2022 OTHER	Westrac: Spring-guide			\$226.68		
/04/2022 OTHER	Westrac: Camshaft, hose ass			\$2,162.78		

Stock No: APH00397 Caterpillar 140M2 Grader					Serial No: CAT0140MKM9D01556	Reg No: 98380D
/04/2022 OTHER	Westrac: Spring as			\$181.17		
/04/2022 OTHER	Westrac: Filter as-lu, gaskets, seal o-rings			\$98.15		
1/03/2022 REPAIR	JB: Clean up parts and cylinder hea. Find part numbers and order (@ 8417 Hours)	8417	\$500.00			
1/03/2022 OTHER	Westrac: Exluder, seals, lifter as- va, rod-valve, gaskets		:	\$1,311.75		
0/03/2022 REPAIR	JB: Remove engine. Clean up and order parts (@ 8417 Hours)	8417	\$500.00			
0/03/2022 OTHER	PH JENNINGS: Supply 1 x Rubber glazed door glass 45D and glazing rubber			\$550.30		
9/03/2022 REPAIR	JB: Remove engine house frame, remove engine wiring harness, remove hydraulic pump, remove pipes and hoses, drain engine oil, remove transmission side covers (@ 8417 Hours)	8417	\$500.00			
4/03/2022 REPAIR	PC Diesel: Engine fault diagnosis. Disassemble, diagnose cause of bent rod. Remove head cam etc		\$1,000.00			
/03/2022 SERVICE	JB: Carry out 250hr service as per manufactures specifications (@ 8410 Hours)	8410	\$135.00			
/03/2022 REPAIR	JB: Fit new push rods to no.1 cylinder. Carry out valve test. Remove starter motor, reseal and refit. Remove drive shaft, replace transmission yoke o-ring and refit driveshaft, top up leaking circle drive box. Refit belly guards (@ 8410 Hours)	8410	\$450.00			
/03/2022 REPAIR	JB: Wash down engine and transmission, remove tappet cover, set up top dead centre, remove beat push rod no.1 cylinder and order new push rod. Check for oil leak, order new starter motor gasket (@ 8410 Hours)	8410	\$315.00			

tock No: APH003	Caterpillar 140M2 C	rader			Serial No: CAT0140MKM9D01556	Reg No: 98380D
03/2022 REPAIR	JB: Carry out cylinder cut out test and injector pump solenoid test. Check and clear old codes OK (@ 8409 Hours)	8409	\$45.00			
/02/2022 OTHER	Next REGISTRATION RENEWALS - date postponed from 23-Feb-22					
02/2022 OTHER	Westrac: Harness and bracket			\$2,049.00		
/01/2022 REPAIR	JB: Replace cutting edges and bolts on blade (@ 8186 Hours)	8186	\$115.00			
/11/2021 OTHER	JB: Replace 2 x lower blade slides and adjust top slides x 2. Washout radiator/intercooler and adjust radiator door stops (@ 8004 Hours)	8004	\$165.00			
/11/2021 SERVICE	JB: Carry out 1000hr service as per manfactures specifications. Replace tandem drive oils. Replace circle drive box oils. Fit missing ripper frame mount bolt and tighten all loose bolts (@ 8004 Hours)	8004	\$450.00			
/11/2021 OTHER	WESTRAC: Oil filter, air filter, fuel/water separator, transmission filter, hydraulic cartidge, fuel filters			\$841.76		
/09/2021 OTHER	WESTRAC: Pump Gp-Wate and Belt			\$833.96		
/05/2021 REPAIR	OMS: Refit missing bolts to GPS pole		\$440.00			
/03/2021 OTHER	DCT: Strip-wear upper half, plate, strip wear lower			\$175.47		
/03/2021 REPAIR	JB: Replace circle pads and adjust. Shim circle plates on top of circle, remove lift cylinder bearing and check over. Adjust both cabin door stickers (@ 7484 Hours)	7484	\$380.00			
/03/2021 OTHER	WESTRAC: Element-prim, as, as- lu, filter as, air filter, filter as f			\$747.48		
/03/2021 SERVICE	JB: Carry out 2000hr Service. Replace LHS blade slides top and bottom, check over (@ 7481 Hours)	7481	\$240.00			

Stock No: APH00	Caterpillar 140M2 C	Grader			Serial No: CAT0140MKM9D01556	Reg No: 98380D
15/10/2020 REPAIR	CPR: Diagnose faulty reciever/dryer, order & Collect parts, replace reciever dryer, vac system, recharge, test performance		\$880.00	\$320.00		
8/07/2020 OTHER	Fit New Cutting Edges (@ 6567 Hours)	6567				
7/07/2020 REPAIR	R&R bllade G.E.T		\$75.00			
7/07/2020 OTHER	DCT - Nut, Blow Bolt, Cutting Edge Curved			\$443.65		
23/06/2020 OTHER	DCT - Element Fuel/Water Sep Bowless			\$45.45		
23/06/2020 OTHER	Check over, R&R Fuel filter, Relcocate 'E' Stop box.		\$100.00			
21/05/2020 OTHER	Tyrepower - Tyre Service			\$600.00		
20/05/2020 SERVICE	Service, Grease, R&R Slew Box Oil, Top up Transmission Oil (@ 6538 Hours)	6538	\$212.50			
16/04/2020 REPAIR	GRACEY: Repair oil leak		\$180.00	\$145.00		
7/04/2020 OTHER	P&H: Glass door			\$451.97		
1/04/2020 REPAIR	GL: Fit Hyd pipe		\$225.00			
28/01/2020 SERVICE	GC: Full Service. R&R Windscreen wiper blades (@ 6233 Hours)	6233	\$125.00			
20/01/2020 REPAIR	GC: Compile filter list, disconnect blade control switch. Fit implement control cover, repair wiring RH mirror		\$125.00			
20/01/2020 OTHER	WESTRAC: 1 x filter kit, 1 x hose			\$265.22		
15/01/2020 REPAIR	GC: Continue with RHS tandem box repairs, disassembly, clean parts, R&R seal, fitment, blade assembly removal		\$500.00			
14/01/2020 REPAIR	GC: Continue with LHS tandem box disassembly. Clean parts, R&R seal and reassembly and fitment. Fill with oil. Fit wheels RHS, Drain tandem box oil, Start on disassembly		\$400.00			
14/01/2020 OTHER	DCT: seal pivot, o-ring			\$386.56		

Orange Truck & Ag

Stock No: APH00	Caterpillar 140M2 Grader		Serial No: CAT0140MKM9D01556	Reg No: 98380D
13/01/2020 OTHER	GC: LHS Drain tandem box oil, remove wheels, disconnect drive chains, remove tandem box	\$250.00		
7/01/2020 OTHER	WESTRAC: 1 x wire harness	\$372.26		
		\$14,412.73 \$19,281.17		