



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO. 99999	CUSTOMER NAME & ADDRESS: [REDACTED]			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 734077
DATE: 14/09/2023	[REDACTED]			YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 193766	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS:	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANT <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air Pwr Turbo

Wheels not rotated

Carry out Year 10 Service Plus B as per schedule.

\$656.00

--- Vehicle interior ---

Reset instrument cluster service interval indicator.

Check instrument cluster indicator lamps.

Check interior lighting.

Check windscreen wiper and washer system operation.

Check headlamp washer operation.

Check horn.

Check satellite navigation map software (if fitted).

Check battery for KEYLESS-GO key (if fitted).

Check vial of perfume atomizer (if fitted).

Replace combination filter.

--- Engine compartment ---

Replace engine oil and oil filter.

Replace brake fluid (EVERY TWO YEARS).

Check windscreen washer fluid level.

Check coolant level.

Replace dust filter.

Check drive belt/s.

Check all visible parts for leaks and damage.

Clean water deflector.

--- Wheels & Brakes ---

*** DOCUMENT COPY ***

This Page Total:

\$656.00



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and service terms. Includes fields for Customer No., Date, Reg No., Model Number, and various phone numbers.

- Remove & install four wheels.
Check wheels and tyres for damage and crack formation.
Check tyre tread depth in mm FL FR RL RR
Check tyre pressure and record bar/psi FL FR RL RR
Check front and rear brake pad thickness.
Check front and rear brake disc thickness and condition.
--- Front & Rear Of Vehicle ---
Check operation of all exterior lights.
Check headlamp operation and alignment.
Check windscreen condition.
Check wiper blade condition.
Fill up with AdBlue.
--- Boot ---
Check TIREFIT repair kit expiration date and record/...../..... (if fitted).
Check spare wheel tyre pressure and record bar/psi (if fitted).
Check first aid kit expiration date and record/...../..... (if fitted).
Check boot lighting.
--- Underside Of The Vehicle ---
Check condition of suspension struts.
Check condition of steering and tie rods.
Check condition of flex discs.
Check condition of front axle and front axle ball joints.
Check condition of rear axle and rear axle ball joints.
Check for signs of damage and corrosion.
Check all visible underbody parts for leaks and damage.

*** DOCUMENT COPY ***

This Page Total: 60.00



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: [REDACTED]	ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 734077
DATE: 14/09/2023	[REDACTED]	YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:	MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:		CHASSIS NUMBER:	KILOMETER: 193766	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:		CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED
			QUOTE PRICE:	Air Pwr Turbo Delivery Date: 12/12/2015

Replace automatic transmission fluid & filter.

--- Final inspection ---

Check bodywork for paint damage.

Carry out final inspection and road test.

Part Number	Part Description	Quantity	Nett Value	Total Cost
166 830 72 01	TS FINE PARTICLE FILTER	1.00	180.05	180.05
166 830 02 18	DUST FILTER	1.00	62.16	62.16
007603 014106	SEAL RING,CU	1.00	3.43	3.43
007603 012102	RING,GENERAL,METAL	1.00	4.30	4.30
004 990 35 12	SCREW	6.00	5.98	35.88
001 990 11 17	SCREW PLUG	1.00	9.39	9.39
004989042013	ADBLUE - DIESEL EXHAUST FLUID	22.00	3.99	87.78
TUF	Top Up Fluid	1.00	5.08	5.08
EPA	Epa / Waste Management Levy	1.00	15.00	15.00
220 271 03 80	GASKIT - OIL PAN	1.00	41.51	41.51
SS	WORKSHOP MATERIALS	1.00	20.00	20.00
000 989 55 04 17FMEE	MERCEDES-BENZ 229.52 5W-30	6.50	31.59	205.34
000 989 44 04 13FULE	MB 236.15 ATF 5L	2.00	119.96	239.92
000 989 56 05 11	BRAKE FLUID 1L	1.00	51.83	51.83
000 986 20 00 09	CLEANING AGENT-WSHR FLUID	1.00	9.69	9.69
651 180 01 09	OIL FILTER	1.00	54.14	54.14
251 271 00 97	PIPE	1.00	7.39	7.39

*** DOCUMENT COPY ***

This Page Total:

\$1,032.89



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and service terms. Includes fields for Customer No., Date, Reg No., Stock No., Purchase Order No., and various phone numbers.

Wheels not rotated as the best tyres are on the front.

Carry out Year 9 Service Plus A as per schedule.

\$165.00

--- Vehicle interior ---

Reset instrument cluster service interval indicator.

Check instrument cluster indicator lamps.

Check interior lighting.

Check horn.

Check satellite navigation map software (if fitted).

Check battery for KEYLESS-GO key (if fitted).

Check vial of perfume atomizer (if fitted).

--- Engine compartment ---

Replace engine oil and oil filter.

Check brake fluid level.

Check windscreen washer fluid level.

Check coolant level.

Replace dust filter.

Clean water deflector.

--- Wheels & Brakes ---

Check tyre tread depth in mm FL FR RL RR

Check tyre pressure and record bar/psi FL FR RL RR

Check front and rear brake pad thickness.

Check front and rear brake disc thickness and condition.

--- Front & Rear Of Vehicle ---

*** DOCUMENT COPY ***

This Page Total:

\$165.00



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and service terms. Includes fields for Customer No., Name & Address, Date, Reg No., Stock No., Purchase Order No., Cash/Charge/Warranty, Home/Business/Mobile Phone, Vehicle ID, Engine No., Time and Date Promised, Time Received, Quote Price, and Delivery Date.

- Check windscreen condition.
Check wiper blade condition.
Fill up with AdBlue.
--- Boot ---
Check TIREFIT repair kit expiration date and record ... (if fitted).
Check spare wheel tyre pressure and record ... bar/psi (if fitted).
Check first aid kit expiration date and record ... (if fitted).
Check boot lighting.
--- Underside Of The Vehicle ---
Check for signs of damage and corrosion.
Check all visible underbody parts for leaks and damage.
--- Final inspection ---
Check bodywork for paint damage.
Carry out final inspection and road test.

Table with 3 columns: Part Number, Part Description, and Total Cost. Lists items like MERCEDES-BENZ 229.52 5W-30, WINDSHIELD WASHER FLUID, OIL FILTER, DUST FILTER, SEAL RING, CU, ADBLUE - DIESEL EXHAUST FLUID, Top Up Fluid, and Epa / Waste Management Levy.

*** DOCUMENT COPY ***

This Page Total: \$356.28



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO. 99999	CUSTOMER NAME & ADDRESS: [REDACTED]			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 707166
DATE: 17/10/2022	[REDACTED]			YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 169766	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS:	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air <input type="checkbox"/> Pwr <input type="checkbox"/> Turbo <input type="checkbox"/>

SS	WORKSHOP MATERIALS	1.00	20.00	20.00
Item Total:				\$376.28

Carry out tyre inspection.
Inspect all tyres including spare.
Adjust tyre pressures.
Check and report any abnormal tyre wear.

Pick up client vehicle

Carry out courtesy car wash at no charge to client.

Recommendations:

Next Service Due: Assyst

* Front windscreen has a crack in it

*** DOCUMENT COPY ***

This Page Total: \$20.00



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: [REDACTED]			ADVISOR: Josip Majdak	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 705611
DATE: 27/09/2022	[REDACTED]			YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 168634	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:		DELIVERY KMS: Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air Pwr Turbo

Work completed:
Carried out ADBLue top up
Filled the Adblue system, tank

Part Number	Part Description	Quantity	Nett Value	Total Cost
004989042013	ADBLUE - DIESEL EXHAUST FLUID	23.00	5.00	115.00
Item Total:				\$115.00

*** DOCUMENT COPY ***

Sub Total for All:	\$115.00
Rounding:	\$0.00
GST:	\$11.50
Total:	\$126.50

Advisor:
1734 | Josip Majdak

Bank Account Details for Direct Payments:
BSB: 105-002 Acc: 122934140
Account Name: Carlin and Gazzard
Reference Number: 705611
BankSA, Mount Gambier

Carlin & Gazzard | Authorised Mercedes-Benz Passenger Car (and Van) Sales, Service & Parts Retailer
ABN 60 134 644 088 | ACN 007 995 619 | LVD 394
116-138 Commercial St East, Mount Gambier SA 5290 | T +61 8 8723 8834 | Fax: +61 8 8723 8866 | www.mbcrlinandgazzard.com.au

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG.



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO. 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 681370
DATE: 21/10/2021				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 146516	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:		DELIVERY KMS: Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air Pwr Turbo

Wheels not rotated as they are wearing evenly

- Carry out tyre inspection.
- Inspect all tyres including spare.
- Adjust tyre pressures.
- Check and report any abnormal tyre wear.

- Carry out Year 8 Service Plus B as per schedule.
- Vehicle interior ---
- Reset instrument cluster service interval indicator.
- Check instrument cluster indicator lamps.
- Check interior lighting.
- Check windscreen wiper and washer system operation.
- Check headlamp washer operation.
- Check horn.
- Check satellite navigation map software (if fitted).
- Check battery for KEYLESS-GO key (if fitted).
- Check vial of perfume atomizer (if fitted).
- Replace combination filter.
- Engine compartment ---
- Replace engine oil and oil filter.
- Replace brake fluid (EVERY TWO YEARS).

\$345.00

*** DOCUMENT COPY ***

This Page Total: \$345.00



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and service notes. Includes fields for Customer No, Name, Address, Date, Reg No, Model, Mileage, and various checkboxes for services performed.

- Check windscreen washer fluid level.
Check coolant level.
Fuel filter replacement not due
Replace air filter.
Replace dust filter.
Check drive belt/s.
Check all visible parts for leaks and damage.
Clean water deflector.
--- Wheels & Brakes ---
Remove & install four wheels.
Check wheels and tyres for damage and crack formation.
Check tyre tread depth in mm FL FR RL RR
Check tyre pressure and record bar/psi FL FR RL RR
Check front and rear brake pad thickness.
Check front and rear brake disc thickness and condition.
--- Front & Rear Of Vehicle ---
Check operation of all exterior lights.
Check headlamp operation and alignment.
Check windscreen condition.
Check wiper blade condition.
Fill up with AdBlue.
--- Boot ---
Check TIREFIT repair kit expiration date and record (if fitted).
Check spare wheel tyre pressure and record bar/psi (if fitted).
Check first aid kit expiration date and record (if fitted).

*** DOCUMENT COPY ***

This Page Total: \$0.00



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 681370
DATE: 21/10/2021				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 146516	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS:	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air <input type="checkbox"/> Pwr <input type="checkbox"/> Turbo <input type="checkbox"/>

- Check boot lighting.
- Underside Of The Vehicle ---
- Check condition of suspension struts.
- Check condition of steering and tie rods.
- Check condition of flex discs.
- Check condition of front axle and front axle ball joints.
- Check condition of rear axle and rear axle ball joints.
- Check for signs of damage and corrosion.
- Check all visible underbody parts for leaks and damage.
- Final inspection ---
- Check bodywork for paint damage.
- Carry out final inspection and road test.

Part Number	Part Description	Quantity	Nett Value	Total Cost
166 830 02 18	DUST FILTER	1.00	56.54	56.54
007603 014106	SEAL RING,CU	1.00	3.25	3.25
004989042013	ADBLUE - DIESEL EXHAUST FLUID	15.00	7.37	110.55
EPA	Epa / Waste Management Levy	1.00	15.00	15.00
166 830 72 01	TS FINE PARTICLE FILTER	1.00	173.42	173.42
SS	WORKSHOP MATERIALS	1.00	20.00	20.00
000 989 55 04 17FMEE	MERCEDES-BENZ 229.52 5W-30	6.50	24.30	157.95
651 094 01 04 64	AIR FILTER INSERT	1.00	108.82	108.82
000 989 08 07 13	MB 331.0 BRAKE FLUID 1L	1.00	43.34	43.34
000 986 20 00 09	CLEANING AGENT-WSHR FLUID	1.00	9.34	9.34

*** DOCUMENT COPY ***

This Page Total: \$698.21



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO. 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 681370			
DATE: 21/10/2021				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250			TEAM		
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:		TAG NO:		
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 146516	PROD DATE:	ENG / TRANS.:		
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:			
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:			DELIVERY KMS:	Delivery Date: 12/12/2015	
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:		TIME RECEIVED	QUOTE PRICE:	Air	Pwr	Turbo

651 180 01 09

OIL FILTER

1.00

50.38

50.38

Item Total:

\$748.59

Complimentary Loan Vehicle - NO CHARGE

Carry out courtesy car wash at no charge to client.

Recommendations:

Next Service Due: Assyst

12 month 24hr Australia Wide Roadside Assistance

Contact phone number - Freecall 1800 817 337

- Flat Battery – vehicle will jump started at the request of driver
- Flat Tyre – vehicle spare wheel will be fitted
- Out of Fuel – minimum 5 litres of unleaded fuel supplied at drivers cost
- Locked/Lost Keys – open vehicle
- Mechanical Breakdown/Towing – vehicle will be transported to issuing dealers service department or nominated repairer

*** DOCUMENT COPY ***

This Page Total:

\$50.38



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: CASH SALE			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 650954
DATE: 31/08/2020				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 128153	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS:	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air <input type="checkbox"/> Pwr <input type="checkbox"/> Turbo <input type="checkbox"/>

Work completed:
Wheels not rotated at customer request
Loan Car Registration: LCSUBA

Complimentary Loan Vehicle - NO CHARGE

- Carry out Year 7 Service Plus A as per schedule.
- Vehicle interior ---
- Reset instrument cluster service interval indicator.
- Check instrument cluster indicator lamps.
- Check interior lighting.
- Check horn.
- Check satellite navigation map software (if fitted).
- Check battery for KEYLESS-GO key (if fitted).
- Check vial of perfume atomizer (if fitted).
- Engine compartment ---
- Replace engine oil and oil filter.
- Check brake fluid level.
- Check windscreen washer fluid level.
- Check coolant level.
- Replace dust filter.
- Clean water deflector.

\$165.60

*** DOCUMENT COPY ***

This Page Total: \$165.60



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and contact data. Includes fields for Customer No., Date, Reg No., Stock No., Purchase Order No., Model Number, Chassis Number, and Engine No.

--- Wheels & Brakes ---

- Check tyre tread depth in mm FL FR RL RR
Check tyre pressure and record bar/psi FL FR RL RR
Check front and rear brake pad thickness.
Check front and rear brake disc thickness and condition.

--- Front & Rear Of Vehicle ---

- Check windscreen condition.
Check wiper blade condition.
Fill up with AdBlue.

--- Boot ---

- Check TIREFIT repair kit expiration date and record/...../..... (if fitted).
Check spare wheel tyre pressure and record bar/psi (if fitted).
Check first aid kit expiration date and record/...../..... (if fitted).
Check boot lighting.

--- Underside Of The Vehicle ---

- Check for signs of damage and corrosion.
Check all visible underbody parts for leaks and damage.

--- Final inspection ---

- Check bodywork for paint damage.
Carry out final inspection and road test.

Table with 4 columns: Part Number, Part Description, Quantity, and Total Cost. Lists items like TS WIPER BLADE, CLEANING AGENT-WSHR FLUID, Misc, and OIL FILTER.

*** DOCUMENT COPY ***

This Page Total: \$302.34



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: CASH SALE			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 650954
DATE: 31/08/2020				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 128153	PROD DATE: ENG / TRANS:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air Pwr Turbo

166 830 02 18	DUST FILTER	1.00	57.90	57.90
007603 014106	SEAL RING,CU	1.00	3.26	3.26
004989042013	ADBLUE - DIESEL EXHAUST FLUID	10.50	6.18	64.89
EPA	Epa / Waste Management Levy	1.00	15.00	15.00
SS	WORKSHOP MATERIALS	1.00	20.00	20.00

Item Total: \$463.39

- Carry out tyre inspection.
- Inspect all tyres including spare.
- Adjust tyre pressures.
- Check and report any abnormal tyre wear.

Replaced front & rear wiper rubbers

Tyre Report: 3mm @ front, 3mm @ rear
 Brake Report: 11mm @ front, 10mm @ rear
 Next Service Due: 153153km or August 2021

*** DOCUMENT COPY ***

This Page Total: \$161.05



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 614117
DATE: 10/05/2019				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 117068	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\		TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE: Air Pwr Turbo

Work Completed:

\$427.80

- Performed Mercedes Benz B service as per manufacturers specifications
- Replaced engine oil and oil filter.
- Replaced air filter.
- Replaced pollen filter.
- Replaced fuel filter.
- Replaced combination filter.
- Replaced brake fluid.
- Inspected under bonnet.
- Carried out battery test.
- Checked & topped up fluids.
- Topped up ad-blue.
- Road tested, all ok.
- Loan Car Registration: LCHOND

Part Number	Part Description	Quantity	Nett Value	Total Cost
SS	WORKSHOP MATERIALS	1.00	10.00	10.00
000 989 30 45 09	FUEL CLEANER DIESEL	1.00	22.10	22.10
000 989 08 07 13	MB 331.0 BRAKE FLUID 1L	1.00	45.83	45.83
000 989 97 01W	Misc	6.50	19.23	125.00
651 180 01 09	OIL FILTER	1.00	47.19	47.19
651 094 01 04	AIR FILTER ELEMENT	1.00	114.49	114.49
651 090 28 52	FUEL FILTER	1.00	283.56	283.56
166 830 72 01	TS FINE PARTICLE FILTER	1.00	189.25	189.25
166 830 02 18	DUST FILTER	1.00	50.96	50.96
007603 014106	SEAL RING,CU	1.00	3.33	3.33

*** DOCUMENT COPY ***

This Page Total:

\$1,319.51



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and contact data. Includes fields for Customer No., Date, Reg No., Stock No., Purchase Order No., and various phone numbers.

Table listing service items with columns for description, quantity, and price. Items include CLAMP, CLEANING AGENT, HOSE CLAMP, and ADBLUE.

Item Total: \$945.20

- 12 month 24hr Australia Wide Roadside Assistance
Contact phone number - Freecall 1800 817 337
• Flat Battery - vehicle will jump started at the request of driver
• Flat Tyre - vehicle spare wheel will be fitted
• Out of Fuel - minimum 5 litres of unleaded fuel supplied at drivers cost
• Locked/Lost Keys - open vehicle
• Mechanical Breakdown/Towing - vehicle will be transported to issuing dealers service department or nominated repairer

Both front mirrors hit posts on property.

Tyre Report: 5mm @ front, 5mm @ rear

*** DOCUMENT COPY ***

This Page Total: \$53.49



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and contact details. Includes fields for Customer No., Date, Reg No., Stock No., Purchase Order No., and various phone numbers.

Work Completed:
Performed Mercedes Benz B service as per manufacturers specifications
Replaced engine oil and oil filter.
Replaced air filter.
Replaced pollen filter.
Replaced fuel filter.
Replaced combination filter.
Replaced brake fluid.
Inspected under bonnet.
Carried out battery test.
Checked & topped up fluids.
Topped up ad-blue.
Road tested, all ok.
Loan Car Registration: LCHOND

\$427.80

Table with 6 columns: Part Number, Part Description, Quantity, Nett Value, Total Cost. Lists various workshop materials and filters.

*** DOCUMENT COPY ***

This Page Total: \$1,319.51



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 614117
DATE: 10/05/2019				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 117068	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air Pwr Turbo

006 997 18 90	CLAMP(CLIC R 86 125)W203	1.00	4.84	4.84
000 986 20 00 09	CLEANING AGENT-WSHR FLUID	1.00	9.38	9.38
004 997 20 90	HOSE CLAMP	1.00	4.37	4.37
004989042013	ADBLUE - DIESEL EXHAUST FLUID	5.00	5.18	25.90
EPA	Epa / Waste Management Levy	1.00	9.00	9.00

Item Total: \$945.20

- *****
- 12 month 24hr Australia Wide Roadside Assistance
 - Contact phone number - Freecall 1800 817 337
 - Flat Battery – vehicle will jump started at the request of driver
 - Flat Tyre – vehicle spare wheel will be fitted
 - Out of Fuel – minimum 5 litres of unleaded fuel supplied at drivers cost
 - Locked/Lost Keys – open vehicle
 - Mechanical Breakdown/Towing – vehicle will be transported to issuing dealers service department or nominated repairer
- *****

Both front mirrors hit posts on property.

Tyre Report: 5mm @ front, 5mm @ rear

*** DOCUMENT COPY ***

This Page Total: \$53.40



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 575516
DATE: 30/01/2018				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 109946	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\	TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air Pwr Turbo

Carry out Mercedes Benz A service as per manufacturer's specifications.

\$119.70

Includes:

- Replace engine oil and oil filter.
- Topped up AdBlue
- Check all fluid levels and top up as required.
- Carry out under bonnet inspection.
- Carry out under vehicle inspection.
- Inspect brakes, suspension and steering components.
- Carry out lighting, electrical and safety checks.
- Carry out final inspection and road test.

Part Number	Part Description	Quantity	Nett Value	Total Cost
000 986 20 00 09	CLEANING AGENT-WSHR FLUID	1.00	9.30	9.30
000 989 97 01W	Misc	6.50	19.23	125.00
651 180 01 09	OIL FILTER	1.00	47.19	47.19
000 989 30 45 09	FUEL CLEANER DIESEL	1.00	21.90	21.90
007603 014106	SEAL RING,CU	1.00	3.33	3.33
Item Total:			\$206.72	

Wheels not rotated as the vehicle requires 4 new tyres.
Wire and canvas showing on the inner edges.

Carry out tyre inspection.

*** DOCUMENT COPY ***

This Page Total: \$326.42



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO: 575516
DATE: 30/01/2018				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 109946	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS:	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANT <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\		TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE: Air Pwr Turbo

Inspect all tyres including spare.
Adjust tyre pressures.
Check and report any abnormal tyre wear.

Carried out courtesy car wash of vehicle at no charge to client.

Complimentary Loan Vehicle - NO CHARGE

On inspection found the front brake pads and rotors close to minimum
Customer ok'd via phone call for replacing the brake pads and rotors.

\$239.40

Note:
* Resecured left hand mirror lower trim. Glass replacement \$615 parts & labour. Parts quote:186914Ex Melb.
* 4 tyres required due to wire showing on the inner edges. \$2400 fitted. Parts quote:186929 ex Melb.

Part Number	Part Description	Quantity	Nett Value	Total Cost
164 540 10 17	SENSOR	1.00	14.92	14.92
007 420 80 20	DISK BRAKE PAD	1.00	277.25	277.25

*** DOCUMENT COPY ***

This Page Total: \$531.57



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and pricing. Includes fields for Customer No, Date, Reg No, Stock No, Purchase Order No, Advisor, Colour, Document No, Year/Make/Model, Model Number, Chassis Number, Kilometer, Prod Date, Eng/Trans, Contract Name, Contract Exo Kms, Exp Date, Delivery Date, and Quote Price.

166 421 10 12

BRAKE DISK, VENTED

2.00

233.99

467.98

Item Total:

\$760.15

Epa / Waste Management Levy

\$9.00

6 month 24hr Australia Wide Roadside Assistance

Contact phone number - Freecall 1800 817 337

- Flat Battery - vehicle will jump started at the request of driver
• Flat Tyre - vehicle spare wheel will be fitted
• Out of Fuel - minimum 5 litres of unleaded fuel supplied at drivers cost
• Locked/Lost Keys - open vehicle
• Mechanical Breakdown/Towing - vehicle will be transported to issuing dealers service department or nominated repairer

As a result of today's visit, you may be invited to complete a survey from Mercedes-Benz Australia.

This survey is a key element of our dedication to customer care, ensuring that you receive the best level of service possible and that you are completely satisfied with your experience with Carlin & Gazzard.

If, for some reason, you are not completely satisfied with your experience, we would appreciate hearing from you before completion of this survey, so that we may address any concerns that you may have.

*** DOCUMENT COPY ***

This Page Total:

\$476.98



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and contact info. Includes fields for Customer No., Date, Reg No., Stock No., Purchase Order No., Cash/Charge/Warranty, Home/Business/Mobile Phone, Vehicle ID, Engine No., Time and Date Promised, Time Received, Quote Price, and Delivery Date.

Carry out Mercedes Benz A service as per manufacturer's specifications.

\$119.70

Includes:

- Replace engine oil and oil filter.
Topped up AdBlue
Check all fluid levels and top up as required.
Carry out under bonnet inspection.
Carry out under vehicle inspection.
Inspect brakes, suspension and steering components.
Carry out lighting, electrical and safety checks.
Carry out final inspection and road test.

Table with 5 columns: Part Number, Part Description, Quantity, Nett Value, Total Cost. Lists items like CLEANING AGENT-WSHR FLUID, OIL FILTER, FUEL CLEANER DIESEL, and SEAL RING, CU.

Item Total: \$206.72

Wheels not rotated as the vehicle requires 4 new tyres.
Wire and canvas showing on the inner edges.

Carry out tyre inspection.

*** DOCUMENT COPY ***

This Page Total: \$326.42



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: Cash Sale			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 575516
DATE: 30/01/2018				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 109946	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\		TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE: Air Pwr Turbo

Inspect all tyres including spare.
Adjust tyre pressures.
Check and report any abnormal tyre wear.

Carried out courtesy car wash of vehicle at no charge to client.

Complimentary Loan Vehicle - NO CHARGE

On inspection found the front brake pads and rotors close to minimum
Customer ok'd via phone call for replacing the brake pads and rotors.

\$239.40

Note:

* Resecured left hand mirror lower trim. Glass replacement \$615 parts & labour. Parts quote:186914Ex Melb.

* 4 tyres required due to wire showing on the inner edges. \$2400 fitted. Parts quote:186929 ex Melb.

Part Number	Part Description	Quantity	Nett Value	Total Cost
164 540 10 17	SENSOR	1.00	14.92	14.92
007 420 80 20	DISK BRAKE PAD	1.00	277.25	277.25

*** DOCUMENT COPY ***

This Page Total: \$531.57



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and contact info. Includes fields for Customer No, Name, Address, Advisor, Colour, Document No, Date, Year/Make/Model, Reg No, Driver Name, Model Number, Carline, Tag No, Stock No, Chassis Number, Kilometer, Prod Date, Eng/Trans, Purchase Order No, Contract Name, Contract Exo Kms, Exp Date, CASH CHARGE WARRANTY, HOME PHONE, BUSINESS PHONE, MOBILE PHONE, EMAIL, DELIVERY KMS, Delivery Date, FLEETCARD CREDIT CARD, VEHICLE ID, ENGINE NO., TIME AND DATE PROMISED, TIME RECEIVED, QUOTE PRICE, Air, Pwr, Turbo.

Work Completed: \$218.30
Check engine light on
Internal open circuit of differential pressure sensor
Carried out quick test
Found codes: P042D00 - catalytic converter temp sensor short & P246364 - soot content of DPF is not ok
Carried out diagnosis procedure for P042D00 & confirmed temperature sensor has an open circuit
Replaced sensor & cleared codes: P246364 - soot content of DPF is not ok, still evident
Carried out diagnosis & found DPF pressure sensor has an electrical fault
Replaced pressure sensor & carried out regeneration on road test, ok

Table with 5 columns: Part Number, Part Description, Quantity, Nett Value, Total Cost. Includes rows for PRESSURE SENSOR and Misc, and an Item Total row.

*** DOCUMENT COPY ***

Summary table with 2 columns: Label, Amount. Includes Sub Total for All (\$654.85), Rounding (\$0.00), GST (\$0.00), and Total (\$654.85).

Advisor:
MINGEM01 M | Melissa White

Bank Account Details for Direct Payments:
BSB: 105-002 Acc: 122934140
Account Name: Carlin and Gazzard
Reference Number: 549352
BankSA, Mount Gambier

Carlin & Gazzard | Authorised Mercedes-Benz Passenger Car (and Van) Sales, Service & Parts Retailer
ABN 60 134 644 088 | ACN 007 995 619 | LVD 394
116-138 Commercial St East, Mount Gambier SA 5290 | T +61 8 8723 8834 | Fax: +61 8 8723 8866 | www.mbcrlinandgazzard.com.au

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG.



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99982	CUSTOMER NAME & ADDRESS: Mercedes Warranty Control			ADVISOR: Melissa White	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 545062
DATE: 6/02/2017				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250	TEAM	
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 101732	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD <input type="checkbox"/> CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\		TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE: Air Pwr Turbo

Work Completed:

\$32.75

Carried out SM2262 Replace charge air hose
Per factory recommendations
Replaced charge air hose as per instructions

Part Number	Part Description	Quantity	Nett Value	Total Cost
166 528 04 82 05	Misc	1.00	281.61	281.61
Item Total:				\$281.61

*** DOCUMENT COPY ***

Sub Total for All:	\$314.36
Rounding:	\$0.00
GST:	\$0.00
Total:	\$314.36

Advisor:
MINGEM01 M | Melissa White

Bank Account Details for Direct Payments:
BSB: 105-002 Acc: 122934140
Account Name: Carlin and Gazzard
Reference Number: 545062
BankSA, Mount Gambier

Carlin & Gazzard | Authorised Mercedes-Benz Passenger Car (and Van) Sales, Service & Parts Retailer
ABN 60 134 644 088 | ACN 007 995 619 | LVD 394
116-138 Commercial St East, Mount Gambier SA 5290 | T +61 8 8723 8834 | Fax: +61 8 8723 8866 | www.mbcrlinandgazzard.com.au

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG.



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and service terms. Includes fields for Customer No, Name, Date, Reg No, Stock No, Purchase Order No, Advisor, Colour, Document No, Year/Make/Model, Model Number, Chassis Number, Mileage, Prod Date, Contract Name, Email, Delivery Date, and Quote Price.

Work Completed:
Performed Mercedes Benz B service as per manufacturers specifications
Replaced engine oil and oil filter
Refilled AdBlue system
Corrected fluid levels
Cleaned water drain
Replaced rear wiper blade
performed roadtest.

\$332.50

Table with 5 columns: Part Number, Part Description, Quantity, Nett Value, Total Cost. Lists various parts like OIL FILTER, DUST FILTER, SEAL RING, CU, CLEANING AGENT-WSHR FLUID, etc.

Item Total: \$494.92

*** DOCUMENT COPY ***

This Page Total: \$627.42



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: CASH SALE			ADVISOR:	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 543797
DATE: 23/01/2017				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250		TEAM
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 101732	PROD DATE: ENG / TRANS.:
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:	DELIVERY KMS:	Delivery Date: 12/12/2015
FLEETCARD CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\		TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE: Air Pwr Turbo

Tyres not rotated as all tyres due for replacing.

- Carried out tyre inspection.
- Inspect all tyres including spare.
- Adjust tyre pressures.
- Check and Report any abnormal tyre wear.

Replaced Cabin Dust Filter

Carried out Brake Fluid Flush

- Check engine light on
- Carried out code check - P042D00. Temperature sensor 2 "Catalytic converter has short to positive
- Requires rebooking to further diagnose
- Note:
- *Vehicle requires front brake pads and rotors in approx 4000kms. \$1060 Parts & labour.Parts quote:168927
- *Requires rebooking to further diagnose issue

*** DOCUMENT COPY ***

This Page Total: \$0.00



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

CUSTOMER NO: 99999	CUSTOMER NAME & ADDRESS: CASH SALE			ADVISOR: Josip Majdak	COLOUR: OBSIDIAN BLACK	DOCUMENT NO.: 543797			
DATE: 23/01/2017				YEAR \ MAKE \ MODEL: 2013 \ MERCEDES-BENZ \ ML250			TEAM		
REG NO: S940BIV	DRIVER NAME:			MODEL NUMBER: WDC1660042A301254	CARLINE:	TAG NO:			
STOCK NO:				CHASSIS NUMBER:	KILOMETER: 101732	PROD DATE:	ENG / TRANS.:		
PURCHASE ORDER NO:				CONTRACT NAME:	CONTRACT EXO KMS	EXP DATE:			
CASH <input type="checkbox"/> CHARGE <input type="checkbox"/> WARRANTY <input type="checkbox"/>	HOME PHONE:	BUSINESS PHONE:	MOBILE PHONE:	EMAIL:		DELIVERY KMS:	Delivery Date: 12/12/2015		
FLEETCARD CREDIT CARD <input type="checkbox"/>	VEHICLE ID:	ENGINE NO.: 65196031831825\		TIME AND DATE PROMISED:	TIME RECEIVED	QUOTE PRICE:	Air	Pwr	Turbo

*Vehicle requires 4 new tyres and a wheel alignment.

Epa / Waste Management Levy

\$9.00

12 month 24hr Australia Wide Roadside Assistance

Contact phone number - Freecall 1800 817 337

- Flat Battery – vehicle will jump started at the request of driver
- Flat Tyre – vehicle spare wheel will be fitted
- Out of Fuel – minimum 5 litres of unleaded fuel supplied at drivers cost
- Locked/Lost Keys – open vehicle
- Mechanical Breakdown/Towing – vehicle will be transported to issuing dealers service department or nominated repairer

Miscellaneous Charges

WORKSHOP MATERIALS

\$9.94

*** DOCUMENT COPY ***

This Page Total:	\$18.94
Sub Total for All:	\$846.36
Rounding:	\$0.00
GST:	\$84.64
Total:	\$931.00

Advisor:
1734 | Josip Majdak

Bank Account Details for Direct Payments:
BSB: 105-002 Acc: 122934140
Account Name: Carlin and Gazzard
Reference Number: 543797
BankSA, Mount Gambier

Carlin & Gazzard | Authorised Mercedes-Benz Passenger Car (and Van) Sales, Service & Parts Retailer
ABN 60 134 644 088 | ACN 007 995 619 | LVD 394
116-138 Commercial St East, Mount Gambier SA 5290 | T +61 8 8723 8834 | Fax: +61 8 8723 8866 | www.mbcrlinandgazzard.com.au

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG.



Mercedes-Benz

Carlin & Gazzard
Authorised Mercedes-Benz
Sales, Service & Parts

SERVICE TAX INVOICE

Table with customer details, vehicle information, and contact data. Includes fields for Customer No., Date, Reg No., Stock No., Purchase Order No., Driver Name, Model Number, Chassis Number, and various phone numbers.

Work completed: BMC \$82.50
Check brake light on.
Rear brake pads worn out.
Replaced rear brake pads and sensors.

Table with 4 columns: Part Number, Part Description, Quantity, and Total Cost. Lists brake wear sensors and a disk brake pad.

Carried out Presale inspection \$165.00
Replaced 1 key battery.

Carried out Merc Benz Approved POV Warranty Inspection \$165.00

Carried out Tier1 Inspection

*** DOCUMENT COPY ***

Summary table showing Sub Total for All (\$641.27), Rounding (\$0.00), GST (\$0.00), and Total (\$641.27).

Advisor:
BirksPaul20 | Paul Birks

Bank Account Details for Direct Payments:
BSB: 105-002 Acc: 122934140
Account Name: Carlin and Gazzard
Reference Number: 513586
BankSA, Mount Gambier

Carlin & Gazzard | Authorised Mercedes-Benz Passenger Car (and Van) Sales, Service & Parts Retailer
ABN 60 134 644 088 | ACN 007 995 619 | LVD 394
116-138 Commercial St East, Mount Gambier SA 5290 | T +61 8 8723 8834 | Fax: +61 8 8723 8866 | www.mbcrlinandgazzard.com.au

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG.