

Transactions		
Job	Date	Details
RDT026 : Komatsu HD605-5	17/07/2012	Check air filters and induction system
RDT026 : Komatsu HD605-5	17/07/2012	Check bad sos for engine/ unpack ute
RDT026 : Komatsu HD605-5	25/07/2012	Parts
RDT026 : Komatsu HD605-5	26/07/2012	Parts
RDT026 : Komatsu HD605-5	26/07/2012	Parts
RDT026 : Komatsu HD605-5	30/07/2012	Tyres
RDT026 : Komatsu HD605-5	28/08/2012	Parts
RDT026 : Komatsu HD605-5	29/08/2012	Mob/ 2000 hour service
RDT026 : Komatsu HD605-5	29/08/2012	Mob/ 2000 hour service
RDT026 : Komatsu HD605-5	29/08/2012	Parts
RDT026 : Komatsu HD605-5	30/08/2012	2000 hour service
RDT026 : Komatsu HD605-5	30/08/2012	Complete 2000 hour service
RDT026 : Komatsu HD605-5	3/09/2012	Parts
RDT026 : Komatsu HD605-5	4/09/2012	Parts
RDT026 : Komatsu HD605-5	5/09/2012	Parts
RDT026 : Komatsu HD605-5	6/09/2012	Parts
RDT026 : Komatsu HD605-5	7/09/2012	Continue pulling a part engine and inspecting dama
RDT026 : Komatsu HD605-5	7/09/2012	Parts
RDT026 : Komatsu HD605-5	7/09/2012	Parts
RDT026 : Komatsu HD605-5	10/09/2012	Parts
RDT026 : Komatsu HD605-5	10/09/2012	Parts
RDT026 : Komatsu HD605-5	13/09/2012	Parts
RDT026 : Komatsu HD605-5	14/09/2012	Carried out cleaning engine parts
RDT026 : Komatsu HD605-5	19/09/2012	Parts
RDT026 : Komatsu HD605-5	19/09/2012	Parts
RDT026 : Komatsu HD605-5	19/09/2012	Sort through parts and checking they are all there
RDT026 : Komatsu HD605-5	20/09/2012	Parts
RDT026 : Komatsu HD605-5	28/09/2012	Started disassembly of parts for rebuilding
rdt026 : Komatsu HD605-5	11/10/2012	Tyres
RDT026 : Komatsu HD605-5	12/10/2012	Parts
RDT026 : Komatsu HD605-5	15/10/2012	Parts
RDT026 : Komatsu HD605-5	22/10/2012	Parts
RDT026 : Komatsu HD605-5	26/10/2012	Parts
RDT026 : Komatsu HD605-5	29/10/2012	Parts
RDT026 : Komatsu HD605-5	31/10/2012	Parts
RDT026 : Komatsu HD605-5	9/11/2012	Tyres
RDT026 : Komatsu HD605-5	21/11/2012	Operated franna to remove engine
RDT026 : Komatsu HD605-5	23/11/2012	Check parts and start reassembly of rear brakes
RDT026 : Komatsu HD605-5	28/11/2012	Engine overhaul
RDT026 : Komatsu HD605-5	29/11/2012	Prep for installing
RDT026 : Komatsu HD605-5	4/12/2012	Fit CB
rdt026 : Komatsu HD605-5	5/12/2012	Tyres
RDT026 : Komatsu HD605-5	25/01/2013	Prep for site, pack ute & get all parts
RDT026 : Komatsu HD605-5	29/01/2013	Fix fuel injection leak
RDT026 : Komatsu HD605-5	29/01/2013	Repair injector return line
RDT026 : Komatsu HD605-5	29/01/2013	Travel ti Ardossan for repairs to as below
RDT026 : Komatsu HD605-5	30/01/2013	Check battery & fault codes
RDT026 : Komatsu HD605-5	30/01/2013	Fix fault with charge light, found broken wire
RDT026 : Komatsu HD605-5	28/02/2013	Travel & Accommodation

rdt026 : Komatsu HD605-5	27/03/2013	Ground Engaging Tools
RDT026 : Komatsu HD605-5	6/05/2013	Check out trans conrtol fault no problem
RDT026 : Komatsu HD605-5	14/05/2013	Parts
RDT026 : Komatsu HD605-5	18/06/2013	Installed seat
RDT026 : Komatsu HD605-5	10/07/2013	Subcontractor - Plant Maintenance
RDT026 : Komatsu HD605-5	19/07/2013	Tyres
RDT026 : Komatsu HD605-5	17/12/2013	Signage
RDT026 : Komatsu HD605-5	18/12/2013	Fit beacons to brackets
RDT026 : Komatsu HD605-5	18/12/2013	Fit hand rail and new light bracket
RDT026 : Komatsu HD605-5	18/12/2013	Remove radiator shroud
rdt026 : Komatsu HD605-5	19/12/2013	Parts
RDT026 : Komatsu HD605-5	19/12/2013	Repair/ paint steps
RDT026 : Komatsu HD605-5	19/12/2013	Service
RDT026 : Komatsu HD605-5	19/12/2013	Sticker
RDT026 : Komatsu HD605-5	19/12/2013	Stickers
RDT026 : Komatsu HD605-5	19/12/2013	Stickers
RDT026 : Komatsu HD605-5	20/12/2013	Service
RDT026 : Komatsu HD605-5	2/01/2014	Check steering & linkages, check leaks
RDT026 : Komatsu HD605-5	7/01/2014	Parts
RDT026 : Komatsu HD605-5	7/01/2014	Reseal brake calipers, refit calipers
RDT026 : Komatsu HD605-5	8/01/2014	1000hr service, install new radio
RDT026 : Komatsu HD605-5	8/01/2014	Parts
RDT026 : Komatsu HD605-5	17/01/2014	Prepare handrail, mirror & window for transport
RDT026 : Komatsu HD605-5	17/01/2014	Site inspection fit steer pump of front struts
RDT026 : Komatsu HD605-5	20/01/2014	Parts
RDT026 : Komatsu HD605-5	22/01/2014	Subcontractor - Plant Maintenance
RDT026 : Komatsu HD605-5	27/01/2014	Help cvhange string hose
RDT026 : Komatsu HD605-5	30/01/2014	Remove brake cooling hose
RDT026 : Komatsu HD605-5	30/01/2014	Service
RDT026 : Komatsu HD605-5	31/01/2014	Parts
RDT026 : Komatsu HD605-5	31/01/2014	Parts
RDT026 : Komatsu HD605-5	4/02/2014	Parts
RDT026 : Komatsu HD605-5	8/02/2014	Cheek fault cokes
RDT026 : Komatsu HD605-5	10/02/2014	Subcontractor - Plant Maintenance
RDT026 : Komatsu HD605-5	11/02/2014	Remove trans ECU amd SVS ECU
RDT026 : Komatsu HD605-5	25/02/2014	Parts
RDT026 : Komatsu HD605-5	27/02/2014	Remove plate
RDT026 : Komatsu HD605-5	28/02/2014	Freight
RDT026 : Komatsu HD605-5	6/03/2014	Service
RDT026 : Komatsu HD605-5	6/03/2014	Service
RDT026 : Komatsu HD605-5	6/03/2014	Service
RDT026 : Komatsu HD605-5	16/03/2014	Remove top relay valve
RDT026 : Komatsu HD605-5	18/05/2014	Prep for sale
RDT026 : Komatsu HD605-5	19/05/2014	Prep for sale
RDT026 : Komatsu HD605-5	22/05/2014	Prep for sale
RDT026 : Komatsu HD605-5	20/01/2015	Parts
RDT026 : Komatsu HD605-5	27/10/2015	Subcontractor - Plant Maintenance
RDT026 : Komatsu HD605-5	28/10/2015	Took ladders off spotted put ladders back on
RDT026 : Komatsu HD605-5	1/02/2016	Inspection/ start relocate to workshop
RDT026 : Komatsu HD605-5	1/02/2016	Tick sheet steering faults, clean up TLC yard
RDT026 : Komatsu HD605-5	2/02/2016	Make up bracket for new UHP and radio aerials

RDT026 : Komatsu HD605-5	2/02/2016	Prep for site
RDT026 : Komatsu HD605-5	3/02/2016	Fix tail shaft guard fix air leaks mnake safe for
RDT026 : Komatsu HD605-5	3/02/2016	Parts
RDT026 : Komatsu HD605-5	3/02/2016	Prep for site
RDT026 : Komatsu HD605-5	3/02/2016	Search for step
RDT026 : Komatsu HD605-5	4/02/2016	Look & recover step of old machine
RDT026 : Komatsu HD605-5	4/02/2016	Parts
RDT026 : Komatsu HD605-5	4/02/2016	Prep for site
RDT026 : Komatsu HD605-5	5/02/2016	Parts
RDT026 : Komatsu HD605-5	5/02/2016	Remove step for B.M
RDT026 : Komatsu HD605-5	10/02/2016	Cut angle for walkway
RDT026 : Komatsu HD605-5	10/02/2016	Lights repair
RDT026 : Komatsu HD605-5	11/02/2016	Faricate walkway and fit
RDT026 : Komatsu HD605-5	12/02/2016	Fabrocate handrails
RDT026 : Komatsu HD605-5	15/02/2016	Weld & fit handrails
RDT026 : Komatsu HD605-5	16/02/2016	Hand rails on dump truck
RDT026 : Komatsu HD605-5	17/02/2016	Hand rails to driver side & mirror bracket
RDT026 : Komatsu HD605-5	17/02/2016	Handrail & walkways
RDT026 : Komatsu HD605-5	17/02/2016	Parts
RDT026 : Komatsu HD605-5	18/02/2016	Cut off wing thread blocks
RDT026 : Komatsu HD605-5	18/02/2016	Finish off handrail & walkway unbolt everything
RDT026 : Komatsu HD605-5	18/02/2016	Make up block bosses for dump truck & weld back on
RDT026 : Komatsu HD605-5	18/02/2016	Prep & paint handrails
RDT026 : Komatsu HD605-5	19/02/2016	Paint welds on tub of dump truck
RDT026 : Komatsu HD605-5	15/03/2016	Load up- take off steps
RDT026 : Komatsu HD605-5	15/03/2016	Remoce steps & load onto float
RDT026 : Komatsu HD605-5	17/03/2016	Assemble walkways
RDT026 : Komatsu HD605-5	19/03/2016	Site inspection
RDT026 : Komatsu HD605-5	8/04/2016	Parts
RDT026 : Komatsu HD605-5	11/04/2016	Parts
RDT026 : Komatsu HD605-5	14/04/2016	Start replacing emerg brake valv e
RDT026 : Komatsu HD605-5	15/04/2016	Carry out parts ordering for service
RDT026 : Komatsu HD605-5	15/04/2016	Replace emergency park brake
RDT026 : Komatsu HD605-5	18/04/2016	Service
RDT026 : Komatsu HD605-5	19/04/2016	Service
RDT026 : Komatsu HD605-5	14/05/2016	Repair steps
RDT026 : Komatsu HD605-5	15/05/2016	Assist pump tp struts
RDT026 : Komatsu HD605-5	15/05/2016	Carry out front strut up carry out repairs to L/H
RDT026 : Komatsu HD605-5	15/05/2016	Repair valve chucks & set up hoses and valves
RDT026 : Komatsu HD605-5	28/05/2016	Wash rear L/H,check diff breather & oil level
RDT026 : Komatsu HD605-5	4/06/2016	Inspect truck to plan job
RDT026 : Komatsu HD605-5	1/07/2016	Set up for diff removal
RDT026 : Komatsu HD605-5	2/07/2016	Start disassembly
RDT026 : Komatsu HD605-5	3/07/2016	Set up truck for diff removal
RDT026 : Komatsu HD605-5	4/07/2016	Check out brake pacls, look for parts
RDT026 : Komatsu HD605-5	4/07/2016	Fabricate diff stand
RDT026 : Komatsu HD605-5	4/07/2016	Remove diff
RDT026 : Komatsu HD605-5	4/07/2016	Remove rear axle
RDT026 : Komatsu HD605-5	4/07/2016	Subcontractor - Plant Maintenance
RDT026 : Komatsu HD605-5	5/07/2016	Clean up around machine
RDT026 : Komatsu HD605-5	6/07/2016	Assist in tyre removal

RDT026 : Komatsu HD605-5	6/07/2016	Assist remove wheels off diff for go off site
RDT026 : Komatsu HD605-5	6/07/2016	Remove wheels tidy work area
RDT026 : Komatsu HD605-5	8/07/2016	Unload truck axle assembly
RDT026 : Komatsu HD605-5	11/07/2016	Disassembly final drives and brake packs
RDT026 : Komatsu HD605-5	12/07/2016	Disassemble final drives and brake packs
RDT026 : Komatsu HD605-5	13/07/2016	32052XNTN bearing per quote 658708
RDT026 : Komatsu HD605-5	13/07/2016	32056XU NTN bearing per quote 658708
RDT026 : Komatsu HD605-5	13/07/2016	Disassemble final drives, parts list
RDT026 : Komatsu HD605-5	13/07/2016	Freight per quote 658708
RDT026 : Komatsu HD605-5	13/07/2016	Inspect wheel end components for reusability
RDT026 : Komatsu HD605-5	14/07/2016	Disassembly of lift cylinder, modify tool to suit
RDT026 : Komatsu HD605-5	14/07/2016	Fit brake packs to axle
RDT026 : Komatsu HD605-5	14/07/2016	Started to get cylinder head off
RDT026 : Komatsu HD605-5	14/07/2016	To BSC
RDT026 : Komatsu HD605-5	15/07/2016	Assemble rear axle
RDT026 : Komatsu HD605-5	15/07/2016	Carry on with removal of seized hoist cylinder nut
RDT026 : Komatsu HD605-5	15/07/2016	parts to assemble rear axle
RDT026 : Komatsu HD605-5	15/07/2016	To BOC re RDT026
RDT026 : Komatsu HD605-5	15/07/2016	Workshop Consumables
RDT026 : Komatsu HD605-5	16/07/2016	Fit hubs to rear axle
RDT026 : Komatsu HD605-5	18/07/2016	Clean parts
RDT026 : Komatsu HD605-5	18/07/2016	Finish shimming hubs, fit axles and hub covers
RDT026 : Komatsu HD605-5	18/07/2016	Parts to repair hoist cylinder
RDT026 : Komatsu HD605-5	19/07/2016	Cleaning hoist cylinder -parts & inspect
RDT026 : Komatsu HD605-5	19/07/2016	Finish off rear brake pack job, fit new sleek
RDT026 : Komatsu HD605-5	19/07/2016	Parts to repair hoist cylinder
RDT026 : Komatsu HD605-5	20/07/2016	Blast paint cylinder covers/ ram hoist
RDT026 : Komatsu HD605-5	20/07/2016	Finish assembly of hoist cylinder got ready for pa
RDT026 : Komatsu HD605-5	21/07/2016	Pack up Komatsu parts
RDT026 : Komatsu HD605-5	27/07/2016	Lay out parts for assembly
RDT026 : Komatsu HD605-5	28/07/2016	Assembly fit rear axle assembly and inside tyres
RDT026 : Komatsu HD605-5	28/07/2016	Install diff
RDT026 : Komatsu HD605-5	29/07/2016	Assist refit tyres
RDT026 : Komatsu HD605-5	29/07/2016	Re-assembly
RDT026 : Komatsu HD605-5	30/07/2016	Repair pos 4 valve extension
RDT026 : Komatsu HD605-5	1/08/2016	Assist with wheel refit
RDT026 : Komatsu HD605-5	1/08/2016	Refit pos 3 and 6 wheels to get off
RDT026 : Komatsu HD605-5	2/08/2016	Assist with service
RDT026 : Komatsu HD605-5	2/08/2016	Bled brakes/ stopped up drift/ F/D's gased rear st
RDT026 : Komatsu HD605-5	2/08/2016	Carry on with assembly
RDT026 : Komatsu HD605-5	2/08/2016	Refill oils after rebuilds assist with fitting com
RDT026 : Komatsu HD605-5	5/08/2016	Adjusted p-brake fault finding warning light
RDT026 : Komatsu HD605-5	6/08/2016	Bled brakes fitted cab door bump stop fixed warnin
RDT026 : Komatsu HD605-5	6/08/2016	Diagnose alarm
RDT026 : Komatsu HD605-5	7/08/2016	Inspect oil leak
RDT026 : Komatsu HD605-5	16/08/2016	Carry out pos 6 tyre replacement
RDT026 : Komatsu HD605-5	16/08/2016	Change pos 6 tyre
RDT026 : Komatsu HD605-5	16/08/2016	Change rear pos 6
RDT026 : Komatsu HD605-5	16/08/2016	Set up to change pos 6
RDT026 : Komatsu HD605-5	21/08/2016	250hr service
RDT026 : Komatsu HD605-5	21/08/2016	Carry out fault diagnosis to hyd oil leak

RDT026 : Komatsu HD605-5	21/08/2016	Investigate oil leak & recovered truck from pit
RDT026 : Komatsu HD605-5	22/08/2016	Remove HMU
RDT026 : Komatsu HD605-5	22/08/2016	Remove steer control valve
RDT026 : Komatsu HD605-5	23/08/2016	Assist fitting steer box
RDT026 : Komatsu HD605-5	23/08/2016	Fitted new HMU & hoses test
RDT026 : Komatsu HD605-5	23/08/2016	Parts
RDT026 : Komatsu HD605-5	27/08/2016	Fit flashing light
RDT026 : Komatsu HD605-5	29/08/2016	Park brake not holding
RDT026 : Komatsu HD605-5	29/08/2016	Toolbox, checked P-brake fault adjusted
RDT026 : Komatsu HD605-5	1/09/2016	Parts
RDT026 : Komatsu HD605-5	3/09/2016	Repairs
RDT026 : Komatsu HD605-5	3/09/2016	Repairs to ladder, Fab new mirror mount, inspect t
RDT026 : Komatsu HD605-5	4/09/2016	Mirror mounts & stop repair
RDT026 : Komatsu HD605-5	3/12/2016	Investigate siezed A/C compressor
RDT026 : Komatsu HD605-5	6/12/2016	Repair A/C
RDT026 : Komatsu HD605-5	12/12/2016	Subcontractor - Plant Maintenance
RDT026 : Komatsu HD605-5	17/12/2016	Check over machine
RDT026 : Komatsu HD605-5	31/12/2016	Repair brake cooling hose
RDT026 : Komatsu HD605-5	3/01/2017	UHF speaker not working
RDT026 : Komatsu HD605-5	10/01/2017	Service
RDT026 : Komatsu HD605-5	11/01/2017	Assist remove & replace pos 4 & 5
RDT026 : Komatsu HD605-5	11/01/2017	Changed pos 4 tyre & w/s dobs
RDT026 : Komatsu HD605-5	11/01/2017	Service
RDT026 : Komatsu HD605-5	12/01/2017	500hr service
RDT026 : Komatsu HD605-5	12/01/2017	Remove & replace pos 5 tyre & rim
RDT026 : Komatsu HD605-5	12/01/2017	SERVICE
RDT026 : Komatsu HD605-5	12/01/2017	Service & tyre fittings
rdt026 : Komatsu HD605-5	12/01/2017	service kit
RDT026 : Komatsu HD605-5	13/01/2017	500hr service
RDT026 : Komatsu HD605-5	13/01/2017	Assist service
RDT026 : Komatsu HD605-5	13/01/2017	Retenion wheel studs
RDT026 : Komatsu HD605-5	15/01/2017	Assist service
RDT026 : Komatsu HD605-5	15/01/2017	Assist workshop
RDT026 : Komatsu HD605-5	8/02/2017	Checked tub up fault, tightened wheel nuts
RDT026 : Komatsu HD605-5	8/02/2017	Tub up warning light
RDT026 : Komatsu HD605-5	8/03/2017	Repair 2nd steer switch mount
RDT026 : Komatsu HD605-5	8/03/2017	Repair emergency steering switch
RDT026 : Komatsu HD605-5	29/03/2017	Service
RDT026 : Komatsu HD605-5	9/06/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	9/06/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	9/06/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	9/06/2017	Prep for dismantle
RDT026 : Komatsu HD605-5	9/06/2017	Wash pos 3 wheelend/prep for dismantle
RDT026 : Komatsu HD605-5	9/06/2017	Working out white dam
RDT026 : Komatsu HD605-5	10/06/2017	Load truck for white dam final drive repair
RDT026 : Komatsu HD605-5	10/06/2017	Loaded up tools onto truck
RDT026 : Komatsu HD605-5	12/06/2017	Measure
RDT026 : Komatsu HD605-5	13/06/2017	Help with lifting
RDT026 : Komatsu HD605-5	13/06/2017	Loaded up truck/ drove to White Dam/ Site inductio
RDT026 : Komatsu HD605-5	13/06/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	13/06/2017	Parts to reseal 1 rear hub

RDT026 : Komatsu HD605-5	13/06/2017	Went to white dam/ started to dismantle pos 3
RDT026 : Komatsu HD605-5	14/06/2017	Completed disassembling wheel end parts
RDT026 : Komatsu HD605-5	14/06/2017	Dismantle hub and f/d assembled brake mounting pla
RDT026 : Komatsu HD605-5	14/06/2017	Help with job
RDT026 : Komatsu HD605-5	14/06/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	15/06/2017	Assemble hub and f/d bleed brakes check for leaks
RDT026 : Komatsu HD605-5	15/06/2017	Completed assembling wheel end
RDT026 : Komatsu HD605-5	15/06/2017	Help with repair
RDT026 : Komatsu HD605-5	16/06/2017	Fit wheels check fault list test drive
RDT026 : Komatsu HD605-5	16/06/2017	Fitted tyres/ ran and tested machine/ truck inspec
RDT026 : Komatsu HD605-5	17/06/2017	Wash for demobe
RDT026 : Komatsu HD605-5	18/06/2017	Finish washing for demobe
RDT026 : Komatsu HD605-5	19/06/2017	Demobe from WD/repairs/clean truck
RDT026 : Komatsu HD605-5	19/06/2017	Unload truck
RDT026 : Komatsu HD605-5	23/06/2017	demobe machine
RDT026 : Komatsu HD605-5	23/06/2017	prep for transport/remove rock guards mirrors side
RDT026 : Komatsu HD605-5	26/06/2017	Hand rails/ cat wlks (linwood)
RDT026 : Komatsu HD605-5	26/06/2017	refit brake hose & top up
RDT026 : Komatsu HD605-5	26/06/2017	travel to linwood, prep to fit handraiks to RDT026
RDT026 : Komatsu HD605-5	27/06/2017	adjust struts (front&rear) fit hand rails,
RDT026 : Komatsu HD605-5	27/06/2017	assemble dump truck rock protectors,prep truck
RDT026 : Komatsu HD605-5	30/06/2017	Check & diagnose not starting
RDT026 : Komatsu HD605-5	1/07/2017	Diagnose no start fault/clean fuel screen
RDT026 : Komatsu HD605-5	5/07/2017	retorque pos 3
RDT026 : Komatsu HD605-5	8/07/2017	Parts
RDT026 : Komatsu HD605-5	8/07/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	8/07/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	8/07/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	8/07/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	10/07/2017	check all fluid levels & top up at linwood quarry
RDT026 : Komatsu HD605-5	10/07/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	10/07/2017	Parts to reseal 1 rear hub
RDT026 : Komatsu HD605-5	15/07/2017	load truck,travel to boral(Linswood) service 250hr
RDT026 : Komatsu HD605-5	20/07/2017	load up & travel to Linwood,diagnose trans fault
RDT026 : Komatsu HD605-5	21/07/2017	600-211-1231 Oil Filter
RDT026 : Komatsu HD605-5	21/07/2017	600-212-1511 By Pass Oil Filter
RDT026 : Komatsu HD605-5	27/07/2017	load and unload tools, travel to and from linwood
RDT026 : Komatsu HD605-5	31/07/2017	Parts Trans Controller
RDT026 : Komatsu HD605-5	1/08/2017	diagnose trans fault
RDT026 : Komatsu HD605-5	2/08/2017	load & unload tools,travel to and from Linwood
RDT026 : Komatsu HD605-5	11/08/2017	check & repair trans fault,unload tools from ute
RDT026 : Komatsu HD605-5	15/08/2017	exit inspection
RDT026 : Komatsu HD605-5	15/08/2017	inspection
RDT026 : Komatsu HD605-5	17/08/2017	repairs & prep for use
RDT026 : Komatsu HD605-5	17/08/2017	repairs & prep for use,travel to workshop
RDT026 : Komatsu HD605-5	18/08/2017	dissmantel,repair step for RDT,fabricate & weld
RDT026 : Komatsu HD605-5	19/08/2017	assemble steps for RDT
RDT026 : Komatsu HD605-5	21/08/2017	Parts to prep
RDT026 : Komatsu HD605-5	21/08/2017	Signage
RDT026 : Komatsu HD605-5	22/08/2017	Parts
RDT026 : Komatsu HD605-5	22/08/2017	repairs on truck & prep for use,clean out LTR024

RDT026 : Komatsu HD605-5	23/08/2017	Parts to prep
RDT026 : Komatsu HD605-5	23/08/2017	repairs & maint- prep for prominent hill
RDT026 : Komatsu HD605-5	24/08/2017	Parts to prep
RDT026 : Komatsu HD605-5	24/08/2017	repair on oil leaks,replace alternator belt
RDT026 : Komatsu HD605-5	25/08/2017	make up tray pin
RDT026 : Komatsu HD605-5	25/08/2017	Parts to prep
RDT026 : Komatsu HD605-5	28/08/2017	repairs on leaks,fit new seat belt,elect faults
RDT026 : Komatsu HD605-5	29/08/2017	front RH wish bone bushes
RDT026 : Komatsu HD605-5	29/08/2017	travel to boral linwood,start removal of wishbones
RDT026 : Komatsu HD605-5	30/08/2017	front RH wish bone bushes c/o(linwood)
RDT026 : Komatsu HD605-5	30/08/2017	removal of wishbone link,bushes & pins replaced
RDT026 : Komatsu HD605-5	31/08/2017	clean & tidy truck & drain waste oils
RDT026 : Komatsu HD605-5	1/09/2017	load tools,travel to Linwood,setup crane
RDT026 : Komatsu HD605-5	2/09/2017	unload machine from float,inspect machine
RDT026 : Komatsu HD605-5	3/09/2017	plant entry inspection & defect repairs
RDT026 : Komatsu HD605-5	3/09/2017	pump oil into struts and gas,fit gas walks
RDT026 : Komatsu HD605-5	6/09/2017	Repair front step
RDT026 : Komatsu HD605-5	11/09/2017	fixed transmission elect fault
RDT026 : Komatsu HD605-5	11/09/2017	look for electrical fault with trans
RDT026 : Komatsu HD605-5	12/09/2017	look for elect fault with trans,fix 3 wires
RDT026 : Komatsu HD605-5	12/09/2017	pulled trans wiring loom out & fixed drive
RDT026 : Komatsu HD605-5	17/09/2017	Freight
RDT026 : Komatsu HD605-5	18/09/2017	Service
RDT026 : Komatsu HD605-5	19/09/2017	Service
RDT026 : Komatsu HD605-5	21/09/2017	Tyres QUOTE SEQ055990
RDT026 : Komatsu HD605-5	26/09/2017	Diagnose low power fault
RDT026 : Komatsu HD605-5	26/09/2017	Look for low power fault,fit new fuel filters
RDT026 : Komatsu HD605-5	27/09/2017	Look for low power fault,clean out screen
RDT026 : Komatsu HD605-5	30/09/2017	Remove blown cooler hose,fit new hose
RDT026 : Komatsu HD605-5	7/10/2017	Wash machine down for fitter to change pos 5 tyre
RDT026 : Komatsu HD605-5	10/10/2017	Moved into tyre yard parked on blocks
RDT026 : Komatsu HD605-5	10/10/2017	Organise machine onto Thiess tyre bay
RDT026 : Komatsu HD605-5	12/10/2017	Diagnose strut fault
RDT026 : Komatsu HD605-5	12/10/2017	Put nitrogen in pos 2 strut, still needs oil
RDT026 : Komatsu HD605-5	13/10/2017	Engine wash down to locate & repair oil leak
RDT026 : Komatsu HD605-5	13/10/2017	Gas RHF strut
RDT026 : Komatsu HD605-5	14/10/2017	Re torque of pos 5/6 wheel
RDT026 : Komatsu HD605-5	14/10/2017	Re torque pos 3 & 4 wheel
RDT026 : Komatsu HD605-5	18/10/2017	Gas R/H front strut
RDT026 : Komatsu HD605-5	1/11/2017	Carry out "Exit inspection" & wash
RDT026 : Komatsu HD605-5	1/11/2017	Done ticksheet
RDT026 : Komatsu HD605-5	14/12/2017	Travel to SWD & communocation Rd for parts
RDT026 : Komatsu HD605-5	20/12/2017	Entry inspection
RDT026 : Komatsu HD605-5	20/12/2017	Fuel filters
RDT026 : Komatsu HD605-5	20/12/2017	Ticksheet, wash, Fix lights, reverse buzzer
RDT026 : Komatsu HD605-5	21/12/2017	Clear W/shop, move truck, put on stands, clean pin
RDT026 : Komatsu HD605-5	21/12/2017	Remove pos 2 wheel, remove grease lines/ oil lines
RDT026 : Komatsu HD605-5	21/12/2017	Search for parts
RDT026 : Komatsu HD605-5	22/12/2017	Clean & assemble strut, start fitment of strut
RDT026 : Komatsu HD605-5	22/12/2017	Clean & assemble strut, start fitting, clean parts
RDT026 : Komatsu HD605-5	22/12/2017	Repair front suspension

RDT026 : Komatsu HD605-5	27/12/2017	Finish fitting RHF strut, fit steering cylinders
RDT026 : Komatsu HD605-5	28/12/2017	Condense Komatsu stillages, move parts into stilla
RDT026 : Komatsu HD605-5	29/12/2017	Continue with 2000hr servicem R&R final drive & di
RDT026 : Komatsu HD605-5	2/01/2018	Continue with 2000hr service
RDT026 : Komatsu HD605-5	2/01/2018	Fix up front steps on bumpy
RDT026 : Komatsu HD605-5	2/01/2018	Repairs to access steps
RDT026 : Komatsu HD605-5	3/01/2018	Brakes
RDT026 : Komatsu HD605-5	3/01/2018	Continue with 2000hr service
RDT026 : Komatsu HD605-5	4/01/2018	Exit inspection, repair washers, set up machine
RDT026 : Komatsu HD605-5	4/01/2018	Repairs to exhaust hole & cracks
RDT026 : Komatsu HD605-5	4/01/2018	Spotter
RDT026 : Komatsu HD605-5	5/01/2018	make hoses as needed @ Darlington
RDT026 : Komatsu HD605-5	16/01/2018	Load up for Boral jobs
RDT026 : Komatsu HD605-5	16/01/2018	Load up for jobs at Linwood, check list
RDT026 : Komatsu HD605-5	17/01/2018	Fit steps/catwalk & rails, repair leaking valves
RDT026 : Komatsu HD605-5	17/01/2018	Load up truck for Bral, fit catwalk/steps, susp
RDT026 : Komatsu HD605-5	25/01/2018	rechrome Komatsu Front Suspension Cylinder Rod
RDT026 : Komatsu HD605-5	28/02/2018	Prep machine for transport
RDT026 : Komatsu HD605-5	28/02/2018	Remove mirrors, cat walk
RDT026 : Komatsu HD605-5	22/03/2018	Tyres
RDT026 : Komatsu HD605-5	26/03/2018	Unload from truck
RDT026 : Komatsu HD605-5	26/03/2018	Unload from truck
RDT026 : Komatsu HD605-5	28/03/2018	Bring to workshop and fit walkway and handrails
RDT026 : Komatsu HD605-5	28/03/2018	Drive to Workshop and repalce steps
RDT026 : Komatsu HD605-5	29/03/2018	Charge struts and entry inspect
RDT026 : Komatsu HD605-5	29/03/2018	Entry inspect
RDT026 : Komatsu HD605-5	1/05/2018	Order parts and filters
RDT026 : Komatsu HD605-5	2/05/2018	Service
RDT026 : Komatsu HD605-5	7/05/2018	Hand brake fault
RDT026 : Komatsu HD605-5	7/05/2018	Investigate park brake fault
RDT026 : Komatsu HD605-5	8/05/2018	Parts
RDT026 : Komatsu HD605-5	9/05/2018	Coolant leak
RDT026 : Komatsu HD605-5	10/05/2018	Replace wiper blade/repair coolant tank issue
RDT026 : Komatsu HD605-5	11/05/2018	Carry out service/defects
RDT026 : Komatsu HD605-5	11/05/2018	Park brake pads
RDT026 : Komatsu HD605-5	14/05/2018	Parts
RDT026 : Komatsu HD605-5	14/05/2018	Pos 4 tyre slow leak, order parts
RDT026 : Komatsu HD605-5	15/05/2018	Parts
RDT026 : Komatsu HD605-5	21/05/2018	Fit new dash assembly
RDT026 : Komatsu HD605-5	22/05/2018	Retorque 3&4
RDT026 : Komatsu HD605-5	22/05/2018	Retorque pos 3 wheel x 3
RDT026 : Komatsu HD605-5	29/05/2018	Order belts
RDT026 : Komatsu HD605-5	1/06/2018	Engine oil pipe couplings
RDT026 : Komatsu HD605-5	2/06/2018	Inspect machine
RDT026 : Komatsu HD605-5	2/06/2018	Top up coolant, no man beam, check tyres
RDT026 : Komatsu HD605-5	7/06/2018	Order filters
RDT026 : Komatsu HD605-5	7/06/2018	Parts
RDT026 : Komatsu HD605-5	7/06/2018	Service
RDT026 : Komatsu HD605-5	8/06/2018	Service
RDT026 : Komatsu HD605-5	8/06/2018	Service
RDT026 : Komatsu HD605-5	8/06/2018	Service

RDT026 : Komatsu HD605-5	8/06/2018	Wind screen wiper
RDT026 : Komatsu HD605-5	9/06/2018	Adjust front struts
RDT026 : Komatsu HD605-5	9/06/2018	Gas struts and wiper
RDT026 : Komatsu HD605-5	12/06/2018	Bring back to WS, remove hoist cylinder
RDT026 : Komatsu HD605-5	12/06/2018	Inspect ploy in hoist
RDT026 : Komatsu HD605-5	12/06/2018	Organise parts for hoist cylinder
RDT026 : Komatsu HD605-5	12/06/2018	Remove RH lift cylinder
RDT026 : Komatsu HD605-5	13/06/2018	Parts
RDT026 : Komatsu HD605-5	14/06/2018	Disassemble & start reassemble hoist cyl
RDT026 : Komatsu HD605-5	14/06/2018	Pick up plants
RDT026 : Komatsu HD605-5	14/06/2018	Rebuild hoist cylinder
RDT026 : Komatsu HD605-5	14/06/2018	Remove hmu hoses and remove fan belts
RDT026 : Komatsu HD605-5	15/06/2018	Assemble & paint hoist cyl
RDT026 : Komatsu HD605-5	15/06/2018	Parts
RDT026 : Komatsu HD605-5	15/06/2018	Parts
RDT026 : Komatsu HD605-5	15/06/2018	Rebuild hoist cylinder
RDT026 : Komatsu HD605-5	18/06/2018	Tyres
RDT026 : Komatsu HD605-5	19/06/2018	Hose, hoist cyl, test
RDT026 : Komatsu HD605-5	19/06/2018	Install hoist cylinder
RDT026 : Komatsu HD605-5	19/06/2018	Parts
RDT026 : Komatsu HD605-5	21/06/2018	Collect Parts
RDT026 : Komatsu HD605-5	21/06/2018	Parts
RDT026 : Komatsu HD605-5	22/06/2018	Parts
RDT026 : Komatsu HD605-5	26/06/2018	Parts
RDT026 : Komatsu HD605-5	26/06/2018	Parts
RDT026 : Komatsu HD605-5	26/06/2018	Parts
RDT026 : Komatsu HD605-5	4/07/2018	Replace fan belts
RDT026 : Komatsu HD605-5	6/07/2018	Parts
RDT026 : Komatsu HD605-5	25/07/2018	Rear strut, mirror
RDT026 : Komatsu HD605-5	30/07/2018	Body raise switch
RDT026 : Komatsu HD605-5	30/07/2018	Tub up sensors
RDT026 : Komatsu HD605-5	3/08/2018	Shut down fault
RDT026 : Komatsu HD605-5	4/08/2018	500 hrs service
RDT026 : Komatsu HD605-5	4/08/2018	Service
RDT026 : Komatsu HD605-5	5/08/2018	Complete service
RDT026 : Komatsu HD605-5	5/08/2018	Service
RDT026 : Komatsu HD605-5	16/08/2018	Tub up thasm fault
RDT026 : Komatsu HD605-5	21/08/2018	Check strut and rock ejector
RDT026 : Komatsu HD605-5	24/08/2018	Straighten step and refit
RDT026 : Komatsu HD605-5	27/08/2018	Service
RDT026 : Komatsu HD605-5	1/09/2018	Weld step
RDT026 : Komatsu HD605-5	2/09/2018	Install step
RDT026 : Komatsu HD605-5	15/09/2018	Remove rock ejector and bring back to workshop
RDT026 : Komatsu HD605-5	15/09/2018	Replace pos 5 tyre
RDT026 : Komatsu HD605-5	16/09/2018	250hr service, straighten rock ejector
RDT026 : Komatsu HD605-5	16/09/2018	Service and repairs
RDT026 : Komatsu HD605-5	18/09/2018	Bleed up fuel and check injector pump
RDT026 : Komatsu HD605-5	18/09/2018	Fuel issue
RDT026 : Komatsu HD605-5	19/09/2018	Retorque
RDT026 : Komatsu HD605-5	20/09/2018	Parts
RDT026 : Komatsu HD605-5	20/09/2018	Parts

RDT026 : Komatsu HD605-5	25/09/2018	Hose and fittings
RDT026 : Komatsu HD605-5	26/09/2018	Order parts
RDT026 : Komatsu HD605-5	28/09/2018	Rock ejector
RDT026 : Komatsu HD605-5	4/10/2018	Parts
RDT026 : Komatsu HD605-5	9/10/2018	Pos 3 tyre SWE leak
RDT026 : Komatsu HD605-5	10/10/2018	Tyre work
RDT026 : Komatsu HD605-5	11/10/2018	Service
RDT026 : Komatsu HD605-5	11/10/2018	Service
RDT026 : Komatsu HD605-5	14/10/2018	Retorque
RDT026 : Komatsu HD605-5	14/10/2018	Retorque wheel
RDT026 : Komatsu HD605-5	15/10/2018	Fuel fault
RDT026 : Komatsu HD605-5	15/10/2018	Service
RDT026 : Komatsu HD605-5	16/10/2018	Retorque pos 3
RDT026 : Komatsu HD605-5	22/10/2018	Fuel issue
RDT026 : Komatsu HD605-5	6/11/2018	Tyres
RDT026 : Komatsu HD605-5	10/11/2018	Hard starting
RDT026 : Komatsu HD605-5	11/11/2018	Hard starting
RDT026 : Komatsu HD605-5	12/11/2018	Remove both starter motors
RDT026 : Komatsu HD605-5	13/11/2018	Test starter motors & prep for transport
RDT026 : Komatsu HD605-5	15/11/2018	Fit starters
RDT026 : Komatsu HD605-5	15/11/2018	Renew starter motors, attend electrical fault
RDT026 : Komatsu HD605-5	15/11/2018	Replace starter motors, diagnose wiring fault, rep
RDT026 : Komatsu HD605-5	15/11/2018	Travel to TB
RDT026 : Komatsu HD605-5	28/11/2018	Jump start E-02 fault
RDT026 : Komatsu HD605-5	7/12/2018	Investigate trans faultcode
RDT026 : Komatsu HD605-5	7/12/2018	Trans fault
RDT026 : Komatsu HD605-5	8/12/2018	Exhaust brake fault
RDT026 : Komatsu HD605-5	11/12/2018	Fault
RDT026 : Komatsu HD605-5	13/12/2018	External - Crane
RDT026 : Komatsu HD605-5	3/01/2019	Batteries
RDT026 : Komatsu HD605-5	3/01/2019	Load on float, follow to Harlty land fill & unload
RDT026 : Komatsu HD605-5	4/01/2019	Refitted handrolls & steps
RDT026 : Komatsu HD605-5	16/01/2019	A/C
RDT026 : Komatsu HD605-5	17/01/2019	A/C
RDT026 : Komatsu HD605-5	21/01/2019	A/c repair,drive to Hartley check a/c system
RDT026 : Komatsu HD605-5	22/01/2019	Make parts list to be ordered
RDT026 : Komatsu HD605-5	22/01/2019	Parts
RDT026 : Komatsu HD605-5	22/01/2019	Parts
RDT026 : Komatsu HD605-5	23/01/2019	A/c repair,started to repair a/c
RDT026 : Komatsu HD605-5	24/01/2019	A/c repairs,changed tx valve,removed compressor
RDT026 : Komatsu HD605-5	24/01/2019	Remove after cooler & wash radiator
RDT026 : Komatsu HD605-5	25/01/2019	A/c repairs fitted new comp,test for leaks
RDT026 : Komatsu HD605-5	7/02/2019	1000hr Service
RDT026 : Komatsu HD605-5	7/02/2019	1000hr service,load up at Darlington
RDT026 : Komatsu HD605-5	8/02/2019	Pressure clean radiator,wiring repairs
RDT026 : Komatsu HD605-5	8/02/2019	Travel to & from Hartley,diagnose fault & repair
RDT026 : Komatsu HD605-5	14/02/2019	Top up oils
RDT026 : Komatsu HD605-5	24/03/2019	Tyre repair
RDT026 : Komatsu HD605-5	4/04/2019	Unload off float
RDT026 : Komatsu HD605-5	5/04/2019	Entry inspection/repairs, travel to workshop
RDT026 : Komatsu HD605-5	6/04/2019	Gas struts, test drive, clean up

RDT026 : Komatsu HD605-5	6/04/2019	Gased struts & finish check list
RDT026 : Komatsu HD605-5	25/07/2019	Tyres
RDT026 : Komatsu HD605-5	16/08/2019	Tyres
RDT026 : Komatsu HD605-5	20/08/2019	Attach number plate
RDT026 : Komatsu HD605-5	20/08/2019	Fit number plate
RDT026 : Komatsu HD605-5	25/11/2019	Tyre repair
RDT026 : Komatsu HD605-5	16/12/2019	Carry out inspection sheet/travel back to W/S
RDT026 : Komatsu HD605-5	16/12/2019	Load truck went to SWD check & fault list sorted p
RDT026 : Komatsu HD605-5	17/12/2019	Inspection repairs/repair oil leaks/replace mirror
RDT026 : Komatsu HD605-5	17/12/2019	Topped hyd oil/repared window washer
RDT026 : Komatsu HD605-5	18/12/2019	/replace stipes around machiens
RDT026 : Komatsu HD605-5	18/12/2019	Drive to Lonsdale/drop off SWR
RDT026 : Komatsu HD605-5	18/12/2019	Dropped struts fit sticjker return to W/S
RDT026 : Komatsu HD605-5	18/12/2019	Signage
RDT026 : Komatsu HD605-5	1/04/2020	Entry tick sheet/ fault list/ travel to .Waste
RDT026 : Komatsu HD605-5	1/04/2020	Machine inspection & tick sheet/drive to dump/load
RDT026 : Komatsu HD605-5	12/05/2020	SOS Process
RDT026 : Komatsu HD605-5	11/08/2020	Attempt to move to Com Rd
RDT026 : Komatsu HD605-5	11/08/2020	it batteries to truck/check over drive to storage
RDT026 : Komatsu HD605-5	11/08/2020	Load up truck go to Tatachilla fit batteries to tr
RDT026 : Komatsu HD605-5	11/08/2020	Move
RDT026 : Komatsu HD605-5	12/08/2020	Get truck out of bog & park up
RDT026 : Komatsu HD605-5	12/08/2020	Recovery, refit batteries, move truck
RDT026 : Komatsu HD605-5	21/09/2020	2x N200 Batteries
RDT026 : Komatsu HD605-5	21/09/2020	Inspection of plant
RDT026 : Komatsu HD605-5	21/09/2020	MV prep, order batteries
RDT026 : Komatsu HD605-5	21/09/2020	Pack tooling, travel to com rd, carry out insp
RDT026 : Komatsu HD605-5	21/09/2020	Prep
RDT026 : Komatsu HD605-5	22/09/2020	Mount OHF, fluid top up
RDT026 : Komatsu HD605-5	23/09/2020	Removal of pedal/repairs, travel to com rd
RDT026 : Komatsu HD605-5	24/09/2020	Prep
RDT026 : Komatsu HD605-5	12/10/2020	Load LTR024, install batt, refuel, remove mirriors
RDT026 : Komatsu HD605-5	12/10/2020	Prep
RDT026 : Komatsu HD605-5	12/10/2020	Removed side mirrors & walkway. Assist loading
RDT026 : Komatsu HD605-5	12/10/2020	Travel to Com Rd install new batteries
RDT026 : Komatsu HD605-5	15/10/2020	Sort parts list, tooling etc
RDT026 : Komatsu HD605-5	24/10/2020	Check tyre pressures
RDT026 : Komatsu HD605-5	24/10/2020	Grease machine,run up to test
RDT026 : Komatsu HD605-5	28/10/2020	Prestart machine top up fluids
RDT026 : Komatsu HD605-5	28/10/2020	Travel to & from MVQ, look at engine over heating
RDT026 : Komatsu HD605-5	29/10/2020	Prestart & inspection
RDT026 : Komatsu HD605-5	30/10/2020	Prestart & isnpection
RDT026 : Komatsu HD605-5	9/11/2020	Changed batteries
RDT026 : Komatsu HD605-5	9/11/2020	N200 batteries
RDT026 : Komatsu HD605-5	9/11/2020	Remove 2x batteries, clean up terminals & leads
RDT026 : Komatsu HD605-5	11/11/2020	Prep
RDT026 : Komatsu HD605-5	14/11/2020	Parts order
RDT026 : Komatsu HD605-5	16/11/2020	Drove to/from McLaren Vale Q, inspect parts etc
RDT026 : Komatsu HD605-5	16/11/2020	Elec/mechanical repairs, load up ute
RDT026 : Komatsu HD605-5	16/11/2020	Sort repairs for susp fault @ MVQ
RDT026 : Komatsu HD605-5	17/11/2020	Check stillages for sensor/clean up

RDT026 : Komatsu HD605-5	17/11/2020	Repair U/S suspension sensor, test
RDT026 : Komatsu HD605-5	17/11/2020	Repair wiring for suspension cylinder, grease
RDT026 : Komatsu HD605-5	23/11/2020	Parts order for coolant taps on filter housing
RDT026 : Komatsu HD605-5	26/11/2020	Prep service kit & paperwork
RDT026 : Komatsu HD605-5	27/11/2020	Fuel Filters
RDT026 : Komatsu HD605-5	28/11/2020	Complete 250hr service & inspection
RDT026 : Komatsu HD605-5	30/11/2020	all out MVQ, lost power to eng/no start
RDT026 : Komatsu HD605-5	30/11/2020	Complete paperwork/workbench
RDT026 : Komatsu HD605-5	2/12/2020	Process SOS & p/work
RDT026 : Komatsu HD605-5	8/12/2020	Bloen P6 sort Bridgestone to C/O P1 & P2 new tyres
RDT026 : Komatsu HD605-5	9/12/2020	2 new VRLS Tyres
RDT026 : Komatsu HD605-5	9/12/2020	Load tools, go to MVQ, inspect & retorque
RDT026 : Komatsu HD605-5	10/12/2020	Check P1, P2, P6 wheel nuts
RDT026 : Komatsu HD605-5	10/12/2020	Fit 2 new tyres to P1&2, fit removed P1 to P6.
RDT026 : Komatsu HD605-5	12/12/2020	Organsie aircleaners for site
RDT026 : Komatsu HD605-5	14/12/2020	Engine lossing power & stalling bleed up fuel
RDT026 : Komatsu HD605-5	14/12/2020	Extra air filters
RDT026 : Komatsu HD605-5	15/12/2020	Retorque po 1,2 & 6
RDT026 : Komatsu HD605-5	18/12/2020	Adj park brake, return to Darlington
RDT026 : Komatsu HD605-5	21/12/2020	Call out MVQ repair float sensor to tub up/down
RDT026 : Komatsu HD605-5	12/01/2021	Fit walkways, mirrors struts
RDT026 : Komatsu HD605-5	12/01/2021	Fit walkways, mirrors, gas stuts
RDT026 : Komatsu HD605-5	21/01/2021	Trans fault, machine wont move
RDT026 : Komatsu HD605-5	28/01/2021	Inspect & c;eam out over heating
RDT026 : Komatsu HD605-5	29/01/2021	Clean out A/C syste,
RDT026 : Komatsu HD605-5	30/01/2021	Call out blown coolant hose
RDT026 : Komatsu HD605-5	30/01/2021	Travel to Harley C/O UHF radop, fix Coax & cables
RDT026 : Komatsu HD605-5	1/02/2021	C/O U/S UHF radio repair, coolant/ oil leaks
rdt026 : Komatsu HD605-5	1/02/2021	coolant over flow hose & fittings
RDT026 : Komatsu HD605-5	3/02/2021	Cab Filters
RDT026 : Komatsu HD605-5	3/02/2021	Prep service kit & paperwork
RDT026 : Komatsu HD605-5	3/02/2021	Service kit/order filters
RDT026 : Komatsu HD605-5	3/02/2021	Sort new fuel pipe retaining clamps & brackets
RDT026 : Komatsu HD605-5	3/02/2021	Sort order to plan in servie
RDT026 : Komatsu HD605-5	5/02/2021	Replace U/S grease nipples
RDT026 : Komatsu HD605-5	6/02/2021	Parts order for V-seals on hyd cooling pipes
RDT026 : Komatsu HD605-5	9/02/2021	Look at cooling issue
RDT026 : Komatsu HD605-5	12/02/2021	Sort load/drop off parts to service kit
RDT026 : Komatsu HD605-5	18/02/2021	Repair A/C fault, coolers into cab/insp
RDT026 : Komatsu HD605-5	18/02/2021	SPEAKER 2
RDT026 : Komatsu HD605-5	19/02/2021	C/O A/C gas, sort & set up
RDT026 : Komatsu HD605-5	19/02/2021	Prep for service & repairs
RDT026 : Komatsu HD605-5	20/02/2021	Carry out 500hr service, replace park brake
RDT026 : Komatsu HD605-5	20/02/2021	Service & repairs
RDT026 : Komatsu HD605-5	22/02/2021	CLEAN UP FROM SERVICES
RDT026 : Komatsu HD605-5	22/02/2021	PROCESS OIL SAMPLES & DEFECT LIST
RDT026 : Komatsu HD605-5	24/02/2021	CAB FILTER
RDT026 : Komatsu HD605-5	24/02/2021	Check damage on belt, C/O U/S radiator
RDT026 : Komatsu HD605-5	24/02/2021	INNER & OUTER AIR CLEANER
RDT026 : Komatsu HD605-5	24/02/2021	PRGANISE/PACK & SEND FILTERS
RDT026 : Komatsu HD605-5	25/02/2021	LOAD UP AND DROP OFF FILTER AND OIL

RDT026 : Komatsu HD605-5	25/02/2021	Oil Sample Bottles
RDT026 : Komatsu HD605-5	25/02/2021	PREP AND PARTS
RDT026 : Komatsu HD605-5	25/02/2021	SORT PARTS FOR COOLING SYSTEM
RDT026 : Komatsu HD605-5	25/02/2021	STARTED REMOVING WATER PUMP
RDT026 : Komatsu HD605-5	26/02/2021	LOADED UTE UP TO HARTLEY
RDT026 : Komatsu HD605-5	26/02/2021	PARTS ORDER FOR COOLING
RDT026 : Komatsu HD605-5	26/02/2021	tyre pressure gauge for site
RDT026 : Komatsu HD605-5	27/02/2021	GO TO HARTLEY REMOVE BOTTOM TURBO
rdt026 : Komatsu HD605-5	1/03/2021	cooler pack parts
RDT026 : Komatsu HD605-5	1/03/2021	COOLING SYSTEM
RDT026 : Komatsu HD605-5	1/03/2021	DISSASSEMBLED WATER PUMP
RDT026 : Komatsu HD605-5	1/03/2021	P/U PARTS
RDT026 : Komatsu HD605-5	2/03/2021	DISSASEEMBALE THERMOSTAT HOWING
RDT026 : Komatsu HD605-5	2/03/2021	GO TO COM ROAD
RDT026 : Komatsu HD605-5	3/03/2021	CHASE UP KOMATSU
RDT026 : Komatsu HD605-5	3/03/2021	CLENAED PARTS
rdt026 : Komatsu HD605-5	4/03/2021	cooler pack parts
RDT026 : Komatsu HD605-5	4/03/2021	COR COOLING
RDT026 : Komatsu HD605-5	4/03/2021	LOAD SERVICE TRUCK
RDT026 : Komatsu HD605-5	4/03/2021	LOAD UP TOOLS
rdt026 : Komatsu HD605-5	4/03/2021	repair after cooler
rdt026 : Komatsu HD605-5	4/03/2021	repair turbo
RDT026 : Komatsu HD605-5	5/03/2021	ASSEMBELED THERMOSTAT HOUSING
RDT026 : Komatsu HD605-5	5/03/2021	BUILD THERMOSTRAT HOUSING
rdt026 : Komatsu HD605-5	5/03/2021	cooler pack parts
RDT026 : Komatsu HD605-5	6/03/2021	DRIVE TO HARTLEY FITTED TURBO
RDT026 : Komatsu HD605-5	6/03/2021	TRAVEL TO HARTLEY
RDT026 : Komatsu HD605-5	9/03/2021	LOAD UP UTE AND TRAVEL TO HARTLEY
RDT026 : Komatsu HD605-5	9/03/2021	SORT REPAIRS AND PARTS
RDT026 : Komatsu HD605-5	10/03/2021	SORT REPAIRS
rdt026 : Komatsu HD605-5	10/03/2021	thermoastat housing orings
RDT026 : Komatsu HD605-5	10/03/2021	TRAVEL TO KOMATSU AND PICK UP O RINGS
RDT026 : Komatsu HD605-5	11/03/2021	SORT LEFT OVER PARTS
RDT026 : Komatsu HD605-5	11/03/2021	SORT OUT TOOLS
rdt026 : Komatsu HD605-5	12/03/2021	belts, fan, alt, a/c
RDT026 : Komatsu HD605-5	12/03/2021	SORT SERVICE
RDT026 : Komatsu HD605-5	15/03/2021	NEW BRAKE HOSES PR &P4
RDT026 : Komatsu HD605-5	15/03/2021	REPLACE ALTENATOR
RDT026 : Komatsu HD605-5	15/03/2021	REPLACE COOLANT FILTER, ALT BELT, COOLING HOSES
RDT026 : Komatsu HD605-5	16/03/2021	UPDATE WORKBENCH
RDT026 : Komatsu HD605-5	17/03/2021	OVER TEMP
RDT026 : Komatsu HD605-5	18/03/2021	U/S BRAKE HOSES & REPAIRS
RDT026 : Komatsu HD605-5	19/03/2021	SORT HI TEMP FAULT & PIRTEK FOR HOSE REPA
RDT026 : Komatsu HD605-5	20/03/2021	FAULT CHECK, RADI BLOCKED AAGAIN, CLEAN, Check Mo
RDT026 : Komatsu HD605-5	22/03/2021	SORT OVER HEATING & CLEANING OF COOLER
RDT026 : Komatsu HD605-5	22/03/2021	TRAVEL TO HARTLEY & CHECK COOLING SYSTEM
RDT026 : Komatsu HD605-5	24/03/2021	OVER HEATING
RDT026 : Komatsu HD605-5	24/03/2021	TRAVEL TO HARTLEY 100K AT OVER HEATING ISSUE
rdt026 : Komatsu HD605-5	25/03/2021	cooler pack parts
RDT026 : Komatsu HD605-5	25/03/2021	FOLLOW UP HOSES
RDT026 : Komatsu HD605-5	25/03/2021	LOOK INTO COOLANT LEAK

RDT026 : Komatsu HD605-5	30/03/2021	C/O BRAKE HOSES P3 & P4
RDT026 : Komatsu HD605-5	30/03/2021	REPLACE HOSES
rdt026 : Komatsu HD605-5	31/03/2021	replace brake hoses (p3 & p4)
RDT026 : Komatsu HD605-5	31/03/2021	REPLACED BRAKE COOLING HOSES
RDT026 : Komatsu HD605-5	15/04/2021	DIAGNOSED REFUEL ISSUE, @ HARTLEY
RDT026 : Komatsu HD605-5	1/05/2021	SORT PARTS ECT UPCOMING SERVICE
RDT026 : Komatsu HD605-5	3/05/2021	SERVICE KITS
RDT026 : Komatsu HD605-5	4/05/2021	P/BRAKE FAULT, AIR LOSS, VALVE
RDT026 : Komatsu HD605-5	5/05/2021	FINISH SERVICE KITS
RDT026 : Komatsu HD605-5	5/05/2021	SORT TRANSPORT, REPAIRS & PARTS
RDT026 : Komatsu HD605-5	6/05/2021	250HR SERVICE & REPAIRS @ HARTLEY
RDT026 : Komatsu HD605-5	6/05/2021	CARRY OUT 250HR SERVICE, EXIT INSPECTION
RDT026 : Komatsu HD605-5	11/05/2021	BEGIN MOBILISING TRACK
RDT026 : Komatsu HD605-5	11/05/2021	BEGIN MOBILISING TRUCK @ MVQ
RDT026 : Komatsu HD605-5	12/05/2021	CLOSE OUT SERVICE
RDT026 : Komatsu HD605-5	12/05/2021	RETRIEVE ALL PARTS & FILTERS FOR MVQ
RDT026 : Komatsu HD605-5	14/05/2021	PARTS ORDER
RDT026 : Komatsu HD605-5	17/05/2021	CHECK OILS, SITE MOBILISATION
RDT026 : Komatsu HD605-5	17/05/2021	PREP TRUCK FOR USE, PATCHED COOLANT LEAK
RDT026 : Komatsu HD605-5	18/05/2021	PREP TRUCK FOR USE
RDT026 : Komatsu HD605-5	19/05/2021	OVER HEATING FAULT & INSPECT
RDT026 : Komatsu HD605-5	20/05/2021	HOIST FAULT, STUCK IN 2ND GEAR
RDT026 : Komatsu HD605-5	20/05/2021	REPAIR TUB UP SWTICH
RDT026 : Komatsu HD605-5	21/05/2021	GO NTHROUGH DEFECT LIST & P/ORDER
RDT026 : Komatsu HD605-5	21/05/2021	SORT OUT PB TYRE CO
RDT026 : Komatsu HD605-5	24/05/2021	CHANGE P6 TYRE, LOOK @ DRIVE FAULT, TRACK BACK T/S
RDT026 : Komatsu HD605-5	24/05/2021	P6 CHANGE OUT, TUB SENSOR REPAIR
RDT026 : Komatsu HD605-5	24/05/2021	PARTS
RDT026 : Komatsu HD605-5	26/05/2021	Parts
RDT026 : Komatsu HD605-5	27/05/2021	OPEN CIR WIRING TO H/LIGHTS
RDT026 : Komatsu HD605-5	28/05/2021	P/U KOMATSU
RDT026 : Komatsu HD605-5	2/06/2021	CHECK OVER
RDT026 : Komatsu HD605-5	9/06/2021	INSPECTION & DEFECT LIST
RDT026 : Komatsu HD605-5	10/06/2021	P6 TYRE REPAIR
rdt026 : Komatsu HD605-5	11/06/2021	rear tyre c/o (p6 blon side wall)
RDT026 : Komatsu HD605-5	11/06/2021	SORT OUT P6 REPAIR
RDT026 : Komatsu HD605-5	12/06/2021	CHECK STEERING CYLS & BUSHES
RDT026 : Komatsu HD605-5	15/06/2021	P6 TYRE REPAIR W/ BRIDGESTONE
rdt026 : Komatsu HD605-5	17/06/2021	call out to MVQ for P6 punture repair
RDT026 : Komatsu HD605-5	17/06/2021	OIL & FILTER STOCK TAKE
RDT026 : Komatsu HD605-5	19/06/2021	DO COOLANT & OILS, INSPECT COOLER LEAK
RDT026 : Komatsu HD605-5	21/06/2021	PARK UP & PARK BRAKE FAULKT
RDT026 : Komatsu HD605-5	22/06/2021	SORT SERVICE DEFECTS & PARTS ORDER
RDT026 : Komatsu HD605-5	25/06/2021	GO TO MVQ FOR INSPECTION
RDT026 : Komatsu HD605-5	28/06/2021	INSPECT MACHINE THROUGH PLANT ACTIONS
RDT026 : Komatsu HD605-5	28/06/2021	REPAIR OIL LEAKS & INSPECTION
RDT026 : Komatsu HD605-5	28/06/2021	UPDATE DEFECT LIST
RDT026 : Komatsu HD605-5	29/06/2021	REPAIR & REMOUNT ALTENATOR
RDT026 : Komatsu HD605-5	30/06/2021	MACHINE DOWN, TRANS OVER TEMP & FAULT CODES
RDT026 : Komatsu HD605-5	1/07/2021	DIAGNOSE ELEC FAULTS
RDT026 : Komatsu HD605-5	1/07/2021	DIAGNOSE ELECTRICAL FAULTS

RDT026 : Komatsu HD605-5	1/07/2021	FAULT FIND
RDT026 : Komatsu HD605-5	2/07/2021	FAUKLT FINBD & REVERSE FAULT
RDT026 : Komatsu HD605-5	3/07/2021	SORT PARTS, SERVICE KIT FOR NEXT WEEK
RDT026 : Komatsu HD605-5	5/07/2021	PREP SERVICE PAPERWORK & FILTER KIT
RDT026 : Komatsu HD605-5	6/07/2021	2000 Hr service filters
RDT026 : Komatsu HD605-5	6/07/2021	CLOSE SERVICE
RDT026 : Komatsu HD605-5	6/07/2021	Service filters & O rings
RDT026 : Komatsu HD605-5	7/07/2021	PU KOMATUSU
RDT026 : Komatsu HD605-5	7/07/2021	Service filters & O rings
RDT026 : Komatsu HD605-5	8/07/2021	Service filters & O rings
RDT026 : Komatsu HD605-5	9/07/2021	LOAD FOR 2,000HR SERVICE
RDT026 : Komatsu HD605-5	9/07/2021	LOAD FOR SERVICE
RDT026 : Komatsu HD605-5	9/07/2021	TRANS FAULT, REPAIRS, WASH
RDT026 : Komatsu HD605-5	10/07/2021	C/O TRANS PUMP
RDT026 : Komatsu HD605-5	10/07/2021	REPLACED TRANS PUMP
RDT026 : Komatsu HD605-5	10/07/2021	TRANS FAULT FIND, START SERVICE
RDT026 : Komatsu HD605-5	12/07/2021	2,000HR SERVICE & REPAIRS
RDT026 : Komatsu HD605-5	12/07/2021	2000HR SERVICE & DEFECTS
RDT026 : Komatsu HD605-5	12/07/2021	FINISH SERVICE & REPAIRS
RDT026 : Komatsu HD605-5	12/07/2021	FINISH SERVICE, REPLACE LHR BRAKE RELAY
RDT026 : Komatsu HD605-5	13/07/2021	DIAGNOSE TRANS & COOLING SYSTEM
RDT026 : Komatsu HD605-5	13/07/2021	DIAGNOSE TRANS & ENGINE FAULT
RDT026 : Komatsu HD605-5	13/07/2021	OVERHEATING FAULT
RDT026 : Komatsu HD605-5	13/07/2021	PROCESS OIL SAMPLES / CLOSE SERVICE
RDT026 : Komatsu HD605-5	13/07/2021	TRANS & ENGINE FAULTS
RDT026 : Komatsu HD605-5	14/07/2021	CLEAN UP AFTER REPAIRS
RDT026 : Komatsu HD605-5	14/07/2021	CLEAN UP FROM REPAIRS
RDT026 : Komatsu HD605-5	29/10/2021	PREP / INSPECT FOR TRANSPORT
RDT026 : Komatsu HD605-5	18/11/2021	RELOCATED READY FOR TRANS
RDT026 : Komatsu HD605-5	27/11/2021	MOVE OUT OF CLIENTS WAY
RDT026 : Komatsu HD605-5	10/01/2022	MOVE TRUCK, C/O TYRES
RDT026 : Komatsu HD605-5	2/03/2022	Insurance Claims/Excess
RDT026 : Komatsu HD605-5	5/04/2022	HIGH COOLANT TEMPS
RDT026 : Komatsu HD605-5	17/05/2022	CHASE UP PARTS
RDT026 : Komatsu HD605-5	4/05/2023	#320777 CLEAN AREA IN FRONT OF VEHICLE
RDT026 : Komatsu HD605-5	5/05/2023	#320777LOAD UTE FOR SITE
RDT026 : Komatsu HD605-5	5/05/2023	#320777REMOVE STICKERS
RDT026 : Komatsu HD605-5	10/05/2023	#320979 MVQ INDUCTIONS
RDT026 : Komatsu HD605-5	11/05/2023	#320783 AUCTION PREP
RDT026 : Komatsu HD605-5	11/05/2023	#320783 AUCTION PREP
RDT026 : Komatsu HD605-5	11/05/2023	#320980 PREP FOR SALE

.....

n

.....

