

Edit Fleet Information

Fleet No

GR004

Unit Description

Caterpillar 12H VHP Plus Articulated Grader

Year Model

2005

Engine No

4ZF22064

Chassis No

CBK00971

Rego No

12236E

Location

Ophir Rd



Vehicle Category Plant Equipment

Vehicle type Grader

Vehicle Status Active

All Fuel

Maintenance

Search

Report

2025

March

Job number	Description	Job type	OD
M 00267	replace rotating beacon	Defect	(11078-Hrs)

January

Job number	Description	Job type	OD
M 00259	Hand piece for UHF needs mount	Defect	(11063-Hrs)

2024

October

Job number	Description	Job type	OD
M 00249	Service	750 HR Service	(10993-Hrs)

February

Job number	Description	Job type	OD
H 00186	engine overheating	Breakdown	(10878-Hrs)

Job number	Description	Job type	OD
<u>H 00186</u>	engine overheating	Breakdown	(10878-Hrs)

2023

≡ December

Job number	Description	Job type	OD
<u>M 00186</u>	Speed sensor replaced	Prestart Defect	(10871-Hrs)

≡ November

Job number	Description	Job type	OD
<u>M 00177</u>	Exhaust & defects	Prestart Defect	(10837-Hrs)

≡ August

Job number	Description	Job type	OD
<u>M 00151</u>	service, replace cutting edges	250 HR Service	(10707-Hrs)

≡ June

Job number	Description	Job type	OD
<u>H 00151</u>	replace L/H side cylinder tie rod end and cylinder rod(threads bound up on disassembly)	Breakdown	(10624-Hrs)

≡ April

Job number	Description	Job type	OD
<u>H 00139</u>	Replace batteries & test alternator	Defect	(10500-Hrs)

≡ February

Job number	Description	Job type	OD
<u>M 00112</u>	Fleet - GR004, Prestart - 89, Jobcard By - Katie Collins	Prestart Defect	(10624-Hrs)

2022

≡ December

Job number	Description	Job type	OD
<u>H 00091</u>	replace handpiece	Defect	(10377-Hrs)
M 00092	Fleet number - GR004, Prestart number - 43, Jobcard created by - corey	500 HR Service	(10441-Hrs)

≡ October

Job number	Description	Job type	OD
<u>M 00075</u>	replace broken step	Accident Damage	(10377-Hrs)

≡ September

Job number	Description	Job type	OD
<u>M 00070</u>	replace broken cutting edge	Accident Damage	(10377-Hrs)

≡ July

Job number	Description	Job type	OD
<u>M 00025</u>	replace cutting edges	Defect	(0-Hrs)

≡ March

Job number	Description	Job type	OD
<u>1664</u>	Trans speed sensor fault	Defect	(0-Hrs)

2021



≡ December

Job number	Description	Job type	OD
<u>1622</u>	Diagnose and test AC fault. Found AC compressor had failed. Replace AC compressor. Pressure test AC, vacuum & gas. Test AC is cutting out on thermostat.	Defect	(0-Hrs)

≡ November

Job number	Description	Job type	OD
<u>1595</u>	Service due in 37hrs AC Compressor	250 HR Service	(0-Hrs)

≡ July

Job number	Description	Job type	OD
<u>1536</u>	Wire in E stops. One in cab & 1 external	Defect	(0-Hrs)

≡ April

Job number	Description	Job type	OD
------------	-------------	----------	----

Job number	Description	Job type	OD
1664	Trans speed sensor fault	Defect	(0-Hrs)

2021

December

Job number	Description	Job type	OD
1622	Diagnose and test AC fault. Found AC compressor had failed. Replace AC compressor. Pressure test AC, vacuum & gas. Test AC is cutting out on thermostat.	Defect	(0-Hrs)

November

Job number	Description	Job type	OD
1595	Service due in 37hrs AC Compressor	250 HR Service	(0-Hrs)

July

Job number	Description	Job type	OD
1536	Wire in E stops. One in cab & 1 external	Defect	(0-Hrs)

April

Job number	Description	Job type	OD
1432	Replace edges	Defect	(0-Hrs)

March

Job number	Description	Job type	OD
1425	Replace and adjust blade guides Carry out service and full inspection Repair wiper Repair arm rest Inflate tyres Repair control console lock Repair flashing light	Defect	(0-Hrs)

Fleet Gallery

+ Add Images

Serviced Hrs

11002

Machine Hrs

11195.9

Next Service

11252

Rego Date

23/03/2025

Rego Due Date

23/03/2026

Update