

RM Service Report

Asset Code	Operational No	Registration No	Service Code	Service Description	Days Remaining to Next Service	Scheduled Service Date	Scheduled Service ODO	Earliest Due Date	Remaining Service Days	Remaining Service ODO	Remaining Service Hrs	Remaining Service Fuel	Current ODO	Current Hours	Current Fuel Burn
TR1050		YQ77FU		TANKER - TRI AXLE											
			ANNUAL	Annual Heavy Vehicle Inspection	-819	31/05/2022	0	31/05/2022	-819	0	0	0	0	0	0
			ANNUAL	Annual Heavy Trailer Inspections	-438	16/06/2023	0	16/06/2023	-438	0	0	0	0	0	0
			TRA		0		15,000		0	0	0	0	0	0	0
			TRB	B Service Trailer	-623	13/12/2022	0	13/12/2022	-623	0	0	0	0	0	0
			TRB	B Service Trailer	-446	8/06/2023	0	8/06/2023	-446	0	0	0	0	0	0
			TRB	B Service Trailer	-888	23/03/2022	0	23/03/2022	-888	0	0	0	0	0	0
			TRB	B Service Trailer	-313	19/10/2023	0	19/10/2023	-313	0	0	0	0	0	0
			TRB	B Service Trailer	-136	13/04/2024	0	13/04/2024	-136	0	0	0	0	0	0
			TRC	C Service Trailer	-438	16/06/2023	0	16/06/2023	-438	0	0	0	0	0	0
			TRC	C Service Trailer	-819	31/05/2022	0	31/05/2022	-819	0	0	0	0	0	0

Report Options:

- Sort By - AssetCode
- Asset Code - TR1050
- Service -
- Preferred Workshop - IPS
- Location Method - Location
- Location Code -
- Meter Reading Date - 27/08/2024
- Actual Date: From -
- To -
- Schedule Date: From -
- To -
- Earliest Due Date: From -
- To -
- Show Disposed Assets - no
- Show Inactive Assets - yes
- Work Orders - Complete
- Include Service Codes Allocated to Work Orders - no
- Hide Subsequent Services - no